



FINAL REPORT

Estimate No. : **b1 49728**
Date Estimated : 11/01/2019
Prepared By : **Gary Poh Chai Hoon**

Page No. :

REPAIR FOR -
Karen Chng Chai Pheng
476 Siglap Road
#05-52

- ACCOUNT - 135
China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

Singapore 454946

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKW5229Z	EG29119	26/03/2018	X2 sDrive20i	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper and attachments include making good the boot lid and knocking out dents caused by the accident	1770.00		1,770.00
To spray paint rear bumper and boot lid	1730.00		1,730.00
To check electrical wiring systems and lightings at the rear section for proper function	150.00		150.00
To supply rear emboss number plate	83.00		83.00
Sundries	80.00		80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
REAR BUMPER PANEL PRIMED (M PDC/ICA	1,167.60	1.00		1,167.60
REAR BUMPER TRIM BOTTOM PANEL PAINT	1,602.60	1.00		1,602.60
SET MOUNTING PDC/PMA SENSOR REAR	60.35	1.00		60.35
LETTERING X2	64.10	1.00		64.10
PLAQUE 74MM	71.25	1.00		71.25
GROMMET	0.75	2.00		1.50
LETTERING S DRIVE 20I	96.15	1.00		96.15
# EXPANDING RIVET *	1.35	20.00		27.00

SUPPLEMENTARY ITEMS

Total Labour :	3,813.00
Total Parts :	3,090.55
Total Labour & Parts :	6,903.55
Deduction for Excess :	0.00
Total Repair Costs less Excess:	6,903.55
GST @7%:	483.25
Grand Total :	7,386.80