

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE

INDIA

VEHICLE NO : SHD 3605U

DATE : 14.01.2019

MAKE :

TEL NO : 6542 5119

MODEL : TOYOTA PRIUS

FAX NO : 6542 6039

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT	
BONNET <i>Dented</i>			\$ 950.50	✓
RADIATOR GRILLE <i>7 NH</i>			\$ 438.00	✗ X
LAMP ASSY, FOG, LH <i>mounting broken</i>			\$ 920.00	✗ ✓
FRONT BUMPER COVER <i>Dented</i>			\$ 499.90	✓
FRONT BUMPER REINFORCEMENT <i>2 NH</i>			\$ 696.40	✗ X
FRONT BUMPER REINFORCEMENT ABSORBER <i>2 NH</i>			\$ 115.70	X
FRONT BUMPER SPONGE <i>2 NH</i>			\$ 78.80	✗ X
FRONT BUMPER CENTRE GRILLE <i>NH</i>			\$ 301.90	X
FRONT BUMPER CLIPS <i>Nec</i>			\$ 22.00	✓
FRONT BUMPER SIDE RETAINER, LH <i>S/C</i>			\$ 77.00	X
SUPPORT FR BUMPER, LH <i>NH</i>			\$ 81.70	X
BRACKET, FRONT BUMPER SIDE, LH <i>NH</i>			\$ 82.30	X
UNIT ASSY, HEADLAMP, LH (LED) <i>mounting broken</i>			\$ 3,455.00	✗ ✓
HEAD LAMP PANEL (LH) <i>NH NH</i>			\$ 240.10	X
TOP PANEL CENTRE <i>2 NH</i>			\$ 364.90	✗ ✓
TOP PANEL SIDE, LH <i>2 NH</i>			\$ 69.20	✗ ✓
RADIATOR ASSY <i>2 NH punctured</i>			\$ 1,841.80	✗ ✓
RADIATOR FAN COWLING ASSY <i>NH</i>			\$ 661.30	X
RADIATOR BOTTOM MOUNTING <i>NH</i>			\$ 27.50	X
STAY, RADIATOR SUPPORT, LH <i>NH</i>			\$ 65.70	X
RADIATOR FAN BLADE (LH) <i>NH</i>			\$ 233.10	X
RADIATOR FAN MOTOR (LH) <i>NH</i>			\$ 543.70	X
DEFLECTOR, RADIATOR SIDE, LH <i>NH</i>			\$ 77.00	X
FENDER SUB-ASSY, FRONT LH <i>Dented</i>			\$ 945.30	✓
FRONT FENDER SHIELD, LH <i>dented</i>			\$ 196.60	✓
FRONT FENDER SHIELD CLIP <i>Nec</i>			\$ 3.80	✓
FRONT FENDER HYBRID EMBLEM, LH <i>Nec</i>			\$ 53.50	✓
FRONT WINDSCREEN GLASS MOULDING <i>NH</i>			\$ 208.60	X
FRONT WINDSCREEN GLASS PILLAR <i>NH</i>			\$ 343.10	X
FRONT WHEEL RIM (LH) <i>cut</i>			\$ 1,555.10	✓
FRONT WHEEL HUB CAP (LH) <i>NH</i>			\$ 177.70	X
FRONT WHEEL HUB BEARING (LH) <i>2 Down</i>			\$ 560.10	✗ ✓
FRONT SHOCK ABSORBER (LH) <i>2 distorted</i>			\$ 401.80	✗ ✓
ABSORBER TOP MOUNTING, LH <i>NH</i>			\$ 196.20	X
FRONT SUSPENSION LOWER ARM (LH) <i>2 distorted</i>			\$ 637.50	✗ ✓
FRONT DRIVE SHAFT (LH) <i>2 distorted</i>			\$ 1,310.10	✗ ✓
RACK & PINION ASSY <i>2 Down</i>			\$ 1,634.90	X
BAR, STABILIZER <i>2 distorted</i>			\$ 360.00	✗ ✓
LINK ASSY, FRONT STABILIZER, LH <i>2 distorted</i>			\$ 199.00	✗ ✓
KNUCKLE, STEERING, LH <i>2 distorted</i>			\$ 562.30	✗ ✓
END SUB-ASSY, TIE ROD, LH <i>2 distorted</i>			\$ 158.10	✗ ✓
ENGINE UNDER COVER <i>NH</i>			\$ 457.20	X
ENGINE CROSS MEMBER <i>2 distorted</i>			\$ 2,531.70	✗ ✓
WIRING FRONT <i>2 NH wiring torn</i>			\$ 8,450.50	✗ ✓
SUB TOTAL			\$ 32,786.60	
LESS 20% <i>25%</i>			\$ 6,557.32	
DISCOUNTED TOTAL			\$ 26,229.28	

SHD 3605U

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT	
FRONT DOOR COMFORT LOGO <i>HC</i>			\$ 75.00	NETT ✓
FRONT WINDSCREEN SEALANT <i>HH</i>			\$ 46.00	NETT X
FRONT TYRE (LH) <i>HH</i>			\$ 216.00	NETT X
			\$ 337.00	
LABOUR CHARGE				
Panel Beating			\$ 1,600.00	600/-
Spray Painting Charge			\$ 1,250.00	600/-
Wiring Charge			\$ 50.00	30/-
Tuff Kote			\$ 100.00	40/-
Towing Charge			\$ 50.00	HH
Remove/Refix Undercarriage (FRT)			\$ 200.00	→ 150/-
FRT Wheel Alignment			\$ 120.00	60/-
Remove/Refix Aircon & Refill Gas			\$ 150.00	→ 80/-
Remove/Refix Dashboard			\$ 400.00	→ 150/-
Remove/Refix Fuse Box			\$ 120.00	→ 50/-
Remove/Refix Front Windscreen Glass			\$ 90.00	HH
Remove/Refix Cushion & Upholstery Front			\$ 150.00	HH
Re-set Frt ABS System			\$ 200.00	HH
Diagnosis & Resetting To Erase Fault Code			\$ 480.00	HH
TOTAL LABOUR			\$ 4,960.00	
ESTIMATE TOTAL			\$ 31,526.28	

17/01/2019 @ 1430m
HA Adam
2/5mm 8 days
[Signature]
2K Auto
[Signature]

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

1/1 time

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE

VEHICLE NO: SHD 3605U (Supplementary)

DATE : 21.01.2019

TEL NO : 6542 5119

MAKE :

FAX NO : 6542 6039

MODEL : TOYOTA PRIUS

PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
CONDENSER ASSY, W/RECEIVER <i>BT</i>			\$ 1,336.60
SUB TOTAL			\$ 1,336.60
LESS 20%			\$ 267.32
DISCOUNTED TOTAL			\$ 1,069.28
			\$ 1,336.60

you

22/01/2019

KK Auto

S

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Bealok

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE

VEHICLE NO: SHD 3605U (Supplementary)

DATE : 22.01.2019

TEL NO : 6542 5119

FAX NO : 6542 6039

MAKE :

MODEL : TOYOTA PRIUS

	PARTS DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Remove/Refix Engine			\$ 400.00 <i>150/-</i>
	TOTAL LABOUR			\$ 400.00
	ESTIMATE TOTAL			\$ 400.00
<p><i>Imp 22/01/2019</i></p> <p><i>LKC AAU</i></p> <p><i>[Signature]</i></p>				

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.