


MODEL	: HYUNDAI i40	FAX : 0542 0037	INDIA	
Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper torn			\$ 553.00
	Rear Bumper Clip 10 pcs Hec			\$ 22.00
	Rear Bumper Bracket, RH WH			\$ 35.60
	Rear Fender With Housing (RH) Bnc			\$ 4,736.80
	Rear Fender Inner Lining (RH) defunct			\$ 169.30
	Rear Windscreen Moulding Hec			\$ 28.30
	Rear Door (RH) Distal			\$ 2,201.10
	Rear Door Gear/Regulator (RH) broken			\$ 242.80
	Rear Door Power Motor (RH) WH			\$ 158.60
	Rocker Panel Outer Garnish (RH) WH			\$ 341.40
	Rear Tyre Rim (RH) WH			\$ 325.30
	Rear Wheel Hub-Cap (RH) cnt			\$ 107.10
	Rear Wheelbearing ING & Hub 2 Distal			\$ 362.00
	Rear Trailing Arm (RH) 2 distal			\$ 192.00
	Rear Assist (RH) 2 distal			\$ 145.70
	Rear Shock Absorber (RH) 2 distal			\$ 276.30
	Rear Shock Absorber Mounting (RH) WH			\$ 81.30
	Rear Crossmember 2 distal			\$ 1,021.50
	Stabilizer Bar 2 distal			\$ 199.60
	Stabilizer Link 2 distal			\$ 85.90
	Rear Upper Arm (RH) 2 distal			\$ 335.75
	Rear Lower Arm (RH) 2 distal			\$ 353.80
	Rear Knuckle Arm (RH) 2 distal			\$ 545.60

SHA 9815G

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			\$ 1,500.00 600/-
	Spray Painting Charge			\$ 1,000.00 600/-
	Wiring Charge			\$ 50.00 44
	Tuff Kote			\$ 100.00 40/-
	Towing Charge			\$ 50.00 44
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00 80/-
	Remove/Refix Rear Windscreen Glass			\$ 120.00 80/-
	Remove/Refix Reverse Sensor			\$ 120.00 40/-
	Transfer of Door			\$ 120.00 60/-
	Remove/Refix Undercarriage (RR)			\$ 200.00 150/-
	Rear Wheel Alignment			\$ 120.00 60/-
	Re-set Rear ABS System			\$ 200.00
	Re-set Rear Power Window System			\$ 200.00 } 180/-
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00
	TOTAL LABOUR			\$ 4,410.00
	ESTIMATE TOTAL			\$ 14,768.60
23/01/2019 @ 1030am HA Ardun 4/Sum 7 days.  Rya LKK Auto 				
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				