

Think One Autocare Pte Ltd
No.18 Defu Avenue 2
Singapore 539522
Tel: 6844 3300 Fax: 6842 4988

PC4501P Yutong ZK6107H

No	Qty	Parts Description	Estimated Parts Price
1	1	Rear left lower panel assy	12/201 \$ 8,605.00 ✓
2	3	Rear left lower panel reflector	17 \$ 180.00 X
3	1	Rear left complete quarter panel	20/201 \$ 3,605.00 ✓
4	1	Rear left lower panel cover	2 \$ 280.00 X
			\$ 12,670.00
Less 10%			\$ 1,267.00
			<u>\$ 11,403.00</u>

Special Nett Items

1	1set	Rear left panel sticker	NF \$ 800.00 X
			<u>\$ 800.00</u>

Total parts

\$ 12,203.00

Not Attach
LAW
2/5/9
4 day
24/1/19
Wright Atkin

Think One Autocare Pte Ltd
No.18 Defu Avenue 2
Singapore 539522
Tel: 6844 3300 Fax: 6842 4988

PC4501P Yutong ZK6107H

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten rear left affected area and replace rear left damaged parts.	\$ 1,200.00 1000
2	To putty and spray painting rear left portion.	\$ 1,200.00 1000
3	To apply anti rust proofing to rear left affected area.	\$ 120.00 50
Total labour :		\$ 2,520.00

Total parts : \$ 12,203.00

Total labour : \$ 2,520.00

Total repair cost : \$ 14,723.00

LKB Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: