

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel:62898126 Fax :62870590

Company Reg No:200704370C GST Reg No ::200704370C

DATE : 22/1/2019

M/S India International Insurance Ltd

DEAR SIR / MADAM

ESTIMATE REPAIR COST FOR GR8235J TOYOTA HIACE LH1620009802

QTY	List Items	AMOUNT
1	1 PC SLIDING DOOR (\$S1128.40 less 25%)	<i>n</i> \$ 846.30 <i>x</i>
2	COMPANY ART WORK	<i>ner</i> \$ 420.00 <i>3805~</i>
3	TO REMOVE AND RENEW PARTS	\$ 520.00 <i>300</i>
4	TO PUTTY AND SPRAY PAINTING	\$ 580.00 <i>350</i>
5	CHECK HARNESS	<i>11</i> \$ 35.00 <i>x</i>
6	TUFF KOTE	<i>11</i> \$ 80.00 <i>x</i>
		<u>\$ 2,481.30</u>

*Not Authorized
make
works
29/1/19
P/P \$1030
2 by.
Whisper After repair*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: