趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5 #01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047 Tel: 6484 1626 (24Hrs) Fax: 6484 0465 Business Reg. No: 221880/00C GST Reg. No: MX-0486007-AO

To: AIG Asia Pacific Insurance Pte Ltd

Accident Date: 04.01.2019

Nos Whash Repains

Policy No:	Third Party	
Date:	22.01.2019	

Specialised in Car Painting, Welding,

FSTIMATE

承接汽车烧焊喷漆及 代理各种车辆赔偿

iel-Beating	g and Insurance Claim.		代理各种车辆赔偿
数 量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost Of Repair To "BMW 5281" Reg. No. SJX7444L Claiming Against Your Insured Reg. No. SLG5658R		
1pc 12pcs 1pc 1pc	Rear Bumper Rear Bumper Clips Rear Bumper Corner Retainer LH Rear Bumper Side Core LH	3.50	1,700.00 42.00 42.00 6 165.00 7 209.00 7 2,116.00 105.80
	Less 5%	to	2,010.20 <i>(4)</i> 500.00
	Labour Charge - Panel Beating, Repairing Of Rear Fender and Par Replacement	is	600.00
	To Respray Affected Areas	Total:	3,110.20
	Ac	LKk Auto Consultants he the Repairer of the follow. To resurvey before the spray To display demanded the spray Parts prices are surject to continue party survey as an arriving No illegal in contractions it is allowed to the spray survey as an arriving to the spray survey as an arriving the survey as a sur	g: ainting p resurvey mation GLI Prejudice* basis