

Adrian Lee - AKG



CHEW MOTOR PTE. LTD.

1 Kaki Bukit Avenue 6, Blk A #01-11 Autobay@Kaki Bukit Singapore 417883

Tel: 6509 5545

Fax: 6509 5567

Website: www.chewmotor.com

Registration No.: 201718369R

19/01/2019

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TPA16
Poh kin

Accident date: 18/01/2019

Estimated repair cost for vehicle no: SLF7159G TOYOTA VIOS E AUTO 1.5 '15

CHASSIS: MHFBT9F3506028142

S/n	Qty	Items	U/price	Amount
1	1	Front Bumper <i>torn</i>		\$381.10 ✓
2	8	Front Bumper Clip <i>new</i>	\$6.50	\$52.00 30
3	1	Front L/H Bumper Side Retainer <i>new</i>		\$132.10 ✓
4	1	Front L/H Head Lamp <i>lit</i>		\$374.45 ✓
5	1	Front L/H Fender <i>dentured</i>		\$581.10 ✓
6	1	Front L/H Fender Cowling <i>rebound</i>		\$191.60 ✓
7	8	Front L/H Fender Cowling Clip <i>new</i>	\$6.50	\$52.00 30
8	1	Front L/H Rim <i>lit</i>		\$850.00 400 (sw)
9	1	Front L/H Tyre <i>new</i>		\$450.00 +
10	1	Front L/H Lower Arm <i>3 best</i>		\$561.60 ✓
11	1	Front L/H Knuckle Arm		\$581.45 ✓
12	1	Front L/H Knuckle Arm Bearing <i>new</i>		\$191.25 ✓
13	1	Front L/H Shock Absorber <i>set</i>		\$561.80 ✓
14	1	Front L/H Drive Shaft <i>7 item</i>		\$1,712.45 +
15	1	Front Steering Rack		\$1,817.40 +
16	1	Front Crossmember		\$972.40 +

Subtotal :- \$9,462.70

3616.45 S.N. 400

2712.33

Labour charges

To remove & refit front L/H undercarriage		\$380.00	220
To remove & refit front drive shaft, steering rack & crossmember		\$450.00	X
To check wheel alignment		\$150.00	80
To check wiring		\$60.00	30
Tuff kote		\$150.00	X
Panel beating	1330	\$850.00	400
Spray painting		\$850.00	600.
Subtotal :-		\$2,890.00	
Total:-		\$12,352.70	

total: 4442.33
L/s: 3.5K

05 days.

3.5K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: