

ALG - Adrian LKE



CHEW MOTOR PTE. LTD.

1 Kaki Bukit Avenue 6, Blk A #01-11 Autobay@Kaki Bukit Singapore 417883

Tel: 6509 5545

Fax: 6509 5567

Website: www.chewmotor.com

Registration No.: 201718369R

25/01/2019

Blk 1 Kaki Bukit Ave 6
01-43
Singapore 417883

TP ALG.

Vic

WBAYE22090DZ21149

Accident date: 21/01/2019

Estimated repair cost for vehicle no: SKN8997S BMW 730Li 3.0 A '14

CHASSIS: WBAYE22090DZ21149

S/n	Qty	Items	U/price	Amount
1	1	Front Bonnet <i>Dented</i>		\$2,983.00 ✓
2	2	Front Bonnet Hinge	\$92.75	\$185.50 ✓
3	1	Front Bonnet Insulator <i>3xHP</i>		\$302.00 ✓
4	10	Front Bonnet Insulator Clip	\$6.50	\$65.00 ✓
5	1	Front Bonnet Emblem Logo <i>New</i>		\$71.25 ✓
6	1	Front R/H Fender <i>Dented</i>		\$1,231.15 ✓
7	1	Front R/H Fender Chrome Moulding <i>New</i>		\$78.85 ✓
8	1	Front R/H Fender Cowling <i>3xHP</i>		\$279.70 ✓
9	10	Front R/H Fender Cowling Clip <i>New</i>	\$6.50	\$65.00 ✓
10	1	Front R/H Head Lamp <i>Lot</i>		\$5,062.80 ✓ 3680
11	1	Front R/H Head Lamp Lower Bracket <i>Cracked</i>		\$131.65 ✓
12	1	Front Bumper <i>Dented</i>		\$1,540.90 ✓
13	1	Front Bumper Wiper Nozzle Cover <i>Missing</i>		\$51.95 ✓
14	1	Front Bumper Wiper Nozzle Motor Assy <i>Damaged</i>		\$183.80 ✓
15	1	Front Bumper Inner Sponge <i>Cracked</i>		\$70.45 ✓
16	1	Front Bumper Reinforcement <i>New</i>		\$830.95 ✓
17	1	Front R/H Bumper Side Retainer <i>New</i>		\$34.25 ✓
18	1	Front R/H Bumper Fog Lamp		\$441.95 ✓
19	1	Front R/H Bumper Fog Lamp Cover <i>3xHP</i>		\$112.00 ✓
20	1	Front R/H Bumper Fog Lamp Top Chrome Moulding <i>New</i>		\$88.70 ✓
21	1	Front R/H Bumper Camera <i>Damaged</i>		\$681.10 ✓
22	1	Front R/H Bumper Sensor <i>Damaged</i>		\$368.80 ✓ 280
23	1	Front R/H Rim <i>Lot</i>		\$1,037.20 ✓
24	1	Front R/H Tyre		\$450.00 ✓
25	1	Front R/H Lower Arm <i>3xHP</i>		\$606.25 ✓
26	1	Front R/H Knuckle Arm		\$659.40 ✓
27	1	Front R/H Knuckle Arm Bearing		\$503.00 ✓
28	1	Front R/H Shock Absorber		\$1,385.65 ✓

12056.15

11453.34

Subtotal :- \$19,502.25

Labour charges

To remove & refit front bumper sensor & camera

~~\$180.00~~ 150.

To remove & refit front R/H undercarriage

~~\$380.00~~ X

To check wheel alignment

~~\$150.00~~ X

To check wiring

~~\$60.00~~ 30

Tuff kote

~~\$100.00~~ X

Panel beating

1680.

~~\$1,400.00~~ 750

Spray painting

~~\$1,400.00~~ 750.

Subtotal :- \$3,670.00

Total:- \$23,172.25

total: 13133.34
h/s: 10.5K
050mgs.

10.5K.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: