

Trans-cab Auto Services Pte Ltd

AAD1901-182

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5216B*Not Notwithstanding
to Sup @ 30%*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHC 5216B

VF1ABL15AUC276169

RENAULT

LATITUDE

18.1.2019

AIG

19/2/2014

	PART
1	FENDER PANEL REAR RH
1	FENDER PANEL INNER TRIM REAR
1	WHEELARCH REAR RH
1	ROCKER PANEL INNER GARNISH RH
1	ROCKER PANEL INNER RH
1	ROCKER PANEL CENTER RH
1	BUMPER COVER REAR
1	BUMPER LOWER REAR
1	BUMPER BRACKET CTR REAR
1	BUMPER BRACKET SIDE RH REAR
1	BUMPER RETAINER RH REAR
1	REAR TAILAMP RH

LIST

\$	<i>rn</i>	3,299.13
\$	<i>rn</i>	671.45
\$	<i>rn</i>	543.47
\$	<i>rn</i>	466.51
\$	<i>rn</i>	1,024.79
\$	<i>rn</i>	990.25
\$	<i>rn</i>	1,108.46
\$	<i>rn</i>	768.84
\$	<i>rn</i>	113.47
\$	<i>rn</i>	135.97
\$	<i>rn</i>	44.99
\$	<i>rn</i>	552.55

X

\$ 9,719.8810% **\$ 971.99**

\$ 8,747.89

Specical Nett

1SET	PARKING AID
1SET	REAR BUMPER CLIP
1SET	BUMPER BRACKET CTR CLIP
1SET	BUMPER BRACKET SIDE CLIP RH RR
1SET	BUMEPR RETAINER RH CLIP RR
1SET	BUMEPR BRACKET SIDE CLIP LH RR
1SET	BUMEPR RETAINER CLIP LH RR
1SET	BUMPER LOWER REAR RIVET
1SET	BUMPER LOWER REAR CLIP

\$	<i>rn</i>	700.00
\$	<i>rn</i>	66.00
\$	<i>rn</i>	33.00
\$	<i>rn</i>	10.00
\$	<i>rn</i>	20.00
\$	<i>rn</i>	10.00
\$	<i>rn</i>	20.00
\$	<i>rn</i>	22.00
\$	<i>rn</i>	66.00

X

TOTAL \$ 947.00

Trans-cab Auto Services Pte Ltd**AAD1901-182**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5216B

TOTAL PARTS	\$	9,694.89
--------------------	-----------	-----------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	3,000.00 <i>Sc1</i>
Putty and spray painting of the affected portion.	\$	3,000.00 <i>2201</i>
To rust-proofing of the affected areas.	\$	<i>na</i> 170.00 <i>X</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>na</i> 380.00 <i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>na</i> 220.00 <i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>na</i> 170.00 <i>X</i>
To Check Electrical Lighting Concerned.	\$	<i>na</i> 170.00 <i>X</i>
To transfer of Rear fender fittings, attachment and perform water seepage test.	\$	<i>na</i> 380.00 <i>X</i>
To transfer of Rear bumper fittings, attachment and perform water seepage test.	\$	<i>na</i> 380.00 <i>X</i>
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	<i>na</i> 380.00 <i>X</i>

TOTAL	\$	8,250.00
--------------	-----------	-----------------

Over All Total	\$	17,944.89
-----------------------	-----------	------------------

LUMP SUM (REPAIR DAY)**~~10~~ DAYS***1 day*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer