

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	24 Jan 2019 Edit Reg		22 Jan 2019 00:00 Edit Adj Rpt	S\$1,540.90 Edit Estimates	S\$1,540.90 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: VERONICA TAN WAN YEE (CHEN WANYU) , ID: S7716245C, Tel: +6599999999									
Main Claimant: BIS MOTORING PTE LTD									
Vehicle Reg. No.:	SLZ2673R	Date of Loss:	10/09/2018 18:00 - :59 [4 Months and 14 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 0711585197SG	Policy/Cover Note No.:	2100286111 (Comprehensive)						
Vehicle Reg. No. (Insured):	SKD8314R	Policy No. (Claimant):	5096898757						
		Excess:							
Repairer:	Xin Hua Workshop Pte Ltd (HQ) 23 Kaki Bukit Ave 4 #04-01, 415933 Kaki Bukit - Tel: 68441985 8292 5595								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Goh, Jeremy-CX] Jeremy.Goh@aig.com								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 01/02/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLZ2673R (0711585197SG)**
[SKD8314R]
TP
BIS MOTORING PTE LTD
Sep 10 2018 6:00PM
[VERONICA TAN WAN YEE (CHEN WANYU)]
Xin Hua Workshop Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio				View View in Browser ▼	
Video				1 per page ▼	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	14/03/19 09:45	TP VIDEO FOOTAGE TP VIDEO FOOTAGE		Load MP4	
Letters/Correspondences				1 per page ▼	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown		Edit	
Photos/Images				3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	14/03/19 09:32	General View		Load JPG	☒
2	14/03/19 09:32	Chassis Number		Load JPG	☒
3	14/03/19 09:32	General View		Load JPG	☒
4	14/03/19 09:32	General View		Load JPG	☒
5	14/03/19 09:32	General View		Load JPG	☒
6	14/03/19 09:32	General View		Load JPG	☒
7	14/03/19 09:32	General View		Load JPG	☒
8	14/03/19 09:32	General View		Load JPG	☒
9	14/03/19 09:32	General View		Load JPG	☒
10	14/03/19 09:32	General View		Load JPG	☒
11	14/03/19 09:32	General View		Load JPG	☒
12	14/03/19 09:32	General View		Load JPG	☒
13	14/03/19 09:32	General View		Load JPG	☒
14	14/03/19 09:32	General View		Load JPG	☒
15	14/03/19 09:32	General View		Load JPG	☒
16	02/04/19 19:04	Reinspection Photo		Load JPG	☒
17	02/04/19 19:04	Reinspection Photo		Load JPG	☒
18	02/04/19 19:04	Reinspection Photo		Load JPG	☒
Documentation				1 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	23/01/19 18:31	TP GIA REPORT		Load PDF	
2	28/04/20 18:07	Authorisation to Act		Load PDF	
3	28/04/20 18:07	LETTER TO OI		Load PDF	
4	28/04/20 18:07	LOD		Load PDF	
5	28/04/20 18:07	LTA SEARCH		Load PDF	
6	28/04/20 18:07	Release Voucher		Load PDF	
7	28/04/20 18:07	RENTAL RECEIPT		Load PDF	
8	28/04/20 18:07	WORKSHOP INVOICE		Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	24/01/19 14:09	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKD8314R (Insd veh)	Model:	KIA CARENS 1.7 D DCT 5DR
	SLZ2673R (TP veh)		FWD (A)
Date of Accident:	10/09/2018		

Global Sum Settlement	:	[]	Yes	[X]	No	
Repair Estimate	:	\$				5,065.80
Final Repair Cost	:	\$				1,540.90
Loss of Use	:	\$				days at \$0.00 per day
Rental (if any)	:	\$				428.00 4 days
LTA / GIA Search Fee	:	\$				7.49
Others:	:	\$				
	:	\$				
Final Settlement Sum	:	\$				1,976.39
Is Third Party Workshop GIA Registered? [] YES [X] NO (Kindly indicate below)						
A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)						
B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____						
BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)						
<i>* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.</i>						
Remarks _____ _____ _____						

Payment Instruction: Payee's Breakdown			
1)	Xin Hua Workshop Pte Ltd	: \$	1,976.39
2)		: \$	
3)		: \$	
4)		: \$	

NUR SHAQILAH BTE ABDOL WAHAB

28 Apr
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG19001524/AEA3S2**Date:** 28/04/2020REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100286111
Claimant Vehicle No :	SLZ2673R	Insured Vehicle No :	SKD8314R
Date of Loss:	10/09/2018	Nature of Claim:	TP
		Claim No:	0711585197SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLZ2673R	Engine No:	D4FDJH550999
Make & Model:	KIA CARENS, 1.7 D DCT 5DR FWD (A)	Chassis No:	KNAHU815VJ7203765
Reg. Date:	27/04/2018 (Man. Year: 2018)	Odometer:	72497 km
Colour:	Red		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Grenlander 6 mm	Rear Left Side:	Grenlander 6 mm
Front Right Side:	Grenlander 6 mm	Rear Right Side:	Grenlander 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,565.80	810.90	2,754.90	77.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,500.00	730.00	770.00	51.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	5,065.80	1,540.90	3,524.90	69.58
+ Car Rental (4.0 x S\$100.00/day + 7.00% GST) (S\$)		428.00		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		1,976.39		

INSPECTION

Date of Assignment:	22/01/2019	
Date Inspected:	22/01/2019	Inspected At: Xin Hua Workshop Pte Ltd (HQ) 23 Kaki Bukit Ave 4 #04-01 Singapore 415933
Estimated Period of Repair:	3.0 days	

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Deformed	764.00 FL	*764.00 FL
2	1		*FRT BUMPER KIA LOGO	Necessary	91.00 FL	*91.00 FL
3	1		*FRT BUMPER TOP RUBBER	Not Necessary	38.00 FL	*- FL
4	10		*FRT BUMPER CLIP	Necessary	25.00 FL	*25.00 FL
5	1		*FRT BUMPER SIDE RETAINER RH	Necessary	21.00 FL	*21.00 FL
6	1		*FRT BUMPER BRACKET RH	Not Necessary	36.00 FL	*- FL
7	1		*FRT BUMPER SPONGE	Not Necessary	117.00 FL	*- FL
8	1		*RH HEADLAMP	Not Necessary	1,713.00 FL	*- FL
9	1		*RH FOG LAMP	Not Necessary	247.00 FL	*- FL
10	1		*RH FOG LAMP COVER	Not Necessary	156.00 FL	*- FL
11	1		*FRT FENDER RH	Repair	445.00 FL	*- FL
12	1		*FRT FENDER INNER SHIELD RH	Not Necessary	96.00 FL	*- FL
13	1		*FRT WIPER WASHER TANK ASSY	Not Necessary	163.00 FL	*- FL
14	1		*FRT NUMBER PLATE	Not Necessary	45.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	3,957.00	901.00
- List Item Discount on L Items 10.00/10.00% (\$)	391.20	90.10
Total Parts (\$)	3,565.80	810.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE / RENEW THE ACCIDENT DAMAGED PORTION, TO PANEL BEATING, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS.	New	600.00	300.00
2	CARRY OUT SPRAY PAINTING ON AFFECTED AREA. FRT BUMPER, FRT FENDER RH, FRT SUPPORT PANEL.	New	600.00	400.00
3	TO DISCONNECT FRONT WIRE HARNESS OF ELECTRICAL COMPONENT T FACILITATE REPAIRS, RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR.	New	180.00	30.00
4	TO REMOVE AND REFIX FRONT BUMPER SENSOR AND CONDUCT TEST.	New	120.00	0.00
Gross Labour Cost (\$)			1,500.00	730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >