

XIN HUA WORKSHOP PTE. LTD.

23 Kaki Bukit Avenue 4, #04-01 (South Wing) Singapore 415933

Tel : 6844-1985 Fax : 6844-5185

Reg : 201838521G

Repair Estimate

Date :21/01/2019

Reference: KIA
Make: CARENS

To Whom It May Concern

Dear Sir,

RE: VEHICLE :SLZ2673R
CHASSIS NO.: KNAHU815VJ7203765
ENGINE NO.: D4FDJH550999

Name of insured :BIS MOTORING PTE LTD

Date of accident.: 10/09/2018

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)
1	1	FRT BUMPER	\$ 764.00
2	1	FRT BUMPER KIA LOGO	\$ 91.00
3	1	FRT BUMPER TOP RUBBER SEAL	\$ 38.00
4	10	FRT BUMPER CLIP	\$ 25.00
5	1	FRT BUMPER SIDE RETAINER RH	\$ 21.00
6	1	FRT BUMPER BRACKET RH	\$ 36.00
7	1	FRT BUMPER SPONGE	\$ 117.00
8	1	RH HEADLAMP	\$ 1,713.00
9	1	RH FOG LAMP	\$ 247.00
10	1	RH FOG LAMP COVER	\$ 156.00
11	1	FRT FENDER RH	\$ 445.00
12	1	FRT FENDER INNERSHIELD RH	\$ 96.00
13	1	FRT WIPER WASHER TANK ASSY	\$ 163.00

Parts Total: \$ 3,912.00
Less 10%: \$ 391.20
Total : \$ 3,520.80

Labour

No.	Labour Description	Price (SGD)
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	\$ 600.00
2	Carry out spray painting on affected area, FRT BUMPER, FRT FENDER RH, FRT SUPORT PANEL	\$ 600.00
3	To disconnect front wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 180.00

<u>4</u>	To remove and refix front bumper sensor and conduct test	\$ 120.00
----------	--	-----------

Others

730

Labour Total : \$ 1,500.00

Other Description

<u>No.</u>		<u>Price (SGD)</u>
<u>1</u>	FRT NUMBER PLATE <i>new</i>	\$ 45.00

Other Total: \$ 45.00

TOTAL: \$ 5,065.80
GST (7%): \$ 354.61

GRAND TOTAL : \$ 5,420.41

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

Yours faithfully

Service Advisor
Kelvin Chew
HP: 8292 5595 Fax: 68445185

Adrian Ling
P/P - 22/01/19.
032yr.
total: 1540.50
(P/P)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: