

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 211S**AAD1901-190***Not Authorized*
11 Sep 8 4400

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration :

SHD 211S

VF1ABL15AUC282192

RENAULT

LATITUDE

19.1.2019

AIG

16/10/2015

PART**LIST**

1	DOOR PANEL REAR RH	\$	1	2,844.66
1	DOOR GUIDE REAR RH	\$	1	176.82
1	DOOR HINGE UPPER RH	\$	1	274.50
1	DOOR HINGE LOWER RH	\$	1	300.55
1	DOOR CHECK REAR LH/RH L70Y	\$	1	203.06
1	DOOR LOCK REAR RH	\$	1	908.75
1	DOOR HANDLE OUTER REAR RH	\$	1	126.49
1	DOOR HANDLE CAP REAR RH	\$	1	35.52
1	DOOR HANDLE SEAL REAR RH	\$	1	7.89
1	DOOR HANDLE COVER REAR RH	\$	1	13.22
1	DOOR HANDLE MODULE REAR RH	\$	1	133.60
1	DOOR REGULATOR REAR RH	\$	1	1,135.10
1	DOOR REGULATOR MOTOR REAR RH	\$	1	893.75
1	DOOR REGULATOR NUT REAR L70Y	\$	1	12.43
1	DOOR REGULATOR MOTOR SCREW REAR L70Y	\$	1	6.31
1	DOOR FINISHER REAR RH	\$	1	423.10
1	DOOR MOULDING REAR RH	\$	1	176.82
1	DOOR MOULDING CLIP L70Y	\$	1	5.92
1	DOOR MOULDING SCREW L70Y	\$	1	6.91
1	DOOR CASING REAR RH	\$	1	1,509.06
1	DOOR WATER SHIELD REAR RH	\$	1	30.39
1	DOOR CASING CLIP	\$	1	12.63
1	DOOR CASING LIGHT L70Y	\$	1	48.74
1	DOOR FINISHER INNER REAR RH	\$	1	323.44
1	DOOR FINISHER BRACKET INNER REAR RH	\$	1	46.97
1	DOOR FINISHER BRACKET INNER REAR RH	\$	1	20.33
1	DOOR FINISHER BRACKET INNER REAR RH	\$	1	20.33
1	DOOR FINISHER BRACKET INNER REAR RH	\$	1	20.33
1	DOOR GRAB HANDLE REAR RH	\$	1	210.96

Trans-cab Auto Services Pte Ltd**AAD1901-190**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 211S

1	DOOR BLIND REAR RH	\$	<i>SL</i> 741.80 X
1	DOOR WHEATHESTRIIP REAR RH	\$	<i>SL</i> 410.66 X
1	DOOR SEAL REAR RH	\$	<i>SL</i> 162.02 X
1	DOOR GLASS RUNNER SEAL REAR RH	\$	<i>SL</i> 229.31 X
1	DOOR WAIST SEAL OUTER REAR RH	\$	<i>SL</i> 334.69 X
1	DOOR WAIST SEAL INNER REAR RH	\$	<i>SL</i> 115.64 X
1	FENDER PANEL REAR RH	\$	<i>BZ</i> 3,299.13 ✓
1	FENDER PANEL INNER TRIM REAR	\$	<i>SL</i> 671.45 X
1	WHEELARCH REAR RH	\$	<i>SL</i> 543.47 X
1	DOOR MIRROR ASSY RH	\$	<i>SL</i> 1,483.40 X
1	ROCKER PANEL INNER GARNISH RH	\$	<i>SL</i> 466.51 X
1	ROCKER PANEL INNER RH	\$	<i>SL</i> 1,024.79 X
1	ROCKER PANEL CENTER RH	\$	<i>SL</i> 990.25 X
1	BUMPER COVER REAR	\$	<i>BZ/SL</i> 1,108.46 ✓

	\$	21,510.16
10%	\$	2,151.02
	\$	19,359.14

Specical Nett

1	FRONT DOOR ADVERTISEMENT STICKER	\$	<i>nn</i> 300.00
1	REAR DOOR ADVERTISEMENT STICKER	\$	<i>nn</i> 300.00
1	ROCKER PANEL ADVERTISEMENT STICKER	\$	<i>nn</i> 300.00
1	DOOR CHECK BOLT	\$	<i>nn</i> 22.69
1	DOOR GUIDE SCREW	\$	<i>nn</i> 10.85
1	DOOR HINGE BOLT	\$	<i>nn</i> 10.85
1	DOOR HINGE NUT RH	\$	<i>nn</i> 14.60
1	DOOR CHECK BOLT	\$	<i>nn</i> 22.69
1	DOOR CHECK NUT	\$	<i>nn</i> 3.75
1	DOOR LOCK SCREW L70Y	\$	<i>nn</i> 6.12
1	DOOR CATCH SCREW L70Y	\$	<i>nn</i> 10.06

TOTAL	\$	1,001.63
--------------	----	-----------------

TOTAL PARTS	\$	20,360.77
--------------------	----	------------------

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 211S**AAD1901-190****LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,500.00	700l
Putty and spray painting of the affected portion.	\$	4,200.00	860l
To rust-proofing of the affected areas.	\$	170.00	30l
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	100l
To check steering geometry and computer wheel alignment	\$	220.00	nn X
To transfer of tire, rim and on wheel balancing.	\$	170.00	nn X
To Check Electrical Lighting Concerned.	\$	170.00	20l
To transfer of front fender fittings, attachment and perform water seepage test.	\$	380.00	nn X
To transfer of front door fittings, attachment and perform water seepage test.	\$	380.00	nn X
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	380.00	nn X
To transfer of Rear fender fittings, attachment and perform water seepage test.	\$	380.00	nn X
To transfer of Rear bumper fittings, attachment and perform water seepage test.	\$	380.00	nn X
Towing Fees.	\$	120.00	nn X

Trans-cab Auto Services Pte Ltd**AAD1901-190**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 2115

To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.

\$ *na* 380.00 *X*

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$ *na* 380.00 *X*

TOTAL \$ 12,590.00

Over All Total \$ 32,950.77

PART-BY-PART (REPAIR DAY)*15 DAYS**5 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: