

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP/AIG/AMK

Claim Type: Third Party

Accident Date: 17/01/2019

Estimate No: ES1991272/AMK

Date: 18 Mar 2019

Policy No: DMPCSN1728981801

Veh Reg No: SBZ9559K

Make/Model: HONDA S2000 2.2 TYPE-S M

Chassis No: AP21100922

Engine No: F22C1010924

Reg. Date: 18/04/2009

Estimate Repair Cost to Vehicle No :SBZ9559K

Description	U/Price	Quantity	List Price	Amount
List Price			<u>S\$</u>	<u>S\$</u>
1 FRONT LH FENDER	752.10	1 PC	752.10	✓
2 FRONT LH FENDER EMBLEM 'S2000'	89.10	1 PC	89.10	✓
3 FRONT LH FENDER INNER SHIELD CLIP	4.30	6 PC	25.80	✓
4 FRONT LH RIM	1,105.60	1 PC	1,105.60	✓
			1,972.60	
		Less 20%	394.52	1,578.08
Labour				
5 REMOVE & REFIX FRT BUMPER, HEADLAMP, FRT LH FENDER & REALIGN THE SAME	400.00	1 LA	400.00	300
6 PUTTY & RESPRAY FRT LH FENDER & ALL AFFECTED AREAS	350.00	1 LA	350.00	250
7 REMOVE & REFIX FRT LH RIM, TYRE, BALANCE & REALIGN THE SAME	50.00	1 LA	50.00	20
8 TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	60.00	1 PC	60.00	✓
9 RUSTPROOFING	30.00	1 LA	30.00	✓
			890.00	890.00
Total			S\$ 2,468.08	
Add GST @ 7%			172.77	
Total Amount Payable			S\$ 2,640.85	

* SURVEY VEHICLE AT ANG MO KIO WORKSHOP

For Cheng Hoe Motor Pte Ltd

DORLYN LI

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: