

INS. CASE OWNER:

ASSIGNMENT

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. : SJW 53720

Name of Insured :

Insured Tel No. : HP:

Excess Sec II : SS D.O.A : 21/1/19

Is driver the owner? (YES / NO) Nature of Accident :

If NO, Driver Name / Age :

Driver Tel No. :

(V/L: YES / NO)

Claim No. :

Policy No. :

Make / Model :

Place of Accident :

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability : % Final ? Yes / No



INSRS:

WSP: Premier

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

24.05.2019

PRE PASS TO TYPIST TO PREPARE REPORT

REPORT DONE

FILE REVIEWED. OI WITH STOP LINE

02/04/19

STATE MANDATE APPROVAL TO LPC

02/04/19

LPC APPROVED MANDATE. LINK - 011.310.0000

SEND 1ST OFFER TO TP.

TP ACCEPTED OFFER.

ALL DOCS IN ORDER.

TO CLOSE.

PRELIMINARY ADVICE

Date/Time: 24/01/19

Sent By: 92

FINALIZATION

Date/Time:

Confirm with:

Confirm by: 92

Repair Cost:

1/2 \$59,600

(10 days) Reduction: 19 %

Email

Call

FINAL SETTLEMENT

Date/Time: 04/04/19

Confirm with: 92

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No. :

If NO or B 28, Ass. Lia :

Repair Cost:

W/SA \$510,373.00

OI TRAVEL STRAIGHT ALONG MINOR ROAD THT TP.

Loss of Rental (LOR):

\$51,104.07

(11 days) X \$100.37

Loss of Use (LOU):

\$5 -

(\$ x days)

Loss of Income (LOI):

\$5 -

(\$ x days)

LOR only ☒ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

\$52.00

Medical:

\$5 -

Disbursement:

\$5 -

(e.g. Tow/ Independent)

Legal Cost

\$5 -

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$400.00

Total:

\$511,378.07

Global Sum SS: 11,200.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$511,200.00

Name 1:

PREMIER AUTOMOTIVE SERVICES PTE LTD

Payee 2: (Strike if N.A.)

\$5 -

Name 2:

-

Payee 3: (Strike if N.A.)

\$5 -

Name 3:

-

Surveyor: Kalvin

REF: _____

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspected Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 10 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHC 6762 Yr Regn: 17 Feb, 2014

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: KIA optima c.c. 1.6

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 62862 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KNA6M44MB5454277

Gen. Cond: Good / FF / Poor / Burnt

Steering: In order / FF / Jammed / Leaked / Burnt or

Brake: In order / FF / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD FF / Rim or

Tyre Size: F: 205 / 65 R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Hankook

Front 7 mm Rear 7 mm

R/Bal. 7 mm L/Bal. 7 mm

D.O.A. 21/1/19 D.O.I. 22/1/19

Survey held at Premier

Des. of Damages: Frt / Rear / 0/s / N/S / U/C / Rooftop or

0/s Body / n/s Front / n/s Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Complete</u>
	<u>45: +9.600 (RED: +3,312.60 19%)</u>

Date/Time, File Pass to?

☐ : Prel. Report

1) _____

☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

Report Format: _____

Lump Sum / I.B.I. (\$) _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Text size + -

Enquire Transaction History**Transaction History Details**

Log Date/Time:	17 Feb 2014 / 10:59:52	Receipt No.:	AACCK001-AX239-140217-000021
Asset Type:	Vehicle	Transaction Amount:	\$70,862.00
Asset ID:	SHC6762J	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20140217105952402828		

Vehicle No.:	SHC6762J
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1:	Air-Con (Taxi)
Vehicle Attachment 2:	-
Vehicle Attachment 3:	-
Vehicle Scheme:	Taxi (Company)

First Registration Date:	17 Feb 2014
--------------------------	-------------

Original Registration Date:	17 Feb 2014
Vehicle Make:	KIA
Vehicle Model:	OPTIMA 1.7(A) DIESEL
Chassis No.:	KNAGM414ME5454277
Engine No.:	D4FDDH308943
Motor No.:	-

Trailer Chassis No.:	-
----------------------	---

Propellant:	Diesel
-------------	--------

Passenger Capacity:	4
---------------------	---

Engine Capacity:	1685
------------------	------

Power Rating:	-
---------------	---

Unladen Weight:	1584
-----------------	------

Maximum Laden Weight:	2050
-----------------------	------

Primary Color:	Silver
----------------	--------

Secondary Color:	-
------------------	---

Manufacturing Year:	2013
---------------------	------

Open Market Value:	\$19,632.00
--------------------	-------------

Minimum PARF Benefit:	\$7,279.00
-----------------------	------------

PARF Eligibility:	Y
-------------------	---

No. of Transfer:	0
------------------	---

Effective Ownership Date/Time:	17 Feb 2014 10:59:52
--------------------------------	----------------------

COE No.:	2014021701000846W
----------	-------------------

COE Expiry Date:	16 Feb 2022
------------------	-------------

COE Bid Category:	-
-------------------	---

Actual QP/PQP Paid Amount:	\$58,590.00
----------------------------	-------------

Lifespan Expiry Date:	16 Feb 2022
-----------------------	-------------

Owner ID Type:	Company
----------------	---------



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA
Our ref: CC3/LPC19001533/K1ea3

Date: 24/01/2019

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHC 6762J


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 22/01/2019 at the premises of M/s Premier Automotive Services Pte Ltd - Changi and have the following to report:-

Workshop Estimate Amount	: S\$	11,912.60
Revised Estimate Amount	: S\$	6,672.90
"Check" Items Amount	: S\$	3,783.70
Total (Including Check Items)	: S\$	10,456.60
Market Value	: S\$	- (est.)
LTA Reimbursement Value	: S\$	- (est.)
Nett Value	: S\$	- (est.)

Description of Damage:

The vehicle sustained damages at the
O/S Body / N/S Front Portion / N/S Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 10.0 days

Yours faithfully,

KALVIN ANG
Licensed Appraiser

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

22-Jan-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6762 J

1 pc	Rear o/s fender ✓	\$	1,205.00
1 pc	Rear o/s fender inner shield X	\$	120.00
1 pc	Rear windscreen moulding ✓	\$	87.00
1 pc	Rear o/s lower arm ?	\$	351.00
1 pc	Rear o/s shock absorber ?	\$	313.00
1 pc	Rear o/s trailing arm ?	\$	159.00
1 pc	Rear o/s assist arm ?	\$	163.00
1 pc	Rear o/s bearing ?	\$	349.00
1 pc	Rear o/s upper arm ?	\$	84.00
1 pc	Hub & Bearing Assy- Rear ?	\$	349.00
1 pc	Rear o/s knuckle arm ?	\$	525.00
1 pc	Rear o/s rim ✓	\$	246.00
1 pc	Rear o/s wheel cover ✓	\$	116.00
1 pc	Rear o/s door ✓	\$	791.00
1 pc	Rear o/s door hinge @\$34.00 X ✓	\$	68.00
1 pc	Rear o/s door regulator ?	\$	290.00
1 pc	Rear o/s door motor ?	\$	270.00
1 pc	Front o/s door ✓	\$	765.00
1 pc	o/s rocker panel garnish ✓	\$	286.00
1 pc	Front n/s lower arm ✓	\$	439.00
1 pc	Front n/s shock absorber ?	\$	330.00
1 pc	Front n/s ball joint ?	\$	59.00
1 pc	Front n/s tie rod end ?	\$	61.00
1 pc	Front n/s knuckle bearing ?	\$	157.00
1 pc	Front n/s stabilizer link ?	\$	86.00
1 pc	Front n/s knuckle arm ?	\$	547.00
1 pc	Front n/s rim ✓	\$	246.00
1 pc	Front n/s wheel cover ✓	\$	116.00
1 pc	Rear n/s wheel cover ✓	\$	116.00
		\$	8,694.00
Less 10%		\$	869.40
		\$	7,824.60

22-Jan-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6762 J

S/NETT

1 set	Rear fender inner shield clips	X	\$	38.00
1 pc	Rear o/s fender sticker	/	\$	60.00
1 pc	Sealant	/	\$	50.00
2 pcs	Tyre @\$200.00	/ 50%	\$	400.00
1 set	o/s door sticker	/	\$	100.00
	Towing Fee		\$	50.00
	Sundry		\$	50.00 20
	To check wheel alignment- Front & Rear		\$	160.00 60
	To dismantle and refit rear windscreen		\$	120.00 100
	To dismantle and replace the rear o/s undercarriage		\$	250.00 100 ?
	To dismantle and replace the front n/s undercarriage		\$	250.00 100
	To dismantle and refit the inner component of rear o/s door into new shell door		\$	150.00 50
	To dismantle and refit the inner component of front o/s door into new shell door		\$	150.00 50
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$	180.00 50
	To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the rear o/s fender. Including knock-out, straighten, repair, reshape and adjust of the o/s centre pillar		\$	800 900.00
	To putty and spray painting on rear o/s fender, o/s rocker panel garnish, rear o/s door, front o/s door, o/s centre pillar		\$	900 1,000.00
	To apply rustproofing on the repaired and replaced panels.		\$	180.00 50
				\$ 11,912.60

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

L&K Auto Consultants (Pty) Ltd
the Repairer of the following:
• To resurvey before/after spray painting
• To replace damaged part(s) during resurvey
• This party survey is on a "Without Prejudice" basis
is subject to final approval by the Insurer

Acknowledged by Repairer:
Signature:
Date:

Kali 11/1/19
22/1/19 16:28hrs
10 Apr.
L/s
After Repair

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

22-Jan-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6762 J

1 pc	Rear o/s fender	✓ Build	\$	1,205.00
1 pc	Rear o/s fender inner shield	✓ trim	\$	120.00
1 pc	Rear windscreen moulding	✓ m	\$	87.00
1 pc	Rear o/s lower arm	✓ Bul	\$	351.00
1 pc	Rear o/s shock absorber	✓ Bul	\$	313.00
1 pc	Rear o/s trailing arm	✓ Bul	\$	159.00
1 pc	Rear o/s assist arm	✓ Bul	\$	163.00
1 pc	Rear o/s bearing	✓ Bul	\$	349.00
1 pc	Rear o/s upper arm	✓ Bul	\$	84.00
1 pc	Hub & Bearing Assy- Rear	✓ Bul	\$	349.00
1 pc	Rear o/s knuckle arm	✓ Bul	\$	525.00
1 pc	Rear o/s rim	✓ Bul	\$	246.00
1 pc	Rear o/s wheel cover	✓ m	\$	116.00
1 pc	Rear o/s door	✓ Bul	\$	791.00
1 pc	Rear o/s door hinge @\$34.00	✓ Bul	\$	68.00
1 pc	Rear o/s door regulator	✓ m	\$	290.00
1 pc	Rear o/s door motor	✓ m	\$	270.00
1 pc	Front o/s door	✓ Bul	\$	765.00
1 pc	o/s rocker panel garnish	✓ m	\$	286.00
1 pc	Front n/s lower arm	✓ Bul	\$	439.00
1 pc	Front n/s shock absorber	✓ Bul	\$	330.00
1 pc	Front n/s ball joint	✓ Bul	\$	59.00
1 pc	Front n/s tie rod end	✓ Bul	\$	61.00
1 pc	Front n/s knuckle bearing	✓ Bul	\$	157.00
1 pc	Front n/s stabilizer link	✓ Bul	\$	86.00
1 pc	Front n/s knuckle arm	✓ Bul	\$	547.00
1 pc	Front n/s rim	✓ Bul	\$	246.00
1 pc	Front n/s wheel cover	✓ m	\$	116.00
1 pc	Rear n/s wheel cover	✓ m	\$	116.00
				\$ 8,694.00
Less 10%				\$ 869.40
				\$ 7,824.60

22-Jan-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6762 J

S/NETT

1 set	Rear fender inner shield clips	X 4	\$ 38.00
1 pc	Rear o/s fender sticker	rec	\$ 60.00
1 pc	Sealant	rec	\$ 50.00
2 pcs	Tyre @\$200.00	included 50%	\$ 400.00
1 set	o/s door sticker	rec	\$ 100.00

Towing Fee	\$ 50.00
Sundry	\$ 50.00 20
To check wheel alignment- Front & Rear	\$ 160.00 60
To dismantle and refit rear windscreen	\$ 120.00 100
To dismantle and replace the rear o/s undercarriage	\$ 250.00 100 2
To dismantle and replace the front n/s undercarriage	\$ 250.00 100
To dismantle and refit the inner component of rear o/s door into new shell door	\$ 150.00 50
To dismantle and refit the inner component of front o/s door into new shell door	\$ 150.00 50
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$ 180.00 50
To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the rear o/s fender. Including knock-out, straighten, repair, reshape and adjust of the o/s centre pillar	\$ 900.00 800
To putty and spray painting on rear o/s fender, o/s rocker panel garnish, rear o/s door, front o/s door, o/s centre pillar	\$ 1,000.00 900
To apply rustproofing on the repaired and replaced panels.	\$ 180.00 50
\$ 11,912.60	

(ALL THE REPAIR COSTS ARE SUBJECT TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Acknowledged by Reparer

Signature:

Date:

18/1/19
1/5 \$9600/10 Rps.
13/187-80

Ka/hi 11/1/19
22/1/19 1638hrs
10 Rps.
4/5
After Repair p 4

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

16-Feb-19

SUPPLEMENTARY ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6762 J

1 pc	Front n/s driveshaft	✓ <i>Ben</i>	\$	866.00
1 pc	Rear n/s shock absorber	✓ <i>Ben</i>	\$	313.00
1 pc	Hub & bearing Assy- Rear n/s	✓ <i>Ben</i>	\$	349.00
			\$	1,528.00
		Less 10%	\$	152.80
			\$	1,375.20

To dismantle and replace the rear n/s undercarriage

\$	100.00
\$	1,475.20

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

**THE ABOVE ESTIMATED COST OF REPAIR DO NOT
INCLUDE ANY UNFORESEEN DAMAGES.**

CASH SALE/WORK ORDER

No: AE 8292



PEOPLE'S VEHICLE SERVICE PTE LTD

BLK 3023A, UBI ROAD 1 #01-60, SINGAPORE 408717

TEL : 6743 1987 (3 LINES) FAX : 6743 0013

Reg No: 200415052W

Date, 21/1/19

寶號

Messrs: p/kennel

車號

Vehicle No: S1C 6762J

車型

Model No: KIA

由

From: Bukit Merah Central

到

To: Cling

其他

Remark: crane up. K/R omega

時間

Time: 7:07/6:40/7:45

AMOUNT: \$

注意：本公司對所拖之車輛，在進行中如有任何損失或破壞，一經由車主自行負責。

NOTE: Vehicle is towed at owner's risk. The company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.

經手人

Authorised by: W167

收貨人

Received by: [Signature]

Mei Kwan (LKKAUTO)


From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Tuesday, 29 January, 2019 12:13 PM
To: Mei Kwan (LKKAUTO)
Cc: MT_Claim_SG
Subject: RE: Direct Settlement - Accident Involving SJW5372D (OI : LPC - TBA) AND SHC6762J (TP : LKK REF - CC3/LPC19001533/K1ea3) on 21/01/2019
Attachments: 29012019120920.pdf
Categories: HMK

Our Ref :18/19/19/VP05/021351

Dear Mei Kwan,

Attached copy of insured's GIA report for your attention.

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



From: Mei Kwan (LKKAUTO) [mailto:Meikwan@lkkauto.com]
Sent: Tuesday, 29 January, 2019 10:46 AM
To: MT_Claim_SG
Cc: GERALD POH WEE BIN; ONG LI LI; ericwoo; Asher Sng (LKKAUTO); Joy Irene (LKKAUTO); Admin A
Subject: RE: Direct Settlement - Accident Involving SJW5372D (OI : LPC - TBA) AND SHC6762J (TP : LKK REF - CC3/LPC19001533/K1ea3) on 21/01/2019

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

Kindly assist to verify validity of our insured's policy and let us have a copy of insured's accident report for our necessary action.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC3/LPC19001533/K1ha3n2

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 10-07-2019

Code : LPC2



1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJW 5372D	Veh. Inspected	SHC 6762J
Policy No.	Z18VP05017599	Coverage (\$)	0.00
Claim No.	18/19/19/VP05/021351	Excess (\$)	0.00
Assign From		Assign Date	22/01/2019

2. Vehicle Particulars & Condition

Make & Model	KIA OPTIMA	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	KNAGM414ME5454277	Colour	SILVER
Odometer	628642	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/65 R16	HANKOOK	7 mm
L/H Front Tyre	205/65 R16	HANKOOK	7 mm
R/H Rear Tyre	205/65 R16	HANKOOK	7 mm
L/H Rear Tyre	205/65 R16	HANKOOK	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY,N/S FRONT AND N/S REAR PORTION . DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	21/01/2019	Inspection Date	22/01/2019
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	10 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 6762J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR O/S FENDER	BUCKLED	1,205.00	1,205.00
1	REAR O/S FENDER INNER SHIELD	TORN	120.00	120.00
1	REAR WINDSCREEN MOULDING	NECESSARY	87.00	87.00
1	REAR O/S LOWER ARM	BENT	351.00	351.00
1	REAR O/S SHOCK ABSORBER	BENT	313.00	313.00
1	REAR O/S TRAILING ARM	BENT	159.00	159.00
1	REAR O/S ASSIST ARM	BENT	163.00	163.00
1	REAR O/S BEARING	BENT	349.00	349.00
1	REAR O/S UPPER ARM	BENT	84.00	84.00
1	HUB & BEARING ASSY - REAR	BENT	349.00	349.00
1	REAR O/S KNUCKLE ARM	BENT	525.00	525.00
1	REAR O/S RIM	BENT	246.00	246.00
1	REAR O/S WHEEL COVER	CRACKED	116.00	116.00
1	REAR O/S DOOR	DENTED	791.00	791.00
2	REAR O/S DOOR HINGE @\$34.00	BENT	68.00	68.00
1	REAR O/S DOOR REGULATOR	CRACKED	290.00	290.00
1	REAR O/S DOOR MOTOR	CRACKED	270.00	270.00
1	FRONT O/S DOOR	DENTED	765.00	765.00
1	O/S ROCKER PANEL GARNISH	CRACKED	286.00	286.00
1	FRONT N/S LOWER ARM	BENT	439.00	439.00
1	FRONT N/S SHOCK ABSORBER	BENT	330.00	330.00
1	FRONT N/S BALL JOINT	BENT	59.00	59.00
1	FRONT N/S TIE ROD END	DENTED	61.00	61.00
1	FRONT N/S KNUCKLE BEARING	BENT	157.00	157.00
1	FRONT N/S STABILIZER LINK	BENT	86.00	86.00
1	FRONT N/S KNUCKLE ARM	BENT	547.00	547.00
1	FRONT N/S RIM	BENT	246.00	246.00
1	FRONT N/S WHEEL COVER	CRACKED	116.00	116.00
1	REAR N/S WHEEL COVER	NECESSARY	116.00	116.00
1	FRONT N/S DRIVESHAFT (ADDITIONAL)	BENT	866.00	866.00
1	REAR N/S SHOCK ABSORBER (ADDITIONAL)	BENT	313.00	313.00

Report Ref No. CC3/LPC19001533/K1ha3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	HUB & BEARING ASSY - REAR N/S (ADDITIONAL)	BENT	349.00	349.00
	LESS 10% DISCOUNT		-1,022.20	-1,022.20
			9,199.80	9,199.80
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR FENDER INNER SHIELD CLIPS (SN)	NOT NECESSARY	38.00	-
1	REAR O/S FENDER STICKER (SN)	NECESSARY	60.00	60.00
1	SEALANT (SN)	NECESSARY	50.00	50.00
2	TYRE @\$200.00 (SN) (50%)	PUNCTURE	400.00	200.00
1	SET O/S DOOR STICKER (SN)	NECESSARY	100.00	100.00
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			698.00	430.00
	<u>LABOUR</u>			
	TOWING FEE.		50.00	50.00
	TO CHECK WHEEL ALIGNMENT - FRONT & REAR.		160.00	60.00
	TO DISMANTLE AND REFIT REAR WINDSCREEN.		120.00	100.00
	TO DISMANTLE AND REPLACE THE REAR O/S UNDERCARRIAGE.		250.00	100.00
	TO DISMANTLE AND REPLACE THE FRONT N/S UNDERCARRIAGE.		250.00	100.00
	TO DISMANTLE AND REFIT THE INNER COMPONENT OF REAR O/S DOOR INTO NEW SHELL DOOR.		150.00	50.00
	TO DISMANTLE AND REFIT THE INNER COMPONENT OF FRONT O/S DOOR INTO NEW SHELL DOOR.		150.00	50.00
	TO DISMANTLE / REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS.		180.00	50.00
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS. TO HEAT / WELD, CUT-OFF THE REAR O/S FENDER. INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF THE O/S CENTRE PILLAR.		900.00	800.00
	TO PUTTY AND SPRAY PAINTING ON REAR O/S FENDER, O/S ROCKER PANEL GARNISH, REAR O/S DOOR, FRONT O/S DOOR, O/S CENTRE PILLAR.		1,000.00	900.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.		180.00	50.00

Report Ref No. CC3/LPC19001533/K1ha3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DISMANTLE AND REPLACE THE REAR N/S UNDERCARRIAGE. (ADDITIONAL)		100.00	80.00
			3,490.00	2,390.00
GRAND TOTAL			13,387.80	12,019.80
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				9,600.00

Report Ref No. CC3/LPC19001533/K1ha3n2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.