

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

22-Jan-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6762 J

1 pc	Rear o/s fender ✓	\$	1,205.00
1 pc	Rear o/s fender inner shield ✕	\$	120.00
1 pc	Rear windscreen moulding ✓	\$	87.00
1 pc	Rear o/s lower arm ?	\$	351.00
1 pc	Rear o/s shock absorber ?	\$	313.00
1 pc	Rear o/s trailing arm ?	\$	159.00
1 pc	Rear o/s assist arm ?	\$	163.00
1 pc	Rear o/s bearing ?	\$	349.00
1 pc	Rear o/s upper arm ?	\$	84.00
1 pc	Hub & Bearing Assy- Rear ?	\$	349.00
1 pc	Rear o/s knuckle arm ?	\$	525.00
1 pc	Rear o/s rim ✓	\$	246.00
1 pc	Rear o/s wheel cover ✓	\$	116.00
1 pc	Rear o/s door ✓	\$	791.00
1 pc	Rear o/s door hinge @\$34.00 ✕ ✓	\$	68.00
1 pc	Rear o/s door regulator ?	\$	290.00
1 pc	Rear o/s door motor ?	\$	270.00
1 pc	Front o/s door ✓	\$	765.00
1 pc	o/s rocker panel garnish ✓	\$	286.00
1 pc	Front n/s lower arm ✓	\$	439.00
1 pc	Front n/s shock absorber ?	\$	330.00
1 pc	Front n/s ball joint ?	\$	59.00
1 pc	Front n/s tie rod end ?	\$	61.00
1 pc	Front n/s knuckle bearing ?	\$	157.00
1 pc	Front n/s stabilizer link ?	\$	86.00
1 pc	Front n/s knuckle arm ?	\$	547.00
1 pc	Front n/s rim ✓	\$	246.00
1 pc	Front n/s wheel cover ✓	\$	116.00
1 pc	Rear n/s wheel cover ✓	\$	116.00
		\$	8,694.00
Less 10%		\$	869.40
		\$	7,824.60

22-Jan-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6762 J

S/NETT

1 set	Rear fender inner shield clips ✕	\$	38.00
1 pc	Rear o/s fender sticker ✓	\$	60.00
1 pc	Sealant ✕ ✓	\$	50.00
2 pcs	Tyre @\$200.00 ✓ 50%	\$	400.00
1 set	o/s door sticker ✓	\$	100.00

Towing Fee	\$	50.00 ✓
Sundry	\$	50.00 20
To check wheel alignment- Front & Rear	\$	160.00 60
To dismantle and refit rear windscreen	\$	120.00 100
To dismantle and replace the rear o/s undercarriage	\$	250.00 100 ?
To dismantle and replace the front n/s undercarriage	\$	250.00 100
To dismantle and refit the inner component of rear o/s door into new shell door	\$	150.00 50
To dismantle and refit the inner component of front o/s door into new shell door	\$	150.00 50
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00 50
To labour charge for dismantle and renew the accident damaged parts. To heat/weld, cut-off the rear o/s fender. Including knock-out, straighten, repair, reshape and adjust of the o/s centre pillar	\$	800 900.00
To putty and spray painting on rear o/s fender, o/s rocker panel garnish, rear o/s door, front o/s door, o/s centre pillar	\$	900 1,000.00
To apply rustproofing on the repaired and replaced panels.	\$	180.00 50
	\$	11,912.60

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES

Acknowledged by Repairer
Signature:
Date:

Ka/hi 11/1/19
22/1/19 1638hrs
10 Apr.
U/s
After Repair p 4

CASH SALE/WORK ORDER

No: AE 8292



PEOPLE'S VEHICLE SERVICE PTE LTD

BLK 3023A, UBI ROAD 1 #01-60, SINGAPORE 408717

TEL : 6743 1987 (3 LINES) FAX : 6743 0013

Reg No: 200415052W

寶號

Messrs:

車號

Vehicle No:

由

From:

到

To:

其他

Remark:

時間

Time :

Date,

SHC 67625

車型

Model No:

Kia

Bukit Merah Central
Clg

crane up. K/R omega

16:07:16:40:17:41

AMOUNT: \$

注意：本公司對所拖之車輛，在進行中如有任何損失或破壞，一概由車主自行負責。

NOTE: Vehicle is towed at owner's risk. The company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.

經手人

Authorised by:

收貨人

Received by: