



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJJ 4613J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REPLACEMENT OF PARTS	CUT		
	COVER-RR BUMPER LWR (CONSISTENT)(SN)		201.00	201.00
			201.00	201.00
	LABOUR			
	REPAIR REAR BUMPER.		550.00	400.00
	SPRAY PAINT FOR REAR BUMPER.		420.00	420.00
	REMOVE & INSTALL PARKING SENSOR.		60.00	60.00
			1,030.00	880.00
GRAND TOTAL			1,231.00	1,081.00
RECOMMENDED COST OF REPAIRS				1,081.00

Report Ref No. CC4/ASM19001537/R1ps3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.