



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
CLARENCE YONG JIA WEI (CLARENCE YANG JIAWEI) BLK 12 DOVER CLOSE EAST #05-208 SINGAPORE 130012 Contact No	Cust No/Name	LCV06061/CLARENCE YONG JIA WEI (CLARENCE
	Reg No/Reg Date	SJJ4613J / 03/07/201
	Date In/Mileage	/ 0
	Chassis No	KNAHU815VJ7208648
	Engine No	D4FDJH553003
	Make/Model	KIA/CARENS 1.7 A D SX FL DY6
	Colour/Trim	IM. TITANIUM SILVER/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LCV06061	CRDVCH	22/01/2019/ 16:13	TLC	442 / CocoLu	43355

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPAIR REAR BUMPER				550.00
E PNT98000 SPRAY PAINT FOR REAR BUMPER				420.00
E PNT88000 REMOVE & INSTALL PARKING SENSOR				60.00
M COVER-RR BUMPER LWR	1.00	201.00	00.00	201.00

Estimate

Confirm & accepted by

7% GST on	Nett 1231.00	1,231.00 86.17
Total Payable		1,317.17

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.