

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0094/2019/PH
Date : 22-Jan-19

Vehicle not in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Ang Li Hsien , Samuel
Address : Blk 159 Yung Ping Road
#03-03
: (S) 610159
Telephone : HP +65 98281078
Type of Claim : Own damage Claims
Policy No. : 2100505869
Vehicle No : **SLM 5745 R**
Model Code : Audi A3 Sedan 1.0 TFSI (A)
Model / Year : 31/3/2017
Engine No : CHZ 142518
Chassis No : WAUZZZ8VXH1017120
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 16-Jan-19

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLM 5745 R.

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer Assy.	S/N \$ 360.00 ✓	
2	To dismantle and renew front bumper, lhs front fender and lhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$ 2,100.00 750 ✓	
3	To respray front bumper and lhs front fender.	\$ 1,500.00 1100 ✓	
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 4,152.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLM 5745 R.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER <i>behind</i>	\$1,830.00	✓
2	FRONT BUMPER FIXING PARTS <i>xl on</i>	\$170.00	x
3	FRONT BUMPER GUIDE SECTION - LH <i>xl on</i>	\$35.00	x
4	FRONT BUMPER GRILLE - CENTER <i>xl on</i>	\$146.00	x
5	FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE <i>xl on</i>	\$488.00	+
6	FRONT BUMPER CLOSING ELEMENT <i>xl on</i>	\$270.00	+
7	FRONT BUMPER COVER TRIM - LH <i>xl on</i>	\$148.00	x
8	ADAPTER WHEEL HOUSING LINER - LH <i>xl on</i>	\$34.00	+
9	RADIATOR GRILLE <i>xl on</i>	\$1,301.00	+
10	CLOSING ELEMENT <i>xl on</i>	\$174.00	+
11	AIR GUIDE GRILLE - LH <i>Do cut</i>	\$171.00	✓
12	FRONT REINFORCEMENT <i>xl on</i>	\$660.00	+
13	FOAM FILLER PIECE <i>xl on</i>	\$172.00	+
14	FOAM FILLER PIECE COVER <i>xl on</i>	\$111.00	+
15	COVER <i>xl on</i>	\$111.00	+
16	CAUTION' SIGN STICKER <i>xl on</i>	\$13.00	+
17	FRONT FENDER - LH <i>Repair</i>	\$778.00	x
18	ATTACHMENT PARTS FOR FENDER	\$65.00	+
19	BRACKET FOR FENDER - LH	\$35.00	+
20	FENDER BRACE	\$88.00	x
SUB TOTAL SPARE PARTS CHARGES		\$ 6,800.00	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLM 5745 R.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	WHEEL HOUSING LINER - LH <i>Not in</i>	\$158.00	<i>x</i>
22	ATTACHMENT PARTS FOR WHEEL HOUSING LINER <i>Not in</i>	\$81.00	<i>x</i>
23	LED HEADLIGHT - LH <i>cut</i>	\$5,029.00	<i>✓</i>
24	HEADLIGHT LIFT CYLINDER <i>new</i>	\$128.00	<i>+</i>
25	FRONT NUMBER PLATE <i>new</i> S/N	\$25.00	<i>x</i>
26	SUNDRIES <i>?</i>	\$500.00	<i>?</i>
TOTAL SPARE PARTS CHARGES		\$ 12,721.00	
TOTAL LABOUR CHARGES		\$ 4,152.00	
GRAND TOTAL		\$ 16,873.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Adrian Ling
23/01/19.

~~Authorised Repairs~~
Not Authorised, 04 Days.

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair; we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant