

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

Email: mg3solution@gmail.com

| | | | |
|---------------------------------|---------------------|----------|--------------|
| TO | : CHINA TAIPING | DATE | : 21/01/2019 |
| ATTENTION | : MOTOR CLAIMS DEPT | JOB TYPE | : T/P CLAIM |
| ESTIMATE REPORT | : | | |
| VEHICLE DETAILS | | | |
| VEHICLE NO | : SFR1133C | | |
| MODEL | : B.M.W.318I | | Xiao Tony |
| CHASSIS NO | | | |
| ACCIDENT DETAILS | DATE : 18-Jan-19 | | |
| | TIME : 18:15HRS | | |
| THIRD PARTY REQUESTOR / CONTACT | : JACK | | |

CLAIM DETAIL : PARTS

| S/N | DESCRIPTION | QTY | UNIT LIST PRICE | TOTAL LIST PRICE |
|-----|---|-----|-----------------|------------------|
| 1 | REAR BUMPER <i>rehd.</i> | 1 | \$ 1,845.00 | \$ 1,845.00 |
| 2 | REAR BUMPER SIDE RETAINER <i>neu</i> | 2 | \$ 109.20 | \$ 218.40 |
| 3 | REAR BUMPER BEAM <i>rehd</i> | 1 | \$ 329.20 | \$ 329.20 |
| 4 | REAR BUMPER REINFORCEMENT <i>Bot</i> | 1 | \$ 695.00 | \$ 695.00 |
| 5 | REAR BUMPER REINFORCEMENT COVER <i>rehd</i> | 1 | \$ 133.50 | \$ 133.50 |
| 6 | REAR BUMPER SENSOR <i>3ms</i> | 2 | \$ 337.00 | \$ 674.00 |
| 7 | REAR BUMPER SENSOR HOLDER <i>1a</i> | 2 | \$ 80.00 | \$ 160.00 |

3002.7

2702.43

| | |
|------------------------|--------------------|
| TOTAL PRICE | \$ 4,055.10 |
| LESS 10% | \$ 405.51 |
| SUB TOTAL PRICE | \$ 3,649.59 |

SPECIAL NETT ITEMS

| S/N | DESCRIPTION | QTY | UNIT S/NETT | TOTAL S/NETT |
|-----|--|-----|-------------|--------------------------|
| 1 | REAR NUMBER PLATE <i>neu</i> | 1 | \$ 100.00 | \$ 100.00 |
| 2 | REAR BUMPER CLIP(SET) <i>neu</i> | 1 | \$ 6.50 | \$ 6.50 |
| 3 | SHIELD COATING <i>neu</i> | 1 | \$ 980.00 | \$ 980.00 250 |
| 4 | REAR END PANEL SEALANT <i>neu neu</i> | 1 | \$ 80.00 | \$ 80.00 |
| 5 | REAR END PANEL TOP GARNISH CLIPS(SET) <i>neu neu</i> | 1 | \$ 6.50 | \$ 6.50 |

256.50

TOTAL \$ 1,173.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

| | | | | |
|---|---|-----------------------|-----|--|
| 1 | PANEL BEATING, REMOVAL AND REPLACING PARTS | \$1,000.00 | 250 | |
| 2 | TO SPRAY PAINT AFFECTED AREA | \$1,000.00 | 250 | |
| 3 | TUFF COAT | \$250.00 | x | |
| 4 | WIRING CHECK | \$120.00 | 30 | |
| 5 | REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINNING TO FACILITATE REPAIR | \$180.00 | x | |
| 6 | CONDUCT WATER LEAKAGE TEST | \$150.00 | x | |
| 7 | REMOVE AND REFIX REAR SENSOR | \$120.00 | 50 | |

580

TOTAL \$2,820.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 4,822.59
 TOTAL LABOUR COST : \$ 2,820.00
 TOTAL REPAIR COST : \$ 7,642.59

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

FAX :

PART BY PART / LUMP SUM :

NO OF DAYS :

Adrian L
 L/S 21/01/19.
 03 Days.

total: 3538.93
 L/S: 2.8K.

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

PAID
INVOICE



CHIA AUTO SERVICES PTE LTD

Co. Reg. No. : 201538764H
No.23 Kaki Bukit Avenue 4
#04-01 Vicom Building
Singapore 415933
Tel: 6243-1373 Fax: 6243-1376
Email: ca3services@gmail.com

Date: 24 Apr 2018
Invoice No.: 280081
Vehicle No : SFR1133S
BWM 3
SERIES
Customer PO No.:1

Bill To:
SFR1133S

| Qty | Description | Unit Price | Total |
|-----|---------------------------|------------|----------|
| 1 | PROTECTION SHIELD COATING | \$980.00 | \$980.00 |

Total \$980.00
Paid \$980.00

KINDLY CONFIRM AND ACKNOWLEDGE

PAYMENT OPTIONS:CASH, NETS OR CHEQUE.