

ASS. REC. BY:

REF:

CS/CT119001549/Agd3n2

Special Instruction:

Surveyor:

Adnan

ASSIGNMENT (Office)

From (Person):

ehong Bun Sen

of

CTI

Date/Time:

23/11/19 @ 2:16pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

SKC3862M

Insured:

SKC3994R

at Workshop m/s

Premium

Tel:

87689828

of

55 ubi Rd 1

Policy No:

DMPCSN30222718033

Claim No:

SNM19D200327COR

Sum Insured:

Excess:

Make of Vch:
(Client's Record)

D.O.A.

17/1/19

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time:

23/1/2019 @

Person Contacted:

justin

Vehicle:

IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SKC3862M-X
	SKC3994R-X
23/1/19 @ 11:09am	confirmed with Carline final fig \$2272, 3 days by email. (Red \$23985, 90%)


Adrian

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 03 889 days Res: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKC3862M- Yr Regn: 2018, Sept.
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi ~~88~~ A8. C.C. 2983
 Colour: Maroon A/C: Insured / Std / NI / NA
 Sp. Reading: 2458 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAAUZZF82JN015440Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 255/45R19R: 255/45R19BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 23/01/19Survey held at Premium.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front 4/5.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP Check.

RECEIVED 29 MAY 2019

mv:

PV:

Nett:

Date/Time, File Pass to?

Date/Time, File Return to?

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic & Add.

S + RS, SI

Photos

Others

TOTAL

2201) 29/5 TUNSA

2)

3)

4)

5)

6)

Prel. Report:

Final Report:

Nivitha (LKK Auto)

From: Shu Pei (LKKAuto) <shupeil@lkkauto.com>
Sent: Wednesday, 23 January 2019 2:16 PM
To: assignments
Subject: FW: our ref: SNM19D200327 / ACCIDENT INVOLVING SKC3862M AND YOUR INSURED SKC3994R DATED ON 17.1.19
Attachments: PA00882019 -SKC 3862 M - A8L D5 3.0 TFSI QU - FRONT LH (CHINA).pdf
Importance: High

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims <claims@premiumauto.com.sg>
Sent: Wednesday, 23 January 2019 1:22 PM
To: 'Chong Boon Sen' <boonsen.chong@sg.cntaiping.com>
Cc: Admin A <admin-a@lkkauto.com>; claims@premiumauto.com.sg
Subject: RE: our ref: SNM19D200327 / ACCIDENT INVOLVING SKC3862M AND YOUR INSURED SKC3994R DATED ON 17.1.19
Importance: High

Dear Chong Boon,

Noted with thanks.

Dear LKK,

Kindly refer to our attach file of SKC 3862 M – Estimate.

Thank you.

Best Regards,

Justin Ee
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



http://www.audi.com.sg/sea/brand/sg/audi_promotions/promotions/car_promotions/new-audi-q2-2017.html

Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: Chong Boon Sen [<mailto:boonsen.chong@sg.cntaiping.com>]

Sent: Wednesday, 23 January, 2019 1:13 PM

To: Claims <claims@premiumauto.com.sg>

Cc: Admin A <admin-a@lkkauto.com>

Subject: RE: our ref: SNM19D200327 / ACCIDENT INVOLVING SKC3862M AND YOUR INSURED SKC3994R DATED ON 17.1.19

Without Prejudice

Dear Sir,

We will appoint LKK.

Pls assist to provide necessary workshop details.

Dear LKK,

Kindly assist.

Regards,

Chong Boon Sen

Claims Executive

Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: boonsen.chong@sg.cntaiping.com

Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Claims [<mailto:claims@premiumauto.com.sg>]

Sent: Wednesday, 23 January, 2019 1:03 PM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Cc: claims@premiumauto.com.sg

Subject: RE: our ref: SNM19D200327 / ACCIDENT INVOLVING SKC3862M AND YOUR INSURED SKC3994R DATED ON 17.1.19

Importance: High

Dear Chong Boon,

Please be informed that we will choose LKK - Adrian Ling for the survey.

Thank you.

Best Regards,
Tony Foong
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



http://www.audi.com.sg/sea/brand/sg/audi_promotions/promotions/car_promotions/new-audi-q2-2017.html

Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: Chong Boon Sen [mailto:boonsen.chong@sg.cntaiping.com]

Sent: Monday, 21 January, 2019 9:01 AM

To: Claims <claims@premiumauto.com.sg>

Subject: our ref: SNM19D200327 / ACCIDENT INVOLVING SKC3862M AND YOUR INSURED SKC3994R DATED ON 17.1.19

Without Prejudice

Dear Sirs

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG

MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you.

Regards,
Chong Boon Sen
 Claims Executive
 Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: boonsen.chong@sg.cntaiping.com

Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

This email has been scanned by the Symantec Email Security.cloud service.
 For more information please visit <http://www.symanteccloud.com>

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 28 May 2019 11:09 AM
To: Carrine Leong; SUR
Cc: 'Boo seng yak'; 'Chang Chee Sing'; jiayee.yap@premiumauto.com.sg
Subject: RE: FINAL REVISION FOR SKC3862M - TP CHINA - SURVEYED ON 23 JAN 2019

Dear Carrine,

WITHOUT PREJUDICE

Confirm final fig \$2,272.00 before GST and 3 repair days.

Kindly send the relevant documents to China Taiping Insurance company.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Carrine Leong <carrine.leong@premiumauto.com.sg>
Sent: Friday, 10 May 2019 11:41 AM
To: Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>; Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Boo seng yak' <boojohnny@gmail.com>; 'Chang Chee Sing' <claims@premiumauto.com.sg>; jiayee.yap@premiumauto.com.sg
Subject: FINAL REVISION FOR SKC3862M - TP CHINA - SURVEYED ON 23 JAN 2019

Hi Adrian/Shiau Chan,

Revised estimate for above vehicle is attached.

Kindly confirm repair cost of \$2272.00 @ 3 days of repairs.

Your early approval will be most appreciated.

Thanks & Best Regard
Carrine Leong
Claims Administrator

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9925 f. +65 6841 1183
e. carrine.leong@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/01/2019 09:23
Date Of Accident	17/01/2019 11:00
Exact Location Of Accident	MOUNT. E NOVENA CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKC3862M
Insured/Policyholder	
Name Of Registered Owner	VIKRAM TELWAR
NRIC No	S2765128C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90269392
Alternative Phone No	OTHERS-90269392

Vehicle Particulars

Manufacturer	AUDI
Model	A8L D5 3.0 TFSI QU
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800113050
Cover Note Number	

Driver

Name of Driver	LEONG WING KANG
NRIC No	S7107419F
Date Of Birth	02/03/1971
Occupation	INDOOR
Date Of Driving Pass	29/08/1988
Driving Experience	30 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98320454
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 315 BUKIT BATOK STREET 32 #04-89
Postcode	650315
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

MY CAR WAS PARKED IN THE CAR PARK LOT AND I WAS INSIDE THE CAR. THE RED CAR REVERSED AND HIT MY CAR, FRONT LEFT CORNER.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKC3994R
Vehicle Make/Model/Colour	SUZUKI / SX4/ RED
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	CORINNE KERK WHEE SING
NRIC/Passport Number	S7010892E
Contact Number	
Address	BLK 895 BUKIT TIMAH ROAD #10-01
Postcode	589632
Insurance Company Name	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN



A: SKC 3962 M
B: SKC 3994 R

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

My ~~the~~ car was parked in the car park lot and I was inside the car. The red car reversed and hit my car front left corner.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Photo



REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: **S7107419F**

LEONG WING KANG

Birth Date: **02 Mar 1971**
Issue Date: **01 Aug 2003**

006719703D




REPUBLIC OF SINGAPORE
IDENTITY CARD NO. **S7107419F**



Name

LEONG WING KANG

梁永剛

Race

CHINESE

Date of Birth

02-03-1971

Sex

M

Country of Birth

SINGAPORE

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES:

Class 1B Motorcycles \leq 200 CC
Class 2A Motorcycles between 201 CC and 400 CC
Class 2 Motorcycles $>$ 400 CC
Class 3 Motor cars \leq 3600 kg with \leq 7 passengers, exclusive of the driver, and motor tractors/vehicles \leq 2500 kg

05 May 2004
26 Jun 2007
28 Apr 2009
29 Aug 1988

S7107419F

S / No. 9000099675

Licence No. S7107419F

NP 428A

2054542



NRIC No. **S7107419F**



Blood Group

Date of Issue

A+

24-05-1994

APT BLK 315 BUKIT BATOK STREET 32 #04-89
SINGAPORE 650315

NRIC No: **S7107419F**

Date: **15-05-1999**

No: **2937726**

Name of Policyholder : Vikram Telwar
Period of Insurance : 11 Sep 2018 To 10 Sep 2020
Engine No. : CZS010139
Chassis No. : WAUZZZF82JN015440

Vehicle No. : SKC3862M
Policy No. : 1800113050
Endorsement No. :
Issued Date : 02 Oct 2018

ABOUT THE COVER

Make/Model : AUDI A8L 3.0 TFSI QU
Engine Capacity/Tonnage : 2,995.00 CC
Driver Restriction : NA
Person or Classes of Persons Entitled to Drive* :
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2018
Insuring with COE/PAF : Yes

a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 3 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 6 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
Fire - \$0 Own Damage - \$1400 Theft - \$0 Flood Cover - \$0

Section 2
Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

Vikram Telwar - \$1400 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6336 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: DBS BANK LTD

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125000

PREMIUM LEASING PTE LTD
281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Manik

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/TP/0088/2019/GW
Date	:	21-Jan-19

Vehicle NOT in workshop. Kindly arrange for survey.

Your Insured Vehicle No. : SKC 3994 R

China Taiping Insurance (SG) Pte Ltd

105 Cecil Street

#19-00 The Octagon

Singapore 069534

Attn: Ms Angie - Motor Claims Dept/Windscreen

Tel: 6389 6541 - Fax: 6224 7175

Owner's Name	:	Mr. Vikram Telwar
Address	:	15 Ardmore Park #12-02 Singapore 259959
Telephone	:	90269392
Type of Claim	:	Third Party Claims
Policy No.	:	1800113050
Vehicle No	:	SKC 3862 M
Model Code	:	Audi Q3 1.4 TFSI
Model / Year	:	A8 D D5 3.0 TFSI Qu
Engine No	:	CZS 010139
Chassis No	:	WAUZZZF82JN015440
Mileage	:	-
Date In	:	-
Liability	:	-
Excess Cost	:	-
Estimated By	:	Allan Wu
Accident Date	:	17-Jan-19
Place of Accident	:	Mount. E Novena Car Park

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKC 3862 M

S/N	Nature of Jobs	Estimated Charges
1	To remove and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ✓
2	To dismantle and renew front bumper and lhs headlight. Re-organise crash management components reinstall all parts removed.	\$ 1,600.00 800
3	To respray front bumper.	\$ 1,200.00 800
4	To carry out diagnostic check .	S/N \$ 192.00 ✓
TOTAL LABOUR CHARGES		: \$ <u>3,472.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKC 3862 M

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>Repair</i>	\$	3,051.00 <i>X</i>
2	FRONT BUMPER FIXING PARTS	\$	475.00 <i>X</i>
3	FRONT BUMPER CLOSING ELEMENT-CENTER <i>Not new</i>	\$	350.00 <i>X</i>
4	FRONT BUMPER COVER <i>Not new</i>	\$	59.00 <i>X</i>
5	FRONT BUMPER COVER-LH <i>Not new</i>	\$	67.00 <i>X</i>
6	FRONT BUMPER BRACKET-LH	\$	100.00 <i>X</i>
7	FRONT BUMPER GRILLE-LOWER CENTRE	\$	424.00 <i>X</i>
8	FRONT BUMPER CHROME TRIM-LH	\$	173.00 <i>X</i>
9	FRONT BUMPER CAP-LH	\$	14.00 <i>X</i>
11	FRONT BUMPER END CAP-LH	\$	53.00 <i>X</i>
12	FRONT BUMPER AIR GUIDE GRILLE-LH	\$	535.00 <i>X</i>
13	FRONT BUMPER AIR GUIDE GRILLE INNER TRIM-LH	\$	200.00 <i>X</i>
14	FRONT BUMPER AIR GUIDE GRILLE SURROUND-LH	\$	200.00 <i>X</i>
15	FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE	\$	238.00 <i>X</i>
16	FRONT BUMPER SPOILER <i>new</i>	\$	271.00 <i>X</i>
17	RADIATOR CLOSING ELEMENT- LOWER CENTRE <i>new</i>	\$	161.00 <i>X</i>
18	FRONT BUMPER SUPPORT-LH	\$	27.00 <i>X</i>
19	FOAM FILL PIECE	\$	116.00 <i>X</i>
20	FRONT BUMPER CARRIER	\$	1,051.00 <i>X</i>
SUB- TOTAL SPARE PARTS		\$	7,565.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKC 3862 M

S/N	Parts Description	Damage Pa	
		S/NETT	RI
21	FRONT BUMPER COVER	\$	181.00 ✓
22	FRONT BUMPER GUIDE SECTION-LH	\$	54.00 ✓
23	RADIATOR GRILLE	\$	2,063.00 ✗
24	INSCRIPTION ' QUATTRO '	\$	87.00 ✗
25	RADIATOR COVER	\$	56.00 ✗
26	ULTRASOUND SENSOR SUPPORT-LH	\$	47.00 ✗
27	LED HEADLIGHT-LH	\$	11,951.00 ✗
28	LED HEADLIGHT LIFT CYLINDER-LH	\$	256.00 ✗
29	FRONT NO. PLATE	S/N \$	25.00 ✗
30	SUNDRIES	\$	500.00 ✗
TOTAL SPARE PARTS		:	\$ 22,785.00
TOTAL LABOUR CHARGES		:	\$ 3,472.00
GRAND TOTAL		:	\$ 26,257.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

:

Adrian Ling

Surveyed Date

:

23/01/19

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

:

Not Authorised, 03 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a 'Without Prejudice' basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

:

This estimate is based on visual inspection of the affected vehicle.

Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.

For inspection of vehicle, please refer to Ms Norah Khai at

Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo

Body Repair Manager

Allan Wu

Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0088/2019/CW
Date : 21-Jan-19

Vehicle NOT in workshop. Kindly arrange for survey.
Your Insured Vehicle NO. : SKC 3994 R

China Taiping Insurance (SG) Pte Ltd
105 Cecil Street
#19-00 The Octagon
Singapore 069534

H/ Adrian
3 days OK - Carline 10 May 2019

Attn: Ms Angie - Motor Claims Dept/Windscreen
Tel: 6389 6541 - Fax: 6224 7175

Owner's Name : Mr. Vikram Telwar
Address : 15 Ardmore Park
#12-02
Singapore 259959
Telephone : 90269392
Type of Claim : Third Party Claims
Policy No. : 1800113050
Vehicle No : **SKC 3862 M**
Model Code :
Model / Year : A8 L D5 3.0 TFSI QU
Engine No : CZ5 010139
Chassis No : WAUZZZF82JN015440
Mileage : -
Date In :
Liability : -
Excess Cost : -
Estimated By : Allan Wu
Accident Date : 17-Jan-19
Place of Accident : Mount. E Novena Car Park

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKC 3862 M

S/N	Nature of Jobs	Estimated Charges	
1	To remove and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid	S/N \$ 480.00	\$ 480.00
2	To dismantle and renew front bumper and lhs headlight. Re-organise crash management components reinstall all parts removed.	\$ 1,600.00	\$ 800.00
3	To respray front bumper.	\$ 1,200.00	\$ 800.00
4	To carry out diagnostic check .	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 3,472.00	\$ 2,272.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKC 3862 M

		<u>Damage Parts & Prices</u>	
<u>S/N</u>	<u>Parts Description</u>	<u>S/NETT</u>	<u>REMARKS</u>
1	FRONT BUMPER	\$ 3,051.00	
2	FRONT BUMPER FIXING PARTS	\$ 475.00	
3	FRONT BUMPER CLOSING ELEMENT-CENTER	\$ 350.00	
4	FRONT BUMPER COVER	\$ 59.00	
5	FRONT BUMPER COVER-LH	\$ 67.00	
6	FRONT BUMPER BRACKET-LH	\$ 100.00	
7	FRONT BUMPER GRILLE-LOWER CENTRE	\$ 424.00	
8	FRONT BUMPER CHROME TRIM-LH	\$ 173.00	
9	FRONT BUMPER CAP-LH	\$ 14.00	
11	FRONT BUMPER END CAP-LH	\$ 53.00	
12	FRONT BUMPER AIR GUIDE GRILLE-LH	\$ 535.00	
13	FRONT BUMPER AIR GUIDE GRILLE INNER TRIM-LH	\$ 200.00	
14	FRONT BUMPER AIR GUIDE GRILLE SURROUND-LH	\$ 200.00	
15	FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE	\$ 238.00	
16	FRONT BUMPER SPOILER	\$ 271.00	
17	RADIATOR CLOSING ELEMENT- LOWER CENTRE	\$ 161.00	
18	FRONT BUMPER SUPPORT-LH	\$ 27.00	
19	FOAM FILLE PIECE	\$ 116.00	
20	FRONT BUMPER CARRIER	\$ 1,051.00	
SUB- TOTAL SPARE PARTS		\$ 7,565.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKC 3862 M

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	FRONT BUMPER COVER	\$ 181.00	
22	FRONT BUMPER GUIDE SECTION-LH	\$ 54.00	
23	RADIATOR GRILLE	\$ 2,063.00	
24	INSCRIPTION ' QUATTRO '	\$ 87.00	
25	RADIATOR COVER	\$ 56.00	
26	ULTRASOUND SENSOR SUPPORT-LH	\$ 47.00	
27	LED HEADLIGHT-LH	\$ 11,951.00	
28	LED HEADLIGHT LIFT CYLINDER-LH	\$ 256.00	
29	FRONT NO. PLATE	S/N \$ 25.00	
30	SUNDRIES	\$ 500.00	
TOTAL SPARE PARTS		: \$ 22,785.00	\$ -
TOTAL LABOUR CHARGES		: \$ 3,472.00	\$ 2,272.00
GRAND TOTAL		: \$ 26,257.00	\$ 2,272.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19001549/AQD3N2

Date: 30/05/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN30222718033	
Claimant Vehicle No :	SKC3862M	Insured Vehicle No :	SKC3994R	
Date of Loss:	17/01/2019	Nature of Claim:	TP	Claim No: SNM19D200327C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKC3862M	Engine No:	CZS010139
Make & Model:	AUDI A8, 3.0 (A)	Chassis No:	WAUZZZF82JN015440
Reg. Date:	11/09/2018 (Man. Year: 2018)	Odometer:	2458 km
Colour:	Maroon		
Engine Capacity:	2995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/45 R19	Rear Tyre Size:	255/45 R19
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,785.00	0.00	22,785.00	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,472.00	2,272.00	1,200.00	34.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	26,257.00	2,272.00	23,985.00	91.35
+ GST 7.00/7.00% (\$\$)	1,837.99	159.04	1,678.95	91.35
Nett Amount (\$\$)	28,094.99	2,431.04	25,663.95	91.35

INSPECTION

Date of Assignment:	28/05/2019	
Date Inspected:	23/01/2019	Inspected At: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days	

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 30 May 2019)
Parts: 143	AUDI A8 3.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKC3862M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	3,051.00 FS	*- FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	475.00 FS	*- FS
3	1		*FRONT BUMPER CLOSING ELEMENT - CENTER	Not Necessary	350.00 FS	*- FS
4	1		*FRONT BUMPER COVER	Not Necessary	59.00 FS	*- FS
5	1		*FRONT BUMPER COVER - LH	Not Necessary	67.00 FS	*- FS
6	1		*FRONT BUMPER BRACKET - LH	Not Necessary	100.00 FS	*- FS
7	1		*FRONT BUMPER GRILLE - LOWER CENTRE	Not Necessary	424.00 FS	*- FS
8	1		*FRONT BUMPER CHROME TRIM - LH	Not Necessary	173.00 FS	*- FS
9	1		*FRONT BUMPER CAP - LH	Not Necessary	14.00 FS	*- FS
10	1		*FRONT BUMPER END CAP - LH	Not Necessary	53.00 FS	*- FS
11	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Not Necessary	535.00 FS	*- FS
12	1		*FRONT BUMPER AIR GUIDE GRILLE INNER TRIM - LH	Not Necessary	200.00 FS	*- FS
13	1		*FRONT BUMPER AIR GUIDE GRILLE SURROUND - LH	Not Necessary	200.00 FS	*- FS
14	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	238.00 FS	*- FS
15	1		*FRONT BUMPER SPOILER	Not Necessary	271.00 FS	*- FS
16	1		*RADIATOR CLOSING ELEMENT - LOWER CENTRE	Not Necessary	161.00 FS	*- FS
17	1		*FRONT BUMPER SUPPORT - LH	Not Necessary	27.00 FS	*- FS
18	1		*FOAM FILLE PIECE	Not Necessary	116.00 FS	*- FS
19	1		*FRONT BUMPER CARRIER	Not Necessary	1,051.00 FS	*- FS
20	1		*FRONT BUMPER COVER	Not Necessary	181.00 FS	*- FS
21	1		*FRONT BUMPER GUIDE SECTION - LH	Not Necessary	54.00 FS	*- FS
22	1		*RADIATOR GRILLE	Not Necessary	2,063.00 FS	*- FS
23	1		*INSCRIPTION QUATTRO	Not Necessary	87.00 FS	*- FS
24	1		*RADIATOR COVER	Not Necessary	56.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
25	1		*ULTRASOUND SENSOR SUPPORT - LH	Not Necessary	47.00 FS	*-FS
26	1		*LED HEADLIGHT - LH	Not Necessary	11,951.00 FS	*-FS
27	1		*LED HEADLIGHT LIFT CYLINDER - LH	Not Necessary	256.00 FS	*-FS
28	1		*FRONT NO. PLATE	Not Necessary	25.00 FS	*-FS
29	1		*SUNDRIES	Not Necessary	500.00 FS	*-FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					22,785.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	New	480.00	480.00
2	TO DISMANTLE AND RENEW FRONT BUMPER AND LHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED.	New	1,600.00	800.00
3	TO RESPRAY FRONT BUMPER.	New	1,200.00	800.00
4	TO CARRY OUT DIAGNOSTIC CHECK.	New	192.00	192.00
Gross Labour Cost (S\$)			3,472.00	2,272.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >