

ASS. REC. BY:

REF: CS/ASM19001SSS/RLS d302 Special Instructions:

Surveyor: Rasul

ASSIGNMENT (Office)

From (Person): Yvonne Ang of ASM CAXA Date/Time: 23/01/2019

Estimated Cost: Bill to:

☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SIM 7733K Insured:

at Workshop m/s Elite Automotive Tel: 63397378

of 280 woodlands Ind. park E5 # 01-17

Policy No: Claim No: S9M01B84

Sum Insured: Excess: NIL

Make of Veh: D.O.A. 19/01/2019
(Client's Record)☒ CA REV / REP. / REV 24 HRS24/1/19
H.O.D. Endorsement:Date/Time: 2:37pm @ 23/1/19 Person Contacted: Christy Vehicle: ☒ IN / ☐ OUT

Date/Time	Action/Instruction (✓) Estimate
	SIM 7733K - CCF/ASM19001360/kija 3 23/01/2019
31/01/19	@ 12:55 p.m. revert authorise repair to Christy (owner) via email.

John

REF:

3600 H


COTR.R4: 2020/July

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 (C) TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: **SJM 7733K**
 at Workshop no: **ELITE AUTO**
 of **280, WOODBURN RD, INNOVATION PK GS # 0177**
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: **NIL**
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bol. or Market Value: **69K**
 IDAC Accident Report: Consistent? **Yes** or No
 GIA / PR Seen: Consistent? **Yes** or No
 Est. Repairs: **12** days Res: **Yes** or No
 Lim Sum: _____ % 3 Val: **Yes** or No

(C) REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: **SJM 7733K** Yl Regn: **2010 July**
 Type: (C) M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: **B.M.W 740LZ 3.0 LA** S.C. **2979**
 Colour: **Grey** A/C: **Insured / Std / NI / NA**
 Sp Reading: **155875** T/Radio: **Insured / Std / NI / NA**
 Eng No: _____
 C/Nr: **WBAKB42040C483247**
 Gen. Cond: **Good** / Fair / Poor / Burnt
 Steering: **Good** / Jammed / Leaked / Burnt or
 Brake: **Good** / Jammed / Leaked / Burnt or
 Mod: **Nil** / S/Rim / STD A/Rim or
 Tyre Size: F: **295/40R19**
 R: **-**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU (C) PIR / SUMI /
 TOYO / YOKO or

Front: _____ Rear: _____
 R/Bal: **6** min R/Bal: **6** min
 L/Bal: **6** min L/Bal: **6** min
 D.O.A: **17/01/19** D.O.I: **24/01/19**
 Survey held at: **ELITE AUTO**

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FRONT

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

repair limit 20K. refer to email
 (\$ 14,741.60 Red - 42%)

Rasul

Pls see my remarks.

RECEIVED 15 AUG 2019

[Signature]
 14/8/2019

Date/Time: File Pass 1/2

14/08/19

Typist

Date/Time: To Return to?

01

Report Format:

Lump Sum / I.B.L: **20K L/S**

Days Of Repair: **12**

Resurvey No. of Trip: **2**

Survey Fee

Transportation

1. ...

2. ...

3. ...

4. ...

5. ...

6. ...

Add Fee: ☐ Site Insp \$

☐ Interview \$

☐ Tech. Insp \$

☐ Weekend \$

300

300




Service Request Details

Claim

S9M01B84

Reference

None 

Loss Date

January 19, 2019

Request Date

January 23, 2019

Due Date

January 30, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (OD)

Type of Loss

Own Damage

Services

Accelerated survey and authorize

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SJM7733K

Make

BMW



Service Address

280 WOODLANDS, ., 757322

Primary Contact/Insured

CHUA TIONG KEE
BLK 33 MARSILING DRIVE, #05-363, 730033, Singapore
91095010
NCDDANNY@GMAIL.COM

Claim Handler

ANG Yvonne
6568804461
yvonne.ang@axa.com.sg

Additional Instructions
EXCESS NIL

- Messages
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes

Document Type

Document SubType

+ Upload Documents

NAME

 Accident Statement

TYPE

Reports & Statement

SUB-TYPE

AUTHOR

Merimen

DATE UPLOADED

NAME

 GIA SHD6661L.PDF

TYPE

Reports & Statement

SUB-TYPE

GIA Report

AUTHOR

VISHNU BATHAM Shekhar



NAME	 GIA SHC6648G.PDF
------	--

TYPE	Reports & Statement
------	---------------------

SUB-TYPE	GIA Report
----------	------------

AUTHOR	VISHNU BATHAM Shekhar
--------	-----------------------

DATE UPLOADED	January 23, 2019
---------------	------------------

NAME	 GIA SHC5005T.PDF
------	--

TYPE	Reports & Statement
------	---------------------

SUB-TYPE	GIA Report
----------	------------

AUTHOR	VISHNU BATHAM Shekhar
--------	-----------------------

DATE UPLOADED	January 23, 2019
---------------	------------------

NAME	 ESTIMATE_.pdf
------	---

TYPE	Forms / Claim Documents
------	-------------------------

SUB-TYPE	Estimate / Quotation
----------	----------------------

AUTHOR	VISHNU BATHAM Shekhar
--------	-----------------------

DATE UPLOADED	January 23, 2019
---------------	------------------

NAME	 EMAIL OD PRI.pdf
------	--

TYPE	Letters and Correspondence
------	----------------------------

SUB-TYPE	Workshop
----------	----------

AUTHOR	VISHNU BATHAM Shekhar
--------	-----------------------



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Information		
Owner ID Type:	Singapore NRIC	
Owner ID:	3600H	
Vehicle Details		
Vehicle No.:	SJM7733K	
Vehicle to be Exported:	No	
Intended Deregistration Date:	24 Jan 2019	
Vehicle Make:	B.M.W.	
Vehicle Model:	740LI 3.0L A/T ABS D/AB 2WD 4DR HID SR	
Primary Colour:	Grey	
Manufacturing Year:	2010	
Engine No.:	09427456N54B30A	
Chassis No.:	WBAKB42040CY83247	
Maximum Power Output:	240.0 kW (321 bhp)	
Open Market Value:	\$78,564.00	
Original Registration Date:	30 Jul 2010	
First Registration Date:	30 Jul 2010	
Transfer Count:	1	
Actual ARF Paid:	\$78,564.00	
PARF Eligibility		
PARF Eligibility:	Yes	
PARF Eligibility Expiry Date:	29 Jul 2020	
PARF Rebate Amount:	\$43,210.00	
COE Information		
COE Expiry Date:	29 Jul 2020	
COE Category:	E - Open Category	
COE Period(Years):	10	
QP Paid:	\$39,000.00	
COE Rebate Amount:	\$5,236.00	
Total Rebate Amount:	\$48,446.00	

The information contained herein is correct as at 24 Jan 2019

OK

69,000
48,446
20,554

(20K)

1yr 6.3

Veron Chen (LKKAuto)

From: Elite Automotive <elite.automotive13@gmail.com>
Sent: Wednesday, 7 August 2019 11:00 AM
To: Rasul (LKKAuto)
Cc: Shirley Hiew (LKK Auto)
Subject: Re: SJM 7733K DOA : 10/01/2019
Attachments: 07082019105751.pdf

Hi Shirley,

Good day! Kindly refer to attached DV and tax invoice, please assist submit to AXA for proceed payment. Thanks!

Regards,

Christy

On Tue, 6 Aug 2019 at 17:27, Elite Automotive <elite.automotive13@gmail.com> wrote:
Hi Rasul,

We accept the offer \$20K. Thanks!

Regards,

Christy

On Wed, 31 Jul 2019 at 18:47, Rasul (LKKAuto) <Rasul@lkkauto.com> wrote:

Hi Christy,

Finalised amount of \$ 20,000 (repair limit) / 12 days lump sum is confirmed

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

LKK Auto
Consultants
Pte Ltd *Save the Earth. Print only when necessary.*

From: Elite Automotive [<mailto:elite.automotive13@gmail.com>]

Sent: Thursday, 24 January, 2019 3:36 PM

To: Rasul (LKKAuto)

Subject: Re: SJM 7733K DOA : 10/01/2019

Hi Rasul,

Good day! Just as spoken on phone, this car repair limit should be \$20k, our client car got sunroof, same the model in the SG CAR MART. Kindly refer to attached photo. Thanks!

Regards,

Christy

On Thu, 24 Jan 2019 at 15:25, Rasul (LKKAUTO) <Rasul@lkkauto.com> wrote:

Email to me the sunroof photo

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Rasul (LKKAUTO)

Sent: Thursday, 24 January, 2019 3:19 PM

To: 'elite.automotive13@gmail.com'

Subject: SJM 7733K DOA : 10/01/2019

Hi Christy,

Repair limit for this vehicle is 13K only

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Ph 102

Save the Earth. Print only when necessary.

--

Regards,

--

Regards,

--

Regards,

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 31 January 2019 12:55 PM
To: 'Elite Automotive'
Cc: SUR
Subject: RE: SJM 7733K DOA : 10/01/2019

Dear Elite,

As instructed by our client, please proceed at repair cost not exceeding \$20,000.00 (inclusive supplementary) to repair the insured vehicle **SJM 7733K (Excess \$0/-)** on lump Sum basis.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Elite Automotive [<mailto:elite.automotive13@gmail.com>]
Sent: Thursday, 24 January, 2019 3:36 PM
To: Rasul (LKKAuto)
Subject: Re: SJM 7733K DOA : 10/01/2019

Hi Rasul,

Good day! Just as spoken on phone, this car repair limit should be \$20k, our client car got sunroof, same the model in the SG CAR MART. Kindly refer to attached photo. Thanks!

VISHNU BATHAM Shekhar

From: Elite Automotive <elite.automotive13@gmail.com>
Sent: Tuesday, January 22, 2019 6:09 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey
Cc: SG AXA Insurance SM Claims Service Team
Subject: Claim Own Damage For Vehicle No: SJM 7733K
Attachments: 22012019180637.pdf

Categories: Shekhar

Hi,

Good day! Kindly refer to attached estimate and accident report, please arrange surveyor come down for survey this vehicle. Thanks!

Regards,

Christy

Veron Chen (LKKAUTO)

From: Rasul (LKKAUTO)
Sent: Thursday, 24 January 2019 4:44 PM
To: Veron Chen (LKKAUTO)
Subject: FW: SJM 7733K DOA : 10/01/2019
Attachments: IMG_0599.JPG; IMG_0598.JPG; IMG_0600.JPG; IMG_0601.JPG


Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Elite Automotive [mailto:elite.automotive13@gmail.com]
Sent: Thursday, 24 January, 2019 3:36 PM
To: Rasul (LKKAUTO)
Subject: Re: SJM 7733K DOA : 10/01/2019

Hi Rasul,

Good day! Just as spoken on phone, this car repair limit should be \$20k, our client car got sunroof, same the model in the SG CAR MART. Kindly refer to attached photo. Thanks!

Regards,

Christy

On Thu, 24 Jan 2019 at 15:25, Rasul (LKKAUTO) <Rasul@lkkauto.com> wrote:

Email to me the sunroof photo

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Rasul (LKKAuto)

Sent: Thursday, 24 January, 2019 3:19 PM

To: 'elite.automotive13@gmail.com'

Subject: SJM 7733K DOA : 10/01/2019

Hi Christy,

Repair limit for this vehicle is 13K only

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

Rasul (LKKAuto)

From: Rasul (LKKAuto)
Sent: Thursday, 24 January, 2019 3:19 PM
To: 'elite.automotive13@gmail.com'
Subject: SJM 7733K DOA : 10/01/2019

Hi Christy,

Repair limit for this vehicle is 13K only


Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.



Auto
Consultants
Pte Ltd

Company Registration No. 198607198R

11, UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408033 TEL : (065) 62563561 FAX : (065) 62564319

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 25/01/2019

Survey Details:

Date of loss	19-Jan-19
Date of appointment	23-Jan-19
Date of survey	24-Jan-19
Location of survey	280 WOODLANDS INDUSTRIAL PARK E5 #01-17 HARVEST@WOODLANDS SINGAPORE 757322

Vehicle Details:

Claim Type:	Own Damage
Vehicle number	SJM 7733K
Make and Model	BMW 740LI 3.0 A/T ABS/D/AB 2WD
Date of registration	30-Jul-10
Excess	\$0
Market Value	\$69,000
Parf Rebate	\$48,446
Nett Loss	\$20,554

Repair details:

Initial Estimate	34,741.60
------------------	-----------

Proposed/Revised repair cost:

Parts	\$14,202.60
Check items (estimate)	\$8,529.00
Labour	\$3,560.00
Total	\$26,291.60
Lump Sum(if applicable)	\$20,000.00 (ESTIMATE)

Number of days for repair	12 DAYS
---------------------------	---------



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 URAVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 409333 TEL : (66) 62563561 FAX : (66) 62564318

Remarks:

DAMAGES CONSISTENT, REPAIR COST ECONOMICAL. WE HAVE AUTHORIZED REPAIR. REPAIRER AGREED TO UNDERTAKE THE REPAIR COST NOT EXCEEDING \$ 20,000.00 ON LUMP SUM BASIS.

Mandate:

Liability(TP)	%	
Proposed repair cost	\$	
Loss of use	\$ no. of days	
Loss of rental	\$ no. of days	
Loss of income	\$ no. of days	
LTA search fees	\$	
Others	\$	
Proposed Total	#VALUE!	

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	21/01/2019 11:41
Date Of Accident	19/01/2019 22:00
Exact Location Of Accident	BAYFRONT AVENUE LAMPPOST 13F TOWARD TEMASAK
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SJM7733K
Insured/Policyholder	
Name Of Registered Owner	CHUA TIONG KEE
NRIC No	S7173600H
Email Address	NCDDANNY@GMAIL.COM
Mobile Phone No	(LOCAL) +65-91095010
Alternative Phone No	OTHERS-91095010
Vehicle Particulars	
Manufacturer	BMW
Model	740LI 3.0L A/T ABS D/AB 2WD 4DR HID SR
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA241805/1
Cover Note Number	
Driver	
Name of Driver	CHUA TIONG KEE
NRIC No	S7173600H
Date Of Birth	15/08/1971
Occupation	INDOOR
Date Of Driving Pass	03/10/1992
Driving Experience	26 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91095010
Fax Number	
Contact Number	OTHERS-91095010
Email Address	NCDDANNY@GMAIL.COM

Address	BLK 108A CANBERRA WALK #05-11
Postcode	751108
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	4
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO THE ATTACHMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHC6648G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	SEE LUB HOK
NRIC/Passport Number	S0095690B
Contact Number	81099369
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SHC5005T
-----------------------------	----------

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

TAXI

Name of Driver

WONG SOON CHAI

NRIC/Passport Number

S0092439C

Contact Number

97501009

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

SHD6661L

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

TAXI

Name of Driver

YU CHIN SENG

NRIC/Passport Number

S2567416B

Contact Number

96226711

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time: 24/1/2019 11:30:40


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/IN No.:

SKETCH PLAN

BAYFRONT AVE TOWARD TENASAK.

A: SFM7733K



B: SHC6648G

C: SHC5005T

D: SHD6661L

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along the upslope of Bayfront Ave, when I suddenly saw a taxi queuing up along the road. It was too sudden and I didn't manage to react in time. Tried to brake but it was too late already and my car collided with the taxi in front.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 21/1/2019/11.30am

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No:



redefining / insurance

LETTER OF UNDERTAKING/ AUTHORIZATION FOR LUMP SUM REPAIR

1. I, [Name] [NRIC] Chua Tiong Kee S71736007 the owner/
authorized driver of vehicle [Registration No.] STM 7733K ("Vehicle") do hereby
authorize the [Workshop/Insurer] to repair the Vehicle on a lump sum basis instead of part
by part.
 2. The [Workshop/Insurer] has explained to me the difference between lump sum repair and
part by part repair and the consequences of my authorization for lump sum repair for the
Vehicle.
 3. I understand that with lump sum repair, the Workshop may use a mixture of genuine parts,
original equipment manufacturer (OEM) parts, reconditioned and second hand parts to
carry out the repair and I note that the [Workshop/Insurer] will not be furnishing a detailed
breakdown of parts or price for such lump sum repair.
 4. I am aware that AXA Insurance Pte Ltd ("AXA Insurance") does not encourage lump sum
repair as AXA Insurance strongly recommends repairs for vehicles on a part by part basis
for transparency reasons. I confirm that I will hold AXA Insurance harmless from any claims
arising from the lump sum repair of the Vehicle which I have authorized.
 5. * To be applicable where person authorizing is the authorized driver.
- I confirm that I have the authority from the owner of the Vehicle to authorize the lump sum
repairs and that I have duly notified the owner of the Vehicle of the contents of this Letter
of Authorization.

Signed and acknowledged by:

Signature of policyholder/ authorized driver* and company stamp (where applicable)

Date:



Name and signature of workshop personnel including workshop stamp

Date:

24/1/19

*authorized driver to either the named drivers as per motor insurance policy or in the case of commercial
vehicles, permitted drivers who are permitted to drive the insured Vehicle.

ELITE AUTOMOTIVE PTE LTD

280 Woodlands Industrial Park E5, #01-17,

Harvest @ Woodlands Singapore 757322

Tel: 6339 7378 Fax: 6339 7475

Vehicle Number : SJM 7733K

Vehicle Model : BMW 740LI

Chassis Number : WBAKB42040CY83247

admind

admin - d@kk.com

Estimated Repair Cost

S/N	Parts Description	Qty	Price
1	BONNET <i>9A</i> ✓	1 S	2900.00
2	BONNET LOCK <i>8A</i> ✓	1pc ✓ S	380.00
3	BONNET LOCK CATCH <i>M</i> ✓	1pc ✓ S	160.00
4	BONNET CENTER LOCK CATCH <i>X</i>	1 S	45.00
5	BONNET INSULATION <i>ac</i> ✓	1 S	300.00
6	BONNET INSULATION CLIPS <i>ac</i> ✓	25 S	125.00
7	BONNET RUBBERSTRIP <i>ac</i> ✓	1 S	50.00
8	BONNET CENTER RUBBERSTRIP <i>ac</i> ✓	1 S	45.00
9	BONNET HINGES (LH & RH) <i>RH-X / LH-X SVC</i>	1pc ✓ S	180.00
10	FRONT BUMPER <i>BTOR</i> ✓	1 S	1500.00
11	FRONT BUMPER CLIPS <i>ac</i> ✓	10 S	50.00
12	FRONT BUMPER CHROME MOULDING LH & RH <i>CRA</i> ✓	2 S	96.00
13	FRONT BUMPER LOWER GRILLE (LH & RH) <i>RH-DE / LH-X</i>	2pc S	70.00
14	FRONT BUMPER CENTER GRILLE <i>M4</i> ✓	1 S	68.00
15	FRONT BUMPER INNER SPONGE <i>CRA</i> ✓	1 S	70.00
16	FRONT BUMPER REINFORCEMENT <i>9A</i> ✓	1 S	800.00
17	FRONT BUMPER BRACKET <i>ac</i> ✓	2 S	30.00
18	FRONT BUMPER INNER V-BAR <i>8A</i> ✓	2 S	44.00
19	HEADLAMP NOZZLE (LH & RH) <i>RH-CRA / LH-X</i>	1pc ✓ S	360.00
20	HEADLAMP NOZZLE COVER (LH & RH) <i>RH-DE / LH-X</i>	1pc ✓ S	100.00
21	HEADLAMP NOZZLE HOSE <i>cut</i> ✓	1 S	48.00
22	HEADLAMP TOP RUBBER (LH & RH) <i>X</i>	2 S	140.00
23	HEADLAMP (LH & RH) (HID) <i>RH-BRO / LH-R / CRA</i>	2 S	5600.00
24	HEADLAMP RH BALLAST <i>Bro</i> ✓	1 S	800.00
25	HEADLAMP RH BULB <i>CRA</i> ✓	1pc ✓ S	760.00
26	HEADLAMP PANEL RH <i>X Repair</i>	1 S	130.00
27	FRONT GRILLE (LH & RH) <i>CRA</i> ✓	2 S	350.00
28	FRONT GRILLE INNER BRACKET <i>ac</i> ✓	1 S	240.00
29	SUPPORT PANEL <i>ac</i> ✓	1pc S	630.00
30	FOG LAMP RH <i>3 / CRA</i>	1 S	270.00
31	FRONT SPLASH SHIELD (LH & RH) <i>RH-SOL / LH-X</i>	1pc ✓ S	660.00
32	FRONT SPLASH SHIELD CLIPS <i>ac</i> ✓	20pc S	100.00
33	OIL COOLER RH <i>7 / DD</i>	1 S	740.00
34	BRAKE AIR DUCT RH <i>CRA</i> ✓	1 S	65.00
35	FRONT FENDER RH & LH <i>RH-BRO / LH-Repair</i>	2pc S	2460.00
36	FRONT FENDER UPPER GARNISH (LH & RH) <i>RH-SOL / LH-X</i>	2pc S	300.00
37	FRONT FENDER UPPER GARNISH CLIPS (LH & RH) <i>LH-X / RH-X</i>	20pc S	100.00
38	AIRCON SUCTION PIPE <i>ac</i> ✓	1 S	350.00

ELITE AUTOMOTIVE PTE LTD

280 Woodlands Industrial Park E5, #01-17,

Harvest @ Woodlands Singapore 757322

Tel: 6339 7378 Fax: 6339 7475

39	AIRCON PRESSURE PIPE 3 BT✓	1	S	310.00
40	AIRCON DISCHARGE PIPE 3 BT✓	1	S	310.00
41	ENGINE UNDER COVER 1/2 CUT✓	1	S	200.00
42	ENGINE UNDER COVER CLIPS 1/2 NECL✓	20	S	30 100.00
43	CHASSIS MEMBER RH Repair✓	1	S	2500.00

Spare Parts Total Price	S	24536.00
Cost Price +10%	S	2453.60
	S	26,989.60

S/N	Special Nett Items:	Qty			
1	FRONT BUMPER DISTANCE SENSOR	2PCS 2PCS	S	1610.00	} price?
2	FRONT BUMPER DISTANCE SENSOR HOLDER New✓	2PCS 2PCS	S	420.00	
3	FRONT BUMPER DISTANCE SENSOR SEAL New✓	2PCS 2PCS	S	42.00	
4	FRONT NUMBER PLATE WITH HOLDER New✓	1SET		80.00	50
	Special Nett Total		S	2152.00	
	Spare Part's Total Price		S	29141.60	

* Engine upper cover

Rashid

Hp 90010068

12 days

~~1/2~~ 4/5

28/01/19 @ 0900 hrs

EXCESS: NIL

Authorized

Reserving b/c part

Kindly provide letter of undertaking for imp sum repair

ELITE AUTOMOTIVE PTE LTD

280 Woodlands Industrial Park E5, #01-17,

Harvest @ Woodlands Singapore 757322

Tel: 6339 7378 Fax: 6339 7475

Vehicle Number : SJM 7733K

Vehicle Model : BMW 740LI

Chassis Number : WBAKB42040CY83247

S/N	Labour Descriptions	Charges
1	LABOUR CHARGES TO REMOVE & INSTALL FRONT END ATTACHMENTS & FITTINGS TO ENABLE REPAIRS; TO STRAIGHTEN & REPAIRS RH HEADLAMP PANEL, FRONT LH & RH FENDER AND FRONT SUPPORT PANEL; TO REMOVE & REPLACE FRONT DAMAGED PARTS AS LISTED ABOVE.	S 2500.00 1600
2	TO SPRAY PAINTING ON: BONNET (INNER, OUTER), FRONT BUMPER, FRONT SUPPORT PANEL AND FRONT BOTH FENDER, FRONT RH DOOR.	S 2000.00 1500
3	TO REMOVE & INSTALL A/C CONDENSER, A/C PIPINGS & FITTINGS TO ENABLE REPAIRS; TO VACUUM & CHARGES UP GAS.	S 200.00 120
4	TO REMOVE & INSTALL RADIATOR & HOSES & ELECTRICAL FANS TO ENABLE REPAIRS; INCLUDING PRESSURIZE COOLING.	S 100.00 80
5	TO REMOVE & REPLACE HEADLAMP, CHECK LIGHTING & FOCUS HEADLIGHTS.	S 100.00 50
6	TO DRILL 7 PCS SENSORS HOLES AND REPLACE SENSORS.	S 150.00 60
7	TO REMOVE & REPLACE HEADLAMP WIPER JET C/W MOTOR, RE-ALIGN & TEST FUNCTION.	S 100.00 X
8	TO CARRY OUT E.C.U. CHECK, REMOVE & CLEAR FAULT CODES AFTER NECESSARY ACCIDENT REPAIRS.	S 300.00 150
9	LABOUR CHARGE FOR TOP UP ENGINE COOLANT	S 150.00

Labour Total S 5600.00

Parts & Labour Total S 34741.60

LKK Auto Care Centre shall be the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ELITE AUTOMOTIVE PTE LTD

280 Woodlands Industrial Park E5, #01-17,

Harvest @ Woodlands Singapore 757322

Tel: 6339 7378 Fax: 6339 7475

Vehicle Number : SJM 7733K

Vehicle Model : BMW 740LI

Chassis Number : WBAKB42040CY83247

Estimated Repair Cost

S/N	Parts Description	Qty	Price
1	BONNET <i>9A</i> ✓	1 S	2900.00
2	BONNET LOCK <i>9A</i>	1pc ✓ S	380.00 190
3	BONNET LOCK CATCH <i>9A</i> ✓	1pc ✓ S	160.00 80
4	BONNET CENTER LOCK CATCH <i>Xsu</i>	1 S	45.00 X
5	BONNET INSULATION <i>9A</i> ✓	1 S	300.00
6	BONNET INSULATION CLIPS <i>9A</i> ✓	25 S	125.00
7	BONNET RUBBERSTRIP <i>9A</i> ✓	1 S	50.00
8	BONNET CENTER RUBBERSTRIP <i>9A</i> ✓	1 S	45.00
9	BONNET HINGES (LH & RH) <i>RH-2/LH-Xsu</i>	1pc ✓ S	180.00 X
10	FRONT BUMPER <i>9A</i> ✓	1 S	1500.00
11	FRONT BUMPER CLIPS <i>9A</i> ✓	10 S	50.00
12	FRONT BUMPER CHROME MOULDING LH & RH <i>9A</i> ✓	2 S	96.00
13	FRONT BUMPER LOWER GRILLE (LH & RH) <i>RH-DE/LH-XSVC</i>	2pc S	70.00 35
14	FRONT BUMPER CENTER GRILLE <i>9A</i> ✓	1 S	68.00
15	FRONT BUMPER INNER SPONGE <i>9A</i> ✓	1 S	70.00
16	FRONT BUMPER REINFORCEMENT <i>9A</i> ✓	1 S	800.00
17	FRONT BUMPER BRACKET <i>9A</i> ✓	2 S	30.00
18	FRONT BUMPER INNER V-BAR <i>9A</i> ✓	2 S	44.00
19	HEADLAMP NOZZLE (LH & RH) <i>RH-CRA/LH-Xsu</i>	1pc ✓ S	360.00 180
20	HEADLAMP NOZZLE COVER (LH & RH) <i>RH-DE/LH-Xsu</i>	1pc ✓ S	100.00 50
21	HEADLAMP NOZZLE HOSE <i>9A</i> ✓	1 S	48.00
22	HEADLAMP TOP RUBBER (LH & RH) <i>Xsu</i>	2 S	140.00
23	HEADLAMP (LH & RH) (HID) <i>RH-BRO/LH-2.CRA</i>	2 S	5600.00
24	HEADLAMP RH BALLAST <i>9A</i> ✓	1 S	800.00
25	HEADLAMP RH BULB <i>9A</i> ✓	1pc ✓ S	760.00 380
26	HEADLAMP PANEL RH <i>? Repair</i>	1 S	130.00 X
27	FRONT GRILLE (LH & RH) <i>9A</i> ✓	2 S	350.00
28	FRONT GRILLE INNER BRACKET <i>9A</i> ✓	1 S	240.00
29	SUPPORT PANEL <i>9A</i> ✓	4 S	630.00
30	FOG LAMP RH <i>? CRA</i>	1 S	270.00
31	FRONT SPLASH SHIELD (LH & RH) <i>RH-Su/LH-XAN</i>	1pc ✓ S	660.00 330
32	FRONT SPLASH SHIELD CLIPS <i>9A</i> ✓	20pc S	100.00 50
33	OIL COOLER RH <i>? 00</i>	1 S	740.00
34	BRAKE AIR DUCT RH <i>9A</i> ✓	1 S	65.00
35	FRONT FENDER RH & LH <i>RH-Buc/LH-Repair</i>	1pc ✓ S	2460.00 1230
36	FRONT FENDER UPPER GARNISH (LH & RH) <i>RH-Su/LH-Xsu</i>	2pc S	300.00 150
37	FRONT FENDER UPPER GARNISH CLIPS (LH & RH) <i>LH-2/RH-20/10pc</i>	20pc S	100.00 50
38	AIRCON SUCTION PIPE <i>? 9A</i> ✓	1 S	350.00

17,896

ELITE AUTOMOTIVE PTE LTD

280 Woodlands Industrial Park E5, #01-17,

Harvest @ Woodlands Singapore 757322

Tel: 6339 7378 Fax: 6339 7475

920

39	AIRCON PRESSURE PIPE	1	S	310.00
40	AIRCON DISCHARGE PIPE	1	S	310.00
41	ENGINE UNDER COVER	1	S	200.00
42	ENGINE UNDER COVER CLIPS	20	S	100.00
43	CHASSIS MEMBER RH	1	S	2500.00

18816
+ 10%
20697.60

Spare Parts Total Price	\$	24536.00
Cost Price +10%	\$	2453.60
	\$	26,989.60

S/N	Special Nett Items:	Qty		
1	FRONT BUMPER DISTANCE SENSOR	2PCS	\$ 460	1610.00
2	FRONT BUMPER DISTANCE SENSOR HOLDER	2PCS	\$ 75	420.00
3	FRONT BUMPER DISTANCE SENSOR SEAL	2PCS	\$ 21	42.00
4	FRONT NUMBER PLATE WITH HOLDER	1SET		80.00
	Special Nett Total		\$	2152.00

Spare Part's Total Price	\$	29141.60
--------------------------	----	----------

20,697.60
972.00
3560.00
25,229.60

20%
20,183.68

Repair limit 20k

Rasul
28/1/19

Hp 90010068

12 days

4/5

28/01/19 @ 0900 hrs

EXCESS: NIL

Authorized

Reserving b & part

Kindly provide letter of undertaking for lump sum repair

ELITE AUTOMOTIVE PTE LTD

280 Woodlands Industrial Park E5, #01-17,

Harvest @ Woodlands Singapore 757322

Tel: 6339 7378 Fax: 6339 7475

Vehicle Number : SJM 7733K

Vehicle Model : BMW 740LI

Chassis Number : WBAKB42040CY83247

S/N	Labour Descriptions	Charges
1	LABOUR CHARGES TO REMOVE & INSTALL FRONT END ATTACHMENTS & FITTINGS TO ENABLE REPAIRS; TO STRAIGHTEN & REPAIRS RH HEADLAMP PANEL, FRONT LH & RH FENDER AND FRONT SUPPORT PANEL; TO REMOVE & REPLACE FRONT DAMAGED PARTS AS LISTED ABOVE.	\$ 2500.00 1600
2	TO SPRAY PAINTING ON: BONNET (INNER, OUTER), FRONT BUMPER, FRONT SUPPORT PANEL AND FRONT BOTH FENDER, FRONT RH DOOR.	\$ 2000.00 1500
3	TO REMOVE & INSTALL A/C CONDENSER, A/C PIPINGS & FITTINGS TO ENABLE REPAIRS; TO VACUUM & CHARGES UP GAS.	\$ 200.00 120
4	TO REMOVE & INSTALL RADIATOR & HOSES & ELECTRICAL FANS TO ENABLE REPAIRS; INCLUDING PRESSURIZE COOLING.	\$ 100.00 80
5	TO REMOVE & REPLACE HEADLAMP, CHECK LIGHTING & FOCUS HEADLIGHTS.	\$ 100.00 50
6	TO DRILL 7 PCS SENSORS HOLES AND REPLACE SENSORS.	\$ 150.00 80
7	TO REMOVE & REPLACE HEADLAMP WIPER JET C/W MOTOR, RE-ALIGN & TEST FUNCTION.	\$ 100.00 X 111
8	TO CARRY OUT E.C.U. CHECK, REMOVE & CLEAR FAULT CODES AFTER NECESSARY ACCIDENT REPAIRS.	\$ 300.00 150
9	LABOUR CHARGE FOR TOP UP ENGINE COOLANT	\$ 150.00 X 111
Labour Total		\$ 5600.00
Parts & Labour Total		\$ 34741.60

LKK Auto Centre has provided the Repaired of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claim No : _____

OWN DAMAGE CLAIM DISCHARGE VOUCHER

TO : AXA INSURANCE SINGAPORE PTE LTD

I / We hereby declare that the repairs to my / our vehicle registration no SJM 7733K have been completed to my / our satisfaction and

I / We acknowledge that payment of the sum of \$ 21,400.00 to me / the repairer for such repair shall be in full discharge of my / our under Policy No : GA241805/1 in respect of the damage caused to my / our said motor vehicle in the accident which occurred on the 19/1/19.

Policy holder / Driver/ On Behalf

Name : Chua Tiong Kee

NRIC No : S7173600H

Signature : [Signature]

Date : 26/2/19

With modern technology, glass removal may affect the memory of the default security setting. If it happen, we cannot be responsible for the reselling

Remarks : _____
: _____
: _____
: _____

Elite
Automotive Pte Ltd

23HRS SERVICES

Co.Regn No: 201700196D

GST.Reg.No: 201700196D

280 Woodlands Industrial Park E5 #01-17 Harvest@Woodlands (S) 757322

Hotline: 8660 6722 Tel: 6339 7378 Fax: 6339 7475 Email: elite.automotive13@gmail.com

TAX INVOICE NO : EA1908-359

Messrs : AXA INSURANCE PTE LTD

Date : 7/8/2019

Address : 8 SHENTON WAY, #27-01

SINGAPORE 068811

Email :

Mobile :

Home/Office Tel :

No	Description	Qty	Amount
	<u>VEHICLE NO: SJM 7733K (BMW 740Li)</u>		
1	LUMP SUM REPAIR	1	\$ 20,000.00
			\$ 20,000.00
	GST	7%	\$ 1,400.00
	Total		\$ 21,400.00



Elite Automotive Pte Ltd

Customer Signature & Company Stamp