



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com

Website: www.nhtmotor.com

Tel: 6747 9241

Fax: 6741 7276

UEN: 201718370K

22/01/2019

Blk 1 Kaki Bukit Ave 6

# 01-43

Singapore 417883

TP Con Pac.

Xiao Tang.

Accident date: 21/01/2019

Estimated repair cost for vehicle no: SLW974B MITSUBISHI LANCER 2.0 A '09

| S/n | Qty | Items                                       | U/price | Amount          |
|-----|-----|---------------------------------------------|---------|-----------------|
| 1   | 1   | Front Bumper <i>Deformed</i>                |         | \$758.00 ✓      |
| 2   | 10  | Front Bumper Clip <i>re</i>                 | \$6.50  | \$65.00 30      |
| 3   | 1   | Front L/H Bumper Side Retainer <i>re</i>    |         | \$38.00 ✓       |
| 4   | 1   | Front L/H Head Lamp <i>cracked</i>          |         | \$652.00 ✓      |
| 5   | 1   | Front L/H Head Lamp Lower Bracket <i>re</i> |         | \$23.00 +       |
| 6   | 1   | Front L/H Fender <i>Deformed</i>            |         | \$486.00 ✓      |
| 7   | 1   | Front L/H Fender Signal Lamp <i>re</i>      |         | \$68.00 +       |
| 8   | 1   | Front L/H Fender Cowling <i>Deformed</i>    |         | \$107.00 ✓      |
| 9   | 8   | Front L/H Fender Cowling Clip <i>re</i>     | \$6.50  | \$52.00 30      |
| 10  | 1   | Front L/H Door <i>Deformed</i>              |         | \$1,065.00 ✓    |
| 11  | 2   | Front L/H Door Frame Sticker <i>re</i>      | \$36.00 | \$72.00 ✓       |
| 12  | 1   | Front L/H Rim <i>lt</i>                     |         | \$680.00 450(w) |
| 13  | 1   | Front L/H Tyre <i>re</i>                    |         | \$350.00 +      |
| 14  | 1   | Front L/H Lower Arm <i>Be</i>               |         | \$292.00 ✓      |
| 15  | 1   | Front L/H Knuckle Arm <i>Be</i>             |         | \$358.00 ✓      |
| 16  | 1   | Front L/H Knuckle Arm Bearing <i>re</i>     |         | \$259.00 ✓      |
| 17  | 1   | Front L/H Stabilizer Bar <i>re</i>          |         | \$309.00 +      |
| 18  | 1   | Front L/H Shock Absorber <i>Be</i>          |         | \$387.00 ✓      |
| 19  | 1   | Front L/H Drive Shaft <i>re</i>             |         | \$1,386.00 +    |
| 20  | 1   | Front Steering Rack <i>re</i>               |         | \$1,833.00 +    |
| 21  | 1   | Front Crossmember <i>re</i>                 |         | \$956.00 +      |

4534

Subtotal :- \$10,196.00

4080.60

S.W 450

### Labour charges

|                                                                                               |                           |
|-----------------------------------------------------------------------------------------------|---------------------------|
| To remove & refit front L/H undercarriage                                                     | \$380.00 <del>220</del>   |
| To remove & refit L/H drive shaft, steering rack & crossmember                                | \$450.00 X                |
| To remove & refit front L/H door, glass, lock, rubber, gear motor, frame sticker & trim board | \$150.00 <del>80</del>    |
| To check wheel alignment                                                                      | \$150.00 <del>80</del>    |
| To check wiring                                                                               | \$100.00 <del>30</del>    |
| Towing fee                                                                                    | \$100.00 X                |
| Tuff kote                                                                                     | \$150.00 X                |
| Panel beating                                                                                 | \$1,400.00 <del>800</del> |
| Spray painting                                                                                | \$1,400.00 <del>600</del> |

Subtotal :- \$4,280.00

Total:- \$14,476.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

total: 6140.60  
h/s: 4.9k.

05 Pays.

4.9k