

Surveyor: WHP DOI: 21/1/19 Date / Time: 21/1/19 Registered in Merimen: -

Pre-assign / CCU / FTE

SJX 1644R



Insured Vehicle No. : SJX 1644R Claim No. : _____
Name of Insured : LOH HUBY WFN Policy No. : _____
Insured Tel No. : _____ HP: _____ Make / Model : _____
Excess Sec II :SS _____ D.O.A : 19-01-19 Place of Accident : _____
Is driver the owner? (YES / NO) Nature of Accident : _____
If NO, Driver Name / Age : CHAM WAF 70M OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO
Driver Tel No. : _____ (V/L: YES / NO) Insured Liability : _____ % Final ? Yes / No

SMP 4516S → SLT 5723S → unknown → SJX 1644R → SLH 434A



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS:



INSRS: WSP: Tel: Liability: RMKS: 01



INSRS: WSP: W30M Tel: TP Liability: RMKS:

Date/ Time		STAGE	DATE / PIC
<u>3/3</u>	<u>SLH 434A</u>	Non-Reporting ltr (1st):	
<u>08/1</u>	<u>SJX 1644R</u>	Non-Reporting ltr (2nd):	
		Non-Reporting ltr (Final):	
		Notification ltr (if non-pickup):	
		Call OI:	<u>11/4/19 central</u>
		After call ltr to OI:	<u>12/4/19 central no-acc</u>
		Documentation Check List:	Handler Typist
		Notification ltr (if non-pickup)	<input checked="" type="checkbox"/> <input type="checkbox"/>
		After call ltr to OI:	<input checked="" type="checkbox"/> <input type="checkbox"/>
		Authorisation To Act:	<input checked="" type="checkbox"/> <input type="checkbox"/>
		Release Voucher:	<input checked="" type="checkbox"/> <input type="checkbox"/>
		Final Repair Bill:	<input checked="" type="checkbox"/> <input type="checkbox"/>
		Car Rental Invoice:	<input checked="" type="checkbox"/> <input type="checkbox"/>
		Towing Invoice	<input type="checkbox"/> <input type="checkbox"/>
		LTA / GIA :	<input checked="" type="checkbox"/> <input type="checkbox"/>
		Medical Bill:	<input type="checkbox"/> <input type="checkbox"/>
		PIR:	<input type="checkbox"/> <input type="checkbox"/>
		Mandate/Reject Instruction:	<input checked="" type="checkbox"/> <input type="checkbox"/>
		LOD	<input checked="" type="checkbox"/> <input type="checkbox"/>
		Payment Breakdown Form:	<input type="checkbox"/> <input type="checkbox"/>
		Post-Repair Photos:	<input type="checkbox"/> <input type="checkbox"/>
		Others:	<input type="checkbox"/> <input type="checkbox"/>

12/4 - call OI, OI no answer. To email and mail out LOI as requested. Inform TP claim willing to settle & advise NED will be withheld.
21/4 - offer rec BOR to TP - pending LOD.
- LOD in, TP claim that original document mail out to CTI on 11/4/19 offer global of \$7810. (pending acceptance)
- File PAS to report team type mandate.
22/5 - seek mandate of \$802340 - pending approval.

* ORIGINAL LOD WITH CTI

PRELIMINARY ADVICE	Date/Time:	Sent By:	Confirm with:	Confirm by: <u>WHP</u>
Repair Cost:	<u>\$5,800</u>	(<u>7</u> days) Reduction:	<u>67</u> %	Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>
FINAL SETTLEMENT	Date/Time: <u>24.01.19</u>	Confirm with: <u>MIENHUE</u>	Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>	
Final Liability:	% <u>100</u>	(Agreed / Assessed) BOLA S/N No.:	<u>28</u>	If NO or B 28, Ass. Lia:
Repair Cost: (W/CST)	\$5 <u>6741.00</u>			<u>chain collision</u>
Loss of Rental (LOR):	\$5 <u>8400</u>	(<u>7</u> days) x <u>200</u>		<u>(OI 2nd veh)</u>
Loss of Use (LOU):	\$5 <u>-</u>	(<u>5</u> x days)		
Loss of Income (LOI):	\$5 <u>-</u>	(<u>5</u> x days)		
LOR only <input checked="" type="checkbox"/> LOU only <input type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/>	[Tick only one]			
GIA/LTA Search	\$5 <u>7.45</u>			
Medical:	\$5 <u>-</u>			
Disbursement:	\$5 <u>-</u>	(e.g. Tow/ Independent)		
Legal Cost	\$5 <u>-</u>			
Total:	\$5 <u>7,588.45</u>	Global Sum \$5:	<u>5</u>	
FINAL PAYMENT	Date/Time: <u>24.01.19</u>	Confirm with: <u>MIENHUE</u>	Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>	
Payee 1:	\$5 <u>7,588.45</u>	Name 1:	<u>VISION AUTOWORK PTE. LTD.</u>	
Payee 2: (Strike if N.A.)	\$5 <u>-</u>	Name 2:		
Payee 3: (Strike if N.A.)	\$5 <u>-</u>	Name 3:		

COMPLET
21/1/19

ASS. REC. BY:

REF:

Adrian

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SLH2139A. Yr Regt: 2016 / Oct.
 Type: (M.Cas) / M.Cyclic / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Toyota Wish. C.C. 1798
 Colour: Gold. A/C: Insured / Std / Nil / NA
 Sp. Reading: 29892 T/Radio: Insured / Std / Nil / NA
 Eng/No: _____
 C/No: JTDG66LW50J005540
 Gen. Cond: (Good) / Fair / Poor / Burnt
 Steering: (In order) / Jammed / Leaked / Burnt or _____
 Brake: (In order) / Jammed / Leaked / Burnt or _____
 Modl: Nil / (S/Rim) / STD A/Rim or _____
 Tyre Size: F: 195/65R15
 R: 195/65R15.
 BS / DUN / EXNOVA (GY) / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____

(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rport: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 7 days Res: Yes or No
 Lum Sum: 70 % 3 Val: Yes or No

Front Rear
 R/Bal. 06 mm R/Bal. 06 mm
 L/Bal. 06 mm L/Bal. 06 mm
 D.O.A. _____ D.O.I. 21/07/19.

CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Survey held at Vision.
 Des. of Damages: Frt / (Rear) / O/S / N/S / U/C / Rooftop or _____
 The U/C / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
	<u>TP Chosen.</u>
	<u>L/S \$6300 with 7 repair days</u>
	<u>MV : 80K.</u>
	<u>PV : 59.2K</u>
	<u>Nett: 20.6K.</u>
	<u>(Red = \$12413.75 / 67%)</u>

Date/Time, File Pass to?	Date/Time, File Return to?	Part Prices Check:		Survey Fee:	Date:					
1)	2)	IN	OUT	Basic & Add	<table border="1"> <tr><td> </td></tr> <tr><td> </td></tr> <tr><td> </td></tr> <tr><td> </td></tr> <tr><td> </td></tr> </table>					
3)	4)			____ S + RS, ____ SI						
5)	6)			Photos						
Prel. Report				Others						
Final Report				TOTAL						



Toyota Wish 1.8A | \$77,800 | \$9,430 /yr | 31-Mar-2016 | 1,798 cc | - | MPV | Available

Good Buy, Good Car! Smooth Engine. Beautiful Model. Call Us Now.

Ka-Hup Vehicles Trading

Posted: 25-Jan-2016 | Tags: 2016 Toyota Wish, 2016 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota

PREMIUM AD



Toyota Wish 1.8A X | \$79,800 | \$9,860 /yr | 04-Apr-2016 | 1,797 cc | - | MPV | Available

Low Interest Rate From 1.99% Onwards, In House Loan Available, Well Taken Care Of By Previous Owner. Almost New Tyres! Extended Warranty Available! Professional Evaluation Services Included! Buy With ...

Dickson Automobile

Posted: 24-Dec-2016 | Tags: 2016 Toyota Wish, 2016 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota



Toyota Wish 1.8A | \$75,800 | \$8,960 /yr | 26-May-2016 | 1,798 cc | 49,500 km | MPV | Available

From Borneo Motors. In Excellent Condition. Well Kept By Owner. Regularly Serviced. Low Mileage Done. High Loan And Trade In Welcome.call Now For Viewing

Posted: 12-Jan-2016 | Tags: 2016 Toyota Wish, 2016 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota

PREMIUM AD



Auction your Car to 500+ Dealers

Get a Bid Price ready in 1 hour with sqCarMart Quitz - Singapore's most efficient bidding system with a network of 500+ Dealers. Get paid immediately with FAST iBanking and a flexible 2-week handover. Highest Price Guaranteed, or get \$100 cash from us.

Find out more!



Toyota Wish 1.8A | \$84,999 | \$9,970 /yr | 01-Aug-2016 | 1,798 cc | 46,000 km | MPV | Available

Under Borneo Motors Warranty. Full Borneo Motor Service. Change New Battery. Low Mileage. 100% Accident Free. Excellent Condition. Extra Feature: 1 Ceramic Pro Nano Coating 5 Layers, 2nd Row Aircon Blo...

Posted: 06-Jan-2016 | Tags: 2016 Toyota Wish, 2016 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota

CREDIT CHECK



Toyota Wish 1.8A | \$78,888 | \$9,120 /yr | 12-Aug-2016 | 1,798 cc | - | MPV | Available

Super Reliable Model Among The MPV Group. Purchase Comes With 1 Year Free Servicing. Bank Loan Interest Rate At 2.18%. ALL TRADE IN Vehicle Are Welcomed. Please SMS Or Whatsapp The Vehicle Car Plate N...

Posted: 23-Jan-2016 | Tags: 2016 Toyota Wish, 2016 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota

PREMIUM AD



Toyota Wish 1.8A | \$86,888 | \$10,050 /yr | 16-Sep-2016 | 1,798 cc | 38,000 km | MPV | Available

Posted: 24-Dec-2016 | Tags: 2016 Toyota Wish, 2016 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota

CREDIT CHECK



Toyota Wish 1.8A | \$83,000 | \$9,500 /yr | 28-Sep-2016 | 1,798 cc | 36,000 km | MPV | Available

Borneo Motors Unit (Not PJ) 5 Years Unlimited Mileage Warranty. Personal Usage Car, Not PHV. Pearl White Colour. 1 Careful Owner/Under Utilised/High Part Rebate And Deregistration Value. Viewing At Se...

Posted: 27-Dec-2016 | Tags: 2016 Toyota Wish, 2016 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota

CREDIT CHECK



Toyota Wish 1.8A | \$79,800 | \$9,000 /yr | 24-Oct-2016 | 1,798 cc | 63,456 km | MPV | Available

Cheapest In Market Low Mileage Most Popular Family MPV! Ultra Reliable And Fuel Saving! Agent Unit, High ARF. Single Owner And Well Maintained Unit! Loan And Trade In Packages Available! Come View And...

AL Autocar Pte Ltd

Posted: 07-Jan-2016 | Tags: 2016 Toyota Wish, 2016 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota

PREMIUM AD



Toyota Wish 1.8A Elegance | \$82,800 | \$9,390 /yr | 25-Oct-2016 | 1,798 cc | 49,000 km | MPV | Available

Just Arrived, 1 Owner, Regular Borneo Motor Servicing, 5 Years Warranty From Original Registration Date, Well Maintained And Very Good Condition, High Loan With High Trade In Available. Price Negotiab...

Posted: 23-Dec-2016 | Tags: 2016 Toyota Wish, 2016 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota



Toyota Wish 1.8A | \$81,888 | \$9,240 /yr | 04-Nov-2016 | 1,798 cc | 35,000 km | MPV | Available

Drive With Peace Of Mind As Your Car Will Be Fully Serviced And Warranty Under Borneo Motors Warranty Until Nov 19. Great Hand Me Down Car With Extraordinary Reliability And Superb Fuel Efficiency. Ex...

Audax Auto Pte Ltd

Posted: 09-Jan-2016 | Tags: 2016 Toyota Wish, 2016 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota

PREMIUM AD



Toyota Wish 1.8A Elegance | \$85,000 | \$9,460 /yr | 28-Dec-2016 | 1,798 cc | 29,078 km | MPV | Available

Unbelievable Flexible In House Loan. High Loan Available. Extremely Well Maintained By Previous Owner. Full Agent Service. No Repair Needed. 150 Point Assurance Check Completed. Please Contact Our Sal...

Inchcape Pre-Owned

Posted: 19-Jan-2016 | Tags: 2016 Toyota Wish, 2016 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota

PREMIUM AD

REGISTERED MEMBER

Compare

Save this search criteria, to get email alerts whenever a match is found.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	2197G
Vehicle No.:	SLH2134A
Vehicle to be Exported:	Yes
Intended Deregistration Date:	22 Jan 2019
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8 CVT
Primary Colour:	Beige
Manufacturing Year:	2016
Engine No.:	22R1843132
Chassis No.:	JTDGG20W50J005540
Maximum Power Output:	105.0 kW (140 bhp)
Open Market Value:	\$19,955.00
Original Registration Date:	26 Oct 2016
First Registration Date:	26 Oct 2016
Transfer Count:	0
Actual ARF Paid:	\$19,955.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Oct 2026
PARF Rebate Amount:	\$14,966.00
COE Expiry Date:	25 Oct 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,002.00
COE Rebate Amount:	\$44,222.00
Total Rebate Amount:	\$59,188.00

The information contained herein is correct as at 22 Jan 2019

OK

Vision Autowork Pte.Ltd.

(ROC / GST Reg. No. 201500371E)
 8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
 Singapore 415875
 Tel : 6341 6789 Fax: 6341 6778
 E-mail:visionautowork@gmail.com

DATE : 19.01.19

TO : CHINA MOTOR CLAIMS DEPTS
 VEHICLE NO : SLH2134A
 MODEL : TOYOTA WISH
 DATE OF ACCIDENT : 19.01.19
 TIME OF ACCIDENT : 15:30HRS

JTDGG2OW50J005540.

Xiao Tony

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE <i>Distorted</i>	1	\$ 1,340.00	\$ 1,340.00
2	TAILGATE LAMP <i>new</i>	2	\$ 345.00	\$ 690.00
3	TAILGATE LOGO <i>new</i>	1	\$ 64.00	\$ 64.00
4	TAILGATE MOULDING <i>cracked</i>	1	\$ 239.00	\$ 239.00
5	TAILGATE NUMBER PLATE LAMP <i>new</i>	2	\$ 64.00	\$ 128.00
6	TAILGATE OUTER BUTTOM SWITCH LOCK <i>new</i>	1	\$ 218.00	\$ 218.00
7	TAILGATE TOP LOCK <i>Distorted</i>	1	\$ 359.00	\$ 359.00
8	TAILGATE LOCK CATCH <i>new</i>	1	\$ 35.00	\$ 35.00
9	TAILGATE WEATHER STRIP <i>lit</i>	1	\$ 329.00	\$ 329.00
10	TAILGATE INNER BOARD <i>cracked</i>	1	\$ 398.00	\$ 398.00
11	TAILGATE DAMPER <i>new</i>	2	\$ 196.00	\$ 392.00
12	TAILGATE DETECTOR <i>cracked</i>	1	\$ 489.00	\$ 489.00
13	TAIL GATE DETECTOR WIREHARNNESS <i>new</i>	1	\$ 768.00	\$ 768.00
14	TAILGATE STOPPER <i>new</i>	2	\$ 25.00	\$ 50.00
15	TAILGATE WINDSCREEN MOULDING <i>new</i>	1	\$ 246.00	\$ 246.00
16	TAILLAMP <i>new</i>	2	\$ 397.00	\$ 794.00
17	REAR BUMPER <i>Distorted</i>	1	\$ 1,167.00	\$ 1,167.00
18	REAR BUMPER REFLECTOR <i>new</i>	2	\$ 68.00	\$ 136.00
19	REAR BUMPER SIDE RETAINER (FRONT) <i>new</i>	2	\$ 95.00	\$ 190.00
20	REAR BUMPER SIDE RETAINER (REAR) <i>new</i>	2	\$ 76.00	\$ 152.00
21	REAR BUMPER BRACKET <i>Distorted</i>	2	\$ 105.00	\$ 210.00
22	REVERSE SENSOR <i>Distorted MV</i>	2	\$ 240.00	\$ 480.00
23	REVERSE SENSOR WIRE HARNNESS <i>3 m</i>	1	\$ 795.00	\$ 795.00
24	REVERSE SENSOR CLIP <i>1 m</i>	1	\$ 65.00	\$ 65.00
25	REAR FENDER INNER COWLING <i>new</i>	2	\$ 247.00	\$ 494.00
26	REAR FENDER INNER TRIM <i>cracked</i>	2	\$ 722.00	\$ 1,444.00
27	REAR END PANEL <i>Distorted</i>	1	\$ 530.00	\$ 530.00
28	REAR END PANEL TOP GARNISH <i>Distorted</i>	1	\$ 295.00	\$ 295.00

Handwritten notes and marks on the right side of the table:

- Checkmarks (✓) next to rows 1, 3, 4, 7, 11, 13, 14, 15, 17, 18, 19, 20, 21, 22, 23, 24, 25, 27, 28.
- Plus signs (+) next to rows 2, 5, 6, 8, 9, 10, 12, 16, 26.
- Handwritten numbers: 11220 (next to row 12), 623.70 (next to row 17), 1310 (next to row 26).
- Handwritten text: "200/500" X (next to row 22).

TO : CHINA MOTOR CLAIMS DEPTS
 VEHICLE NO : SLH2134A
 MODEL : TOYOTA WISH
 DATE OF ACCIDENT : 19.01.19
 TIME OF ACCIDENT : 15:30HRS

29	REAR FLOOR PANEL <i>Repr</i>	1	\$ 742.00	\$ 742.00	+
30	REAR FLOOR PANEL TOP BOARD <i>3 pieces</i>	1	\$ 598.00	\$ 598.00	+ 456.60
31	REAR FLOOR PANEL SIDE BOARD <i>new</i>	2	\$ 125.00	\$ 250.00	*
32	REAR FLOOR PANEL TOP BOARD INNER SUPPORT <i>new</i>	1	\$ 360.00	\$ 360.00	✓
33	REAR SPARE TYRE CHAIN BLOCK <i>new</i>	1	\$ 420.00	\$ 420.00	+
34	REAR SEAT BACK REST COVER BOARD <i>new</i>	1	\$ 560.00	\$ 560.00	+
35	REAR EXHAUST BOX <i>2</i>	1	\$ 649.00	\$ 649.00	+
36	REAR EXHAUST GASKET (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	+
37	REAR EXHAUST MOUNTING <i>1</i>	3	\$ 45.00	\$ 135.00	+

7014.50
5268.37

TOTAL PRICE \$ 16,271.00
 LESS 25% \$ 4,067.75
 SUB TOTAL PRICE \$ 12,203.25

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>Best</i>	1	\$ 50.00	\$ 50.00	✓
2	REAR BUMPER CLIPS (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	30.
3	TAILGATE SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00	+
4	TAILGATE OUTER MOULDING CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	30
5	TAILGATE UPPER TRIM CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	+
6	TAILGATE INNER BOARD CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 80.00	→ 30
7	TAILGATE WINDSCREEN SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00	30
8	TAILGATE WINDSCREEN INNER SHIELD <i>new</i>	1	\$ 60.00	\$ 60.00	✓
9	TAILGATE EMBLEM 'VALVE MATIC' (SPECIAL TYPE) <i>new</i>	1	\$ 120.00	\$ 120.00	50.
10	TAILLAMP CLIPS (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	+
11	REAR FENDER INNER TRIM CLIPS (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	✓
12	REAR FENDER INNER COWLING CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	+
13	REAR FENDER INNER UPPER TRIM CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	+
14	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 150.00	\$ 150.00	60
15	REAR END PANEL TOP GARNISH CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	10 390
16	REAR FLOOR PANEL INSULATION SEAL <i>new</i>	1	\$ 350.00	\$ 350.00	+
17	REAR SPARE TYRE <i>new</i>	1	\$ 360.00	\$ 360.00	+

TOTAL \$ 1,720.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 1,800.00	900

TO : CHINA MOTOR CLAIMS DEPTS
 VEHICLE NO : SLH2134A
 MODEL : TOYOTA WISH
 DATE OF ACCIDENT : 19.01.19
 TIME OF ACCIDENT : 15:30HRS

2	TO SPRAY PAINT AFFECTED AREA	\$ 1,600.00	900
3	TUFF COAT	\$ 250.00	60
4	WIRING AND BULB CHECK	\$ 180.00	30
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTRY & ROOF LINING TO FACILITATE REPAIR	\$ 350.00	80
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	30
7	TRANSFER TAILGATE MECHANISM	\$ 80.00	✓
8	CONDUCT WATER LEAKAGE TEST	\$ 180.00	x
9	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	/
10	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 180.00	x
11	REMOVE AND REFIX FUEL TANK TO FACILITATE FENDER REPLACEMENT	\$ 120.00	x
12	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 350.00	x

TOTAL \$ 5,290.00

2220

ESTIMATE REPORT

TOTAL PARTS COST : \$13,923.25
 TOTAL LABOUR COST : \$5,290.00
 TOTAL REPAIR COST : \$19,213.25

Adrian Lj
 H/s 22/01/19
 07 Pags.

total 78783
 H/s: 6.3K

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
 PARTS PRICES ARE SUBJECT TO CHANGES

YOURS FAITHFULLY,

ABBY
 SERVICE ADVISOR
 ABBY
 HP : 9856 4815

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

6.3K

Mei Kwan (LKKAuto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Tuesday, 5 March, 2019 10:12 AM
To: Mei Kwan (LKKAuto)
Cc: Hsiao Tong (LKKAuto); Admin A
Subject: RE: Direct Settlement - Accident Involving SJX1644R (OI : CAI - TBA) AND SLH2134A (TP : LKK REF - CC6/CTI19001564/Apa3) on 19/01/2019
Attachments: insured report.PDF
Categories: HMK

Dear Mei Kwan,

Pls find Insured report.

Regards,
Chong Boon Sen
Claims Executive
Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower
Singapore 079909
Co. Reg. No. 200208384E
DID: 63896171
Fax: 62247175
Email: boonsen.chong@sg.cntaiping.com
Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Mei Kwan (LKKAuto) [mailto:Meikwan@lkkauto.com]
Sent: Monday, March 4, 2019 10:26 AM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Cc: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: RE: Direct Settlement - Accident Involving SJX1644R (OI : CAI - TBA) AND SLH2134A (TP : LKK REF - CC6/CTI19001564/Apa3) on 19/01/2019

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear Sir / Madam,

We refer to the above matter.

Kindly let us have a copy of your insured's GIA report for our necessary action.

Thank you.
Best Regards,



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC6/CTI19001564/Aea3n2	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Date : 08-08-2019	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJX 1644R	Veh. Inspected	SLH 2134A
Policy No.	DMPCSN3077821700	Coverage (\$)	0.00
Claim No.	SNM19D200408C02/4	Excess (\$)	0.00
Assign From		Assign Date	21/01/2019
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA WISH	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JTDGG20W50J005540	Colour	GOLD
Odometer	29892	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	GOODYEAR	6 mm
L/H Front Tyre	195/65 R15	GOODYEAR	6 mm
R/H Rear Tyre	195/65 R15	GOODYEAR	6 mm
L/H Rear Tyre	195/65 R15	GOODYEAR	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	19/01/2019	Inspection Date	21/01/2019
Survey held at	VISION AUTOWORK PTE LTD 8 KAKI BUKIT AVE 4, #08-09 PREMIER @ KAKI BUKIT SINGAPORE 415875		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6258 3561 FAX: 6258 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLH 2134A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	TAILGATE	DENTED	1,340.00	1,340.00
2	TAILGATE LAMP @\$345.00	NOT NECESSARY	690.00	-
1	TAILGATE LOGO	NECESSARY	64.00	64.00
1	TAILGATE MOULDING	CRACKED	239.00	239.00
2	TAILGATE NUMBER PLATE LAMP @\$64.00	NOT NECESSARY	128.00	-
1	TAILGATE OUTER BUTTOM SWITCH LOCK	NOT NECESSARY	218.00	-
1	TAILGATE TOP LOCK	DAMAGED	359.00	359.00
1	TAILGATE LOCK CATCH	NOT NECESSARY	35.00	-
1	TAILGATE WEATHERSTRIP	CUT	329.00	329.00
1	TAILGATE INNER BOARD	CRACKED	398.00	398.00
2	TAILGATE DAMPER @\$196.00	NOT NECESSARY	392.00	-
1	TAILGATE DETECTOR	CRACKED	489.00	112.20
1	TAIL GATE DETECTOR WIREHARNES	NOT NECESSARY	768.00	-
2	TAILGATE STOPPER @\$25.00	NOT NECESSARY	50.00	-
1	TAILGATE WINDSCREEN MOULDING	NECESSARY	246.00	246.00
2	TAILLAMP @\$397.00	NOT NECESSARY	794.00	-
1	REAR BUMPER	DEFORMED	1,167.00	623.70
2	REAR BUMPER REFLECTOR @\$68.00	NOT NECESSARY	136.00	-
2	REAR BUMPER SIDE RETAINER (FRONT) @\$95.00	NOT NECESSARY	190.00	-
2	REAR BUMPER SIDE RETAINER (REAR) @\$76.00	NECESSARY	152.00	152.00
2	REAR BUMPER BRACKET @\$105.00	DENTED	210.00	210.00
2	REVERSE SENSOR @\$240.00	NOT NECESSARY	480.00	-
1	REVERSE SENSOR WIRE HARNES	NOT NECESSARY	795.00	-
1	REVERSE SENSOR CLIP	NOT NECESSARY	65.00	-
2	REAR FENDER INNER COWLING @\$247.00	NOT NECESSARY	494.00	-
2	REAR FENDER INNER TRIM @\$722.00	CRACKED	1,444.00	1,310.00
1	REAR END PANEL	DISTORTED	530.00	530.00
1	REAR END PANEL TOP GARNISH	DEFORMED	295.00	295.00
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	742.00	-
1	REAR FLOOR PANEL TOP BOARD	DEFORMED	598.00	456.60

Report Ref No. CC6/CT119001564/Aea3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR FLOOR PANEL SIDE BOARD @\$125.00	NOT NECESSARY	250.00	-
1	REAR FLOOR PANEL TOP BOARD INNER SUPPORT	CRACKED	360.00	360.00
1	REAR SPARE TYRE CHAIN BLOCK	NOT NECESSARY	420.00	-
1	REAR SEAT BACK REST COVER BOARD	NOT NECESSARY	560.00	-
1	REAR EXHAUST BOX	NOT NECESSARY	649.00	-
1	SET REAR EXHAUST GASKET	NOT NECESSARY	60.00	-
3	REAR EXHAUST MOUNTING @\$45.00	NOT NECESSARY	135.00	-
	LESS 25% DISCOUNT		-4,067.75	-1,756.13
			12,203.25	5,268.37
	<u>SPECIAL NETT ITEMS</u>			
1	REAR NUMBER PLATE (SN)	BENT	50.00	50.00
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	60.00	30.00
1	TAILGATE SEALANT (SN)	NOT NECESSARY	80.00	-
1	SET TAILGATE OUTER MOULDING CLIP (SN)	NECESSARY	50.00	20.00
1	SET TAILGATE UPPER TRIM CLIP (SN)	NOT NECESSARY	50.00	-
1	SET TAILGATE INNER BOARD CLIP (SN)	NECESSARY	60.00	30.00
1	TAILGATE WINDSCREEN SEALANT (SN)	NECESSARY	80.00	30.00
1	TAILGATE WINDSCREEN INNER SHIELD (SN)	NECESSARY	60.00	60.00
1	TAILGATE EMBLEM 'VALVE MATIC' (SPECIAL TYRE) (SN)	NECESSARY	120.00	50.00
1	SET TAILLAMP CLIPS (SN)	NOT NECESSARY	30.00	-
1	SET REAR FENDER INNER TRIM CLIPS (SN)	NECESSARY	50.00	50.00
1	SET REAR FENDER INNER COWLING CLIP (SN)	NOT NECESSARY	60.00	-
1	SET REAR FENDER INNER UPPER TRIM CLIP (SN)	NOT NECESSARY	60.00	-
1	REAR END PANEL INSULATION SEAL (SN)	NECESSARY	150.00	60.00
1	SET REAR END PANEL TOP GARNISH CLIP (SN)	NECESSARY	50.00	10.00
1	REAR FLOOR PANEL INSULATION SEAL (SN)	NOT NECESSARY	350.00	-
1	REAR SPARE TYRE (SN)	NOT NECESSARY	360.00	-
			1,720.00	390.00
	<u>LABOUR</u>			
	TO PANEL BEAT ,REMOVE AND REPLACE PARTS.INCLUSIVE OF THE REPAIR OF REAR FLOOR PANEL.		1,800.00	900.00
	TO SPRAY PAINT AFFECTED AREA.		1,600.00	900.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TUFF COAT.		250.00	60.00
	WIRING AND BULB CHECK.		180.00	30.00
	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR.		350.00	80.00
	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING.		80.00	50.00
	TRANSFER TAILGATE MECHANISM.		80.00	80.00
	CONDUCT WATER LEAKAGE TEST .	NOT NECESSARY	180.00	-
	REMOVE AND REFIX TAILGATE WINDSCREEN.		120.00	120.00
	REMOVE AND REFIX REAR EXHAUST PIPE .	NOT NECESSARY	180.00	-
	RMEOVE AND REFIX FUEL TANK TO FACILITATE FENDER REPLACEMENT .	NOT NECESSARY	120.00	-
	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC.	NOT NECESSARY	350.00	-
			5,290.00	2,220.00
	GRAND TOTAL		19,213.25	7,878.37
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,300.00

Report Ref No. CC6/CT119001564/Aea3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES - This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.