

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

Email : mg3solution@gmail.com

TO	: AIG	DATE	: 18/01/2019
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SGJ6762J		
MODEL	: TOYOTA COROLLA ALTIS 1.6 A		Joy
CHASSIS NO			
<u>ACCIDENT DETAILS</u>		DATE	: 18-Jan-19
		TIME	: 07:07HRS
THIRD PARTY REQUESTOR / CONTACT		:	JACK LI

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	BOOTLID <i>Buckled</i>	1	\$ 847.60	\$ 847.60
2	BOOTLID LOGO	1	\$ 54.20	\$ 54.20
3	BOOTLID '1.6' EMBLEM	1	\$ 58.00	\$ 58.00
4	BOOTLID 'E' EMBLEM	1	\$ 45.50	\$ 45.50
5	BOOTLID 'WT-I' EMBLEM	1	\$ 65.40	\$ 65.40
6	BOOTLID 'COROLLA' EMBLEM <i>re</i>	1	\$ 58.60	\$ 58.60
7	BOOTLID 'ALTIS' EMBLEM <i>re</i>	1	\$ 65.20	\$ 65.20
8	BOOTLID TOP LOCK <i>2nd</i>	1	\$ 124.00	\$ 124.00
9	BOOTLID LOWER CATCH <i>re</i>	1	\$ 87.00	\$ 87.00
10	BOOTLID WEATHER STRIP <i>for</i>	1	\$ 157.00	\$ 157.00
11	REAR BUMPER <i>Rehnd</i>	1	\$ 650.20	\$ 650.20 425.90
12	REAR BUMPER SIDE RETAINER <i>re</i>	2	\$ 62.50	\$ 125.00 64
13	REAR BUMPER BRACKET <i>Rehnd</i>	1	\$ 88.50	\$ 88.50 43.20
14	TAIL LAMP <i>re</i> <i>can't</i>	2	\$ 467.50	\$ 935.00 579
15	TAILLAMP PANEL RH <i>Buckled</i>	1	\$ 581.50	\$ 581.50 381.20
16	TAILLAMP LOWER PANEL RH <i>Rehnd</i>	2	\$ 95.00	\$ 190.00 95
17	REAR END PANEL <i>Rehnd</i>	1	\$ 768.00	\$ 768.00
18	REAR END PANEL TOP GARNISH <i>Rehnd</i>	1	\$ 146.00	\$ 146.00

19	REAR FLOOR PANEL TOP BOARD <i>tom</i>	1	\$ 168.00	\$ 168.00	✓
----	---------------------------------------	---	-----------	-----------	---

414580

3109.35

TOTAL PRICE	\$ 5,214.70
LESS 25%	\$ 1,303.68
SUB TOTAL PRICE	\$ 3,911.03

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>all n</i>	1	\$ 50.00	\$ 50.00	+
2	BOOTLID SEALANT <i>all n</i>	1	\$ 80.00	\$ 80.00	+
3	REAR BUMPER CLIPS <i>n</i>	1	\$ 20.00	\$ 20.00	✓
4	TAILLAMP PANEL SEALANT RH <i>2</i>	1	\$ 80.00	\$ 80.00	+
5	TAILLAMP LOWER PANEL RIVET <i>1 n</i>	1	\$ 25.00	\$ 25.00	+
6	TAILLAMP LOWER PANEL SEALANT RH	1	\$ 80.00	\$ 80.00	+
7	REAR END PANEL INSULATION SEAL <i>n</i>	1	\$ 150.00	\$ 150.00	60.
8	REAR END PANEL TOP GARNISH CLIPS <i>n</i>	6	\$ 5.50	\$ 33.00	10
9	REVERSE SENSOR <i>2nd</i>	1	\$ 220.00	\$ 220.00	200.

290

TOTAL \$ 688.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,400.00	800	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,200.00	800	
3	TUFF COAT	\$ 180.00	60	
4	TO CONDUCT WATER LEAKAGE TEST	\$ 250.00	x	
5	WIRING CHECK	\$ 150.00	30	
6	TRANSFER BOOTLID MECHANISM	\$ 100.00	50	
7	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50	

1790

TOTAL \$3,360.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 4,599.03

Adrian Lj total 389.35
4/3 21/01/19. 4/5: 4.1K
06 Aug.

TOTAL LABOUR COST : \$ 3,360.00

TOTAL REPAIR COST : \$ 7,959.03

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

FAX :

PART BY PART / LUMP SUM :

NO OF DAYS :

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: