

SS. REC. BY:

REF: CS

ASM19001580 / Zhd354

Special Instruction:

Surveyor: Haizal

ASSIGNMENT (Office)

From (Person): Jas Tan

of

ASM (AXA)

Date/Time: 23/01/2019

Estimated Cost:

Bill to:

☒ OD ☐ IF ☐ WS/TP RES / ☐ OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGG 7507P

Insured:

at Workshop m/s

SHL Automobile

Tel:

6271 9129

of

Blk 1005 Blk Meruh Lane 2 # 01-16

Policy No:

Claim No:

S9M01B1B

Sum Insured:

Excess:

NIL

Make of Veh:

(Client's Record)

D.O.A. 21/01/2019CA / REV / REP. / REV 24 HRS ^{lup}Date/Time: 9:18am @ 24/1/19

Person Contacted:

Mr. Sum

H.O.D. Endorsement:

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate
24/1/19	- Haizal say will ammg with wisp SGG 7507P-X
25/1/19	Revert Smart claims preli advise
	Submit extensive total loss report

REF: ASM(AxA)

Fire case (Investigation)

ASSIGNMENT

From: Date: 24/1/2019

Estimated Cost:

OD/ P WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No:

SGG 7507P

at Workshop m/s

SHL Automobile

of Blk 1005, Blk Merah Lane 2 #01-16

Insured:

Policy No.

1A1/GA 105225/1

Claims No.

Sum Insured:

Excess:

NIL

(Client's Record)

Make of Veh:

Mr. Sum @ 6271 9129

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

\$ 66,000

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: SGG 7507P

V. Regn:

2006

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mercedes Benz

C.C.

28 2799

Colour:

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading:

Burnt

T/Radio:

Insured / Std / NI / NA

Eng/No:

11292231997890

C/No:

WDB 2200632A 480740

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 205/45 ZR 18

R: 205/45 ZR 18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Conti

Front

Rear

R/Bal.

6

mm

R/Bal.

5

mm

L/Bal.

7

mm

L/Bal.

5

mm

D.O.A.

D.O.I.

24/1/2019

Survey held at

Blk 1005, Blk Merah Lane 2

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

#01-16

Burnt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

24th Jan 19 Visit workshop for fire investigation - Extent of fire damage.
25th Jan 19 Arrange interview with M.S. Org WY at Tota Payah Hub 24th floor

MR: 66K LTA: 33.7M NV: 32.279

Repair cost not exceed \$32,279

Date/Time, File Pass to?

☐

: Preli. Report

1) 10/3 Typist

☒

: Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

G + P.S. SI

Photos

Others

FIRE REPORT

TOTAL

Report Format:

TL-00

Lump Sum / L.B.I. (\$)

ADD Fee:
 Site Insp (\$
 Interview (\$
 Tech. Invs (\$
 Weekend (\$

LINK (GA)

1/2/19
Soyan

207

\$ 170.00