



Your Ref : S9M01BIB

Date: 18th March 2019

Our Ref : CS/ASM19001580/Ztd3s2

M/s AXA Insurance Pte Ltd
8 Shenton Way #24-01
AXA Tower
Singapore 068811
(The Motor Claims Department)

Attn: Jas Tan

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SGG 7507P
ACCIDENT ON 21/01/2019**

Instruction was received to inspect the vehicle Reg. No. SGG 7507P. The inspection was conducted on 24/01/2019 at the premises of M/s SHL Automobile Resources, Blk 1005 Bukit Merah Lane 2 #01-16 Singapore 159761.

The following vehicle information was recorded:


Registration Number	: SGG 7507P
Make/Model	: Mercedes Benz
Year of Registration	: 2006
Body Colour	: Silver
Chassis Number	: WDB2200632A480740
Engine Capacity	: 2799 cc
Speedometer Reading	: Burnt

The vehicle burnt. (Details see photographs enclosed)


In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **"Total Loss"**.

Market Value	S\$ 66,000.00
Less: LTA Reimbursement Value (RV)	(S\$ 33,721.00)
Nett Liability	<u>S\$ 32,279.00</u>

Vehicle Inspected By:



ROHAIZAL A. RAHIM (HAIZAL)
Technical Investigator



K.K.LAU
MSc(Eng M), B Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),
AM CATARI(CAN), M. MATA(USA), M. MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.