

ASS. REC. BY:

REF:

CS/INC19001583/Bvd3er

Special Instruction:

Surveyor:

Mr Jim

ASSIGNMENT (Office)

From (Person):

Daniel Koh

of

INC

Date/Time:

24/1/19 @ 9:28am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGJ 7118M

Insured:

81P8605A

at Workshop m/s

Torque 5

Tel:

81316318

of

8 kalci Bkt Ave 4 # 01-49 premier

Policy No:

Claim No:

MT-1029083-002

Sum Insured:

Excess:

Make of Veh:

D.O.A.

22/01/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:11am @ 24/1/19

Person Contacted:

Lucas

Vehicle:

IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SGJ 7118M - 004/LPC16013535/Uub3n2

D.O.A.: 19/06/2016

26/1/19

Recd file from Assignment Team.

26/1/19

LS \$4000 confirmed by email (Recd 12, 25.30, 75/1)

REF: INC

## ASSIGNMENT

From: \_\_\_\_\_ Date: **24/01/2014**

Estimated Cost: \_\_\_\_\_

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: **SGJ 7118M**

at Workshop n/s: **Torque 5**

of: **8 kaki Bukit Ave 4 # 01-49 premier**

Insured: \_\_\_\_\_

Policy No.: \_\_\_\_\_

Claims No.: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: **5** days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS **1 up**

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: **SGJ 7118 M** Yr Regn: **19/7/2006**

Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **TOYOTA WISH** C.C. **1.797**

Colour: **GREY** A/C Insured / Std / NI / NA

Sp. Reading: **282901** T/Radio: Insured / Std / NI / NA

Eng/No: **1ZZ261039**

C/No: **2NE 100373088**

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ Inorder / Jammed / Leaked / Burnt or

Brake: ☒ Inorder / Jammed / Leaked / Burnt or

Modi: **Nil** / ☒ Rim / STD A/Rim or

Tyre Size: F: **185/65/15**  
R: **185/65/15**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or **HANKOOK**

Front

Rear

R/Bal. **5** mm R/Bal. **5** mmL/Bal. **5** mm L/Bal. **5** mmD.O.A. **22/1/19** D.O.I. **24/1/19 @ 0254PM**Survey held at **TORQUE 5**Des. of Damages: Frt / ☒ Rear / O/S / **NS** / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 27 FEB 2019

MV 16,000/2

PV 14,810/2

NV 4,190/2

TTCim

31/1/19

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: **5**

1)

☐ : Final ReportResurvey No. of Trip: **1**

Date/Time, File Return to?

Survey Fee: **290**2) **7/1> - typist**Add Fee: ☐ Site Insp (\$)

Transportation

☐ Interview (\$)

Y \$ + RS \$

☐ Tech. Invs (\$)

J. Photos

☐ Weekend (\$)

J. Other

Report Format: **TP**Lump Sum / I.B.I. (\$) **Hook**

TOTAL

**290**

**Nivitha (LKK Auto)**

**From:** Daniel Koh <daniel.koh@income.com.sg>  
**Sent:** Thursday, 24 January 2019 9:28 AM  
**To:** 'assignments@lkkauto.com'  
**Cc:** Toh Choon Hin; Thio Tse Kiat  
**Subject:** FW: TP CASE FARMED OUT TO LKK ON 24/1/2019

Dear Veron / Catherine,

Please assist to survey the vehicles as per Mr Toh's instruction :-

| S/NO | THIRD PARTY | OUR INSURED | WORKSHOP / CONTACT                   | DOA / REF / OFFICER                        | TIMING      |
|------|-------------|-------------|--------------------------------------|--------------------------------------------|-------------|
| 1    | SGJ7118M    | SJP8605A    | TORQUE 5 PTE LTD / Lucas<br>81316318 | 22-1-2019 / MT-1029083-002<br>/ fiona Shen | 10:00-12:00 |
| 2    | GBF6329H    | SIQ5241E    | TORQUE 5 PTE LTD / Lucas<br>81316318 | 23-1-2019 / MT-1029220-001<br>/ Jeff Lin   | 10:00-12:00 |

Please contact workshops.

Please ack.

Thank You

**Daniel Koh**  
Senior Admin Assistant, Motor Insurance  
**T +65 6430 7901**  
[www.income.com.sg](http://www.income.com.sg)



---

#### Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

#### Vehicle Owner Particulars

Owner ID Type: Business  
Owner ID: 2780K

#### Vehicle Details

Vehicle No.: SGJ7118M  
Vehicle to be Exported: Yes  
Intended Deregistration Date: 23 Jan 2019  
Vehicle Make: TOYOTA  
Vehicle Model: WISH 1.8 A  
Primary Colour: Grey  
Manufacturing Year: 2006  
Engine No.: 1ZZ2610393  
Chassis No.: ZNE100313088  
Maximum Power Output: 97.0 kW (130 bhp)  
Open Market Value: \$21,313.00  
Original Registration Date: 19 Jul 2006  
First Registration Date: 19 Jul 2006  
Transfer Count: 1  
Actual ARF Paid: \$23,445.00

#### Intended PARF Rebate Details

PARF Eligibility: Forfeited  
PARF Eligibility Expiry Date: -  
PARF Rebate Amount: \$0.00

#### Intended COE Rebate Details

COE Expiry Date: 30 Jun 2021  
COE Category: E - Open Category  
COE Period(Years): 5  
PQP Paid: \$24,240.00  
COE Rebate Amount: \$11,810.00  
Total Rebate Amount: \$11,810.00

#### Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 23 Jan 2019

OK

Dep 7,450/yr  
621/mth

MV 16,000/2  
PV 11,810/2  
NV 4,190/2

  
31/1/19



Posted: 21-Jan-2019 Tags: 2006 Toyota Wish, 2006 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota



**Toyota Wish 1.8A (COE till 06/2021)** **\$17,700** **\$7,450 /yr** **09-Jun-2006** **1,794 cc** **122,744 km** **MPV** **Available**

Cheapest In The Market, Can't Go Any Lower! Interior/Exterior Extremely Well Taken Care. No Weird Smeil And Etc. Comes With A Really Good Sound System! Engine/Gear Box Healthy Condition. Mileage Only ...

PREMIUM AD

Posted: 27-Dec-2018 Tags: 2006 Toyota Wish, 2006 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota



**Toyota Wish 1.8A (COE till 06/2021)** **\$22,899** **\$9,560 /yr** **16-Jun-2006** **1,794 cc** **133,000 km** **MPV** **Available**

Cheap And Practical 7 Seater Up For Grabs! Economical And Reliable Engine, Low Maintenance Cost. Spend Almost \$7000 In To Replace All Part (With Receipts). Well Take Care By Lady Owner. Buy With Trust...

Ken Garage Pte Ltd

Posted: 20-Jan-2019 Tags: 2006 Toyota Wish, 2006 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota



**Toyota Wish 1.8A (COE till 05/2026)** **\$42,800** **\$5,820 /yr** **18-Jul-2006** **1,794 cc** **70,000 km** **MPV** **Available**

Super Low Mileage Done 70000km Only, Very Well Maintained, View To Appreciate.

Posted: 19-Jan-2019 Tags: 2006 Toyota Wish, 2006 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota



**Toyota Wish 1.8A (COE till 10/2021)** **\$22,500** **\$8,350 /yr** **04-Oct-2006** **1,794 cc** **216,000 km** **MPV** **Available**

Replacements Since Purchase In Dec 2016: 1. New Leather Upholstery 2. New 17" Alloy Rims 3. New 17" Tyres (latest Change May 18) 4. New Windscreen (01/17) 5. Rear Brake Shoes And Front Brake Pads (01/...

CONSIGNMENT

Carro

Posted: 26-Dec-2018 Tags: 2006 Toyota Wish, 2006 toyota wish, Toyota Wish, toyota wish, Toyota, Wish, wish, Used Toyota

Make & Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view **Expired ads**

40 results/page

Home New Cars Used Cars Sell My Car Directory Products Insurance Article Forum Resources

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used WISH, WISH Singapore, used WISH Singapore, used WISH, used vehicles Singapore or even buy used WISH Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow **sgCarMart.com**

About Us Careers Contact Us Sitemap Terms of Service Privacy Policy Personal Data Protection Statement

©2004-2019 sgCarMart. All rights reserved.

Email: [sm@idac.com.sg](mailto:sm@idac.com.sg)  
Tel no: 6555 6888 Fax no: 6454 3279

### Personal Particulars of Owner & Driver (Vehicle A)

Date of Accident: 22 / 01 / 2019 (dd/mm/yy) Time of Accident: 14 : 30 (24-HR-FORMAT)  
Vehicle No.: SG 77118M Vehicle Make & Model: Toyota Wish 1.8  
Exact location of Accident: Bedok North rd twds Bedok North Ave 2  
Policyholder's Name / IC No.: STEVEN KALLIE / 53312780K  
Driver's Name / IC No.: Steven Tay zhi Yuan / 569424766 (As Above) ☐  
Driver's Contact No.: 9387 2476 Company Contact No.: \_\_\_\_\_  
Driver's Address: 470B Fernvale link #25-434 S'pore 792470  
Insurance Company: NTUC Email address (if any): \_\_\_\_\_

#### Relationship between Owner & Driver: (Please CIRCLE one only)

☒ Owner / ☐ Spouse / ☐ Children / ☐ Friend / ☐ Parents / ☐ Sibling / ☐ Relative / ☐ Employee / ☐ Hirer or Others specify: \_\_\_\_\_

#### What do you wish to claim? (Please TICK one only)

☐ Own Insurance / ☒ Other Vehicle (The one you want to claim against) / ☐ Reporting (For Record Purpose)

#### Exact purpose for which the vehicle Was being used at time of accident?

☐ Private use / ☒ Work purpose

Occupation (nature of job) ☐ Indoor / ☒ Outdoor

No. of Passengers (Including Driver): 03

#### Weather condition & Road conditions? (On the day of accident)

☒ Clear & Dry / ☐ Raining & Wet / ☐ After-Rain & Wet / ☐ Drizzling & Wet / Others: \_\_\_\_\_

Was there any video captured by your Car Camera? ☐ Yes / ☒ No

Any Injuries: ☐ Yes / ☒ No (If YES) Injured Person's Name: \_\_\_\_\_

Injuries Sustain: \_\_\_\_\_ Injured Person in Which Vehicle: \_\_\_\_\_

Police Report filed: ☐ Yes / ☒ No (If YES) Which Police Station: \_\_\_\_\_

### The Other Party(s) Details:

1. Driver's Name / IC No.: \_\_\_\_\_ Vehicle No: SGP8605A

Driver's Contact No.: \_\_\_\_\_ Insurance Company (If any): \_\_\_\_\_

2. Driver's Name / IC No.: \_\_\_\_\_ Vehicle No: \_\_\_\_\_

Driver's Contact No.: \_\_\_\_\_ Insurance Company (If any): \_\_\_\_\_

\*Independent Witness (If Any): \_\_\_\_\_ Contact No: \_\_\_\_\_

Preferred Workshop Name: \_\_\_\_\_ Contact No: \_\_\_\_\_

\*If no proper documents are produced, IDAC should not file the report. Information will be discarded after one week.

## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated date and time, I vehicle 'A' was travelling on the stated venue. I was travelling in my lane awaiting to turn right, While waiting, suddenly I felt an impact on my vehicle rear portion. my passenger seated at the back with seat belts on felted too. As I was in the middle of the junction, We did not stop to exchange particulars, Instead after completing the turn, we then stop at the side and exchange. I wish to state that upon impact, my vehicle was stationary.

Grab Passenger 1: Female

Grab Passenger 2: Female

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

X

*[Signature]*

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



**Torque 5 Pte Ltd**  
 No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875  
 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com  
 Co. & GST Reg. No.: 201313221G

## ESTIMATION REPORT

**Vehicle No** : SGJ7118M  
**Make & Model** : TOYOTA, WISH 1.8 A, ZNE100313088  
**Year of Manufacture** : 2006

**Estimation No.** : E19010028  
**DOA** : 23/01/2019

| No                         | Description                      | Qty  | U/P      | Amt                                        |
|----------------------------|----------------------------------|------|----------|--------------------------------------------|
| <b>Section: List Items</b> |                                  |      |          |                                            |
| 1                          | Rear bumper                      | 1.00 | 650.00   | <sup>616.30</sup><br><del>650.00</del> BRV |
| 2                          | Rear bumper retainer long (LH)   | 1.00 | 87.00    | 87.00                                      |
| 3                          | Rear bumper retainer long (RH)   | 1.00 | 87.00    | 87.00                                      |
| 4                          | Rear bumper reflector (LH)       | 1.00 | 99.00    | 99.00                                      |
| 5                          | Rear bumper reflector (RH)       | 1.00 | 99.00    | 99.00                                      |
| 6                          | Rear bumper bracket (LH)         | 1.00 | 70.00    | <del>70.00</del> NNX                       |
| 7                          | Rear bumper bracket (RH)         | 1.00 | 70.00    | <del>70.00</del> NNX                       |
| 8                          | Rear bumper retainer short (LH)  | 1.00 | 112.00   | 112.00                                     |
| 9                          | Rear bumper retainer short (RH)  | 1.00 | 112.00   | 112.00                                     |
| 10                         | Tail lamp (LH)                   | 1.00 | 481.20   | <del>481.20</del> ? NNX                    |
| 11                         | Tail lamp (RH)                   | 1.00 | 481.20   | 481.20 ? BRV                               |
| 12                         | Tail lamp gasket (LH)            | 1.00 | 0.00     | <del>0.00</del> NNX                        |
| 13                         | Tail lamp gasket (RH)            | 1.00 | 0.00     | <del>0.00</del> NNX                        |
| 14                         | Tail lamp inner panel (LH)       | 1.00 | 442.40   | <del>442.40</del> RX                       |
| 15                         | Tail lamp inner panel (RH)       | 1.00 | 442.40   | 442.40                                     |
| 16                         | Tailgate                         | 1.00 | 1,071.00 | ✓ 1,071.00 DDV                             |
| 17                         | Tailgate lock                    | 1.00 | 407.30   | ✓ 407.30 ? DDV                             |
| 18                         | Tailgate lock catch              | 1.00 | 0.00     | <del>0.00</del> NNX                        |
| 19                         | Tailgate lock sensor             | 1.00 | 0.00     | <del>0.00</del> NNX                        |
| 20                         | Tailgate chrome garnish          | 1.00 | 0.00     | <del>0.00</del> NNX                        |
| 21                         | License lamp (LH)                | 1.00 | 442.40   | <del>442.40</del> NNX                      |
| 22                         | License lamp (RH)                | 1.00 | 442.40   | 442.40                                     |
| 23                         | Tailgate emblem - Logo           | 1.00 | 87.60    | 87.60 NECV                                 |
| 24                         | Tailgate inner trim board        | 1.00 | 705.60   | 705.60 ? BRV                               |
| 25                         | Tailgate inner side garnish (LH) | 1.00 | 0.00     | 0.00 NNX                                   |

Continue on next page...



## Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875  
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com  
Co. & GST Reg. No.: 201313221G

### ESTIMATION REPORT

**Vehicle No** : SGJ7118M  
**Make & Model** : TOYOTA, WISH 1.8 A, ZNE100313088  
**Year of Manufacture** : 2006

**Estimation No.** : E19010028  
**DOA** : 23/01/2019

| No | Description                      | Qty  | U/P    | Amt    |        |
|----|----------------------------------|------|--------|--------|--------|
| 26 | Tailgate inner side garnish (RH) | 1.00 | 0.00   | 0.00   | } NNx  |
| 27 | Tailgate centre garnish          | 1.00 | 0.00   | 0.00   |        |
| 28 | Tailgate hinge (LH)              | 1.00 | 98.70  | 98.70  | } NNx  |
| 29 | Tailgate hinge (RH)              | 1.00 | 98.70  | 98.70  |        |
| 30 | Tailgate damper (LH)             | 1.00 | 278.00 | 278.00 |        |
| 31 | Tailgate damper (RH)             | 1.00 | 278.00 | 278.00 |        |
| 32 | Rear windscreen moulding         | 1.00 | 124.70 | 124.70 | NECV   |
| 33 | Tailgate wiper motor             | 1.00 | 567.90 | 567.90 | } NNx  |
| 34 | Tailgate wiper arm               | 1.00 | 121.35 | 121.35 |        |
| 35 | End panel                        | 1.00 | 520.65 | 520.65 | DDV    |
| 36 | End panel top garnish            | 1.00 | 272.50 | 272.50 | DLV    |
| 37 | Rear fender inner trim (LH)      | 1.00 | 22.00  | 22.00  | } ?NNx |
| 38 | Rear fender inner trim (RH)      | 1.00 | 22.00  | 22.00  |        |
| 39 | Rear floor panel top board       | 1.00 | 653.60 | 653.60 | ?NNx   |
| 40 | Rear exhaust mid pipe            | 1.00 | 945.00 | 945.00 | RX     |
| 41 | Rear exhaust heat shield         | 1.00 | 0.00   | 0.00   | NNx    |
| 42 | Rear exhaust muffler             | 1.00 | 861.70 | 861.70 | RX     |

|    |                      |      |       |                  |           |
|----|----------------------|------|-------|------------------|-----------|
| 43 | Rear fender air vent | BR ✓ | 58.00 | Amt              | S\$       |
|    |                      |      |       |                  | 11,254.30 |
|    |                      |      |       | Discount (0.00%) | S\$ 0.00  |
|    |                      |      |       | Subtotal         | S\$       |
|    |                      |      |       |                  | 11,254.30 |

#### Section: Special Nett Items

|    |                            |      |        |              |        |
|----|----------------------------|------|--------|--------------|--------|
| 43 | Reverse sensor set         | 1.00 | 250.00 | 200.00 SHD   | 250.00 |
| 44 | reverse camera             | 1.00 | 500.00 | 500.00 ?NNx  | 500.00 |
| 45 | Rear number plate & casing | 1.00 | 45.00  | 35.00 CUT ✓  | 45.00  |
| 46 | Rear bumper clip set       | 1.00 | 45.00  | 45.00 NECV ✓ | 45.00  |

Continue on next page...



## Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875  
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com  
Co. & GST Reg. No.: 201313221G

### ESTIMATION REPORT

**Vehicle No** : SGJ7118M  
**Make & Model** : TOYOTA, WISH 1.8 A, ZNE100313088  
**Year of Manufacture** : 2006

**Estimation No.** : E19010028  
**DOA** : 23/01/2019

| No | Description                           | Qty  | U/P    | Amt      |       |
|----|---------------------------------------|------|--------|----------|-------|
| 47 | Tailgate inner trim board clip set    | 1.00 | 40.00  | 25 40.00 | NEC ✓ |
| 48 | End panel top garnish clip set        | 1.00 | 30.00  | 20 30.00 | NEC ✓ |
| 49 | Rear fender inner trims clip set (LH) | 1.00 | 45.00  | 45.00    | NNX   |
| 50 | Rear fender inner trims clip set (RH) | 1.00 | 45.00  | 45.00    | NNX   |
| 51 | Rear windscreen tinted                | 1.00 | 200.00 | 200.00   | NNX   |
| 52 | Decal                                 | 1.00 | 30.00  | 30.00    | NEC ✓ |
| 53 | End panel sealant                     | 1.00 | 50.00  | 30 50.00 | NEC ✓ |
| 54 | Rear windscreen sealant               | 1.00 | 50.00  | 50.00    | NEC ✓ |
| 55 | Exhaust mounting set                  | 1.00 | 160.00 | 160.00   | NNX   |

**Amt** S\$ 1,490.00

**Discount (0.00%)** S\$ 0.00

**Subtotal** S\$ 1,490.00

#### Section: Labour Items

|    |                                                  |      |          |               |        |
|----|--------------------------------------------------|------|----------|---------------|--------|
| 56 | To R&R rear bumper reverse sensor                | 1.00 | 60.00    | 60.00         | ✓      |
| 57 | To check wiring & lighting system                | 1.00 | 80.00    | 50.00 80.00   | ✓      |
| 58 | To supply undercoating / putty on parts replaced | 1.00 | 80.00    | 60.00 80.00   | ✓      |
| 59 | To perform anti rust treatment on affected areas | 1.00 | 60.00    | 30.00 60.00   | ✓      |
| 60 | To R&R rear exhaust assy                         | 1.00 | 250.00   | 120.00 250.00 | R      |
| 61 | To R&R rear windscreen                           | 1.00 | 180.00   | 100.00 180.00 | ✓      |
| 62 | To R&R tailgate mechanism                        | 1.00 | 180.00   | 80.00 180.00  | ✓      |
| 63 | To repair, replace and realign damaged areas     | 1.00 | 1,200.00 | 1,200.00      | 600.00 |
| 64 | To spray painting on affected areas              | 1.00 | 1,000.00 | 1,000.00      | 600.00 |
| 65 | To perform water seepage test after repair       | 1.00 | 150.00   | 150.00        | 60.00  |
| 66 | To R&R rear trims, garnish and seats assy        | 1.00 | 160.00   | 160.00        | 60.00  |
| 67 | Sundries                                         | 1.00 | 50.00    | 50.00         | NNX    |

Continue on next page...



## Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875  
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com  
Co. & GST Reg. No.: 201313221G

### ESTIMATION REPORT

Vehicle No : SGJ7118M  
Make & Model : TOYOTA, WISH 1.8 A, ZNE100313088  
Year of Manufacture : 2006

Estimation No. : E19010028  
DOA : 23/01/2019

| No | Description | Qty | U/P | Amt                       |
|----|-------------|-----|-----|---------------------------|
|    |             |     |     | Amt S\$ 3,450.00          |
|    |             |     |     | Discount (0.00%) S\$ 0.00 |
|    |             |     |     | Subtotal S\$ 3,450.00     |

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

? photo  
26/2/19  
TGC in line 24/1/19 1515  
L/s repair  
5+ 5 repair days  
hi

hi  
1/2/19

16, 255.30

|                             |               |
|-----------------------------|---------------|
| List Items Subtotal         | S\$ 11,254.30 |
| Special Nett Items Subtotal | S\$ 1,490.00  |
| Labour Items Subtotal       | S\$ 3,450.00  |
| Total                       | S\$ 16,194.30 |



**Torque 5 Pte Ltd**  
 No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875  
 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com  
 Co. & GST Reg. No.: 201313221G

## ESTIMATION REPORT

Vehicle No : SGJ7118M  
 Make & Model : TOYOTA, WISH 1.8 A, ZNE100313088  
 Year of : 2006  
 Manufacture

Estimation No. : E19010028  
 DOA : 23/01/2019

| No                         | Description                      | Qty  | U/P      | Amt                     |
|----------------------------|----------------------------------|------|----------|-------------------------|
| <u>Section: List Items</u> |                                  |      |          |                         |
| 1                          | Rear bumper                      | 1.00 | 650.00   | 650.00 BRV              |
| 2                          | Rear bumper retainer long (LH)   | 1.00 | 87.00    | 87.00                   |
| 3                          | Rear bumper retainer long (RH)   | 1.00 | 87.00    | 87.00 } NECV            |
| 4                          | Rear bumper reflector (LH)       | 1.00 | 99.00    | 99.00 } BRV             |
| 5                          | Rear bumper reflector (RH)       | 1.00 | 99.00    | 99.00 } BRV             |
| 6                          | Rear bumper bracket (LH)         | 1.00 | 70.00    | <del>70.00</del> } RX   |
| 7                          | Rear bumper bracket (RH)         | 1.00 | 70.00    | 70.00 } DDV             |
| 8                          | Rear bumper retainer short (LH)  | 1.00 | 112.00   | 112.00                  |
| 9                          | Rear bumper retainer short (RH)  | 1.00 | 112.00   | 112.00 } NECV           |
| 10                         | Tail lamp (LH)                   | 1.00 | 481.20   | <del>481.20</del> ? NNX |
| 11                         | Tail lamp (RH)                   | 1.00 | 481.20   | 481.20 ? BRV            |
| 12                         | Tail lamp gasket (LH)            | 1.00 | 0.00     | 0.00                    |
| 13                         | Tail lamp gasket (RH)            | 1.00 | 0.00     | <del>0.00</del> } NNX   |
| 14                         | Tail lamp inner panel (LH)       | 1.00 | 442.40   | 442.40                  |
| 15                         | Tail lamp inner panel (RH)       | 1.00 | 442.40   | 442.40 } RX             |
| 16                         | Tailgate                         | 1.00 | 1,071.00 | 1,071.00 DDV            |
| 17                         | Tailgate lock                    | 1.00 | 407.30   | 407.30 ? BTV            |
| 18                         | Tailgate lock catch              | 1.00 | 0.00     | 0.00                    |
| 19                         | Tailgate lock sensor             | 1.00 | 0.00     | 0.00 } NNX              |
| 20                         | Tailgate chrome garnish          | 1.00 | 0.00     | 0.00                    |
| 21                         | License lamp (LH)                | 1.00 | 442.40   | <del>442.40</del> } NNX |
| 22                         | License lamp (RH)                | 1.00 | 442.40   | 442.40                  |
| 23                         | Tailgate emblem - Logo           | 1.00 | 87.60    | 87.60 NECV              |
| 24                         | Tailgate inner trim board        | 1.00 | 705.60   | <del>705.60</del> ? BTV |
| 25                         | Tailgate inner side garnish (LH) | 1.00 | 0.00     | 0.00 NNX                |

Continue on next page...



**Torque 5 Pte Ltd**  
 No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875  
 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com  
 Co. & GST Reg. No.: 201313221G

## ESTIMATION REPORT

**Vehicle No** : SGJ7118M  
**Make & Model** : TOYOTA, WISH 1.8 A, ZNE100313088  
**Year of Manufacture** : 2006

**Estimation No.** : E19010028  
**DOA** : 23/01/2019

| No | Description                      | Qty  | U/P    | Amt    |       |
|----|----------------------------------|------|--------|--------|-------|
| 26 | Tailgate inner side garnish (RH) | 1.00 | 0.00   | 0.00   | } NNX |
| 27 | Tailgate centre garnish          | 1.00 | 0.00   | 0.00   |       |
| 28 | Tailgate hinge (LH)              | 1.00 | 98.70  | 98.70  | } NNX |
| 29 | Tailgate hinge (RH)              | 1.00 | 98.70  | 98.70  |       |
| 30 | Tailgate damper (LH)             | 1.00 | 278.00 | 278.00 |       |
| 31 | Tailgate damper (RH)             | 1.00 | 278.00 | 278.00 |       |
| 32 | Rear windscreen moulding         | 1.00 | 124.70 | 124.70 | NECV  |
| 33 | Tailgate wiper motor             | 1.00 | 567.90 | 567.90 | } NNX |
| 34 | Tailgate wiper arm               | 1.00 | 121.35 | 121.35 |       |
| 35 | End panel                        | 1.00 | 520.65 | 520.65 | ? DDV |
| 36 | End panel top garnish            | 1.00 | 272.50 | 272.50 | # DLV |
| 37 | Rear fender inner trim (LH)      | 1.00 | 22.00  | 22.00  | NNX   |
| 38 | Rear fender inner trim (RH)      | 1.00 | 22.00  | 22.00  | CUT   |
| 39 | Rear floor panel top board       | 1.00 | 653.60 | 653.60 | ? NNX |
| 40 | Rear exhaust mid pipe            | 1.00 | 945.00 | 945.00 | RX    |
| 41 | Rear exhaust heat shield         | 1.00 | 0.00   | 0.00   | NNX   |
| 42 | Rear exhaust muffler             | 1.00 | 861.70 | 861.70 | RX    |

43 Rear fender air vent BR ✓ 58.00

**Amt** S\$ 11,254.30  
**Discount (0.00%)** S\$ 0.00  
**Subtotal** S\$ 11,254.30

### Section: Special Nett Items

|    |                            |      |        |        |        |
|----|----------------------------|------|--------|--------|--------|
| 43 | Reverse sensor set         | 1.00 | 250.00 | 250.00 |        |
| 44 | reverse camera             | 1.00 | 500.00 | 500.00 | ? NNX  |
| 45 | Rear number plate & casing | 1.00 | 45.00  | 45.00  | CUT ✓  |
| 46 | Rear bumper clip set       | 1.00 | 45.00  | 45.00  | NECV ✓ |

Continue on next page...



**Torque 5 Pte Ltd**  
 No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875  
 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com  
 Co. & GST Reg. No.: 201313221G

## ESTIMATION REPORT

**Vehicle No** : SGJ7118M  
**Make & Model** : TOYOTA, WISH 1.8 A, ZNE100313088  
**Year of Manufacture** : 2006

**Estimation No.** : E19010028  
**DOA** : 23/01/2019

| No | Description                           | Qty  | U/P    | Amt    |       |
|----|---------------------------------------|------|--------|--------|-------|
| 47 | Tailgate inner trim board clip set    | 1.00 | 40.00  | 40.00  | NECV  |
| 48 | End panel top garnish clip set        | 1.00 | 30.00  | 30.00  | NECV  |
| 49 | Rear fender inner trims clip set (LH) | 1.00 | 45.00  | 45.00  | ? NNX |
| 50 | Rear fender inner trims clip set (RH) | 1.00 | 45.00  | 45.00  | NECV  |
| 51 | Rear windscreen tinted                | 1.00 | 200.00 | 200.00 | NNX   |
| 52 | Decal                                 | 1.00 | 30.00  | 30.00  | NEC   |
| 53 | End panel sealant                     | 1.00 | 50.00  | 50.00  | NECV  |
| 54 | Rear windscreen sealant               | 1.00 | 50.00  | 50.00  | NECV  |
| 55 | Exhaust mounting set                  | 1.00 | 160.00 | 160.00 | NNX   |

**Amt** S\$ 1,490.00  
**Discount (0.00%)** S\$ 0.00  
**Subtotal** S\$ 1,490.00

### Section: Labour Items

|    |                                                  |      |          |          |        |
|----|--------------------------------------------------|------|----------|----------|--------|
| 56 | To R&R rear bumper reverse sensor                | 1.00 | 60.00    | 60.00    | ✓      |
| 57 | To check wiring & lighting system                | 1.00 | 80.00    | 80.00    | ✓      |
| 58 | To supply undercoating / putty on parts replaced | 1.00 | 80.00    | 80.00    | ✓      |
| 59 | To perform anti rust treatment on affected areas | 1.00 | 60.00    | 60.00    | ✓      |
| 60 | To R&R rear exhaust assy                         | 1.00 | 250.00   | 250.00   | R      |
| 61 | To R&R rear windscreen                           | 1.00 | 180.00   | 180.00   | ✓      |
| 62 | To R&R tailgate mechanism                        | 1.00 | 180.00   | 180.00   | ✓      |
| 63 | To repair, replace and realign damaged areas     | 1.00 | 1,200.00 | 1,200.00 | 700.00 |
| 64 | To spray painting on affected areas              | 1.00 | 1,000.00 | 1,000.00 | 600.00 |
| 65 | To perform water seepage test after repair       | 1.00 | 150.00   | 150.00   | 60.00  |
| 66 | To R&R rear trims, garnish and seats assy        | 1.00 | 160.00   | 160.00   | 60.00  |
| 67 | Sundries                                         | 1.00 | 50.00    | 50.00    | NNX    |

Continue on next page...



## Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875  
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com  
Co. & GST Reg. No.: 201313221G

### ESTIMATION REPORT

Vehicle No : SGJ7118M  
Make & Model : TOYOTA, WISH 1.8 A, ZNE100313088  
Year of : 2006  
Manufacture

Estimation No. : E19010028  
DOA : 23/01/2019

| No                      | Description | Qty | U/P | Amt                       |
|-------------------------|-------------|-----|-----|---------------------------|
| Parts = 5190 - 25% AAA. |             |     |     | Amt S\$ 3,450.00          |
| = 4117.54               |             |     |     | Discount (0.00%) S\$ 0.00 |
|                         |             |     |     | Subtotal S\$ 3,450.00     |

S/N : 525

Labour = 1920

PTSL = 6562.54 - 20% L/S  
= \$5250.

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

? photo

TTCim Min 24/1/19 1515

L/S repair

5+ 5 repair days

hir

Resurvey 25/1/19 1700

TTCim Min

|                       |              |
|-----------------------|--------------|
| List Items Subtotal   | S\$          |
|                       | 11,254.30    |
| Special Nett Items    | S\$ 1,490.00 |
| Subtotal              |              |
| Labour Items Subtotal | S\$ 3,450.00 |
| Total                 | S\$          |
|                       | 16,194.30    |

## Veron Chen (LKKAUTO)

---

**From:** Veron Chen (LKKAUTO)  
**Sent:** Wednesday, 27 February 2019 10:28 AM  
**To:** 'Torque 5 Assessment'  
**Cc:** claims@torque5.com; sam.chang@torque5.com  
**Subject:** RE: SGJ 7118 M - After Repair Photo And Finalisation.

Dear Lucas,

Noted with thanks.

Kindly send Final invoice and all supporting documents to NTUC INCOME

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Torque 5 Assessment <assessment@torque5.com>  
**Sent:** Tuesday, 26 February 2019 6:15 PM  
**To:** Veron Chen (LKKAUTO) <veronchen@lkkauto.com>  
**Cc:** 'Torque 5 Assessment' <assessment@torque5.com>; claims@torque5.com; sam.chang@torque5.com  
**Subject:** RE: SGJ 7118 M - After Repair Photo And Finalisation.

Dear Veron ,



We hereby confirm the COR \$4000 with 05 days .

Thank you .

*Warmest Regards,*  
**Lucas Chow**  
Assessor | Motor Claims Department

Hotline (65) 6452 4457 | Fax (65) 6452 4584

Mobile (65) 8131 6518



Email [lucas.chow@torque5.com](mailto:lucas.chow@torque5.com)

Address 8 Kaki Bukit Ave 4, #01-49/50/51/52/53/54  
Premier @ KB, Singapore 415875

[www.torque5.com](http://www.torque5.com)



---

**From:** Veron Chen (LKKAuto) [<mailto:veronchen@lkkauto.com>]  
**Sent:** Tuesday, February 26, 2019 5:52 PM  
**To:** Torque 5 Assessment; SUR  
**Cc:** [claims@torque5.com](mailto:claims@torque5.com); [sam.chang@torque5.com](mailto:sam.chang@torque5.com)  
**Subject:** RE: SGJ 7118 M - After Repair Photo And Finalisation.

Dear Lucas,

WITHOUT PREJUDICE

Offer repair limit, Lump Sum \$4000/- @ 5 working days

Please check and confirm.

Best Regards,

Veron Chen | Case Handler



LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email

:sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Torque 5 Assessment <[assessment@torque5.com](mailto:assessment@torque5.com)>

**Sent:** Wednesday, 30 January 2019 2:43 PM

**To:** Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>; Admin-D (LKKAuto) <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>

**Cc:** 'Torque 5 Assessment' <[assessment@torque5.com](mailto:assessment@torque5.com)>; [claims@torque5.com](mailto:claims@torque5.com); [sam.chang@torque5.com](mailto:sam.chang@torque5.com)

**Subject:** SGJ 7118 M - After Repair Photo And Finalisation.

Dear All ,



Please kindly check the attach and confirm the finalise amount.

Thank you.

*Warmest Regards,*

*Lucas Chow*

Assessor | Motor Claims Department

Hotline (65) 6452 4457 | Fax (65) 6452 4584

Mobile (65) 8131 6518

Email [lucas.chow@torque5.com](mailto:lucas.chow@torque5.com)

Address 8 Kaki Bukit Ave 4, #01-49/50/51/52/53/54  
Premier @ KB, Singapore 415875

[www.torque5.com](http://www.torque5.com)



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**DAMAGE ASSESSMENT REPORT**

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19001583/Bvd3e2

73 BRAS BASAH ROAD  
#05-01 NTUC TRADE UNION HOUSESINGAPORE  
189556

Date: 01-03-2019



ATTN : FIONA SHEN

Code: INC

**1. Policy Particulars :- THIRD PARTY CLAIM**

|              |                |                |            |
|--------------|----------------|----------------|------------|
| Insured Veh. | SJP 8605A      | Veh. Inspected | SGJ 7118M  |
| Policy No.   |                | Coverage (\$)  | 0.00       |
| Claim No.    | MT-1029083-002 | Excess (\$)    | 0.00       |
| Assign From  | DANIEL KOH     | Assign Date    | 24/01/2019 |

**2. Vehicle Particulars & Condition**

|              |              |              |            |
|--------------|--------------|--------------|------------|
| Make & Model | TOYOTA WISH  | c.c          | 1797       |
| Engine No.   | HIDDEN       | Year of Reg. | 2006       |
| Chassis No.  | ZNE100313088 | Colour       | GREY       |
| Odometer     | 282901 KM    | Steering     | IN ORDER   |
| Brakes       | IN ORDER     | Modification | SPORTS RIM |
| General      | GOOD         |              |            |

**3. Conditions of Tyres**

|                | Size       | Make    | Balance |
|----------------|------------|---------|---------|
| R/H Front Tyre | 185/65 R15 | HANKOOK | 5 mm    |
| L/H Front Tyre | 185/65 R15 | HANKOOK | 5 mm    |
| R/H Rear Tyre  | 185/65 R15 | HANKOOK | 5 mm    |
| L/H Rear Tyre  | 185/65 R15 | HANKOOK | 5 mm    |

**4. Description of Damages**

|                                                                            |
|----------------------------------------------------------------------------|
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.<br>DAMAGES SEE DETAILS. |
|----------------------------------------------------------------------------|

**5. General Information**

|                |                                                                                              |                     |                         |
|----------------|----------------------------------------------------------------------------------------------|---------------------|-------------------------|
| Accident Date  | 22/01/2019                                                                                   | Inspect Date / Time | 24/01/2019 ( 02:54 PM ) |
| Survey held at | TORQUE 5 PTE LTD<br>8 KAKI BUKIT AVENUE 4<br>#01-50 PREMIER @ KAKI BUKIT<br>SINGAPORE 415875 |                     |                         |

**5a. Remarks**

|                                                                                                                                        |
|----------------------------------------------------------------------------------------------------------------------------------------|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|----------------------------------------------------------------------------------------------------------------------------------------|

**5b. Estimate Days of Repair**

|                                     |                |
|-------------------------------------|----------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 5 Working Days |
|-------------------------------------|----------------|



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGJ 7118M

| Qty | Description of Parts                   | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|----------------------------------------|----------------------|---------------------------|-------------------|
|     | <b><u>REPLACEMENT OF PARTS</u></b>     |                      |                           |                   |
| 1   | REAR BUMPER                            | BROKEN               | 650.00                    | 616.30            |
| 1   | REAR BUMPER RETAINER LONG (LH)         | NECESSARY            | 87.00                     | 87.00             |
| 1   | REAR BUMPER RETAINER LONG (RH)         | NECESSARY            | 87.00                     | 87.00             |
| 1   | REAR BUMPER REFLECTOR (LH)             | BROKEN               | 99.00                     | 99.00             |
| 1   | REAR BUMPER REFLECTOR (RH)             | BROKEN               | 99.00                     | 99.00             |
| 1   | REAR BUMPER BRACKET (LH)               | NOT NECESSARY        | 70.00                     | -                 |
| 1   | REAR BUMPER BRACKET (RH)               | NOT NECESSARY        | 70.00                     | -                 |
| 1   | REAR BUMPER RETAINER SHORT (LH)        | NECESSARY            | 112.00                    | 112.00            |
| 1   | REAR BUMPER RETAINER SHORT (RH)        | NECESSARY            | 112.00                    | 112.00            |
| 1   | TAIL LAMP (LH)                         | NOT NECESSARY        | 481.20                    | -                 |
| 1   | TAIL LAMP (RH)                         | BROKEN               | 481.20                    | 481.20            |
| 1   | TAIL LAMP GASKET (LH) (NPA)            | NOT NECESSARY        | -                         | -                 |
| 1   | TAIL LAMP GASKET (RH) (NPA)            | NOT NECESSARY        | -                         | -                 |
| 1   | TAIL LAMP INNER PANEL (LH)             | TO REPAIR SEE LABOUR | 442.40                    | -                 |
| 1   | TAIL LAMP INNER PANEL (RH)             | TO REPAIR SEE LABOUR | 442.40                    | -                 |
| 1   | TAILGATE                               | DENTED               | 1,071.00                  | 1,071.00          |
| 1   | TAILGATE LOCK                          | DENTED               | 407.30                    | 407.30            |
| 1   | TAILGATE LOCK CATCH (NPA)              | NOT NECESSARY        | -                         | -                 |
| 1   | TAILGATE LOCK SENSOR (NPA)             | NOT NECESSARY        | -                         | -                 |
| 1   | TAILGATE CHROME GARNISH (NPA)          | NOT NECESSARY        | -                         | -                 |
| 1   | LICENSE LAMP (LH)                      | NOT NECESSARY        | 442.40                    | -                 |
| 1   | LICENSE LAMP (RH)                      | NOT NECESSARY        | 442.40                    | -                 |
| 1   | TAILGATE EMBLEM - LOGO                 | NECESSARY            | 87.60                     | 87.60             |
| 1   | TAILGATE INNER TRIM BOARD              | BROKEN               | 705.60                    | 705.60            |
| 1   | TAILGATE INNER SIDE GARNISH (LH) (NPA) | NOT NECESSARY        | -                         | -                 |
| 1   | TAILGATE INNER SIDE GARNISH (RH) (NPA) | NOT NECESSARY        | -                         | -                 |
| 1   | TAILGATE CENTRE GARNISH (NPA)          | NOT NECESSARY        | -                         | -                 |
| 1   | TAILGATE HINGE (LH)                    | NOT NECESSARY        | 98.70                     | -                 |
| 1   | TAILGATE HINGE (RH)                    | NOT NECESSARY        | 98.70                     | -                 |
| 1   | TAILGATE DAMPER (LH)                   | NOT NECESSARY        | 278.00                    | -                 |
| 1   | TAILGATE DAMPER (RH)                   | NOT NECESSARY        | 278.00                    | -                 |
| 1   | REAR WINDSCREEN MOULDING               | NECESSARY            | 124.70                    | 124.70            |

Report Ref No. CS/INC19001583/Bvd3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

| Qty | Description of Parts                              | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|---------------------------------------------------|----------------------|---------------------------|-------------------|
| 1   | TAILGATE WIPER MOTOR                              | NOT NECESSARY        | 567.90                    | -                 |
| 1   | TAILGATE WIPER ARM                                | NOT NECESSARY        | 121.35                    | -                 |
| 1   | END PANEL                                         | DENTED               | 520.65                    | 520.65            |
| 1   | END PANEL TOP GARNISH                             | DISLODGE             | 272.50                    | 272.50            |
| 1   | REAR FENDER INNER TRIM (LH)                       | NOT NECESSARY        | 22.00                     | -                 |
| 1   | REAR FENDER INNER TRIM (RH)                       | NOT NECESSARY        | 22.00                     | -                 |
| 1   | REAR FLOOR PANEL TOP BOARD                        | NOT NECESSARY        | 653.60                    | -                 |
| 1   | REAR EXHAUST MID PIPE                             | TO REPAIR SEE LABOUR | 945.00                    | -                 |
| 1   | REAR EXHAUST HEAT SHIELD (NPA)                    | NOT NECESSARY        | -                         | -                 |
| 1   | REAR EXHAUST MUFFLER                              | TO REPAIR SEE LABOUR | 861.70                    | -                 |
| 1   | REAR FENDER AIR VENT                              | BROKEN               | 58.00                     | 58.00             |
|     | LESS 25% DISCOUNT                                 |                      | -                         | -1,235.21         |
|     |                                                   |                      | 11,312.30                 | 3,705.64          |
|     | <b><u>SPECIAL NETT ITEMS</u></b>                  |                      |                           |                   |
| 1   | SET REVERSE SENSOR (SN)                           | SHORTED              | 250.00                    | 200.00            |
| 1   | REVERSE CAMERA (SN)                               | NOT NECESSARY        | 500.00                    | -                 |
| 1   | REAR NUMBER PLATE & CASING (SN)                   | CUT                  | 45.00                     | 35.00             |
| 1   | SET REAR BUMPER CLIP (SN)                         | NECESSARY            | 45.00                     | 30.00             |
| 1   | SET TAILGATE INNER TRIM BOARD CLIP (SN)           | NECESSARY            | 40.00                     | 25.00             |
| 1   | SET END PANEL TOP GARNISH CLIP (SN)               | NECESSARY            | 30.00                     | 20.00             |
| 1   | SET REAR FENDER INNER TRIMS CLIP (LH) (SN)        | NOT NECESSARY        | 45.00                     | -                 |
| 1   | SET REAR FENDER INNER TRIMS CLIP (RH) (SN)        | NOT NECESSARY        | 45.00                     | -                 |
| 1   | REAR WINDSCREEN TINTED (SN)                       | NOT NECESSARY        | 200.00                    | -                 |
| 1   | DECAL (SN)                                        | NOT NECESSARY        | 30.00                     | -                 |
| 1   | END PANEL SEALANT (SN)                            | NECESSARY            | 50.00                     | 30.00             |
| 1   | REAR WINDSCREEN SEALANT (SN)                      | NECESSARY            | 50.00                     | 50.00             |
| 1   | SET EXHAUST MOUNTING (SN)                         | NOT NECESSARY        | 160.00                    | -                 |
| 1   | SUNDRIES (SN)                                     | NOT NECESSARY        | 50.00                     | -                 |
|     |                                                   |                      | 1,540.00                  | 390.00            |
|     | <b><u>LABOUR</u></b>                              |                      |                           |                   |
|     | TO R&R REAR BUMPER REVERSE SENSOR.                |                      | 60.00                     | 60.00             |
|     | TO CHECK WIRING & LIGHTING SYSTEM.                |                      | 80.00                     | 50.00             |
|     | TO SUPPLY UNDERCOATING / PUTTY ON PARTS REPLACED. |                      | 80.00                     | 60.00             |

Report Ref No. CS/INC19001583/Bvd3e2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

| Qty                                                                                     | Description of Parts                                                                                                                                                             | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|---------------------------|-------------------|
|                                                                                         | TO PERFORM ANTI RUST TREATMENT ON AFFECTED AREAS.                                                                                                                                |           | 60.00                     | 30.00             |
|                                                                                         | TO R&R REAR EXHAUST ASSY.                                                                                                                                                        |           | 250.00                    | 120.00            |
|                                                                                         | TO R&R REAR WINDSCREEN.                                                                                                                                                          |           | 180.00                    | 100.00            |
|                                                                                         | TO R&R TAILGATE MECHANISM.                                                                                                                                                       |           | 180.00                    | 80.00             |
|                                                                                         | TO REPAIR, REPLACE AND REALIGN DAMAGED AREAS. INCLUSIVE OF THE REPAIR OF TAIL LAMP INNER PANEL (LH), TAIL LAMP INNER PANEL (RH), REAR EXHAUST MID PIPE AND REAR EXHAUST MUFFLER. |           | 1,200.00                  | 600.00            |
|                                                                                         | TO SPRAY PAINTING ON AFFECTED AREAS.                                                                                                                                             |           | 1,000.00                  | 600.00            |
|                                                                                         | TO PERFORM WATER SEEPAGE TEST AFTER REPAIR.                                                                                                                                      |           | 150.00                    | 60.00             |
|                                                                                         | TO R&R REAR TRIMS, GARNISH AND SEATS ASSY.                                                                                                                                       |           | 160.00                    | 60.00             |
|                                                                                         |                                                                                                                                                                                  |           | 3,400.00                  | 1,820.00          |
| <b>GRAND TOTAL</b>                                                                      |                                                                                                                                                                                  |           | <b>16,252.30</b>          | <b>5,915.64</b>   |
| <b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b> |                                                                                                                                                                                  |           |                           | <b>4,000.00</b>   |

Report Ref No. CS/INC19001583/Bvd3e2

**LIM TEOW GUAN**

Automotive Assessor

**HO LEONG CHUAN**

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.