

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 6890S


DATE 23/1/2019 15:16

MAKE :

MODEL : HYUNDAI i40

| Qty | Parts Description/ Labour | Type | Unit Price | Amount |
|-----|--|------|------------|--------------------------|
| | Rear Bumper | | | \$ 553.00 |
| | Rear Bumper Reinforcement ? | | | \$ 428.40 |
| | Rear Bumper Reinforcement Bracket (LH/RH)? | | \$ 80.30 | \$ 160.60 |
| | Rear Bumper Clip 10 pcs | | | \$ 22.00 |
| | Rear Bumper Bracket ? | | \$ 35.60 | \$ 71.20 |
| | Rear Bumper Sponge ? | | | \$ 103.50 |
| | Rear Bumper Under Cover | | | \$ 228.00 |
| | Rear Bumper Reflector Lamp (RH) | | | \$ 30.60 |
| | <i>Rear Bumper lower guard x repair</i> | | | |
| | SUB TOTAL | | | \$ 1,597.30 |
| | LESS 20% | | | \$ 319.46 |
| | DISCOUNTED TOTAL | | | \$ 1,277.84 |
| | | | | |
| | Rear Bumper Reverse Sensor X | | | \$ 135.70 |
| | | | | \$ 135.70 |
| | Labour Charge | | | |
| | Panel Beating | | | \$ 400.00 |
| | Spray Painting Charge | | | \$ 300.00 400 |
| | Wiring Charge | | | \$ 30.00 X |
| | Remove/Refix Reverse Sensor | | | \$ 80.00 X |
| | TOTAL LABOUR | | | \$ 810.00 |
| | ESTIMATE TOTAL | | | \$ 2,223.54 |

Kalvi/10/11/19
23/1/19 1600h
20/1/19
4/1/19
After Repair pte



This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.