

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

24-Jan-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHD 1169 A

1 pc	Rear n/s door ✓	\$	791.00
2 pcs	Rear n/s door hinges @ \$34.00 <i>1 pc X repair (lower) 1 pc ✓ (upper)</i>	\$	68.00
		\$	859.00
	Less 10%	\$	85.90
		\$	773.10
S/NETT			
1 set	n/s door stickers ✓	\$	100.00
1 pc	Rear n/s fender sticker X	\$	60.00
	Sundry	\$	50.00 20
	To dismantle / refit inner components of the rear n/s door onto new shell door	\$	150.00 50
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the rear n/s fender, etc.	\$	500.00 200
	To putty and spray painting on rear n/s door, rear n/s fender X	\$	400.00 180
	To apply rustproofing on the repaired and replaced panels.	\$	80.00 30
		\$	2,113.10

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)
THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.

Ka Wei 10/1/19
24/1/19 1535h
2 Reps
4/5
After Repair photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: