

REPAIR ESTIMATE*

VEHICLE NO : SHB 6378R

DATE 23/1/2019

MAKE :

MODEL : MERCEDES BENZ

EQ-45

IS

LKK - Kalvin

| Qty | Parts Description/ Labour | Type | Unit Price | Amount |
|-----|---|------|------------|--------------------|
| | Rear Bumper | | | \$ 1,510.00 |
| | Rear Bumper Reinforcement ? | | | \$ 1,150.00 |
| | Rear Bumper Bracket Lower (LH/RH) ? | | \$ 135.00 | \$ 270.00 |
| | Rear Bumper Bracket Top (LH/RH) ? | | \$ 125.00 | \$ 250.00 |
| | Rear Bumper Retainer Mounting (LH/RH) ? | | \$ 115.00 | \$ 230.00 |
| | Rear Bumper Lower Cover x rep | | | \$ 325.00 |
| | SUB TOTAL | | | \$ 3,735.00 |
| | LESS 20% | | | \$ 747.00 |
| | DISCOUNTED TOTAL | | | \$ 2,988.00 |
| | Rear Bumper Sensor | | | \$ 388.00 |
| | Labour Charge | | | |
| | Panel Beating | | | \$ 400.00 |
| | Spray Painting Charge | | | \$ 300.00 |
| | Wiring Charge | | | \$ 30.00 |
| | Remove/Refix Reverse Sensor | | | \$ 120.00 |
| | TOTAL LABOUR | | | \$ 850.00 |
| | ESTIMATE TOTAL | | | \$ 4,226.00 |

Nett

Labour Charge

Panel Beating

Spray Painting Charge

Wiring Charge

Remove/Refix Reverse Sensor

TOTAL LABOUR**ESTIMATE TOTAL**

Kalvin

23/1/19 1010h

2 Rep.

Uy

Ashe Rppp U

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display, maintain & parts during resurvey
- Parts price pre-survey information
- Third party survey is on a "no surprise" basis
- No legal liability for damage
- Supplemental charges are subject to change

Acknowledged by

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.