

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 464D**AAD1901-227***Not Noted**Resony B4paint*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD 464D

VF1ABL15AUC283247

RENAULT

LATITUDE

23.1.2019

III

7/8/2017

PART**LIST**

1	DOOR PANEL REAR LH	\$	<i>B</i> 2,844.66 ✓
1	DOOR GUIDE REAR LH	\$	<i>Pa</i> 176.82
1	DOOR HINGE UPPER LH	\$	<i>n</i> 274.50
1	DOOR HINGE LOWER LH	\$	<i>n</i> 300.55
1	DOOR CHECK REAR LH	\$	<i>n</i> 203.06
1	DOOR LOCK REAR LH	\$	<i>n</i> 908.75
1	DOOR HANDLE OUTER REAR LH	\$	<i>Sn</i> 126.49
1	DOOR HANDLE CAP REAR LH	\$	<i>Sn</i> 35.52
1	DOOR HANDLE SEAL REAR LH	\$	<i>Sn</i> 7.89
1	DOOR HANDLE COVER REAR LH	\$	<i>Sn</i> 13.22
1	DOOR HANDLE MODULE REAR LH	\$	<i>Sn</i> 133.60
1	DOOR REGULATOR REAR LH	\$	1,135.10 ?
1	DOOR REGULATOR MOTOR REAR LH	\$	893.75 ?
1	DOOR REGULATOR NUT REAR LH	\$	<i>Sn</i> 12.43
1	DOOR REGULATOR MOTOR SCREW REAR L70Y	\$	<i>Sn</i> 6.31
1	DOOR FINISHER REAR LH	\$	<i>Pa</i> 423.10
1	DOOR MOULDING REAR LH	\$	<i>Pa</i> 176.82
1	DOOR MOULDING CLIP L70Y	\$	<i>nn</i> 5.92
1	DOOR MOULDING SCREW L70Y	\$	<i>nn</i> 6.91
1	DOOR CASING REAR LH	\$	<i>Pa</i> 1,509.06
1	DOOR WATER SHIELD REAR LH	\$	<i>Sn</i> 30.39
1	DOOR CASING CLIP	\$	<i>nn</i> 12.63
1	DOOR CASING LIGHT L70Y	\$	<i>Sn</i> 48.74
1	DOOR FINISHER INNER REAR LH	\$	<i>Pa</i> 323.44
1	DOOR FINISHER BRACKET INNER REAR LH	\$	<i>n</i> 46.97
1	DOOR FINISHER BRACKET INNER REAR LH	\$	<i>n</i> 20.33
1	DOOR FINISHER BRACKET INNER REAR LH	\$	<i>n</i> 20.33
1	DOOR FINISHER BRACKET INNER REAR LH	\$	<i>n</i> 20.33
1	DOOR GRAB HANDLE REAR LH	\$	<i>Sn</i> 210.96
1	DOOR BLIND REAR LH	\$	<i>Sn</i> 741.80
1	DOOR WHEATHESTRIIP REAR LH	\$	<i>Sn</i> 410.66

Trans-cab Auto Services Pte Ltd**AAD1901-227**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 464D

1	DOOR SEAL REAR LH	\$	162.02	}	X
1	DOOR GLASS RUNNER SEAL REAR LH	\$	229.31		
1	DOOR WAIST SEAL OUTER REAR LH	\$	334.69		
1	DOOR WAIST SEAL INNER REAR LH	\$	115.64		
1	FENDER PANEL REAR LH	\$	3,299.13		
1	FENDER PANEL INNER TRIM REAR	\$	671.45		
1	WHEELARCH REAR LH	\$	543.47		
1	BUMPER COVER REAR	\$	1,108.46		
1	BUMPER LOWER REAR	\$	768.84		
1	BUMPER BRACKET CTR REAR	\$	113.47		
1	BUMPER RETAINER LH REAR	\$	44.99		
1	BUMPER BEAM REAR	\$	777.52		
1	BUMPER BEAM BRACKET LH REAR	\$	225.95		
1	DOOR MIRROR ASSY LH	\$	1,483.40		
1	TAILLAMP LH	\$	552.55		
1	ROCKER PANEL INNER GARNISH LH	\$	466.51		
1	ROCKER PANEL INNER LH	\$	1,024.79		
1	ROCKER PANEL CENTER LH	\$	990.25		

\$	23,993.48
10% \$	2,399.35
\$	21,594.14

Special Nett

1	REAR DOOR STICKER '6555 3333'	\$	80.00	}	X
1	DOOR CHECK BOLT	\$	22.69		
1	DOOR GUIDE SCREW	\$	10.85		
1	DOOR HINGE BOLT	\$	10.85		
1	DOOR HINGE NUT RH	\$	14.60		
1	DOOR CHECK BOLT	\$	22.69		
1	DOOR CHECK NUT	\$	3.75		
1	DOOR LOCK SCREW L70Y	\$	6.12		
1	DOOR CATCH SCREW L70Y	\$	10.06		

TOTAL	\$	181.63
--------------	----	---------------

TOTAL PARTS	\$	21,775.77
--------------------	----	------------------

Trans-cab Auto Services Pte Ltd

AAD1901-227

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 464D

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	500/ 3,000.00
To apply paint protection system (PPS) maintain and enhancement	\$	380.00 X
Putty and spray painting of the affected portion.	\$	3,000.00 60/
To rust-proofing of the affected areas.	\$	170.00 30/
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00 60/
To check steering geometry and computer wheel alignment	\$	220.00 X
To transfer of tire, rim and on wheel balancing.	\$	170.00 X
To Check Electrical Lighting Concerned.	\$	170.00 20/
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	170.00 X
To Transfer Of Door Fittings, Attachments And Perform Water Seepage Test.	\$	170.00 60/

TOTAL \$ 7,830.00**Over All Total \$ 29,605.77**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

PART-BY-PART (REPAIR DAY)~~15 DAYS~~

3 days