

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
 BEDOK NORTH AVE 4,
 #01-2008/10/12 SINGAPORE 489977
 TEL : 6441 5655 FAX : 6441 5355/6243 8121
 R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : SXXX0426D
 PATAMA LOVAJANA
 BLK 579 PASIR RIS STREET 53
 #11-79
 SINGAPORE 510579
 TEL : FAX :
 PH : 96613772
 ATTN :

ESTIMATE BILL

Number : EB00005069
Date : 24/01/2019
Case No : AD00010207
Vehicle No : SJM7697G
Chassis: NZT2603034217
Year of Mfr 2008
Policy No 5055198005-06
Model : TOYOTA ALLION A15
 1.5 (A)

Term:

Sn	DESCRIPTION	QTY	U_PRICE	DISC	AMOUNT
1	FRONT DOOR RH	1.0	896.90	25	672.68
	List Price - Parts Sub Total				672.68
2	WING MIRROR RH - REPAIR	1.0			
3	FRONT DOOR HANDLE RH - REPAIR	1.0			
4	ROCKER PANEL RH - REPAIR	1.0			
	Special Nett Price - Parts Sub Total				0.00
	Parts Total				672.68
5	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	500.00	0	500.00
6	SPRAY PAINT ON THE AFFECTED AREAS	1.0	500.00	0	500.00
7	ANTI-RUST COATING	1.0	100.00	0	100.00
	Labour 1 Sub Total				1,100.00
SINGAPORE DOLLARS : ONE THOUSAND EIGHT HUNDRED NINETY-SIX AND CENTS SEVENTY-SEVEN ONLY			Less Excess		0.00
			SUBTOTAL		1,772.68
			GST 7.00%		124.09
			TOTAL		1,896.77

Date of accident : 18/01/2019 03:30 PM. Place : CARPARK OF BLK147 POTONG PASIR AVE 1

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

 CUSTOMER SIGNATURE

 AUTHORISED SIGNATURE