

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0080/2019/GW
Date : 17-Jan-19

Vehicle NOT in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Peter Benedict lim sin Pang
Address : 1 RHU Cross
#16-13
Singapore 437431
Telephone : Hp : +65 96655293
Type of Claim : Own Damage Claims
Policy No. :
Vehicle No : **SBT 1323 H**
Model Code : Audi A4 Sedan 1.4 TFSI
Model / Year : Nov-17
Engine No : CVN 045502
Chassis No : WAUZZZF4BJA025197
Mileage : -
Date In :
Liability : -
Excess Cost : -
Estimated By : Allan Wu
Accident Date : 15-Jan-19
Place of Accident : 29 Tuas Avenue Car park

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SBT 1323 H

S/N	Nature of Jobs	Estimated Charges
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓
2	To dismantle and renew front bumper, lhs front fender and lhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$ 2,100.00 1000
3	To respray front bumper and lhs front fender.	\$ 1,500.00 1100
4	To carry out diagnostic check.	S/N \$ 192.00 ✓
TOTAL LABOUR CHARGES		: \$ <u>4,152.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SBT 1323 H

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>Rehanded</i>	\$ 1,946.00	✓
2	FRONT BUMPER FIXING PARTS	\$ 258.00	+
3	FRONT BUMPER SECURING STRIP	\$ 32.00	+
4	FRONT BUMPER AIR GUIDE -LH	\$ 56.00	+
5	FRONT BUMPER AIR GUIDE GRILLE -LH	\$ 333.00	+
6	FRONT BUMPER GUIDE SECTION-LH <i>Hel new</i>	\$ 33.00	+
7	FRONT FENDER-LH <i>Dented</i>	\$ 700.00	✓
8	FRONT FENDER ATTACHMENT PARTS-LH	\$ 48.00	?
9	FRONT FENDER CLOSING LEMENT-LH <i>new</i>	\$ 45.00	+
11	FRONT FENDER BRACKET-LH	\$ 32.00	?
12	FRONT FENDER BRACKET DEFORMATIONPN ELEMENT-LH <i>new</i>	\$ 45.00	✓
13	FRONT FENDER BRAC-LH	\$ 107.00	?
14	FRONT WHEEL HOUSING LINER-LH <i>new</i>	\$ 223.00	+
15	FRONT WHEEL HOUSING LINER ATACHMENT PARTS-LH	\$ 82.00	+
16	FRONT WHEEL SPOILER-LH <i>new</i>	\$ 66.00	+
17	FRONT FENDER LEDGE-LH	\$ 32.00	✓
18	FRONT STONE CHIP GUARD-LH	\$ 46.00	✓
19	FRONT FENDER COVER-LH	\$ 28.00	✓
20	FRONT FENDER TOP COVER-LH	\$ 21.00	✓
SUB SPARE PARTS		\$ 4,133.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SBT 1323 H

		<u>Damage Parts & Prices</u>	
<u>S/N</u>	<u>Parts Description</u>	<u>S/NETT</u>	<u>REMARKS</u>
21	LED HEADLIGHT-LH <i>lit</i>	\$ 7,087.00	✓
22	LIFT CYLINDER -LH <i>not in</i>	\$ 192.00	x
23	SUNDRIES ?	\$ 500.00	?
TOTAL SPARE PARTS		: \$ 11,912.00	
TOTAL LABOUR CHARGES		: \$ 4,152.00	
GRAND TOTAL		: \$ 16,064.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian L
Surveyed Date : 24/01/19
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, O.K. Day 2

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant