

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0100/2019/KN
Date : 10-Jan-19

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Lim Yan An
Address : 38 Chuan View
Singapore 554599
Telephone : HP +65 91739923
Type of Claim : Own Damage Claims
Policy No. : 2100229161-08
Vehicle No : **SGG 8118 Y**
Model Code : Audi A5 TFSI QU 8T306
Model / Year : 16/9/2010
Engine No : CDN 139926
Chassis No : WAUZZZ8T7BA011667
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 12-Jan-19
Place of Accident : Junct of Bayfront Ave & Central BLVD

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SGG 8118 Y

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00	✓
2	To dismantle and renew front bumper and LHS headlight. Re-organise crash management components. Reinstall all parts removed.	\$ 1,400.00 500	
3	To respray front bumper	\$ 900.00 550	
5	To carry out diagnostic check.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ <u>2,972.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SGG 8118 Y**

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER <i>Rehanded</i>	\$ 1,907.00	✓
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$ 234.00	✗
3	FRONT BUMPER SIDE REINFORCEMENT ?	\$ 802.00	?
4	FRONT BUMPER SUPPORT-LH ?	\$ 26.00	?
5	FRONT BUMPER BRACKET-LH ?	\$ 207.00	?
7	FRONT BUMPER GUIDE PIECE <i>new</i>	\$ 40.00	✗
8	FRONT BUMPER SECURING STRIP - LHS	\$ 32.00	✗
9	FRONT BUMPER SECURING STRIP - RHS <i>new</i>	\$ 32.00	✗
10	FRONT BUMPER COVER <i>Cracked</i>	\$ 116.00	✓
11	FRONT BUMPER CLOSING ELEMENT <i>new</i>	\$ 216.00	✗
12	FRONT BUMPER TRIM CHROME <i>new</i>	\$ 527.00	✗
13	FRONT BUMPER FOAM FILLER PIECE ?	\$ 116.00	?
14	FRONT BUMER AIR GUIDE GRILLE - LH <i>new</i>	\$ 134.00	✗
15	FOG LAMP TRIM - LH <i>new</i>	\$ 64.00	✗
16	FRONT BUMPER COVER ?	2 \$ 89.00	?
17	RADIATOR GRILLE <i>Cracked</i>	\$ 1,851.00	✓
18	RADIATOR GRILLE CHROME TRIM <i>Cracked</i>	\$ 113.00	✓
19	FRONT PARKING SENSOR <i>Not new</i>	2 \$ 419.00	✗
20	FRONT PARKING SENSOR SEAL RING <i>Not new</i>	4 \$ 5.00	✗
SUB-TOTAL SPARE PARTS		\$ 6,930.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SGG 8118 Y**

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	Remark
21	WARNING SIGN FOR ENGINE COVER <i>Free</i>	\$ 13.00	X
22	AIR CONDITIONER STICKER	\$ 18.00	X
23	FRONT CORNERING HEADLIGHT-LH ?	\$ 2,467.00	?
24	FRONT MAIN BEM HEADLIGHT MOUNTING-LH ?	\$ 114.00	?
25	FRONT MAIN BEAM HEADLIGHT BRACKET-LH ?	\$ 73.00	?
26	HEADLIGHT WIPER WASHER CYLINDER <i>when</i>	\$ 251.00	X
27	FRONT NUMBER PLATE <i>Best</i>	S/N 25	✓
28	SUNDRIES ?	500	?
TOTAL SPARE PARTS		\$ 10,391.00	
TOTAL LABOUR CHARGES		\$ 2,972.00	
GRAND TOTAL		\$ 13,363.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

: Adrian Lj
: 24/01/19
:
:
:
:
: Not Authorised, 03 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant