

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

## Telefax

|                   |   |                    |
|-------------------|---|--------------------|
| <b>Estimate</b>   | : | Accident Repairs   |
| <b>Workshop</b>   | : | Ubi Road 1         |
| <b>Contact No</b> | : | 6366 2323          |
| <b>Fax No</b>     | : | 6841 1183          |
| <b>Reference</b>  | : | PA/OD/0100/2019/KN |
| <b>Date</b>       | : | 10-Jan-19          |

Vehicle NOT IN workshop. Kindly arrange for survey.

## AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

**Attn: Mr. Adrian Ling - Motor Claims Dept**

**Tel: 6841 0055 - Fax: 6256 4315**

|                          |   |                                      |
|--------------------------|---|--------------------------------------|
| <b>Owner's Name</b>      | : | Mr. Lim Yan An                       |
| <b>Address</b>           | : | 38 Chuan View<br>Singapore 554599    |
| <b>Telephone</b>         | : | HP +65 91739923                      |
| <b>Type of Claim</b>     | : | Own Damage Claims                    |
| <b>Policy No.</b>        | : | 2100229161-08                        |
| <b>Vehicle No</b>        | : | <b>SGG 8118 Y</b>                    |
| <b>Model Code</b>        | : | Audi A5 TFSI QU 8T306                |
| <b>Model / Year</b>      | : | 16/9/2010                            |
| <b>Engine No</b>         | : | CDN 139926                           |
| <b>Chassis No</b>        | : | WAUZZZ8T7BA011667                    |
| <b>Mileage</b>           | : |                                      |
| <b>Date In</b>           | : |                                      |
| <b>Liability</b>         | : | -                                    |
| <b>Excess Cost</b>       | : | -                                    |
| <b>Estimated By</b>      | : | Johnny Boo / Allan Wu                |
| <b>Accident Date</b>     | : | 12-Jan-19                            |
| <b>Place of Accident</b> | : | Junct of Bayfront Ave & Central BLVD |

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SGG 8118 Y

| S/n                  | Nature of Jobs                                                                                                                            | Estimated Charges      | Surveyor's Recommendation |
|----------------------|-------------------------------------------------------------------------------------------------------------------------------------------|------------------------|---------------------------|
| 1                    | To remove and transfer front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid. | S/N \$ 480.00          | ✓ ✓                       |
| 2                    | To dismantle and renew front bumper and LHS headlight. Re-organise crash management components. Reinstall all parts removed.              | \$ <del>1,400.00</del> | 500 ✓                     |
| 3                    | To respray front bumper                                                                                                                   | \$ <del>900.00</del>   | 550 ✓                     |
| 5                    | To carry out diagnostic check.                                                                                                            | S/N \$ 192.00          | ✓ ✓                       |
| TOTAL LABOUR CHARGES |                                                                                                                                           | : \$ <u>2,972.00</u>   |                           |

**Premium Automobiles**

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

**Telefax****Material List for Accident Vehicle Regn No. SGG 8118 Y**

| S/N                          | Parts Description                             | <u>Damaged Parts &amp; Prices</u> |           |
|------------------------------|-----------------------------------------------|-----------------------------------|-----------|
|                              |                                               | S/Nett                            | Remark    |
| 1                            | FRONT BUMPER <i>Rehanded</i>                  | \$ 1,907.00                       | ✓ 1525.60 |
| 2                            | FRONT BUMPER FIXING PARTS <i>new</i>          | \$ 234.00                         | ✓         |
| 3                            | FRONT BUMPER SIDE REINFORCEMENT <i>Best</i>   | \$ 802.00                         | ? 641.20  |
| 4                            | FRONT BUMPER SUPPORT-LH <i>new</i>            | \$ 26.00                          | ? X       |
| 5                            | FRONT BUMPER BRACKET-LH <i>new</i>            | \$ 207.00                         | ? X       |
| 7                            | FRONT BUMPER GUIDE PIECE <i>new</i>           | \$ 40.00                          | ✓         |
| 8                            | FRONT BUMPER SECURING STRIP - LHS             | \$ 32.00                          | ✓         |
| 9                            | FRONT BUMPER SECURING STRIP - RHS             | \$ 32.00                          | ✓         |
| 10                           | FRONT BUMPER COVER <i>Crashed</i>             | \$ 116.00                         | ✓ 92.40   |
| 11                           | FRONT BUMPER CLOSING ELEMENT <i>new</i>       | \$ 216.00                         | ✓         |
| 12                           | FRONT BUMPER TRIM CHROME <i>new</i>           | \$ 527.00                         | ✓         |
| 13                           | FRONT BUMPER FOAM FILLER PIECE <i>new</i>     | \$ 116.00                         | ? X       |
| 14                           | FRONT BUMER AIR GUIDE GRILLE - LH <i>new</i>  | \$ 134.00                         | ✓         |
| 15                           | FOG LAMP TRIM - LH <i>new</i>                 | \$ 64.00                          | ✓         |
| 16                           | FRONT BUMPER COVER <i>Crashed</i>             | 2 \$ 89.00                        | ? 70.88   |
| 17                           | RADIATOR GRILLE <i>Crashed</i>                | \$ 1,851.00                       | ✓ 1480.80 |
| 18                           | RADIATOR GRILLE CHROME TRIM <i>Crashed</i>    | \$ 113.00                         | ✓ 90      |
| 19                           | FRONT PARKING SENSOR <i>Not new</i>           | 2 \$ 419.00                       | ✓         |
| 20                           | FRONT PARKING SENSOR SEAL RING <i>Not new</i> | 4 \$ 5.00                         | ✓         |
| <b>SUB-TOTAL SPARE PARTS</b> |                                               | <b>\$ 6,930.00</b>                |           |

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

**Premium Automobiles**

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

**Telefax****Material List for Accident Vehicle Regn No. SGG 8118 Y**

| S/N                         | Parts Description                                   | <u>Damaged Parts &amp; Prices</u> |         |
|-----------------------------|-----------------------------------------------------|-----------------------------------|---------|
|                             |                                                     | S/Nett                            | Remark  |
| 21                          | WARNING SIGN FOR ENGINE COVER <i>Free</i>           | \$ 13.00                          | X       |
| 22                          | AIR CONDITIONER STICKER <i>Free</i>                 | \$ 18.00                          | X       |
| 23                          | FRONT CORNERING HEADLIGHT-LH <i>Free</i>            | \$ 2,467.00                       | ? X     |
| 24                          | FRONT MAIN BEM HEADLIGHT MOUNTING-LH <i>Cracked</i> | \$ 114.00                         | ? 90.80 |
| 25                          | FRONT MAIN BEAM HEADLIGHT BRACKET-LH <i>Free</i>    | \$ 73.00                          | ? X     |
| 26                          | HEADLIGHT WIPER WASHER CYLINDER <i>Free</i>         | \$ 251.00                         | X       |
| 27                          | FRONT NUMBER PLATE <i>Best</i>                      | S/N 25                            | ✓ 25    |
| 28                          | SUNDRIES <i>Free</i>                                | 500                               | ? X     |
| <b>TOTAL SPARE PARTS</b>    |                                                     | <b>\$ 10,391.00</b>               |         |
| <b>TOTAL LABOUR CHARGES</b> |                                                     | <b>\$ 2,972.00</b>                |         |
| <b>GRAND TOTAL</b>          |                                                     | <b>\$ 13,363.00</b>               |         |

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

: Adrian Lij  
: 24/01/19  
:  
:  
:  
:  
: Not Authorised, 03 Days

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## Please Note

- : This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant