



Case Details

Case Reference Number :

TAX/01/19/2108

Type of Repair : Accident Repair

Vehicle Registration Number :

SHD6426A

Company Type : SMRT Taxis Pte Ltd

Estimation ID : EST-5467-ID

Assigned By : Taxi Claims Manager Team

Insurance Company Name : China Taiping Insurance (Singapore) Pte Ltd

Accident Date and Time : 21/01/2019 11:30 PM

Vehicle Age(In Months) : 13

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			FENDER SUB-ASSY, FR , RH	1	933.10	933.10	25.00	699.83	Replace	1	0	Repair ▾	
One Time Key In	Main			EMBLEM, SIDE PANEL (HYBRID)	1	52.90	52.90	25.00	39.67	Replace	1	39.67	Replace ▾	NEL
One Time Key In	Main			COVER, FR BUMPER	1	495.50	495.50	25.00	371.63	Replace	1	0	Repair ▾	
One Time Key In	Main			SUPPORT, FR BUMPER RH	1	76.90	76.90	25.00	57.68	Replace	0	0	Not Give ▾	NN
One Time Key In	Main			SUPPORT, FR BUMPER LH	1	82.30	82.30	25.00	61.72	Replace	0	0	Not Give ▾	NN
One Time Key In	Main			LAMP ASSY, FOG, RH	1	910.20	910.20	10.00	819.18	Replace	0	0	Not Give ▾	NN
One Time Key In	Main			COVER, FR BUMPER RH	1	28.10	28.10	25.00	21.08	Replace	0	0	Not Give ▾	NN
One Time Key In	Main			UNIT, HEADLAMP , RH	1	2,558.90	2,558.90	10.00	2,303.01	Replace	1	2,303.01	Replace ▾	CRA
Total Spare Part Cost									4,373.80		Surveyor Total		2,342.68	
Lump Sum Discount (%)									0.00		Lump Sum Dis (%)		0	
Final Spare Part Cost									4,373.80		Final Sur Total		2,342.68	

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:			676.00	450.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR RH FRONT PORTION	676.00	450	
Total:			676.00	450.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY FRONT FENDER RH	378.00	200	
2	Main	TO REPSRAY FRONT BUMPER	180.00	180	
Total:			558.00	380.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	
2	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	30	
3	Main	TO WASH AND VACUUM	60.00	0	
4	Main	TO REPLACE SUNDRY PARTS	100.00	0	
Total:			340.00	50.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	4,373.80	2,342.68
Total Labour Cost	676.00	450.00
Total Spray Painting	558.00	380.00
Other	340.00	50.00
Overall Total	4,373.80	3,222.68
Lump Sum Repair Option	☐	☐
Lump Sum Total	0.00	3,222.68
Surveyor Approved Amount		3,222.68
No of Repair Days*	4	3
Remarks	-	P/P repair, photo before paint

Estimator Assessment(\$)		Surveyor Assessment(\$)
Surveyor Name	Hwee jie	
Signature		
Survey Date	23/01/2019	Save Clear

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: