

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Sompo Insurance Singapore Pte. Ltd.  
50 Raffles Place  
#05-01/06, Singapore Land Tower  
Singapore 048623

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: HAN CHEUNG YONG BERNARD

Date: 25 Jan 2019

**Preliminary Advice**

Vehicle No	: FBN5549D	Accident Date	: 13/01/2019
Make	: YAMAHA MTM850A (XSR900)	Policy No.	: D18MTMC01006932
Assignment Date	: 24/01/2019	Excess	: S\$1,250.00
Date of Inspection	: 24/01/2019	Est. Duration of Repair	: 10.00
Inspection At	: HONG LEONG CORPORATION - YAMAHA DIVISION (HQ) 178 PAYA LEBAR ROAD #01-01 SINGAPORE 409030		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages n/s body and parts claimed are consistent to the accident.

RePAIRer's Estimate (Gross)	:S\$	10,859.30
Revised Amount	:S\$	6,470.30
Check Items (Estimated)	:S\$	3,017.25
Total	:S\$	9,487.55

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	21,000.00
COE / PARF Rebate	:S\$	3,856.00
Salvage Value	:S\$	
Margin for Repair	:S\$	17,144.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :