

CASS REC BY:

REF:

08/8MD19001621/R1vd30v

Serial Instruction:

ok

Surveyor
merimen

Rasu

ASSIGNMENT (Office)

From (Person)

Hen cheung Yung

of

SMO

Date/Time

24/1/19 @ 1:56pm

Estimated Cost:

Bill to:

OB

TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBN 5549D

Insured:

at Workshop n/s

Hong Leong Corporation

Tel:

6746 0415 / 9383 5711

of

178 Payer Lekar Rd #01-01

Policy No:

D18MTM C01006432

Claim No:

CMTD1900511

Sum Insured:

Excess:

\$1250.00

Make of Vch:

(Client's Record)

D.O.A.

13/01/2019

CA / REV / REP. / REV 24 HRS

mv: \$21K

Date/Time:

3:33pm @ 24/1/19

Person Contacted:

Daniel

**OD Endorsement:

Vehicle IN/OUT

daniel
zhang@hrcorp.com.sg

Date/Time

Action/Instruction (✓) Estimate

FBN 5549D-X

125/1/19

Revert via merimen

28/1/19

Here approved from Bernard Han by merimen

28/1/19

Informed Daniel c/A ex \$1250 by email

12/3/19

@ 2:18pm Daniel said vehicle pending for spare parts

Passbook

REF: SMO

92 CS/SMO19001621/R1v13

4715J

ASSIGNMENT

From: Date 24/01/2019

Estimated Cost:

☒ OD / ☐ TP / ☐ WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV

To inspect Vehicle No

FBN 5549D

at Workshop/mis

Hong Leong Corporation

at 178 paya lebar Rd #01-01

Insured:

Policy No

Claim No

Sum Insured:


Excess: \$1250.00

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res: Yes or No

Lump Sum:

%

3 Val: Yes or No

CA / ☒ REV / ☐ REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No

FBN 5549D

W Regn 2018 OCT

Type: M/Car / ☒ M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make

YAMAHA MTM 850A (XSR900) cc 847

Colour

BLACK

A/C Insured / Std / NI / NA

Sp Reading

-

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No

JYARN 43P000001026

Gen. Cond: Good / ☒ Fair / Poor / Burnt

Steering: ☒ Order / Jammed / Leaked / Burnt or

Brake: ☒ Order / Jammed / Leaked / Burnt or

Modi: Nil / ☒ STD A/Rim or

Tyre Size:

F:

120/70ZR17

R:

180/55ZR17

☒ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

4

mm

R/Bal.

4

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

13/01/19

D.O.I.

24/01/19

Survey held at

HONG LEONG CORPORATION

Des. of Damages: Frt / Rear / O/S / ☒ U/C / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

4/4/19 @ 1156am Daniel said vehicle pending for spare parts.

3/6/19 Final fig \$10,553.60 Confirmed by email (Ref 1240.80, 119)

RECEIVED 03 JUN 2019

[Signature]
3/6/2019

Date/Time: File Pass to?

☐

: Preli. Report

11

☐

: Final Report

Date/Time: File Return to?

3/6- typist

Days Of Repair:

10

Resurvey No. of Trip:

2

Survey Fee:

Transportation

1. 2. 3. 4. 5.

1. 2. 3. 4. 5.

1. 2. 3. 4. 5.

1. 2. 3. 4. 5.

1. 2. 3. 4. 5.

1. 2. 3. 4. 5.

Report Format:

merimen

Lump Sum / L.B. 1: 15

10,553.60

Add Fee:

☐

Site Insp 15

☐

Inten/24 15

☐

Tech Insp 15

☐

Week-end 15

350
11
361

Form

REF SMO

47153

ASSIGNMENT

Page:

Date: 24/01/2019

Sub No:

FBN 55490

Yr Page: 2018 OCT

Endowed Code:

(10) TP / WS / TP RES / OIL RES / EVA / INV / MV

Type: M/Car / Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

To Inspect Vehicle No:

FBN 55490

Make:

YAMAHA MTM 850A (X5290) 847

at Workshop No:

Hong Leong Corporation

Colour:

BLACK

A/C Insured / Std / NI / NA

at

178 paya lebar Rd #01-01

Sp Reading:

-

T/Radio: Insured / Std / NI / NA

Amount:

EngNo:

3492N43P000001026

Policy No:

ChNo:

Cover To:

Gen. Cond: Good / Car / Poor / Burnt

Sum Insured:

Excess: \$1250.00

Sleeping: Border / Jammed / Leaked / Burnt or

(Client's Record)

Brake: Border / Jammed / Leaked / Burnt or

Make of Sub:

Mod: NI / SRM / STD A/Rim or

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Est. or Market Value:

IDAC Accident Report

Consistent?: Yes or No

GIA / PR Seen

Consistent?: Yes or No

Est. Repair:

Days Res: Yes or No

Est. Sum:

% 3-Val: Yes or No

CA / REV / REP / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Front

Back

R/Bal

4

mm

R/Bal

4

mm

L/Bal

mm

L/Bal

mm

D.O.A

13/01/19

D.O.I

24/01/19

Survey held at

HONG LEONG CORPORATION

Pos. of Damages: Frt / Rear / O/S / U/C / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date: Time

Action / Instruction

MV 19K-20K

hir

25/1/19

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Jan 2019		24 Jan 2019 13:56 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	LAW SOON KEAT, ID: S7824715J, Tel: +6591066011, Email: PHINEASLAW@GMAIL.COM		
Vehicle Reg. No.:	FBN5549D	Date of Loss:	13/01/2019 01:00 - :59 [228 Months and 12 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / CMTD1900511	Policy/Cover Note No.:	D18MTMC01006932 (Comprehensive)
		Excess:	S\$1,250.00
Repairer:	Hong Leong Corporation - Yamaha Division (HQ) 178 PAYA LEBAR ROAD #01-01, 409030 Paya Lebar - Tel:		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by HAN CHEUNG YONG BERNARD - 6322 4659]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 04/02/2019]		
Driver/Custodian:	LAW SOON KEAT (40 / Male), NRIC: S7824715J, Tel: +6591066011		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Received Message

This mail is associated with :

***FBN5549D (CMTD1900511)**

OD

Jan 13 2019 1:00AM

[LAW SOON KEAT]

Hong Leong Corporation - Yamaha Division

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From Sompo Insurance Singapore Pte. Ltd. (SOMPO_SG), sent on 31/05/2019 16:23 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$10553.60) - FBN5549D - Claim Handler: HAN CHEUNG YONG BERNARD

Approved:10553,60:Please proceed to authorise repairs if damage consistent, \$1,250 excess is applicable.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199907198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompoo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: HAN CHEUNG YONG BERNARD

Date: 31 May 2019

Preliminary Advice

Vehicle No	: FBN5549D	Accident Date	: 13/01/2019
Make	: YAMAHA MTM850A (XSR900)	Policy No.	: D18MTMC01006932
Assignment Date	: 24/01/2019	Excess	: S\$1,250.00
Date of Inspection	: 24/01/2019	Est. Duration of Repair	: 10.00
Inspection At	: HONG LEONG CORPORATION - YAMAHA DIVISION (HQ) 178 PAYA LEBAR ROAD #01-01 SINGAPORE 409030		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,794.40 (incl.supplementary \$935.10)
Revised Amount	:S\$	10,553.60 (incl.supplementary \$935.10)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	10,553.60

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	21,000.00
COE / PARF Rebate	:S\$	3,856.00
Salvage Value	:S\$	
Margin for Repair	:S\$	17,144.00

Remarks

(X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

() Other comments :

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Monday, 28 January 2019 3:44 PM
To: danielzhang@hlcorp.com.sg; SUR
Subject: FBN 5549D-DOA: 13/1/2019 (SOMPO OD)

Dear Daniel,

As instructed by our client , please proceed to repair the **insured vehicle FBN 5549D (Excess \$1250/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

***FBN5549D (CMTD1900511)**

OD

Jan 13 2019 1:00AM

[LAW SOON KEAT]

Hong Leong Corporation - Yamaha Division

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From Sampo Insurance Singapore Pte. Ltd. (SOMPO_SG), sent on 28/01/2019 14:32 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$9487.55) - FBN5549D - Claim Handler: HAN CHEUNG YONG BERNARD

Approved:9487.55:Please proceed to authorise repairs if damage consistent, \$1,250 excess is applicable.

DOCUMENTS SUMMARY

There are no documents.

Veron Chen (LKKAUTO)

From: Rasul (LKKAUTO)
Sent: Tuesday, 26 February 2019 12:05 PM
To: Danial Zhang
Cc: Veron Chen (LKKAUTO)
Subject: RE: FBN5549D - 2nd before repair survey

Hi Danial,

Proceed with the repair

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Danial Zhang [<mailto:danialzhang@hlcorp.com.sg>]
Sent: Tuesday, 26 February, 2019 12:03 PM
To: Rasul (LKKAUTO)
Cc: Veron Chen (LKKAUTO)
Subject: RE: FBN5549D - 2nd before repair survey

Hi Rasul,

As spoken on the phone, please refer to the attached pictures of the motor assy. The gears of the motor assy are damaged and therefore needed to be replaced. Do get back to me asap on this, appreciate it.

Thank you.

Regards,

Danial Zhang

Yamaha Division (Service Centre)

Tel: 6746 0415 (EXT. 122) | Fax: 6748 9238

Service HP (SMS Only): 9383 5711

E-mail: danialzhang@hlcorp.com.sg

bizSAFE₃

From: Rasul (LKKAUTO) [<mailto:Rasul@lkkauto.com>]
Sent: Tuesday, 26 February 2019 8:33 AM
To: Danial Zhang <danialzhang@hlcorp.com.sg>

Cc: Veron Chen (LKKAuto) <veronchen@lkkauto.com>

Subject: RE: FBN5549D - 2nd before repair survey

Hi Danial,

Can proceed with the repair but the additional part motor assy not given


Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Danial Zhang [<mailto:danialzhang@hlcorp.com.sg>]

Sent: Monday, 25 February, 2019 11:07 AM

To: Rasul (LKKAuto)

Cc: Veron Chen (LKKAuto)

Subject: RE: FBN5549D - 2nd before repair survey

Hi Rasul,

For the approval of the check items and supplementary parts.

Thank you.

Regards,

Danial Zhang

Yamaha Division (Service Centre)

Tel: 6746 0415 (EXT. 122) | Fax: 6748 9238

Service HP (SMS Only): 9383 5711

E-mail: danialzhang@hlcorp.com.sg

bizSAFE₃

From: Rasul (LKKAuto) [<mailto:Rasul@lkkauto.com>]

Sent: Monday, 25 February 2019 9:14 AM

To: Danial Zhang <danialzhang@hlcorp.com.sg>

Cc: Veron Chen (LKKAuto) <veronchen@lkkauto.com>

Subject: RE: FBN5549D - 2nd before repair survey

Hi Danial,

What confirmation actually you asking?


Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Veron Chen (LKKAuto)

Sent: Monday, 25 February, 2019 8:46 AM

To: Rasul (LKKAuto)

Subject: FW: FBN5549D - 2nd before repair survey

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Danial Zhang <danialzhang@hlcorp.com.sg>

Sent: Friday, 22 February 2019 3:45 PM

To: SUR <sur@lkkauto.com>

Cc: chandramoorthi <chandramoorthi@hlcorp.com.sg>

Subject: FBN5549D - 2nd before repair survey

Hi Rasul,

We are awaiting for your confirmation email so that we may proceed with the ordering of the necessary parts. Your colleague came to our workshop to look on the check items on 18 Feb and said that you will get back to us through email. Kindly get back to us asap with thanks.

Thank you.

Regards,

Danial Zhang

Yamaha Division (Service Centre)

Tel: 6746 0415 (EXT. 122) | Fax: 6748 9238

Service HP (SMS Only): 9383 5711

E-mail: danialzhang@hlcorp.com.sg

bizSAFE₃

From: Danial Zhang <danialzhang@hlcorp.com.sg>
Sent: Friday, 22 February 2019 3:45 PM
To: SUR
Cc: chandramoorthi
Subject: FBN5549D - 2nd before repair survey

Hi Rasul,

We are awaiting for your confirmation email so that we may proceed with the ordering of the necessary parts. Your colleague came to our workshop to look on the check items on 18 Feb and said that you will get back to us through email. Kindly get back to us asap with thanks.

Thank you.

Regards,
Danial Zhang
Yamaha Division (Service Centre)
Tel: 6746 0415 (EXT. 122) | Fax: 6748 9238
Service HP (SMS Only): 9383 5711
E-mail: danialzhang@hlcorp.com.sg

bizSAFE₃

Disclaimer & Email Privacy Statement : This message, together with any attachment, is intended only for the use of the individual or entity to which it is addressed, and may contain information that is legally privileged and confidential. If you are not the intended recipient, please be informed that any dissemination, distribution or copying of this message, or any attachment thereto is strictly prohibited. Kindly note that email communications are not secure and therefore are susceptible to alteration. We will not accept any responsibility, legal or otherwise, for the contents of this message. If you have received this message in error, please advise the sender by reply e-mail, and delete the message. Thank you for your co-operation.

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4715J
Vehicle Details	
Vehicle No.:	FBN5549D
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Jan 2019
Vehicle Make:	YAMAHA
Vehicle Model:	MTM850A (XSR900)
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	N701E108294
Chassis No.:	JYARN43P000001026
Maximum Power Output:	-
Open Market Value:	\$9,085.00
Original Registration Date:	30 Oct 2018
First Registration Date:	30 Oct 2018
Transfer Count:	1
Actual ARF Paid:	\$2,793.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	29 Oct 2028
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$3,951.00
COE Rebate Amount:	\$3,856.00
Total Rebate Amount:	\$3,856.00

The information contained herein is correct as at 25 Jan 2019

OK

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompoo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: HAN CHEUNG YONG BERNARD

Date: 25 Jan 2019

Preliminary Advice

Vehicle No	: FBN5549D	Accident Date	: 13/01/2019
Make	: YAMAHA MTM850A (XSR900)	Policy No.	: D18MTMC01006932
Assignment Date	: 24/01/2019	Excess	: S\$1,250.00
Date of Inspection	: 24/01/2019	Est. Duration of Repair	: 10.00
Inspection At	: HONG LEONG CORPORATION - YAMAHA DIVISION (HQ) 178 PAYA LEBAR ROAD #01-01 SINGAPORE 409030		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,859.30
Revised Amount	:S\$	6,470.30
Check Items (Estimated)	:S\$	3,017.25
Total	:S\$	9,487.55

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	21,000.00
COE / PARF Rebate	:S\$	3,856.00
Salvage Value	:S\$	
Margin for Repair	:S\$	17,144.00

Remarks

(X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

() Other comments :

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/01/2019 13:31
Date Of Accident	13/01/2019 01:00
Exact Location Of Accident	REPUBLIC BOULEVARD ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBN5549D
Insured/Policyholder	
Name Of Registered Owner	LAW SOON KEAT
NRIC No	S7824715J
Email Address	PHINEASLAW@GMAIL.COM
Mobile Phone No	(LOCAL) +65-91066011
Alternative Phone No	OFFICE-91066011

Vehicle Particulars

Manufacturer	YAMAHA
Model	MTM850A (XSR900)-847CC
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D18MTMC01006932
Cover Note Number	

Driver

Name of Driver	LAW SOON KEAT
NRIC No	S7824715J
Date Of Birth	01/09/1978
Occupation	INDOOR
Date Of Driving Pass	15/11/2005
Driving Experience	13 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-91066011
Fax Number	
Contact Number	OFFICE-91066011
Email Address	PHINEASLAW@GMAIL.COM

Address	BLK 488A, CHOA CHU KANG AVE 5 #09-125
Postcode	681488
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	NO COLLISION
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	1
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 13.1.19 ABOUT 1AM, RIDER GOING HOME FROM SUNTEC CITY AND PASS BY REPUBLIC BOULEVARD AND SKIDDED. THE FLOOR CONDITION WERE WET

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Following Date Signature

Date Time 22.11.2019

Driver's Signature

Date Time 22.11.2019

Date Time 22.11.2019

Following

Date Signature

Date Signature 22.11.2019

Date Signature 22.11.2019

SKETCH PLAN

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 13.01.19 about 1 AM, Rider going home from Sinter City
and pass by Republic Boulevard and skidded.
The floor condition were wet.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]

[Signature]

22.1.2019

22.1.2019



Signature of the Police Officer
Wong Chai Lan
215000012



Accident Photo




Accident Photo



Accident Photo



Accident Photo



Hong Leong Corporation Holdings Pte Ltd

Yamaha Division (Incorporated in Singapore)

178 Paya Lebar Road #01-01 Singapore 409030
Tel: 6746 0415 / 6749 0588 Fax: 6748 9238

23-Jan-19

Sompo Insurance Singapore Pte Ltd
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

Tel: 6461 6555
Fax:
Email:

Attention: Vehicle Claim(s) Department

Dear Sir/Madam,

ESTIMATED COST OF ACCIDENT REPAIR FOR YAMAHA BIKE XSR900 OF REGISTRATION NO. FBN5549D

The above-captioned motorcycle is currently in our workshop.

Your client, rider of FBN5549D is doing a own damage (1st party) claim

We append herewith the estimated quotation of repair / replacement to the damaged parts.

S/no	Description	Qty	Unit Price	Total Price
DISCOUNT ITEMS				
1	GASKET HEAD COVER <i>NE</i>	1	\$ 13.00	\$ 13.00
2	GASKET CYLINDER HEAD <i>NE</i>	1	\$ 36.00	\$ 36.00
3	PLANE BEARING CRANKSHAFT (00) <i>7xsr</i>	8	\$ 7.00	\$ 56.00
4	PLANE BEARING CRANKSHAFT (10) <i>7ne</i>	8	\$ 7.00	\$ 56.00
5	PLANE BEARING CRANKSHAFT (20) <i>7xsr</i>	8	\$ 7.00	\$ 56.00
6	PLANE BEARING CRANKSHAFT (30) <i>7xsr</i>	8	\$ 7.00	\$ 56.00
7	PLANE BEARING CRANKSHAFT (40) <i>7xsr</i>	8	\$ 7.00	\$ 56.00
8	METAL BALANCE WEIGHT (00) <i>7xsr</i>	4	\$ 5.00	\$ 20.00
9	METAL BALANCE WEIGHT (10) <i>7xsr</i>	4	\$ 5.00	\$ 20.00
10	METAL BALANCE WEIGHT (20) <i>7xsr</i>	4	\$ 5.00	\$ 20.00
11	METAL BALANCE WEIGHT (30) <i>7xsr</i>	4	\$ 5.00	\$ 20.00
12	METAL BALANCE WEIGHT (40) <i>7xsr</i>	4	\$ 5.00	\$ 20.00
13	GASKET TENSIONER CASE <i>NE</i>	1	\$ 3.00	\$ 3.00
14	O-RING	1	\$ 1.00	\$ 1.00
15	O-RING	1	\$ 2.00	\$ 2.00
16	O-RING	1	\$ 6.00	\$ 6.00
17	O-RING	1	\$ 2.00	\$ 2.00
18	O-RING	1	\$ 1.00	\$ 1.00
19	O-RING	1	\$ 6.00	\$ 6.00
20	GASKET STRAINER COVER <i>NE</i>	1	\$ 15.00	\$ 15.00
21	STRAINER COVER ASSY <i>NE</i>	1	\$ 15.00	\$ 15.00
22	OIL FILTER <i>NE</i>	1	\$ 15.00	\$ 15.00
23	CRANKCASE ASSY <i>7xsr</i>	1	\$ 2,200.00	\$ 2,200.00
24	O-RING (16325) <i>7xsr</i>	2	\$ 1.00	\$ 2.00
25	O-RING (14369) <i>7xsr</i>	1	\$ 1.00	\$ 1.00
26	BOLT, CRANKCASE JOURNAL	4	\$ 5.00	\$ 20.00
27	BOLT WITH WASHER (13)	6	\$ 7.00	\$ 42.00
28	BOLT WITH WASHER (10)	2	\$ 8.00	\$ 16.00
29	BOLT FLANGE	1	\$ 1.00	\$ 1.00
30	BOLT FLANGE	1	\$ 1.00	\$ 1.00
31	GAUGE LEVEL	1	\$ 10.00	\$ 10.00
32	GASKET CRANKCASE COVER 2	1	\$ 14.00	\$ 14.00
33	GASKET OIL PUMP COVER	1	\$ 6.00	\$ 6.00
34	GASKET CRANKCASE COVER 1	1	\$ 12.00	\$ 12.00
35	O-RING	1	\$ 1.00	\$ 1.00
36	O-RING	1	\$ 6.00	\$ 6.00
37	BOLT HEXAGON SOCKET HEAD	2	\$ 2.00	\$ 4.00
38	BOLT HEXAGON SOCKET HEAD	2	\$ 1.50	\$ 3.00
39	BOLT BUTTON HEAD	1	\$ 1.00	\$ 1.00

40	SCREW		✓	3	\$	1.00	\$	3.00
41	OIL SEAL	} ? new	✓	1	\$	10.00	\$	10.00
42	OIL SEAL		✓	1	\$	2.00	\$	2.00
43	BEARING		✓	1	\$	7.00	\$	7.00
44	STOPPER SCREW	? new	✓	1	\$	5.00	\$	5.00
45	ROTOR ASSY	st	✓	1	\$	180.00	\$	180.00
46	STATOR ASSY	st	✓	1	\$	250.00	\$	250.00
47	BOLT	} ? new	✓	3	\$	6.00	\$	18.00
48	LEVER 1		✓	1	\$	18.00	\$	18.00
49	HANDLEBAR	st	✓	1	\$	120.00	\$	120.00
50	SHIFT PEDAL ASSY	sc	✓	1	\$	59.00	\$	59.00
51	CAST WHEEL FRONT	repair ch	✓	1	\$	450.00	\$	450.00
52	BEARING	} ? new	✓	2	\$	9.00	\$	18.00
53	OIL SEAL		✓	2	\$	4.00	\$	8.00
54	FRONT FOOTREST ASSY (LHS)	st	✓	1	\$	39.00	\$	39.00
55	REAR ARM COMP	sc	✓	1	\$	950.00	\$	950.00
56	BEARING	? new	✓	3	\$	13.50	\$	40.50
57	OIL SEAL (33004)	} ? new	✓	2	\$	5.00	\$	10.00
58	OIL SEAL (22002)		✓	2	\$	5.00	\$	10.00
59	STRAINER HOUSING ASSY	? ch	✓	1	\$	20.00	\$	20.00
60	O-RING (22001)	? new	✓	1	\$	1.00	\$	1.00
61	MUFFLER ASSY	st	✓	1	\$	1,100.00	\$	1,100.00
62	PLUG, STRAIGHT SCREW	? new	✓	1	\$	15.00	\$	15.00
63	GEAR IDLER	? ch	✓	1	\$	45.00	\$	45.00
64	STARTER ONE WAY ASSY	? ch	✓	1	\$	72.00	\$	72.00
37	GEAR 3	? ch	✓	1	\$	70.00	\$	70.00
38	END GRIP	sc	✓	1	\$	10.00	\$	10.00
39	GRIP (LHS)	? ch	✓	1	\$	7.50	\$	7.50
40	OIL LEVEL GAUGE ASSY	? ch	✓	1	\$	50.00	\$	50.00
41	BOLT FLANGE	? new	✓	2	\$	1.00	\$	2.00
42	DRIVE-CHAIN (DID525V-110LL)	? ch	✓	1	\$	190.00	\$	190.00
SubTotal							\$	6,615.00
Discount: Less 10%							\$	661.50
SubTotal (A)							\$	5,953.50
S/no	Description			Qty	Unit Price		Total Price	
NETT-PRICED ITEMS								
1	COOLANT	new	✓	1	\$	25.00	\$	25.00
2	ENGINE OIL	new	✓	1	\$	91.80	\$	91.80
3	VITAS INSPECTION	new	✓	1	\$	69.00	\$	69.00
4	LTA DOCUMENTATION	new	✓	1	\$	100.00	\$	100.00
5	LABOUR - FORK ALIGNMENT		✓	1	\$	120.00	\$	120.00
6	LABOUR - REPLACE ENGINE CRANKCASE ASSY & ACCIDENT PARTS			1	\$	4,500.00	\$	4,500.00
SubTotal (B)							\$	4,905.80
Total (A) TO (B)							\$	10,859.30

* Price is subject to 7% GST upon Invoicing.

Kindly assign a Surveyor down to our workshop as soon as possible.

In the meantime, please do not hesitate to contact me at 6746 0415 (ext. 122) should you have further clarifications to the said matter.

Thank you.

Yours sincerely

Daniel Zhang (Mr)

Hong Leong Corporation Holdings Pte Ltd

YAMAHA DIVISION

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To resurvey damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

11794210

28/1/19

PASUL
Hp 90010068

10 days

7/P

24/01/19 @ 1710 hrs

EXCESS: 1250

sur@lkkauto.com

REPAIR

Resurvey by paint

Hong Leong Corporation Holdings Pte Ltd

Yamaha Division (Incorporated in Singapore)

178 Paya Lebar Road #01-01 Singapore 409030
Tel: 6746 0415 / 6749 0588 Fax: 6748 9238

23-Jan-19

Sompo Insurance Singapore Pte Ltd
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

Tel: 6461 6555
Fax:
Email:

DANIAL ZHANG
@HLCORP.COM.SG.

Attention: Vehicle Claim(s) Department

Dear Sir/Madam,

ESTIMATED COST OF ACCIDENT REPAIR FOR YAMAHA BIKE XSR900 OF REGISTRATION NO. FBN5549D

The above-captioned motorcycle is currently in our workshop.

Your client, rider of FBN5549D is doing a own damage (1st party) claim

We append herewith the estimated quotation of repair / replacement to the damaged parts.

S/no	Description	Qty	Unit Price	Total Price
DISCOUNT ITEMS				
1	GASKET HEAD COVER <i>acc</i>	1	\$ 13.00	\$ 13.00
2	GASKET CYLINDER HEAD <i>acc</i>	1	\$ 36.00	\$ 36.00
3	PLANE BEARING CRANKSHAFT (00)	8	\$ 7.00	\$ 56.00
4	PLANE BEARING CRANKSHAFT (10)	8	\$ 7.00	\$ 56.00
5	PLANE BEARING CRANKSHAFT (20)	8	\$ 7.00	\$ 56.00
6	PLANE BEARING CRANKSHAFT (30)	8	\$ 7.00	\$ 56.00
7	PLANE BEARING CRANKSHAFT (40)	8	\$ 7.00	\$ 56.00
8	METAL BALANCE WEIGHT (00)	4	\$ 5.00	\$ 20.00
9	METAL BALANCE WEIGHT (10)	4	\$ 5.00	\$ 20.00
10	METAL BALANCE WEIGHT (20)	4	\$ 5.00	\$ 20.00
11	METAL BALANCE WEIGHT (30)	4	\$ 5.00	\$ 20.00
12	METAL BALANCE WEIGHT (40)	4	\$ 5.00	\$ 20.00
13	GASKET TENSIONER CASE <i>acc</i>	1	\$ 3.00	\$ 3.00
14	O-RING	1	\$ 1.00	\$ 1.00
15	O-RING	1	\$ 2.00	\$ 2.00
16	O-RING	1	\$ 6.00	\$ 6.00
17	O-RING	1	\$ 2.00	\$ 2.00
18	O-RING	1	\$ 1.00	\$ 1.00
19	O-RING	1	\$ 6.00	\$ 6.00
20	GASKET STRAINER COVER <i>acc</i>	1	\$ 15.00	\$ 15.00
21	STRAINER COVER ASSY <i>acc</i>	1	\$ 15.00	\$ 15.00
22	OIL FILTER <i>acc</i>	1	\$ 15.00	\$ 15.00
23	CRANKCASE ASSY	1	\$ 2,200.00	\$ 2,200.00
24	O-RING (16325)	2	\$ 1.00	\$ 2.00
25	O-RING (14369)	1	\$ 1.00	\$ 1.00
26	BOLT, CRANKCASE JOURNAL	4	\$ 5.00	\$ 20.00
27	BOLT WITH WASHER (13)	6	\$ 7.00	\$ 42.00
28	BOLT WITH WASHER (10)	2	\$ 8.00	\$ 16.00
29	BOLT FLANGE	1	\$ 1.00	\$ 1.00
30	BOLT FLANGE	1	\$ 1.00	\$ 1.00
31	GAUGE LEVEL	1	\$ 10.00	\$ 10.00
32	GASKET CRANKCASE COVER 2	1	\$ 14.00	\$ 14.00
33	GASKET OIL PUMP COVER	1	\$ 6.00	\$ 6.00
34	GASKET CRANKCASE COVER 1	1	\$ 12.00	\$ 12.00
35	O-RING	1	\$ 1.00	\$ 1.00
36	O-RING	1	\$ 6.00	\$ 6.00
37	BOLT HEXAGON SOCKET HEAD	2	\$ 2.00	\$ 4.00
38	BOLT HEXAGON SOCKET HEAD	2	\$ 1.50	\$ 3.00
39	BOLT BUTTON HEAD	1	\$ 1.00	\$ 1.00

40	SCREW	3	\$	1.00	\$	3.00
41	OIL SEAL	1	\$	10.00	\$	10.00
42	OIL SEAL	1	\$	2.00	\$	2.00
43	BEARING	1	\$	7.00	\$	7.00
44	STOPPER SCREW	1	\$	5.00	\$	5.00
45	ROTOR ASSY	1	\$	180.00	\$	180.00
46	STATOR ASSY	1	\$	250.00	\$	250.00
47	BOLT	3	\$	6.00	\$	18.00
48	LEVER 1	1	\$	18.00	\$	18.00
49	HANDLEBAR	1	\$	120.00	\$	120.00
50	SHIFT PEDAL ASSY	1	\$	59.00	\$	59.00
51	CAST WHEEL FRONT	1	\$	450.00	\$	450.00
52	BEARING	2	\$	9.00	\$	18.00
53	OIL SEAL	2	\$	4.00	\$	8.00
54	FRONT FOOTREST ASSY (LHS)	1	\$	39.00	\$	39.00
55	REAR ARM COMP	1	\$	950.00	\$	950.00
56	BEARING	3	\$	13.50	\$	40.50
57	OIL SEAL (33004)	2	\$	5.00	\$	10.00
58	OIL SEAL (22002)	2	\$	5.00	\$	10.00
59	STRAINER HOUSING ASSY	1	\$	20.00	\$	20.00
60	O-RING (22001)	1	\$	1.00	\$	1.00
61	MUFFLER ASSY	1	\$	1,100.00	\$	1,100.00
62	PLUG, STRAIGHT SCREW	1	\$	15.00	\$	15.00
63	GEAR IDLER	1	\$	45.00	\$	45.00
64	STARTER ONE WAY ASSY	1	\$	72.00	\$	72.00
37	GEAR 3	1	\$	70.00	\$	70.00
38	END GRIP	1	\$	10.00	\$	10.00
39	GRIP (LHS)	1	\$	7.50	\$	7.50
40	OIL LEVEL GAUGE ASSY	1	\$	50.00	\$	50.00
41	BOLT FLANGE	2	\$	1.00	\$	2.00
42	DRIVE-CHAIN (DID525V-110LL)	1	\$	190.00	\$	190.00
SubTotal					\$	6,615.00
Discount: Less 10%					\$	661.50
SubTotal (A)					\$	5,953.50
NETT-PRICED ITEMS						
1	COOLANT	1	\$	25.00	\$	25.00
2	ENGINE OIL	1	\$	91.80	\$	91.80
3	VITAS INSPECTION	1	\$	69.00	\$	69.00
4	LTA DOCUMENTATION	1	\$	100.00	\$	100.00
5	LABOUR - FORK ALIGNMENT	1	\$	120.00	\$	120.00
6	LABOUR - REPLACE ENGINE CRANKCASE ASSY & ACCIDENT PARTS	1	\$	4,500.00	\$	4,500.00
SubTotal (B)					\$	4,905.80
Total (A) TO (B)					\$	10,859.30

* Price is subject to 7% GST upon Invoicing.

Kindly assign a Surveyor down to our workshop as soon as possible.

In the meantime, please do not hesitate to contact me at 6746 0415 (ext. 122) should you have further clarifications to the said matter.

Thank you.

Yours sincerely
Daniel Zhang (Mr.)
Hong Leong Corporation Holdings Pte Ltd
YAMAHA DIVISION

PASUL
Hp 90010068

10 days

7/P

24/01/19 @ 1710 hrs

EXCESS: 1250

sur@lkkauto.com

Revert

Resurvey by paint

Hong Leong Corporation Holdings Pte Ltd

Yamaha Division (Incorporated in Singapore)

178 Paya Lebar Road #01-01 Singapore 409030

Tel: 6746 0415 / 6749 0588 Fax: 6748 9238

14-Jan-19

Sompo Insurance Singapore Pte Ltd
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

Tel: 6461 6555

Fax:

Email:

Attention: Vehicle Claim(s) Department

ADDITIONAL

Dear Sir/Madam,

ESTIMATED COST OF ACCIDENT REPAIR FOR YAMAHA BIKE XSR900 OF REGISTRATION NO. FBN5549D

The above-captioned motorcycle is currently in our workshop.

Your client, rider of FBN5549D is doing a own damage (1st party) claim

We append herewith the estimated quotation of repair / replacement to the damaged parts.

S/no	Description	Qty	Unit Price	Total Price
DISCOUNT ITEMS				
1	FRONT FORK (L.H)	1	\$ 680.00	\$ 680.00
2	OH-LEVEL GAUGE ASSY	1	\$ 50.00	\$ 50.00
3	O-RING	1	\$ 0.80	\$ 0.80
4	O-RING	1	\$ 1.20	\$ 1.20
5	MOTOR ASSY	1		\$ 265.00
	SubTotal		\$	997.00
	Discount: Less 10%		\$	99.70
	SubTotal (A)		\$	897.30
NETT-PRICED ITEMS				
1			\$	-
	SubTotal (B)		\$	-
	Total (A) TO (B)		\$	897.30

See /
X-represented (40)
See /
See /
See /

* Price is subject to 7% GST upon Invoicing.

Kindly assign a Surveyor down to our workshop as soon as possible.

In the meantime, please do not hesitate to contact me at 6746 0415 (ext. 122) should you have further clarifications to the said matter.

Thank you.

Yours sincerely

Danial Zhang (Mr.)

Hong Leong Corporation Holdings Pte Ltd

YAMAHA DIVISION

Hong Leong Corporation Holdings Pte Ltd

Yamaha Division (Incorporated in Singapore)

178 Paya Lebar Road #01-01 Singapore 409030
Tel: 6746 0415 / 6749 0588 Fax: 6748 9238

22-May-19

Sompo Insurance Singapore Pte Ltd
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

Tel: 6461 6555
Fax:
Email:

Attention: Vehicle Claim(s) Department

FINALISED

Dear Sir/Madam,

ESTIMATED COST OF ACCIDENT REPAIR FOR YAMAHA BIKE XSR900 OF REGISTRATION NO. FBN5549D

The above-captioned motorcycle is currently in our workshop.

Your client, rider of FBN5549D is doing a own damage (1st party) claim

We append herewith the estimated quotation of repair / replacement to the damaged parts.

S/no	Description	Qty	Unit Price	Total Price
DISCOUNT ITEMS				
1	GASKET HEAD COVER	1	\$ 13.00	\$ 13.00
2	GASKET CYLINDER HEAD	1	\$ 36.00	\$ 36.00
3	PLANE BEARING CRANKSHAFT (10)	4	\$ 7.00	\$ 28.00
4	METAL BALANCE WEIGHT (10)	4	\$ 5.00	\$ 20.00
5	METAL BALANCE WEIGHT (20)	4	\$ 5.00	\$ 20.00
6	GASKET TENSIONER CASE	1	\$ 3.00	\$ 3.00
7	O-RING	1	\$ 1.00	\$ 1.00
8	O-RING	1	\$ 2.00	\$ 2.00
9	O-RING	1	\$ 6.00	\$ 6.00
10	O-RING	1	\$ 2.00	\$ 2.00
11	O-RING	1	\$ 1.00	\$ 1.00
12	O-RING	1	\$ 6.00	\$ 6.00
13	GASKET STRAINER COVER	1	\$ 15.00	\$ 15.00
14	STRAINER COVER ASSY	1	\$ 15.00	\$ 15.00
15	OIL FILTER	1	\$ 15.00	\$ 15.00
16	CRANKCASE ASSY	1	\$ 2,200.00	\$ 2,200.00
17	O-RING (16325)	2	\$ 1.00	\$ 2.00
18	O-RING (14369)	1	\$ 1.00	\$ 1.00
19	BOLT, CRANKCASE JOURNAL	4	\$ 5.00	\$ 20.00
20	BOLT WITH WASHER (13)	6	\$ 7.00	\$ 42.00
21	BOLT WITH WASHER (10)	2	\$ 8.00	\$ 16.00
22	BOLT FLANGE	1	\$ 1.00	\$ 1.00
23	BOLT FLANGE	1	\$ 1.00	\$ 1.00
24	GAUGE LEVEL	1	\$ 10.00	\$ 10.00
25	GASKET CRANKCASE COVER 2	1	\$ 14.00	\$ 14.00
26	GASKET OIL PUMP COVER	1	\$ 6.00	\$ 6.00
27	GASKET CRANKCASE COVER 1	1	\$ 12.00	\$ 12.00
28	O-RING	1	\$ 1.00	\$ 1.00
29	O-RING	1	\$ 6.00	\$ 6.00
30	BOLT HEXAGON SOCKET HEAD	2	\$ 2.00	\$ 4.00
31	BOLT HEXAGON SOCKET HEAD	2	\$ 1.50	\$ 3.00
32	BOLT BUTTON HEAD	1	\$ 1.00	\$ 1.00
33	SCREW	3	\$ 1.00	\$ 3.00
34	OIL SEAL	1	\$ 10.00	\$ 10.00
35	OIL SEAL	1	\$ 2.00	\$ 2.00
36	BEARING	1	\$ 7.00	\$ 7.00
37	STOPPER SCREW	1	\$ 5.00	\$ 5.00
38	ROTOR ASSY	1	\$ 180.00	\$ 180.00
39	STATOR ASSY	1	\$ 250.00	\$ 250.00

40	BOLT	3	\$ 6.00	\$ 18.00
41	LEVER 1	1	\$ 18.00	\$ 18.00
42	HANDLEBAR	1	\$ 120.00	\$ 120.00
43	SHIFT PEDAL ASSY	1	\$ 59.00	\$ 59.00
44	CAST WHEEL FRONT	1	\$ 450.00	\$ 450.00
45	BEARING	2	\$ 9.00	\$ 18.00
46	OIL SEAL	2	\$ 4.00	\$ 8.00
47	FRONT FOOTREST ASSY (LHS)	1	\$ 39.00	\$ 39.00
48	REAR ARM COMP	1	\$ 950.00	\$ 950.00
49	BEARING	3	\$ 13.50	\$ 40.50
50	OIL SEAL (33004)	2	\$ 5.00	\$ 10.00
51	OIL SEAL (22002)	2	\$ 5.00	\$ 10.00
52	STRAINER HOUSING ASSY	1	\$ 20.00	\$ 20.00
53	O-RING (22001)	1	\$ 1.00	\$ 1.00
54	MUFFLER ASSY	1	\$ 1,100.00	\$ 1,100.00
55	PLUG, STRAIGHT SCREW	1	\$ 15.00	\$ 15.00
56	GEAR IDLER	1	\$ 45.00	\$ 45.00
57	STARTER ONE WAY ASSY	1	\$ 72.00	\$ 72.00
58	GEAR 3	1	\$ 70.00	\$ 70.00
59	END GRIP	1	\$ 10.00	\$ 10.00
60	GRIP (LHS)	1	\$ 7.50	\$ 7.50
61	OIL LEVEL GAUGE ASSY	1	\$ 50.00	\$ 50.00
62	BOLT FLANGE	2	\$ 1.00	\$ 2.00
63	DRIVE-CHAIN (DID525V-110LL)	1	\$ 190.00	\$ 190.00
64	FRONT FORK (LHS)	1	\$ 680.00	\$ 680.00
37	O-RING (21001)	1	\$ 0.80	\$ 0.80
38	O-RING (15566)	1	\$ 1.20	\$ 1.20
39	MOTOR ASSY	1	\$ 265.00	\$ 265.00
40	BOLT CONNECTING ROD	6	\$ 2.00	\$ 12.00
41	COVER CRANKCASE 1	1	\$ 80.00	\$ 80.00
SubTotal				\$ 7,342.00
Discount: Less 10%				\$ 734.20
SubTotal (A)				\$ 6,607.80
S/no	Description	Qty	Unit Price	Total Price
NETT-PRICED ITEMS				
1	COOLANT	1	\$ 25.00	\$ 25.00
2	ENGINE OIL	1	\$ 91.80	\$ 91.80
3	VITAS INSPECTION	1	\$ 69.00	\$ 69.00
4	LTA DOCUMENTATION	1	\$ 100.00	\$ 100.00
5	LABOUR - FORK ALIGNMENT	1	\$ 60.00	\$ 60.00
6	LABOUR - REPLACE ENGINE CRANKCASE ASSY & ACCIDENT PARTS	1	\$ 3,600.00	\$ 3,600.00
SubTotal (B)				\$ 3,945.80
Total (A) TO (B)				\$ 10,553.60

* Price is subject to 7% GST upon Invoicing.

Kindly assign a Surveyor down to our workshop as soon as possible.

In the meantime, please do not hesitate to contact me at 6746 0415 (ext. 122) should you have further clarifications to the said matter.

Thank you.

Yours sincerely

Daniel Zhang (Mr.)

Hong Leong Corporation Holdings Pte Ltd
YAMAHA DIVISION

Hong Leong Corporation Holdings Pte Ltd

Yamaha Division (Incorporated in Singapore)

178 Paya Lebar Road #01-01 Singapore 409030
Tel: 6746 0415 / 6749 0588 Fax: 6748 9238

22-May-19

Sompo Insurance Singapore Pte Ltd
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

Tel: 6461 6555
Fax:
Email:

Attention: Vehicle Claim(s) Department

ADDITIONAL

Dear Sir/Madam,

ESTIMATED COST OF ACCIDENT REPAIR FOR YAMAHA BIKE XSR900 OF REGISTRATION NO. FBN5549D

The above-captioned motorcycle is currently in our workshop.

Your client, rider of FBN5549D is doing a own damage (1st party) claim

We append herewith the estimated quotation of repair / replacement to the damaged parts.

S/no	Description	Qty	Unit Price	Total Price
DISCOUNT ITEMS				
1	FRONT FORK (L.H)	1	\$ 680.00	\$ 680.00
2	O-RING (21001)	1	\$ 0.80	0.80
3	O-RING (15566)	1	\$ 1.20	1.20
4	MOTOR ASSY	1	\$ 265.00	265.00
5	BOLT CONNECTING ROD	6	\$ 2.00	12.00
6	COVER CRANKCASE 1	1	\$ 80.00	80.00
	SubTotal		\$	1,039.00
	Discount: Less 10%		\$	103.90
	SubTotal (A)		\$	935.10
S/no	Description	Qty	Unit Price	Total Price
NETT-PRICED ITEMS				
1			\$	-
	SubTotal (B)		\$	-
	Total (A) TO (B)		\$	935.10

scr
nec
nec
cut
nec
cra

* Price is subject to 7% GST upon Invoicing.

Kindly assign a Surveyor down to our workshop as soon as possible.

In the meantime, please do not hesitate to contact me at 6746 0415 (ext. 122) should you have further clarifications to the said matter.

Thank you.

Yours sincerely
Danial Zhang (Mr.)
Hong Leong Corporation Holdings Pte Ltd
YAMAHA DIVISION

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 3 June 2019 10:11 AM
To: Danial Zhang; SUR
Cc: Rasul (LKKAUTO); chandramoorthi@hlcorp.com.sg
Subject: RE: FBN5549D - 2nd before repair survey

Dear Danial,

Confirmed amount \$10,553.60 before excess \$1250 @ 10 working days.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 23 May 2019 10:39 AM
To: assignments <assignments@lkkauto.com>
Subject: FW: FBN5549D - 2nd before repair survey

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Danial Zhang <danialzhang@hlcorp.com.sg>
Sent: Thursday, 23 May 2019 10:31 AM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; Rasul (LKKAUTO) <Rasul@lkkauto.com>
Cc: chandramoorthi <chandramoorthi@hlcorp.com.sg>
Subject: RE: FBN5549D - 2nd before repair survey

Hi Veron,

Bike has been fully repaired. Able to be surveyed anytime weekday 9am to 5.30pm (except lunchtime 12.30 to 1.30pm). Kindly refer to attachments for the additional parts and finalised copy.

Thank you.

Regards,

Danial Zhang

Yamaha Division (Service Centre)

Tel: 6746 0415 (EXT. 122) | Fax: 6748 9238

Service HP (SMS Only): 9383 5711

E-mail: danialzhang@hlcorp.com.sg

bizSAFE₃

From: Veron Chen (LKKAUTO) [<mailto:veronchen@lkkauto.com>]

Sent: Tuesday, 7 May 2019 4:57 PM

To: Rasul (LKKAUTO) <Rasul@lkkauto.com>; Danial Zhang <danialzhang@hlcorp.com.sg>

Subject: RE: FBN5549D - 2nd before repair survey

Dear Danial,

Kindly advise vehicle status.

If vehicle has been repaired, please finalize with us.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Rasul (LKKAUTO)

Sent: Tuesday, 26 February 2019 12:05 PM

To: Danial Zhang <danialzhang@hlcorp.com.sg>

Cc: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>

Subject: RE: FBN5549D - 2nd before repair survey

Hi Danial,

Proceed with the repair

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

LKK

Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Danial Zhang [<mailto:danialzhang@hlcorp.com.sg>]

Sent: Tuesday, 26 February, 2019 12:03 PM

To: Rasul (LKKAUTO)

Cc: Veron Chen (LKKAUTO)

Subject: RE: FBN5549D - 2nd before repair survey

Hi Rasul,

As spoken on the phone, please refer to the attached pictures of the motor assy. The gears of the motor assy are damaged and therefore needed to be replaced. Do get back to me asap on this, appreciate it.

Thank you.

Regards,

Danial Zhang

Yamaha Division (Service Centre)

Tel: 6746 0415 (EXT. 122) | Fax: 6748 9238

Service HP (SMS Only): 9383 5711

E-mail: danialzhang@hlcorp.com.sg

bizSAFE₃

From: Rasul (LKKAUTO) [<mailto:Rasul@lkkauto.com>]

Sent: Tuesday, 26 February 2019 8:33 AM

To: Danial Zhang <danialzhang@hlcorp.com.sg>

Cc: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>

Subject: RE: FBN5549D - 2nd before repair survey

Hi Danial,

Can proceed with the repair but the additional part motor assy not given

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

LKK

Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Danial Zhang [<mailto:danialzhang@hlcorp.com.sg>]

Sent: Monday, 25 February, 2019 11:07 AM

To: Rasul (LKKAUTO)

Cc: Veron Chen (LKKAUTO)

Subject: RE: FBN5549D - 2nd before repair survey

Hi Rasul,

For the approval of the check items and supplementary parts.

Thank you.

Regards,

Danial Zhang

Yamaha Division (Service Centre)

Tel: 6746 0415 (EXT. 122) | Fax: 6748 9238

Service HP (SMS Only): 9383 5711
E-mail: danialzhang@hlcorp.com.sg

bizSAFE₃

From: Rasul (LKKAuto) [<mailto:Rasul@lkkauto.com>]
Sent: Monday, 25 February 2019 9:14 AM
To: Danial Zhang <danialzhang@hlcorp.com.sg>
Cc: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Subject: RE: FBN5549D - 2nd before repair survey

Hi Danial,

What confirmation actually you asking?

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

LKK

Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Veron Chen (LKKAuto)
Sent: Monday, 25 February, 2019 8:46 AM
To: Rasul (LKKAuto)
Subject: FW: FBN5549D - 2nd before repair survey

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Danial Zhang <danialzhang@hlcorp.com.sg>
Sent: Friday, 22 February 2019 3:45 PM
To: SUR <sur@lkkauto.com>
Cc: chandramoorthi <chandramoorthi@hlcorp.com.sg>
Subject: FBN5549D - 2nd before repair survey

Hi Rasul,

We are awaiting for your confirmation email so that we may proceed with the ordering of the necessary parts. Your colleague came to our workshop to look on the check items on 18 Feb and said that you will get back to us through email. Kindly get back to us asap with thanks.

Thank you.

Regards,

Danial Zhang

Yamaha Division (Service Centre)

Tel: 6746 0415 (EXT. 122) | Fax: 6748 9238

Service HP (SMS Only): 9383 5711

E-mail: danialzhang@hlc corp.com.sg

bizSAFE₃

Disclaimer & Email Privacy Statement : This message, together with any attachment, is intended only for the use of the individual or entity to which it is addressed, and may contain information that is legally privileged and confidential. If you are not the intended recipient, please be informed that any dissemination, distribution or copying of this message, or any attachment thereto is strictly prohibited. Kindly note that email communications are not secure and therefore are susceptible to alteration. We will not accept any responsibility, legal or otherwise, for the contents of this message. If you have received this message in error, please advise the sender by reply e-mail, and delete the message. Thank you for your co-operation.

Disclaimer & Email Privacy Statement : This message, together with any attachment, is intended only for the use of the individual or entity to which it is addressed, and may contain information that is legally privileged and confidential. If you are not the intended recipient, please be informed that any dissemination, distribution or copying of this message, or any attachment thereto is strictly prohibited. Kindly note that email communications are not secure and therefore are susceptible to alteration. We will not accept any responsibility, legal or otherwise, for the contents of this message. If you have received this message in error, please advise the sender by reply e-mail, and delete the message. Thank you for your co-operation.

Disclaimer & Email Privacy Statement : This message, together with any attachment, is intended only for the use of the individual or entity to which it is addressed, and may contain information that is legally privileged and confidential. If you are not the intended recipient, please be informed that any dissemination, distribution or copying of this message, or any attachment thereto is strictly prohibited. Kindly note that email communications are not secure and therefore are susceptible to alteration. We will not accept any responsibility, legal or otherwise, for the contents of this message. If you have received this message in error, please advise the sender by reply e-mail, and delete the message. Thank you for your co-operation.

Disclaimer & Email Privacy Statement : This message, together with any attachment, is intended only for the use of the individual or entity to which it is addressed, and may contain information that is legally privileged and confidential. If you are not the intended recipient, please be informed that any dissemination, distribution or copying of this message, or any attachment thereto is strictly prohibited. Kindly note that email communications are not secure and therefore are susceptible to alteration. We will not accept any responsibility, legal or otherwise, for the contents of this message. If you have received this message in error, please advise the sender by reply e-mail, and delete the message. Thank you for your co-operation.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Jan 2019		24 Jan 2019 13:56 Edit Adj Rpt	S\$10,553.60 Edit Estimates	S\$10,553.60 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	LAW SOON KEAT, ID: S7824715J, Tel: +6591066011, Email: PHINEASLAW@GMAIL.COM								
Vehicle Reg. No.:	FBN5549D	Date of Loss:	13/01/2019 01:00 - :59 [2 Months and 14 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / CMTD1900511	Policy/Cover Note No.:	D18MTMC01006932 (Comprehensive)						
		Excess:	S\$1,250.00						
Repairer:	Hong Leong Corporation - Yamaha Division (HQ) 178 PAYA LEBAR ROAD #01-01, 409030 Paya Lebar - Tel:								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by HAN CHEUNG YONG BERNARD - 6322 4659]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 04/02/2019]								
Driver/Custodian:	LAW SOON KEAT (40 / Male), NRIC: S7824715J, Tel: +6591066011 Email: PHINEASLAW@GMAIL.COM								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
- SOMPO_SG (31/05/2019): Alert - Adj Mandate Approved (S\$10553.60) - FBN5549D - Claim Handler: HAN CHEUNG... - SOMPO_SG (28/01/2019): Alert - Adj Mandate Approved (S\$9487.55) - FBN5549D - Claim Handler: HAN CHEUNG ...									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FBN5549D (CMTD1900511)
 OD
 Jan 13 2019 1:00AM
 [LAW SOON KEAT]
 Hong Leong Corporation - Yamaha Division

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/01/19 16:08	Adjuster Immediate Advice	 Load HTM	☐
2	31/05/19 10:09	Adjuster Immediate Advice	 Load HTM	☐
Photos/Images			3 per page	☒
No	Relabel/ Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/01/19 10:33	General View	 Load JPG	☒
2	28/01/19 10:33	General View	 Load JPG	☒
3	28/01/19 10:33	General View	 Load JPG	☒
4	28/01/19 10:33	General View	 Load JPG	☒
5	28/01/19 10:33	General View	 Load JPG	☒
6	28/01/19 10:33	General View	 Load JPG	☒
7	28/01/19 10:33	General View	 Load JPG	☒
8	28/01/19 10:33	General View	 Load JPG	☒
9	28/01/19 10:33	General View	 Load JPG	☒
10	28/01/19 10:33	General View	 Load JPG	☒
11	28/01/19 10:33	General View	 Load JPG	☒
12	28/01/19 10:33	General View	 Load JPG	☒
13	28/01/19 10:33	General View	 Load JPG	☒
14	28/01/19 10:33	General View	 Load JPG	☒
15	28/01/19 10:33	General View	 Load JPG	☒
16	28/01/19 10:33	General View	 Load JPG	☒
17	28/01/19 10:33	General View	 Load JPG	☒
18	28/01/19 10:33	General View	 Load JPG	☒
19	28/01/19 10:33	General View	 Load JPG	☒
20	28/01/19 10:33	General View	 Load JPG	☒
21	28/01/19 10:33	General View	 Load JPG	☒
22	28/01/19 10:33	General View	 Load JPG	☒
23	28/01/19 10:33	General View	 Load JPG	☒
24	28/01/19 10:33	General View	 Load JPG	☒
25	28/01/19 10:33	General View	 Load JPG	☒
26	28/01/19 10:33	General View	 Load JPG	☒
27	28/01/19 10:33	General View	 Load JPG	☒
28	28/01/19 10:33	General View	 Load JPG	☒
29	28/01/19 10:33	General View	 Load JPG	☒
30	28/01/19 10:33	General View	 Load JPG	☒
31	28/01/19 10:33	General View	 Load JPG	☒
32	28/01/19 10:33	General View	 Load JPG	☒
33	28/01/19 10:33	General View	 Load JPG	☒
34	28/01/19 10:33	General View	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
35	28/01/19 10:33	General View	 Load JPG	☒
36	28/01/19 10:33	General View	 Load JPG	☒
37	28/01/19 10:33	General View	 Load JPG	☒
38	28/01/19 10:33	General View	 Load JPG	☒
39	28/01/19 10:33	General View	 Load JPG	☒
40	28/01/19 10:33	General View	 Load JPG	☒
41	28/01/19 10:33	General View	 Load JPG	☒
42	28/01/19 10:33	General View	 Load JPG	☒
43	28/01/19 10:33	General View	 Load JPG	☒
44	28/01/19 10:33	General View	 Load JPG	☒
45	28/01/19 10:33	General View	 Load JPG	☒
46	28/01/19 10:33	General View	 Load JPG	☒
47	28/01/19 10:33	General View	 Load JPG	☒
48	28/01/19 10:33	General View	 Load JPG	☒
49	28/01/19 10:33	General View	 Load JPG	☒
50	28/01/19 10:33	General View	 Load JPG	☒
51	28/01/19 10:33	General View	 Load JPG	☒
52	28/01/19 10:33	General View	 Load JPG	☒
53	28/01/19 10:33	General View	 Load JPG	☒
54	28/01/19 10:33	General View	 Load JPG	☒
55	28/01/19 10:33	General View	 Load JPG	☒
56	28/01/19 10:33	General View	 Load JPG	☒
57	28/01/19 10:33	General View	 Load JPG	☒
58	26/02/19 13:13	Reinspection Photo	 Load JPG	☒
59	26/02/19 13:13	Reinspection Photo	 Load JPG	☒
60	26/02/19 13:13	Reinspection Photo	 Load JPG	☒
61	26/02/19 13:13	Reinspection Photo	 Load JPG	☒
62	26/02/19 13:13	Reinspection Photo	 Load JPG	☒
63	26/02/19 13:13	Reinspection Photo	 Load JPG	☒
64	26/02/19 13:13	Reinspection Photo	 Load JPG	☒
65	26/02/19 13:13	Reinspection Photo	 Load JPG	☒
66	26/02/19 13:13	Reinspection Photo	 Load JPG	☒
67	26/02/19 13:13	Reinspection Photo	 Load JPG	☒
68	26/02/19 13:13	Reinspection Photo	 Load JPG	☒
69	26/02/19 13:13	Reinspection Photo	 Load JPG	☒
70	26/02/19 13:13	Reinspection Photo	 Load JPG	☒
71	26/02/19 13:13	Reinspection Photo	 Load JPG	☒
72	26/02/19 13:13	Reinspection Photo	 Load JPG	☒
73	26/02/19 13:13	Reinspection Photo	 Load JPG	☒
74	26/02/19 13:13	Reinspection Photo	 Load JPG	☒
75	26/02/19 13:13	Reinspection Photo	 Load JPG	☒
76	26/02/19 13:13	Reinspection Photo	 Load JPG	☒
77	26/02/19 13:13	Reinspection Photo	 Load JPG	☒
78	26/02/19 13:13	Reinspection Photo	 Load JPG	☒
79	26/02/19 13:13	Reinspection Photo	 Load JPG	☒
80	26/02/19 13:13	Reinspection Photo	 Load JPG	☒
81	26/02/19 13:13	Reinspection Photo	 Load JPG	☒
82	26/02/19 13:13	Reinspection Photo	 Load JPG	☒
83	26/02/19 13:13	Reinspection Photo	 Load JPG	☒
84	26/02/19 13:13	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
85	26/02/19 13:13	Reinspection Photo	 Load JPG	☒
86	26/02/19 13:13	Reinspection Photo	 Load JPG	☒
87	26/02/19 13:13	Reinspection Photo	 Load JPG	☒
88	26/02/19 13:13	Reinspection Photo	 Load JPG	☒
89	26/02/19 13:13	Reinspection Photo	 Load JPG	☒
90	26/02/19 13:13	Reinspection Photo	 Load JPG	☒
91	26/02/19 13:13	Reinspection Photo	 Load JPG	☒
92	26/02/19 13:13	Reinspection Photo	 Load JPG	☒
93	26/02/19 13:13	Reinspection Photo	 Load JPG	☒
94	26/02/19 13:13	Reinspection Photo	 Load JPG	☒
95	26/02/19 13:13	Reinspection Photo	 Load JPG	☒
96	26/02/19 13:13	Reinspection Photo	 Load JPG	☒
97	26/02/19 13:13	Reinspection Photo	 Load JPG	☒
98	26/02/19 13:13	Reinspection Photo	 Load JPG	☒
99	26/02/19 13:13	Reinspection Photo	 Load JPG	☒
100	26/02/19 13:13	Reinspection Photo	 Load JPG	☒
101	26/02/19 13:13	Reinspection Photo	 Load JPG	☒
102	26/02/19 13:13	Reinspection Photo	 Load JPG	☒
103	26/02/19 13:13	Reinspection Photo	 Load JPG	☒
104	26/02/19 13:13	Reinspection Photo	 Load JPG	☒
105	26/02/19 13:13	Reinspection Photo	 Load JPG	☒
106	26/02/19 13:13	Reinspection Photo	 Load JPG	☒
107	26/02/19 13:13	Reinspection Photo	 Load JPG	☒
108	26/02/19 13:13	Reinspection Photo	 Load JPG	☒
109	26/02/19 13:13	Reinspection Photo	 Load JPG	☒
110	26/02/19 13:13	Reinspection Photo	 Load JPG	☒
111	26/02/19 13:13	Reinspection Photo	 Load JPG	☒
112	26/02/19 13:13	Reinspection Photo	 Load JPG	☒
113	26/02/19 13:13	Reinspection Photo	 Load JPG	☒
114	26/02/19 13:13	Reinspection Photo	 Load JPG	☒
115	26/02/19 13:13	Reinspection Photo	 Load JPG	☒
116	26/02/19 13:13	Reinspection Photo	 Load JPG	☒
117	03/06/19 10:01	Reinspection Photo	 Load JPG	☒
118	03/06/19 10:01	Reinspection Photo	 Load JPG	☒
119	03/06/19 10:01	Reinspection Photo	 Load JPG	☒
120	03/06/19 10:01	Reinspection Photo	 Load JPG	☒
121	03/06/19 10:01	Reinspection Photo	 Load JPG	☒
122	03/06/19 10:01	Reinspection Photo	 Load JPG	☒
123	03/06/19 10:01	Reinspection Photo	 Load JPG	☒
124	03/06/19 10:01	Reinspection Photo	 Load JPG	☒
125	03/06/19 10:01	Reinspection Photo	 Load JPG	☒
126	03/06/19 10:01	Reinspection Photo	 Load JPG	☒
127	03/06/19 10:01	Reinspection Photo	 Load JPG	☒
128	03/06/19 10:01	Reinspection Photo	 Load JPG	☒
129	03/06/19 10:01	Reinspection Photo	 Load JPG	☒
130	03/06/19 10:01	Reinspection Photo	 Load JPG	☒
131	03/06/19 10:01	Reinspection Photo	 Load JPG	☒
132	03/06/19 10:01	Reinspection Photo	 Load JPG	☒
133	03/06/19 10:01	Reinspection Photo	 Load JPG	☒
134	03/06/19 10:01	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
135	03/06/19 10:01	Reinspection Photo	 Load JPG	☒
136	03/06/19 10:01	Reinspection Photo	 Load JPG	☒
137	03/06/19 10:01	Reinspection Photo	 Load JPG	☒
138	03/06/19 10:01	Reinspection Photo	 Load JPG	☒
139	03/06/19 10:01	Reinspection Photo	 Load JPG	☒
140	03/06/19 10:01	Reinspection Photo	 Load JPG	☒
141	03/06/19 10:01	Reinspection Photo	 Load JPG	☒
142	03/06/19 10:01	Reinspection Photo	 Load JPG	☒
143	03/06/19 10:01	Reinspection Photo	 Load JPG	☒
144	03/06/19 10:01	Reinspection Photo	 Load JPG	☒
145	03/06/19 10:01	Reinspection Photo	 Load JPG	☒
146	03/06/19 10:01	Reinspection Photo	 Load JPG	☒
147	03/06/19 10:01	Reinspection Photo	 Load JPG	☒
148	03/06/19 10:01	Reinspection Photo	 Load JPG	☒
149	03/06/19 10:01	Reinspection Photo	 Load JPG	☒
150	03/06/19 10:01	Reinspection Photo	 Load JPG	☒
151	03/06/19 10:01	Reinspection Photo	 Load JPG	☒
152	03/06/19 10:01	Reinspection Photo	 Load JPG	☒
153	03/06/19 10:01	Reinspection Photo	 Load JPG	☒
154	03/06/19 10:01	Reinspection Photo	 Load JPG	☒
155	03/06/19 10:01	Reinspection Photo	 Load JPG	☒
156	03/06/19 10:01	Reinspection Photo	 Load JPG	☒
157	03/06/19 10:01	Reinspection Photo	 Load JPG	☒
158	03/06/19 10:01	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	22/01/19 17:10	Certificate Schedule	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/02/19 13:17	SUPPLEMENTARY	 Load PDF	
2	31/05/19 11:21	SUPPLEMENTARY MARKING	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Puan Chew Motor Work Pte Ltd (Pandan)	Thumbnail	Print
1	22/01/19 15:23	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Puan Chew Motor Work Pte Ltd (Pandan)	Thumbnail	Print
1	22/01/19 13:41	Accident Photo	 Load JPG	☒
2	22/01/19 15:20	Accident Photo	 Load JPG	☒
3	22/01/19 15:20	Accident Photo	 Load JPG	☒
4	22/01/19 15:20	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Puan Chew Motor Work Pte Ltd (Pandan)	Thumbnail	Print
1	22/01/19 13:40	Sketch Plan	 Load TIFF	
2	22/01/19 13:40	Sketch Plan #2	 Load TIFF	
3	22/01/19 13:41	IC & DRIVING LICENSE	 Load TIFF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Sompo Insurance Singapore Pte. Ltd.
50 Raffles Place, #05-01/06, Singapore Land Tower
Singapore 048623

Our File No: CS/SMO19001621/R1VD3E2

Date: 11/06/2019

REFERENCE

Insured/Claimant: LAW SOON KEAT Policy No: D18MTMC01006932
Date of Loss: 13/01/2019 Nature of Claim: OD Claim No: CMTD1900511

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBN5549D**
Make & Model: YAMAHA MTM850A (XSR900), 847cc Engine No: LTA1901971
Reg. Date: 30/10/2018 (Man. Year: 2017) Chassis No: JYARN43P000001026
Colour: Black Odometer: 0 km
Engine Capacity: 847 cc
Market Value/New Car Price: S\$21,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/70Z R17 Rear Tyre Size: 180/55Z R17
Front Left Side: Bridgestone 4 mm Rear Left Side: Bridgestone 4 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,174.40	6,893.60	280.80	3.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,620.00	3,660.00	960.00	20.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,794.40	10,553.60	1,240.80	10.52
- Excess (S\$)	1,250.00	1,250.00	0.00	0.00
(S\$)	10,544.40	9,303.60	1,240.80	11.77
+ GST 7.00/7.00% (S\$)	738.11	651.25	86.86	11.77
Nett Amount (S\$)	11,282.51	9,954.85	1,327.66	11.77

INSPECTION

Date of Assignment: 24/01/2019
Date Inspected: 24/01/2019 Inspected At:

Hong Leong Corporation - Yamaha
Division (HQ)
178 PAYA LEBAR ROAD #01-01
Singapore 409030

Estimated Period of Repair: 10.0 days

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 10 Jun 2019)	
Parts:	N/A	YAMAHA MTM850A (XSR900) 847cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBN5549D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*GASKET HEAD COVER	Necessary	13.00 FL	*13.00 FL
2	1		*GASKET CYLINDER HEAD	Necessary	36.00 FL	*36.00 FL
3	8		*PLANE BEARING CRANKSHAFT (00)	Serviceable	56.00 FL	*- FL
4	1		*PLANE BEARING CRANKSHAFT (10) (8PCS)	Necessary-4pc only	56.00 FL	*28.00 FL
5	8		*PLANE BEARING CRANKSHAFT (20)	Serviceable	56.00 FL	*- FL
6	8		*PLANE BEARING CRANKSHAFT (30)	Serviceable	56.00 FL	*- FL
7	8		*PLANE BEARING CRANKSHAFT (40)	Serviceable	56.00 FL	*- FL
8	4		*METAL BALANCE WEIGHT (00)	Serviceable	20.00 FL	*- FL
9	4		*METAL BALANCE WEIGHT (10)	Cut	20.00 FL	*20.00 FL
10	4		*METAL BALANCE WEIGHT (20)	Cut	20.00 FL	*20.00 FL
11	4		*METAL BALANCE WEIGHT (30)	Serviceable	20.00 FL	*- FL
12	4		*METAL BALANCE WEIGHT (40)	Serviceable	20.00 FL	*- FL
13	1		*GASKET TENSIONER CASE	Necessary	3.00 FL	*3.00 FL
14	1		*O-RING	Necessary	1.00 FL	*1.00 FL
15	1		*O-RING	Necessary	2.00 FL	*2.00 FL
16	1		*O-RING	Necessary	6.00 FL	*6.00 FL
17	1		*O-RING	Necessary	2.00 FL	*2.00 FL
18	1		*O-RING	Necessary	1.00 FL	*1.00 FL
19	1		*O-RING	Necessary	6.00 FL	*6.00 FL
20	1		*GASKET STRAINER COVER	Necessary	15.00 FL	*15.00 FL
21	1		*STRAINER COVER ASSY	Broken	15.00 FL	*15.00 FL
22	1		*OIL FILTER	Necessary	15.00 FL	*15.00 FL
23	1		*CRANKCASE ASSY	Cracked	2,200.00 FL	*2,200.00 FL
24	2		*O-RING (16325)	Necessary	2.00 FL	*2.00 FL
25	1		*O-RING (14369)	Necessary	1.00 FL	*1.00 FL
26	4		*BOLT, CRANKCASE JOURNAL	Necessary	20.00 FL	*20.00 FL
27	6		*BOLT WITH WASHER (13)	Necessary	42.00 FL	*42.00 FL
28	2		*BOLT WITH WASHER (10)	Necessary	16.00 FL	*16.00 FL
29	1		*BOLT FLANGE	Necessary	1.00 FL	*1.00 FL
30	1		*BOLT FLANGE	Necessary	1.00 FL	*1.00 FL
31	1		*GAUGE LEVEL	Necessary	10.00 FL	*10.00 FL
32	1		*GASKET CRANKCASE COVER 2	Necessary	14.00 FL	*14.00 FL
33	1		*GASKET OIL PUMP COVER	Necessary	6.00 FL	*6.00 FL
34	1		*GASKET CRANKCASE COVER 1	Necessary	12.00 FL	*12.00 FL
35	1		*O-RING	Necessary	1.00 FL	*1.00 FL
36	1		*O-RING	Necessary	6.00 FL	*6.00 FL
37	2		*BOLT HEXAGON SOCKET HEAD	Necessary	4.00 FL	*4.00 FL
38	2		*BOLT HEXAGON SOCKET HEAD	Necessary	3.00 FL	*3.00 FL
39	1		*BOLT BUTTON HEAD	Necessary	1.00 FL	*1.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	3		*SCREW	Necessary	3.00 FL	*3.00 FL
41	1		*OIL SEAL	Necessary	10.00 FL	*10.00 FL
42	1		*OIL SEAL	Necessary	2.00 FL	*2.00 FL
43	1		*BEARING	Necessary	7.00 FL	*7.00 FL
44	1		*STOPPER SCREW	Necessary	5.00 FL	*5.00 FL
45	1		*ROTOR ASSY	Bent	180.00 FL	*180.00 FL
46	1		*STATOR ASSY	Bent	250.00 FL	*250.00 FL
47	3		*BOLT	Necessary	18.00 FL	*18.00 FL
48	1		*LEVER 1	Necessary	18.00 FL	*18.00 FL
49	1		*HANDLEBAR	Bent	120.00 FL	*120.00 FL
50	1		*SHIFT PEDAL ASSY	Scratched	59.00 FL	*59.00 FL
51	1		*CAST WHEEL FRONT	Cracked	450.00 FL	*450.00 FL
52	2		*BEARING	Necessary	18.00 FL	*18.00 FL
53	2		*OIL SEAL	Necessary	8.00 FL	*8.00 FL
54	1		*FRONT FOOTREST ASSY (LHS)	Bent	39.00 FL	*39.00 FL
55	1		*REAR ARM COMP	Scratched	950.00 FL	*950.00 FL
56	3		*BEARING	Necessary	40.50 FL	*40.50 FL
57	2		*OIL SEAL (33004)	Necessary	10.00 FL	*10.00 FL
58	2		*OIL SEAL (22002)	Necessary	10.00 FL	*10.00 FL
59	1		*STRAINER HOUSING ASSY	Cracked	20.00 FL	*20.00 FL
60	1		*O-RING (22001)	Necessary	1.00 FL	*1.00 FL
61	1		*MUFFLER ASSY	Bent	1,100.00 FL	*1,100.00 FL
62	1		*PLUG, STRAIGHT SCREW	Necessary	15.00 FL	*15.00 FL
63	1		*GEAR IDLER	Cut	45.00 FL	*45.00 FL
64	1		*STARTER ONE WAY ASSY	Cut	72.00 FL	*72.00 FL
65	1		*GEAR 3	Cut	70.00 FL	*70.00 FL
66	1		*END GRIP	Scratched	10.00 FL	*10.00 FL
67	1		*GRIP (LHS)	Cut	7.50 FL	*7.50 FL
68	1		*OIL LEVEL GAUGE ASSY	Cut	50.00 FL	*50.00 FL
69	2		*BOLT FLANGE	Necessary	2.00 FL	*2.00 FL
70	1		*DRIVE-CHAIN (DID525V-110LL)	Cut	190.00 FL	*190.00 FL
71	1		*COOLANT	Necessary	25.00 FS	*25.00 FS
72	1		*ENGINE OIL	Necessary	91.80 FS	*91.80 FS
73	1		*VITAS INSPECTION	Necessary	69.00 FS	*69.00 FS
74	1		*LTA DOCUMENTATION	Necessary	100.00 FS	*100.00 FS
75	1		*FRONT FORK (LH)	Scratched	680.00 FL	*680.00 FL
76	1		*O-RING (21001)	Necessary	0.80 FL	*0.80 FL
77	1		*O-RING (15566)	Necessary	1.20 FL	*1.20 FL
78	1		*MOTOR ASSY	Cut	265.00 FL	*265.00 FL
79	6		*BOLT CONNECTING ROD	Necessary	12.00 FL	*12.00 FL
80	1		*COVER CRANKCASE 1	Cracked	80.00 FL	*80.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc

Sub Total (S\$)	7,939.80	7,627.80
- List Item Discount on L Items 10.00/10.00% (S\$)	765.40	734.20
Total Parts (S\$)	7,174.40	6,893.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR - FORK ALIGNMENT	New	120.00	60.00
2	LABOUR - REPLACE ENGINE CRANKCASE ASSY & ACCIDENT PARTS	New	4,500.00	3,600.00
Gross Labour Cost (S\$)			4,620.00	3,660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >