

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE***

VEHICLE NO : SHA 3550J (Supplementary)



DATE : 28.01.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Engine Crossmember <i>distorted</i>			\$ 2,094.40
	Engine Oil Filter Housing <i>Down</i>			\$ 688.00
	Engine Oil - 6 Litres <i>Leaky 1mlc</i>			\$ 300.00 120.00
	SUB TOTAL		2902.40	\$ 3,082.40
	LESS 20%		2321.92	\$ 616.48
	DISCOUNTED TOTAL			\$ 2,465.92
	<div>28/01/2019</div> <div></div> <div>L Kk And</div> <div></div>			
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				