Surveyor:	2		9001632/ Als	302 Special I	ostruction:	
12	8itham	ASSIGN	MENT (Office)	Date	Time 517pm 24	lilia
Estimated Co.	st		Bill to:	Lieuz	Time 31 17.16) 2 1	7
To Inspect Ve	strick No:	ES/EVA/INV/MY		Insured-	8HC 7121C	
at Workshop 1	m/s	Kah r	10for		072 1769	7
of		255 Alex	rundru Road			
Policy No:			Claim No:	0000	672MFSH	
Sum Insured:			Excess:			
Make of Veh: (Client's Record)		7	D.O.	24/01/2019	
CA / REV /	REP. / REV 241	IRS up		11.0	11 149 D. Endorsement:	
Date/Time:	5.23pm@24/11	Person Contacte	d Sintai	Vehicle	TUO(M	
Date/Time	Action/Instruction	(V) Estima				
	SLGQ70	15B-X		10 1		
		- CSIFCI 190	00669/Asd	3	DOA: 8/1	Ta
		direct morning			10011.011	
28/01/19	@ 15:20					

-

ASSIGNMENT

Covies	Date	Veh No	SUG 9795B	Yr Regn 2	016 00	_
From Estimated Cost.	Date	1 10 11 11 11 11	M.Gycle / Bus / Van / L			
OD/Pyws/TPRES/O	DD RES / EVA / INV / MV		Trailer or			
To Inspect Vehicle No:	SL4 9795B	Make:	HONDA CITY	1.5 UTEL 0	. 1497	
	4 morus	Colour	Maroon		ed / Std / NI / NA	4
	1 RS 228	Sp.Reading	106758		ed / Std / NI / NA	4
Insured	Fel	Eng/No:				
Policy No.		Č/No:	MR46M 666	OH Povo 2	62	
Claims No.		Gen. Cond: Go	ood / Tan Poor / Burr	nt		
Sum Insured:	Excess	Steering; Irrorg	Pr / Jammed / Leaked	I / Burnt or	•	
(Client's Record)		Brake: nord	ler / Jammed / Leaked	I/Burnt or		
Make of Veh:		Modi: Nil /	SRM / STD A/Rim	or		
		Tyre Size:	F: 18	5/55R16		
(Policy Condition)			R:			
Remark: The veh had con	nmenced its N/S O	BS / DUN / EX	NOVA / GY / FS / LIZA	/ MIC / OHTSU / P	IR / SUMI /	
repair at the tim	e of inspection.	TOYOIXOK	or or			
Bal. or Market Value:		Front		Rear		
IDAC Accident Rport:	Consistent? : Yes or No	R/Bal.	S mm	R/Bal.	S m	m
GIA / PR Seen:	Consistent? ; Yes or No	L/Bal.	5 mm			m
Est. Repairs:	days Res.: Yes or No	D.O.A. 24	101/19	D.O.I. 25	101/19	
Lum Sum:	% 3 Val.: Yes or No	Survey held at		MOTOR		
CA / BEV / BEB /	24 HRS	Des. of Damag	ges : Frt / Rea / O/S	I N/S / U/C / Re	ooftop or	
CA / REV / REP. /	Vehicle: IN / 0	AND LABOUR TO	C			
Date: Per	rson Contacted:	The U/C /	Chassis frame / Bo	dy Structure affect	ed due to collisio	on.
	Instruction Med P/P \$ 17,884 5,111.70 Red - RECEI	4.72 @ / 22%) VED 14 MAR		jth Ras	13/3/ m/	to 20.
Date/Time, File Pass to? 1/4/03/19 Tya:c4	: Preli. Report	Days Of Rep Resurvey No		Survey Fee:	12×15= 13	- Address
Date/Time Pile Return to?				Transportation	50	
2)	Add		rsp (\$) _s+Rs _s	1.4	
	2.	-	ew (\$	Photos 089	NJC 89	
Report Format :	17,884.72 8/	-	invs (\$) chelle /4	145	
Lump Sum / I.B.I; (\$	17,884.72	Weak	end is) 22		-
				TOTAL	539	1



MS First Capital Insurance Limited Co.Reg. No. 195000106C GST Reg. No. M2-0001676-9 6 Raffles Quay #21-00 Singapore 048580 Tel: (65) 6222 2311 Fax: (65) 6222 3547

Claims & Motor Underwriting Dept: 36 Robinson Road #16-01 City House Singapore 068877 Tel: (65) 6507 3848 Fax: (65) 6507 3849

www.msfirstcapital.com.sg

MOTOR SURVEY ASSIGNMENT

Date

24-01-2019

Our Ref No. D19000672MFSH

Accident Date

24-01-2019

Claim Type. Third Party

Insured Vehicle

SHC7121C

Third Party Vehicle. SLG9795B

Survey Location

BODY REPAIR & PAINT CENTRE 255 ALEXANDRA ROAD

Contact Person.

NG SIN HAI

Contact No.

64715419/90721769

Fax No. 0

Survey Type

WITHOUT PREJUDICE:

Appointed

Surveyor

LKK AUTO CONSULTANTS PTE LTD

Contact Person

NA

Fax No. 68416315

Contact Number.

NA

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc: Workshop

KAH MOTOR CO. SDN.

Attention, NIL

Cc: TP Solicitor

BHD. NA

TP Solicitor Fax No. NA

Officer Incharge

SITHARA

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection. This is a computer generated letter, no signature required.

Shirley Hiew (LKK Auto)

From:

Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Sent:

Thursday, 14 March 2019 10:17 AM

To:

'Ng Sin Hai'

Cc:

Rasul (LKKAuto); SUR

Subject:

RE: Submission Pre-Invoice for vehicle SLG9795B

Dear Sin Hai,

Confirmed final fig \$17,884.72 (part by part) @ 17 days of repairs before GST.

Final invoice and all supporting documents sent over to First Capital Ins Ltd.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>Sur@lkkauto.com</u> | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Ng Sin Hai [mailto:shng@kahmotor.onmicrosoft.com]

Sent: Wednesday, 13 February 2019 4:53 PM

To: Rasul (LKK Auto) < Rasul@lkkauto.com>; SUR < sur@lkkauto.com>

Subject: RE: Submission Pre-Invoice for vehicle SLG9795B

Dear Rasul,

Kindly refer to the attached pdf for the pre-invoice final repair cost amount for abovementioned vehicle .

Cost of repair: \$17,884.72 (before GST) No of working days: 17 days. (LOR)

We will proceed for closing after 1 week of submission to you.

Kindly contact me if there is any discrepancy.

Thank you and have a nice day, ©

Warmest Regards,

Ng Sin Hai

Kah Motor Co. Sdn. Bhd

(A member of Oriental Holdings Berhad)

Body Repair & Paint Centre

255 Alexandra Road

Singapore 159937

DID: 6471 5419

HP: 9072 1769

· E-mail: shng@honda.com.sg



Please consider the environment before printing this email

CONFIDENTIAL NOTE: The Information contained in the e-mail is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable low. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you for your collaboration.

Veron Chen (LKKAuto)

From:

Ng Sin Hai <shng@kahmotor.onmicrosoft.com>

Sent:

Wednesday, 13 February 2019 4:53 PM

To:

Rasul (LKKAuto); SUR

Subject:

RE: Submission Pre-Invoice for vehicle SLG9795B

Attachments:

1456_001.pdf; 020.jpg; 021.jpg; 022.jpg; 023.jpg; 024.jpg; 025.jpg; 026.jpg; 027.jpg; 028.jpg; 029.jpg; 001.jpg; 002.jpg; 003.jpg; 004.jpg; 005.jpg; 006.jpg; 007.jpg; 008.jpg; 009.jpg; 010.jpg; 011.jpg; 012.jpg; 013.jpg; 014.jpg; 015.jpg;

016.jpg; 017.jpg; 018.jpg; 019.jpg

Dear Rasul,

Kindly refer to the attached pdf for the pre-invoice final repair cost amount for abovementioned vehicle .

Cost of repair: \$17,884.72 (before GST) No of working days: 17 days. (LOR)

We will proceed for closing after 1 week of submission to you. Kindly contact me if there is any discrepancy.

Thank you and have a nice day, @

Warmest Regards,

Ng Sin Hai

Kah Motor Co. Sdn. Bhd

(A member of Oriental Holdings Berhad)

Body Repair & Paint Centre

255 Alexandra Road

Singapore 159937

DID: 6471 5419

HP: 9072 1769

E-mail: shng@honda.com.sg



Please consider the environment before printing this email

CONFIDENTIAL NOTE: The Information contained in the e-mail is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable low. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you for your collaboration.

Shirley Hiew (LKK Auto)

From:

Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Sent:

Monday, 28 January 2019 3:20 PM

To:

'Sithara'; 'CWS Motor Claims'

Cc:

SUR; Admin-D (LKKAuto); assignments

Subject:

RE: SURVEY ASSESSMENT - D19000672MFSH/1

Attachments:

SLG 9795B - Preli Advise -.pdf

Dear Sithara,

Enclosed herewith preliminary advice of SLG 9795B.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>Sur@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]

Sent: Thursday, 24 January 2019 5:37 PM

To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>

Cc: 'Sithara' <Sithara@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>

Subject: RE: SURVEY ASSESSMENT - D19000672MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed repairer agreed survey on 25/01/2019.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]

Sent: Thursday, 24 January 2019 5:17 PM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWS Motor Claims < cwsmotorclaims@msfirstcapital.com.sg>; Sithara < Sithara@msfirstcapital.com.sg>

Subject: PRI: SURVEY ASSESSMENT - D19000672MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards, Admin Team Claim Workflow System Motor Claims Department MS First Capital Insurance Limited

Tel: 6507 3848 Fax: 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

This email has been checked for viruses by AVG antivirus software.
www.avg.com



51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: D19000672MFSH

Date: 28 January 2019

Our Ref: CS/FCI19001632/R1sd3

The Motor Claims Department First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLG 9795B .

Please be informed that we had conducted the inspection of the abovementioned vehicle on <u>25/01/2019</u> at the premises of M/s <u>Kah Motor Co. Sdn. Bhd.</u> and have the following to report:-

Workshop Estimate Amount	: <u>S</u> \$	22,443.39	
Revised Estimate Amount	: S\$	17,263.05	1.
"Check" Items Amount	: S\$	364.88	
Market Value	: S\$		
LTA Reimbursement Value	: S\$		7.
Nett Value	: <u>S</u> \$		

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages Consistent. Repair days: 17 Days

Yours faithfully, Mohammed Rasul Automotive Assessor MKM119011487 / Kah Motor Co Sdn Bhd - Ubi ENTRY DATE & TIME: 24/01/2019 11:23 SUBMITTED BY: NG SIN HAI

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

By the lodgement of this report to the insurers, you aforesaid.	ou hereby consent to the archiving of this report at the centre and to copies of the report bei	ng made available
	ACCIDENT STATEMENT	
Date Of Report	24/01/2019 11:23	
Date Of Accident	24/01/2019 09:20	
Exact Location Of Accident	LENTOR AVE	
Country/State of Loss	SINGAPORE	
	DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLG9795B	
Insured/Policyholder		
Name Of Registered Owner	GOI WAY SERN JONATHAN	
NRIC No	S8137002H	
Email Address	NOEMAIL	

(LOCAL) +65-98459542

OFFICE-98459542

Alternative Phone No. Vehicle Particulars

Mobile Phone No

Manufacturer HONDA

Model CITY-1.5 VTEC (A)

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

PRIVATE CAR

Insurance Company

Name of Insurance Company

LIBERTY INSURANCE PTE LTD

Type Of Coverage

COMPREHENSIVE

Fleet Policy

NO

Policy Number

Cover Note Number

Driver

Name of Driver GOI WAY SERN JONATHAN

NRIC No S8137002H Date Of Birth 22/11/1981 Occupation **INDOOR** Date Of Driving Pass 17/01/2005

14 YEARS AND 0 MONTHS **Driving Experience**

Gender

MALE

Mobile Number

(LOCAL) +65-98459542

Fax Number

Contact Number

OFFICE-98459542

EMail Address

NOEMAIL

Address SIN

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own
Vehicle Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle)

involved in the accident

Was any body injured in the Accident?

Was any injured conveyed to hospital by

ambulance?

Was any other material or property damaged?

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

Number of Passengers (Including Driver)

Details of Police Action

Was the accident reported to the police?

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

If Yes, against whom?

Circumstances of Accident

REFER

Attachment(s)

Are accident photos available for attachment?

YES

2

NO

NO

YES

NO

1

NO

NO

Was there any video captured by Car Camera?

YES

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SHC7121C

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

TAXI

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Vehicle No	SKETC	HPLAN	Annex D
IMPORTANT NOTICE			
1. Please report correctly the	details of the accident to speed up the	claims process.	
2. This Formmust be complete	ed by the Policyholder and/or the A	Authorised Driver.	
allow insurance companies to g	enudiate policy liability.		ntation or withholding of material facts may
companies.	this Form by insurance companies is n		ability on the part of the insurance
	of referred to the Police for Investi		120
of Singapore (GIA) for archiving	and that copies of this report will for a	a fee be made available upo	[1] [2] [2] [1] [2] [2] [2] [2] [2] [2] [2] [2] [2] [2
report being made available afor		to the archiving of this repo	ort at the centre and to copies of the
	nal Data Protection Act (PDPA)		
Lunderstand, acknowledge, agn			The second secon
and/or process my personal dat possessed by my insurer (collect who have insured vehicle(s) inv collectively referred to as the "In government agency/authority (si	volved in this accident (all insurer(s) with neurons"), the insurers law yers/law fouch as the police), for the purposo(s) of	orm) and any other persona and disclose and transfer so to tuve insured vehicle(s) firms, the Monetary Authorit of:	al information provided by me or such Personal Information to all insurer(s) involved in this accident shall be ity of Singapore and any relevant
the claims;		flement of the claims and an	ny necessary investigations relating to
(ii) investigating the accident and		A CONTRACTOR OF THE PARTY	
	rith my instructions or responding to an	Maria Control of the	the many subleds and definitions
disclosure of certain personal de packages); and/or	ata about me to bring about delivery of	the same as well as on the	
	v in administering, processing, handling	g and/or dealing with my cla	sims.
(collectively the "Purposes")	to the applicant	The second second second	the collection of the collection
use, disclose and/or process my	Personal Information for one or more of	of the above Purposes; and	The representation of the contract of the cont
(c) my Personal Information may/	can be disclosed by any of the insurer s), which may be siled outside of Sings	rs and/or GIA to their third p	party service providers or agents
0			
(),			
6N			\umathcaller \lambda
V.			XIIQ I .
Policyholder's Signature / Date &		the policyholder) / Date	Witnessed by Reporting Centre
Time	& Time	A. Carlotte and Ca	Personnel
Sketch Plan			
111111111111111111111111111111111111111	14-4-1-4-1-4-1-4-1-4-1-4-1-4-1-4-1-4-1-	4111111	

	No		ha Aastu							Annex E
I	Was	trai	re ling	along	Lent	or	Ave	turning	isto	Vishun A
	was	watting	for	ONCOMI	ng tra	ffic	to	clear	at	the slip
Poka	1, "	elircle	B	couldn't	stop	w	time	o and	4:4	· nto
the	real	of	my.	vehicle	A.	_				
										T
		-								
0 00000										
							-	The second		
					-			-		
			-4-							
			7		T-1		-		-	
nt that you	wish to cl	by the work: alm against	your own	policy	- AND THE REAL PROPERTY.	-		-		K Grand La
		Fourteen (1 must be ma					- 14			
ipuleted ti	meframe (rom the day	of occurre	nce.						
laration										
declare the	foregoing (porticulars ar	e true in ev	ery respect.						
1									125	
Mr.								MY	1	
U	gnature / Da			ture (I driver is n			-	Mnossed by	1	

REPUBLIC OF SINGAPORE IDENTITY CARD NO. S8137002H



GOI WAY SERN, JONATHAN (NI WEISHENG, JONATHAN)

化维胜 CHINESE Date of term. Sex 22-11-1981 M

SINGAPORE






06-12-2011

APT BLK 541 JURONG WEST AVENUE 1 #04-1046 SINGAPORE 540541

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSIES!





Liberty Insurance Pte Ltd Registration no. 199002791D 51 Club Street 30-00 Liberty House Singapore 069428 Tel: (65) 6221 8611 Fac: (65) 6225 6890

CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189) MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960 ROAD TRANSPORT ACT, 1987 (MALAYSIA)

MOTOR VEHICLES (THIRD-F	PARTY RISKS) RULES, 1959 (MALAYSIA)
Certificate No	SD16V13898 /VPC2 /R00
Form	MX1
Date of Issue	25-OCT-2016
1.Index Mark and Registration No. of Vehicle:	SLG9795B
2.Chassis number of Vehicle:	MRHGM6560HP000262
3.Name of Policyholder:	GOI WAY SERN, JONATHAN (NI WEISHENG, JONATHAN)
4.Effective date of Commancement of Insurance for the purposes of the Act:	20-OCT-2016 00:00 AM
5.Date of Expiry of Insurance:	19-OCT-2018 23:59 PM
6.Persons or Classes of Persons entitled to drive*:	

A) The Policyholder.

B) Any other person who is driving on the Policyholder's order or with his permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.

7.Limitations as to use*:

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

8. The Policy does not cover:

A) Use for hire or reward.

B) Use for racing, pace-making, reliability trials or speed-testing.

C) Use for the carriage of goods (other than samples) in connection with any trade or business.
 D) Use for any purpose in connection with the Motor Trade.

*Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia) are not to be included under these headings.

I/We hereby certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

For and on behalf of LIBERTY INSURANCE PTE LTD Approved Insurers

Authorised Signature

For Information only:

COVERAGE:

Comprehensive, Unlimited Windscreen, Ncd Protection

SUM INSURED:

MARKET VALUE AT THE TIME OF LOSS

EXCESS:

Section I S\$600,Additional Excess For Young, Elderly & Inexperienced Drivers S\$3000,Windscreen

Excess S\$100

FINANCE COMPANY:

PRODUCER NAME:

KAH MOTOR COMPANY SDN BERHAD

PLST/PLST/26-OCT-16

S1_CI_T1_T3_OE_Template2-Ver1.

26-OCT-16



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Customer

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Document No. : SQT19000428 Page

NOITATOUG

Company Ref. No.: S60FC1380G

GST Reg No.: M200050223

36 ROBINSON ROAD Date : 24. Jan 2019 #16-01 CITY HOUSE Customer No. : WZF002

SINGAPORE 068877 Svc Advisor

Registration No : SLG9795B Engine No

: L15Z14112422 Chassis No : MRHGM6660HP000262 Date | Time : 24. Jan 2019 11:58:00 AM

Model : CITY 1.5SV CVT 2017 Surveyor Name

Owner's Name : GOI WAY SERN, JONATHAN Survey Date

Ins Policy No. Authorisation Date : Date of Accident : 24/1/2019

0% GST Amount Amount Amount incld GST Item Description Qty Unit Price Disc %

TP DIRECT SETTLEMENT (J/NO:)

OWNER:

: MS FIRST CAPITAL INSURANCE

OWNER INSURER:

ACC DATE:

SURVEYED BY:

DATE: REF NO:

TP INSURER

	IP INSURER:						
	TP VEH:						
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N)	1	45.00		45.00	3.15	48.15
68500-T9A-T30ZZ	LID COMPTRUNK	1	457.80 M	25	343.35	24.03	367.38
68610-T9A-T00ZZ	HINGE COMPR.TRUNK	1	69.90 7.	25	52.42	3.67	56.09
68660-T9A-T00ZZ	HINGE COMPL.TRUNK	1	69.90 ? (75	25	52.42	3.67	56.09
74851-T2A-003	LOCK ASSYTRUNK	1	92.60 64	25	69.45	4.86	74.31
74862-T2A-003	STRIKERTRUNK LID	1	9.80 7	25	7.35	0.51	7.86
74865-T9A-T01	WEATHERSTRIPTRUNK LID	1	73.70 1	25	55.27	3.87	59.14
74880-T9A-T01	CABLETRUNK OPENER	1	13.10 7 / 9	25	9.82	0.69	10.51
74890-T9A-T11	GARNISH ASSYRR.LICENSE	1	63.80 7.	25	47.85	3.35	51.20
84631-T9P-J00ZA	LINING ASSYTRUNK LID	1	99.70 7	25	74.77	5.23	80.00
90667-SDA-A01ZA	CLIPTRIM	23.3012	2.40× AA	25	21.60	1.51	23.11
75701-T9A-000	EMBLEM H	1	11.30 1	25	8.47	0.59	9.06
75722-T9A-T00	EMBLEMRR.CITY	1	11.60 M	25	8.70	0.61	9.31
75725-T9A-T00	EMBLEMRR.I-VTEC	1	12.20me	25	9.15	0.64	9.79
33500-T9A-T01	TAILLIGHT ASSYR.	1	205.70	25	154.27	10.80	165.07
33550-T9A-T01	TAILLIGHT ASSYL.	1	205.70 04/	25	154.27	10.80	165.07
34150-T9A-T01	LIGHT ASSY,R.LID	1	74.90 CM/	25	56.17	3.93	60.10
34155-T9A-T01	LIGHT ASSYL.LID	1	74.90 04/	25	56.17	3.93	60.10
90650-T2A-003	CLIPRR.COMBINATION LIGHT	5.20 2	2.60 - 1	25	3.90	0.27	4.17
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR	1	320.00 M		320.00	22.40	342.40
71501-T9A-T00ZZ	FACERR.BUMPER	1	463.70	25	347.77	24.34	372.11



QUOTATION

GST Reg No.: M200050223

Page

2

Company Ref. No.: S60FC1380G

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

: MS FIRST CAPITAL INSURANCE Customer

36 ROBINSON ROAD

#16-01 CITY HOUSE

SINGAPORE 068877

Registration No : SLG9795B

Chassis No : MRHGM6660HP000262

Model

: CITY 1.5SV CVT 2017

Owner's Name Ins Policy No. Date of Accident

: GOI WAY SERN, JONATHAN

: 24/1/2019

Date : 24. Jan 2019

: SQT19000428

: WZF002

Customer No. Svc Advisor

Document No.

Engine No : L15Z14112422

: 24. Jan 2019 11:58:00 AM Date | Time

Surveyor Name Survey Date

Authorisation Date :

Item	Description	Qtv	Unit Price Disc %	Amount	0% GST Amount	Amount incld GST
33505-T9A-T01	REFLECTOR ASSYR.RR.	1	15.10 ? 25	11.32	0.79	12.11
33555-T9A-T01	REFLECTOR ASSYL.RR.	1	15.10 CA / 25	11.32	0.79	12.11
71503-T9A-T00	COVERRR.BUMPER EX.PIPE	1	9.80X 1 25	7.35	0.51	7.86
71593-T9A-J00	SPACER R.RR.BUMPER SIDE	1	11.50 4 25	8.62	0.60	9.22
71598-T9A-J00	SPACERL.RR.BUMPER SIDE	1	11.50 m 25	8.62	0.60	9.22
91505-TM8-003	CLIP,BUMPER 9.1	4	2.30 1 25	6.90	0.48	7.38
66100-T9A-T50ZZ	PANEL COMPRR.	1	333.60 7 25	250.20	17.51	267.71
84521-T9A-T10	LID COMPSPARE TIRE	1	45.00 CM 25	33.75	2.36	36.11
84630-T9A-T10ZA	MATTRUNK FLOOR	1	19.40 7 XM25	14.55	1.02	15.57
84640-T9A-T01ZA	LINING ASSYRR.PANEL	1	66.60 DE / 25	49.95	3.50	53.45
38387-TZ5-A01	ANTENNA ASSYL.F.	1	59.30 2. Ch 25	44.47	3.11	47.58
74940-SZW-003	BUZZER ASSYSMART	1	61.30 ? CA 25	45.97	3.22	49.19
73127-TY0-000	RUBBER CWINDSHIELD DAMPER	03	11.40 14 125	25.65	1.80	27.45
73227-T9A-T00	RUBBER CWINDSHIELD DAMPER	1	17.80 - 25	13.35	0.93	14.28
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00 ~~	120.00	8.40	128.40
04636-T9A-T00ZZ	PANEL SETR.RR.OUTSIDE	1	1168.80 7 25	876.60	61.36	937.96
04646-T9A-T00ZZ	PANEL SETL.RR.OUTSIDE	1	1168.80 1 / 25	876.60	61.36	937.96
	floor paul - pur		Sum Item	4303.39	301.19	4,604.58
BOSUN	SUNDRIES	1	100.00 50	100.00	7.00	107.00
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	180.00	180.00	12.60	192.60
BOBC	BODY UNDERSIDE COATING (N)	1	450.00	450.00	31.50	481.50
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	180.00	180.00	12.60	192.60
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	450.00	450.00	31.50	481.50
BOMISC1	REMOVE, INSTALL & RESET REAR VIEW CAMERA.(N)	1	560.00	560.00	39.20	599.20
BOMISC1	RESET SMART ENTRY SYSTEM AND REMOVE NECCESSARY	1	560.00	560.00	39.20	599.20
BMI02D	REMOVE & INSTALL REAR COMPARTMENT LININGS, R	R1	560.00	560.00	39.20	599.20
BMF00D	RREMOVE & INSTALL FUEL TANK FUEL PIPES.(N)	1	560.00	560.00	39.20	599.20
BKTRR	REMOVE & TRANSFER ITEMS TO NEW TRUNK LID. ADJUST &	1	560.00 280	560.00	39.20	599.20

Printed on 24/1/2019 12:23:56 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)



QUOTATION

GST Reg No.: M200050223

3

Page

Company Ref. No.: S60FC1380G

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

: MS FIRST CAPITAL INSURANCE Customer

36 ROBINSON ROAD

#16-01 CITY HOUSE

SINGAPORE 068877

Registration No

: SLG9795B

Chassis No

: MRHGM6660HP000262

Model

: CITY 1.5SV CVT 2017

Owner's Name Ins Policy No. Date of Accident

: GOI WAY SERN, JONATHAN

: 24/1/2019

Document No.

Date

: SQT19000428

: 24. Jan 2019

Customer No. : WZF002

Svc Advisor

Engine No

: L15Z14112422

Date | Time : 24. Jan 2019 11:58:00 AM Surveyor Name

Survey Date

Authorisation Date

Item	Description	Qty	Unit Price Disc %	Amount	0% GST Amount	Amount incld GST
BKRP02M	CUT OFF & RENEW RR PANEL. STRAIGHTEN	1	8000.00 6720	8000.00	560.00	8560.00
BP06R	SPRAY PAINTING ON TRUNK LID, RR BUMPER, RR PANEL,	1	5000.00 27N	5000.00	350.00	5350.00
BOJSE	BODY JOINT SEALANT FOR TRUNK	1	80.00	80.00	5.60	85.60
BOJSE	BODY JOINT SEALANT FOR REAR END PANEL	1	80.00	80.00	5.60	85.60
BOJSE	BODY JOINT SEALANT FOR REAR FLOOR PANEL	1	80.00	80.00	5.60	85.60
BOJSE	BODY JOINT SEALANT FOR LHR FENDER	1	80.00	80.00	5.60	85.60

BG02R REPLACE RR. WINDSCREEN.(N) BODAMKIT WINDSCREEN DAM KIT.

Total Amount 22,443.39 1,570.99

560.00

100.00

18140.00 1,269.80

39.20

7.00

Total (Inclusive of GST)

Sum Labor

560.00

24,014.38

599.20

107.00

19,409.80

24,014.38

Survey By

Date & Time

Excess Status

Signature

Resun 64 print

900 (0068

72,996.42



SERVICE PRE-INVOICE

GST Reg No.: M200050223 Company Ref. No.: S60FC1380G

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022 255 Alexandra Road Singapore 159937, Tel: +65 6471 5458 Fax: +65 6471 5460

Customer:

MRHGM6660HP000262

Chassis No: License No:

SLG9795B

L15Z14112422

Mileage:

99988

Engine No:

****7002H / GOI WAY SERN,

Document No:

SVO19006013

Printed By:

SHNG

Order Date:

25. January 2019

Order Time:

10:13:14 AM

Service Advisor:

NG SIN HAI

DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Am Amount	ount incld GST
SUPPLEMENTARY PART						
PANEL SETRR.FLOOR 81/	1	421.10	25	315.82	22.11	337.93
STIFFENERRR.JACK UP	1	95.90	25	71.92	5.03	76.95
STIFFENER COMPL.RR.FRAME #	1	169.90	25	127.42	8.92	136.34
PLATESILENCER BAFFLE M	1	20.60	25	15.45	1.08	16.53
OUTLET ASSYRRAIR	1	29.90	25	22.42	1.57	23.99
	4//	SUM	PARTS:	553.03	38.71	591.74
		тот	AL SGD	553.03	38.71	591.74
	SUPPLEMENTARY PART PANEL SETRR.FLOOR BY STIFFENERRR.JACK UP A STIFFENER COMPL.RR.FRAME BY	SUPPLEMENTARY PART PANEL SETRR.FLOOR # 1 STIFFENERR.JACK UP # 1 STIFFENER COMPL.RR.FRAME # 1 PLATESILENCER BAFFLE # 1	SUPPLEMENTARY PART PANEL SETRR.FLOOR 1 421.10 F STIFFENERRR.JACK UP 1 95.90 F STIFFENER COMPL.RR.FRAME 1 169.90 F PLATESILENCER BAFFLE 1 20.60 F OUTLET ASSYRR.AIR 1 29.90 SUM	SUPPLEMENTARY PART PANEL SETRR.FLOOR BY STIFFENERR.JACK UP AT STIFFENER COMPL.RR.FRAME H 1 421.10 A 25 STIFFENER COMPL.RR.FRAME H 1 169.90 A 25 PLATESILENCER BAFFLE AT 1 20.60 A 25	SUPPLEMENTARY PART PANEL SETRR.FLOOR 1 421.10 A 25 315.82 STIFFENERR.JACK UP 1 95.90 A 25 71.92 STIFFENER COMPL.RR.FRAME 1 169.90 A 25 127.42 PLATESILENCER BAFFLE 1 20.60 A 25 15.45 OUTLET ASSYRR.AIR 1 29.90 A 25 22.42 SUM PARTS: 553.03	DESCRIPTION QTY UNIT DISC % AMOUNT Amount SUPPLEMENTARY PART 1 421.10 Å 25 315.82 22.11 STIFFENERRR.JACK UP INTERPRENTED TO STIFFENER COMPLER.FRAME 1 95.90 Å 25 71.92 5.03 STIFFENER COMPLER.FRAME 1 1 169.90 Å 25 127.42 8.92 PLATESILENCER BAFFLE 1 20.60 Å 25 15.45 1.08 OUTLET ASSYRR.AIR 1 29.90 Å 25 22.42 1.57 SUM PARTS: 553.03 38.71

Total Payable (SGD)

591.74

GST Amount is calculated from individual line(s)



SERVICE PRE-INVOIC

GST Reg No.: M200050223 Company Ref. No.: S60FC1380G

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022 255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

Customer:

WZF002 / MS FIRST CAPITAL

Chassis No:

MRHGM6660HP000262

License No:

SLG9795B

Mileage: Engine No: 99988

L15Z14112422

Document No:

SVO19006013

SHNG

Printed By: Order Date:

25. January 2019

Order Time:

10:13:14 AM

Service Advisor:

NG SIN HAI

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Ar Amount	nount inclu GS
	TP DIRECT SETTLEMENT (J/NO:)					
	OWNER:GOI WAY SERN, JONATHAN						
	OWNER INSURER:LIBERTY						
	ACC DATE:24/01/2019						
	SURVEYED BY:RASUL						
	DATE:25/01/2019						
	REF NO:						
	TP INSURER:MS FIRST CAP						
	TP VEH:SHC7121C						
	SUPPLEMENTARY PART						
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N)	1	45.00		45.00	3.15	48.1
68500-T9A-T30ZZ	LID COMPTRUNK	1	457.80	25	343.35	24.03	367.3
74851-T2A-003	LOCK ASSYTRUNK	1	92.60	25	69.45	4.86	74.3
74865-T9A-T01	WEATHERSTRIPTRUNK LID	1	73.70	25	55.27	3.87	59.1
75701-T9A-000	EMBLEM H	1	11.30	25	8.47	0.59	9.0
75722-T9A-T00	EMBLEMRR.CITY	1	11.60	25	8.70	0.61	9.3
75725-T9A-T00	EMBLEMRR.I-VTEC	1	12.20	25	9.15	0.64	9.7
33500-T9A-T01	TAILLIGHT ASSYR.	1	205.70	25	154.27	10.80	165.0
33550-T9A-T01	TAILLIGHT ASSYL.	1	205.70	25	154.27	10.80	165.0
34150-T9A-T01	LIGHT ASSY,R.LID	1	74.90	25	56.17	3.93	60.1
34155-T9A-T01	LIGHT ASSYL.LID	1	74.90	25	56.17	3.93	60.1
90650-T2A-003	CLIPRR.COMBINATION LIGHT	2	2.60	25	3.90	0.27	4.1
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR	1	320.00		320.00	22.40	342.4
1501-T9A-T00ZZ	FACERR.BUMPER	1	463.70	25	347.77	24.34	372.1
33555-T9A-T01	REFLECTOR ASSYL.RR.	1	15.10	25	11.32	0.79	12.1
1593-T9A-J00	SPACER R.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.2
1598-T9A-J00	SPACERL.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.2
1505-TM8-003	CLIP,BUMPER	4	2.30	25	6.90	0.48	7.3
6100-T9A-T50ZZ	PANEL COMPRR.	1	333.60	25	250.20	17.51	267.7
84521-T9A-T10	LID COMPSPARE TIRE	1	45.00	25	33.75	2.36	36.1
34640-T9A-T01ZA	LINING ASSYRR.PANEL	1	66.60	25	49.95	3.50	53.4
8387-TZ5-A01	ANTENNA ASSYL.F.	1	59.30	25	44.47	3.11	47.5
4940-SZW-003	BUZZER ASSYSMART	1	61.30	25	45.97	3.22	49.1
3227-T9A-T00	RUBBER CWINDSHIELD DAMPER	1	17.80	25	13.35	0.93	14.2
O-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00		120.00	8.40	128.4
4646-T9A-T00ZZ	PANEL SETL.RR.OUTSIDE	1	1,168.80	25	876.60	61.36	937.9
4655-T9A-T00ZZ	PANEL SETRR.FLOOR	1	421.10 A		315.82	22.11	337.9
5513-T9A-T00ZZ	STIFFENERRR.JACK UP	1	95.90 €	25	71.92	5.03	76.9
5590-T9A-T10ZZ	STIFFENER COMPL.RR.FRAME	1	169.90	25	127.42	8.92	136.3
4605-T9A-T00	PLATESILENCER BAFFLE	1	20.60 /	25	15.45	1.08	16.5
5450-SDE-T00	OUTLET ASSYRR.AIR	1	29.90	25	22.42	1.57	23.9
			SUM	PARTS:	3,654.72	255.79	3,910.5
OSUN	0701	1	50.00		50.00	3.50	53.50
	SUNDRIES						
BML02I	0701	1	180.00		180.00	12.60	192.6
	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	121	110			1110-0-0-0-0-0-0-0-0-0-0-0-0-0-0-0-0-0-	
	TEST.(N)	120	1 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2		22222	29/22	22202
OBC	1610	1	450.00		450.00	31.50	481.5



SERVICE PRE-INVOICE

GST Reg No.: M200050223 Company Ref. No.: S60FC1380G

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022 255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

				Total Payable (\$			19,136.61
				SUM LABO		996.10 1,251.89	15,226.10
DODAMINI		WINDSCREEN DAM KIT.					U = 12 / = -
BODAMKIT		1757	1	100.00	100.00	7.00	107.00
BG02R		REPLACE RR. WINDSCREEN.(N)	•		ವಸವಾನಿನ		
BC02B		BODY JOINT SEALANT FOR LHR FENDER 1757	1	560.00	560.00	39.20	599.20
BOJSE		FLOOR PANEL 1610	1	80.00	80.00	5.60	85.60
BOJSE		1610 BODY JOINT SEALANT FOR REAR	1	80.00	80.00	5.60	85.60
BOJSE		1610 BODY JOINT SEALANT FOR REAR END PANEL	1	80.00	80.00	5.60	85.60
BOJSE		1610 BODY JOINT SEALANT FOR TRUNK	1	80.00	80.00	5.60	85.60
BP06R		1610 SPRAY PAINTING ON TRUNK LID, RR BUMPER, RR PANEL, FLOOR PANEL, RR R FENDER & RR L FENDER	1	2,700.00	2,700.00	189.00	2,889.00
BKRP02M	2	0671 CUT OFF & RENEW RR PANEL. STRAIGHTEN ALIGN RR FLOOR PAN & RENEW DAMAGE PARTS.	1	6,720.00	6,720.00		
		REMOVE & TRANSFER ITEMS TO NEW TRUNK LID. ADJUST & ALIGN TRUNK LID.(N)		0.700.00	6 720 00	470.40	7,190.40
BKTRR		PIPES.(N) 0671	1	280.00	280.00	19.60	299.60
BMF00D		ETC.(N) 1757 RREMOVE & INSTALL FUEL TANK FUEL	1	560.00	560.00	39.20	599.20
3M102D		1757 REMOVE & INSTALL REAR COMPARTMENT LININGS, RR SEATS, TRUNK LININGS, GARNISHES &	-1	560.00	500.00	00.20	
		RESET SMART ENTRY SYSTEM AND REMOVE NECCESSARY COMPONENT.(N)	4	560.00	560.00	39.20	599.20
BOMISC1		REMOVE, INSTALL & RESET REAR VIEW CAMERA.(N) 0671	1	560.00	560.00	39.20	599.20
OMISC1		0671	1	560.00	560.00	39.20	599.20
P00R		SENSORS-4 PCS (N) 1610 APPLY BODY UNDERSIDE COATING (N).	1	450.00	450.00	31.50	481.50
A02R		0671 REMOVE & RENEW REVERSE	1	180.00	180.00	12.60	192.60
Engine No:		L15Z14112422	Service	Advisor:	NG SIN HAI		
Mileage:		99988	Order T		10:13:14 AM		
icense No:		SLG9795B	Order D	ate: 2	25. January 2019		
hassis No:		MRHGM6660HP000262	Printed	j.	SHNG		
Customer:		WZF002 / MS FIRST CAPITAL	Docume	ent No:	SVO19006013		



5b.

ESTIMATED NORMAL PERIOD FOR REPAIR:

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Interna	ationale Des Experts En Autom	obile
MS FIRST CAPI	ITAL IN	ISURANCE LTD	Ref : CS/FCI1900163	32/R1sd3e2
36 ROBINSON I #16-01 CITY HO		INGAPORE 068877	Date: 18-03-2019 Code: FCI2	
		Policy Particula	rs :- THIRD PARTY CLAI	MARKENER
Insured V	eh.	SHC 7121C	Veh. Inspected	SLG 9795B
Policy No			Coverage (\$)	0.00
Claim No.		D19000672MFSH	Excess (\$)	0.00
Assign Fr	rom	SITHARA	Assign Date	24/01/2019
		Vehicle Pa	rticulars & Condition	NAME OF THE OWNER, WHICH THE
Make & M	lodel	HONDA CITY 1.5 SV CVT	c.c	1497
Engine No	о.	HIDDEN	Year of Reg.	2016
Chassis N	No.	MRHGM6660HP000262	Colour	MAROON
Odometer	r	106758	Steering	IN ORDER
Brakes		IN ORDER	Modification	SPORTS RIM
General		FAIR		
3.		Conc	ditions of Tyres	
		Size	Make	Balance
R/H Front	Tyre	185/55 R16	YOKOHAMA	5 mm
L/H Front	Tyre	185/55 R16	YOKOHAMA	5 mm
R/H Rear	Tyre	185/55 R16	YOKOHAMA	5 mm
L/H Rear	Tyre	185/55 R16	YOKOHAMA	5 mm
		Descrip	otion of Damages	
THE VEHIC		STAINED DAMAGES AT THE	REAR PORTION.	
5.	OLL D		eral Information	
Accident	Date	24/01/2019	Inspection Date	25/01/2019
Survey he		KAH MOTOR CO SDN BERH		
		NO. 255 ALEXANDRA ROAD SINGAPORE 159937		
5a.	10		Remarks	
B)THE INS	PECTIO	ISISTENT TO ACCIDENT REP ON WAS CONDUCTED ON A"V CE TO YOUR INSTRUCTIONS	VITHOUT PREJUDICE" BAS	
OJIN ACCC	ALD AIN	or 10 took indirections	, TETIAL NOT AUTHORIS	LD ILLI MINO.

Estimate Days of Repair

17 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLG 9795B

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)	
	REPLACEMENT OF PARTS				
1	NUMBER PLATE WITH CASING-L (SN)	SCRATCHED	45.00	45.00	
1	LID COMPTRUNK (SN)	BENT	343.35	343.35	
1	HINGE COMPR.TRUNK (SN)	SERVICEABLE	52.42		
1	HINGE COMPL.TRUNK (SN)	SERVICEABLE	52.42		
1	LOCK ASSYTRUNK (SN)	BENT	69.45	69.45	
1	STRIKERTRUNK LID (SN)	SERVICEABLE	7.35		
1	WEATHERSTRIPTRUNK LID (SN)	NECESSARY	55.27	55.27	
1	CABLETRUNK OPENER (SN)	SERVICEABLE	9.82		
1	GARNISH ASSYRR LICENSE (SN)	SERVICEABLE	47.85		
1	LINING ASSYTRUNK LID (SN)	SERVICEABLE	74.77		
12	CLIPTRIM (SN)	NOT NECESSARY	21.60		
1	EMBLEM H (SN)	NECESSARY	8.47	8.47	
1	EMBLEMRR.CITY (SN)	NECESSARY	8.70	8.70	
1	EMBLEMRR.I-VTEC (SN)	NECESSARY	9.15	9.15	
1	TAILLIGHT ASSYR. (SN)	CRACKED	154.27	154.27	
1	TAILLIGHT ASSYL. (SN)	CRACKED	154.27	154.27	
1	LIGHT ASSY, R.LID (SN)	CRACKED	56.17	56.17	
1	LIGHT ASSYL.LID (SN)	CRACKED	56.17	56.17	
2	CLIPRR.COMBINATION LIGHT (SN)	NECESSARY	3.90	3.90	
4	ACT RR.SENSOR (SN)	NECESSARY	320.00	320.00	
1	FACERR.BUMPER (SN)	DEFORMED	347.77	347.77	
1	REFLECTOR ASSYR.RR (SN)	SERVICEABLE	11.32		
1	REFLECTOR ASSYL.RR. (SN)	CRACKED	11.32	11.32	
1	COVERRR.BUMPER EX.PIPE (SN)	NOT NECESSARY	7.35		
1	SPACER R.RR.BUMPER SIDE (SN)	NECESSARY	8.62	8.62	
1	SPACERL.RR.BUMPER SIDE (SN)	NECESSARY	8.62	8.62	
4	CLIP, BUMPER (SN)	NECESSARY	6.90	6.90	
1	PANEL COMPRR. (SN)	BENT	250.20	250.20	
1	LID COMPSPARE TIRE (SN)	CRACKED	33.75	33.75	
1	MATTTRUNK FLOOR (SN)	NOT NECESSARY	14.55	,	
1	LINING ASSYRR PANEL (SN)	DEFORMED	49.95	49.95	

Report Ref No. CS/FCI19001632/R1sd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)	
1	ANTENNA ASSYL.F (SN)	CRACKED	44.47	44.47	
1	BUZZER ASSYSMART (SN)	CRACKED	45.97	45.97	
3	RUBBER CWINDSHIELD DAMPER (SN)	NOT NECESSARY	25.65	2	
1	RUBBER CWINDSHIELD DAMPER (SN)	NECESSARY	13.35	13.35	
2	WINDSCREEN SEALANT (SN)	NECESSARY	120.00	120.00	
1	PANEL SETR.RR.OUTSIDE (SN)	TO REPAIR SEE LABOUR	876.60	-	
1	PANEL SETL.RR.OUTSIDE (SN)	BENT	876.60	876.60	
1	SUNDRIES (SN)	NECESSARY	100.00	50.00	
1	PANEL SETRR.FLOOR (SN) (ADDITIONAL)	BENT	315.82	315.82	
1	STIFFENERRR.JACK UP (SN) (ADDITIONAL)	BENT	71.92	71.92	
1	STIFFENER COMPL.RR.FRAME (SN) (ADDITIONAL)	BENT	127.42	127.42	
1	PLATESILENCER BAFFLE (SN) (ADDITIONAL)	NECESSARY	15.45	15.45	
1	OUTLET ASSYRR.AIR (SN) (ADDITIONAL)	NECESSARY	22.42	22.42	
1	FLOOR PANEL (SN) (NPA)	BUCKLED	-	_	
			4,956.42	3,704.72	
	LABOUR				
	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER.		180.00	180.00	
	BODY UNDERSIDE COATING.		450.00	450.00	
	REMOVE & RENEW REVERSE SENSOR - 4PCS.		180.00	180.00	
	APPLY BODY UNDERSIDE COATING.		450.00	450.00	
	REMOVE, INSTALL & RESET REAR VIEW CAMERA.		560.00	560.00	
	RESET SMART ENTRY SYSTEM AND REMOVE NECESSARY.		560.00	560.00	
	REMOVE & INSTALL REAR COMPARTMENT LININGS, RR.		560.00	560.00	
	REMOVE & INSTALL FUEL TANK FUEL PIPES.		560.00	560.00	
	REMOVE & TRANSFER ITEMS TO NEW TRUNK LID. ADJUST &		560.00	280.00	
	CUT OFF & RENEW RR PANEL. STRAIGHTEN. INCLUSIVE OF THE REPAIR OF PANEL SETR.RR.OUTSIDE.		8,000.00	6,720.00	
	SPRAY PAINTING ON TRUNK LID, RR BUMPER, RR PANEL.		5,000.00	2,700.00	
	BODY JOINT SEALANT FOR TRUNK.		80.00	80.00	
	BODY JOINT SEALANT FOR REAR END PANEL.		80.00	80.00	

Report Ref No. CS/FCI19001632/R1sd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)	
	BODY JOINT SEALANT FOR REAR FLOOR PANEL.		80.00	80.00	
	BODY JOINT SEALANT FOR LHR FENDER.		80.00	80.00	
	REPLACE RR.WINDSCREEN.		560.00	560.00	
	WINDSCREEN DAM KIT.		100.00	100.00	
			18,040.00	14,180.00	
	GRAND TOTAL		22,996.42	17,884.72	

17,884.72

Report Ref No. CS/FCI19001632/R1sd3e2

MKB

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

St. S.

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.