



CHEW MOTOR PTE. LTD.

1 Kaki Bukit Avenue 6, Blk A #01-11 Autobay@Kaki Bukit Singapore 417883

Tel: 6509 5545

Fax: 6509 5567

Website: www.chewmotor.com

Registration No.: 201718369R

22/01/2019

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date: 16/01/2019

Estimated repair cost for vehicle no: SKZ4562B KIA FORTE K3 SX 1.6 A '16

TP A16.
Joy.

S/n	Qty	Items	U/price	Amount
1	1	Rear Bumper <i>torn</i>		\$618.00 ✓
2	1	Rear Bumper Lower <i>wt</i>		\$349.00 ✓
3	10	Rear Bumper Clip <i>new</i>	\$6.50	\$65.00 30 ✓
4	1	Rear R/H Bumper Side Retainer <i>new</i>		\$38.00 ✓
5	1	Rear R/H Bumper Side Reflector <i>fall in</i>		\$99.00 X
6	1	Rear R/H Tail Lamp		\$883.00 ✓
7	1	Rear R/H Rim <i>wt</i>		\$850.00 (850.00) ✓
8	1	Rear R/H Tyre		\$380.00 X
9	1	Rear R/H Axle Bearing <i>fall in</i>		\$458.00 X
10	1	Rear R/H Axle Shock Absorber ✓		\$195.00 X

1035 SN: 680
9 31.50

Subtotal :- \$3,935.00

Labour charges

To remove & refit axle bearing & shock absorber	\$180.00 +
To remove & refit reverse sensor	\$100.00 60
To check wheel alignment	\$150.00 80
Tuff kote	\$60.00 X
Panel beating	\$750.00 250
Spray painting	\$750.00 250

As per Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

total: 2251.50
4/5: 1.8K
03 Days

Subtotal :- \$1,990.00

Total:- \$5,925.00

1.8k
03 days