

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19001678/T1GA3Q2

Date: 14/04/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SMD3030T	Insured Vehicle No :	SHC1084R
Date of Loss: 23/01/2019	Nature of Claim:	TP Claim No: MCT19010677

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMD3030T	Engine No:	G4FGJH703962
Make & Model:	KIA CERATO, 1.6 SX (A)	Chassis No:	KNAF3416MK5013596
Reg. Date:	13/08/2018 (Man. Year: 2018)	Odometer:	9562 km
Colour:	Blue		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Kumho 6 mm	Rear Left Side:	Kumho 6 mm
Front Right Side:	Kumho 6 mm	Rear Right Side:	Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	757.00	757.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,220.00	2,380.00	840.00	26.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,977.00	3,137.00	840.00	21.12
+ GST 7.00/7.00% (S\$)	278.39	219.59	58.80	21.12
Nett Amount (S\$)	4,255.39	3,356.59	898.80	21.12
+ Car Rental (7.0 x S\$107.00/day) (S\$)		749.00		
		4,105.59		

INSPECTION

Date of Assignment:	25/01/2019	
Date Inspected:	05/03/2019	Inspected At:
		Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	4.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 21 Nov 2019)
Parts: 143	KIA CERATO 1.6 SX (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMD3030T)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	20.00 FS	*20.00 FS
2	1		*MIRROR ASSY ,OUTSIDE RR VIEW ,RH	Cut	559.00 FS	*559.00 FS
3	1		*HANDLE ASSY -DOOR OUTSIDE ,RH	Cut	164.00 FS	*164.00 FS
4	1		*COVER-FR DR O/S HDL RH	Cut	14.00 FS	*14.00 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 757.00 757.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPAIR REAR RH DOOR ,AND FRT RH DOOR ,RENEW FRT LH VIEW MIRROR	New	1,650.00	1,100.00
2	PAINT WORK SPRAY REAR DOOR RH ,FRT DOOR RH ,FRT RH VIEW COVER	New	1,260.00	1,050.00
3	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
4	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	200.00	200.00
5	TO APPLY ANTI COROSSION	New	80.00	0.00
Gross Labour Cost (\$)			3,220.00	2,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >