



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road
#08-1339 Singapore 470130
Tel: 9450 7920
* zoomautowerks@gmail.com

Not Allowed

25 JANUARY 2019

25/1/19

2/5 \$2400

4 day. John Philip Atkinson

REG NO. : SFZ 2085 J
MAKE/MODEL : HONDA AIRWAVE

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(S\$)
	<u>LIST ITEMS</u>	
1	Rear door -L/H 1150	1,260.50
1	Rear door glass outer moulding 11	109.60 X
1	Rear door inner lock 11	307.70 X
1	Rear door outer handle 11	96.00 X
1	Rear door regulator with motor 11	462.30 X
1	Rear door rubber 11	134.80
1	Rear taillamp -L/H 11	490.60 X
1	Rear bumper 11	1,182.50 X
1	Rear bumper side retainer 31	58.60
1	Rear fender 11	991.60 X
1	Rear fender inner air vent 11	68.50 X
1	Rear fender inner shield 11	82.60 X
1	Rear fender quarter glass moulding 11	186.50 X
1	Rear wheel hub with bearing 11	364.90 X
1	Rear shock absorber 11	286.00 X
1	Rear knuckle arm 11	362.00 X
1	Rear axle 11	1,226.50 X
		\$ 7,671.20
	Less 20%	\$ 1,534.24
		\$ 6,136.96

1343.4

c/f:

\$

6,136.96

SPECIAL NETT ITEMS

1	Rear bumper clip (1 set)	\$ 11	45.00	X
1	Rear fender inner shield clip (1 set)	\$ 11	35.00	X
1	Rear fender quarter glass sealant	\$ 11	80.00	X
1	Rear tyre	\$ 11	400.00	X
1	Rear wheel rim	\$ 61	700.00	400
		\$	1,260.00	

S/NLABOUR CHARGES

1	To remove, replaced damaged lamps and check up rear wiring.	\$	80.00	20
2	To remove and refit inner garnishes.	\$	180.00	80
3	To remove and refit fuel tank assembly with all attachments.	\$	150.00	60
4	To remove and refit rear undercarriage.	\$ 11	400.00	20
5	To conduct wheel alignment.	\$	160.00	60
6	To remove and refit quarter glass to assist repair.	\$ 11	150.00	X
7	To remove, replace door damaged parts and transfer all fittings.	\$	150.00	60
8	To apply undercoating.	\$	180.00	50
9	Panel beating.	\$	1,600.00	600
10	To re-spray painting on the affected areas.	\$	1,500.00	600
		\$	4,550.00	600

GRAND TOTAL :

\$ 11,946.96

3004.72
2406.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Repair measures subject to confirmation
- Third Party survey is on a "Without Prejudice" basis
- No second modification(s) is allowed
- Temporary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: