

Adrian

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No. _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: \$300/-
 (Client's Record)
 Make of Veh: _____

Veh No: EY13BA Yr Regn: 2018 / Feb.
 Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Audi A5 c.c. 1984
 Colour: White A/C: Insured / Std / Nil / NA
 Sp. Reading: 11378 T/Radio: Insured / Std / Nil / NA
 Eng/No: _____
 C/No: WAU222FSSJA054228
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 265/30R20
 R: 265/30R20
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIRY SUMI /
 TOYO / YOKO or

N/S	O/S

(Priority Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 152k
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 21 days Res.: Yes or No
 Lum Sum: _____ % J Val.: Yes or No

Front Rear
 R/Bal. 06 mm R/Bal. 06 mm
 L/Bal. 06 mm L/Bal. 06 mm
 D.O.A. _____ D.O.I. 25/01/19

CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Survey held at Premium
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>OD ALG.</u>
<u>28/01/19</u>	<u>@ 12:45 p.m. revised IA to Tong Shing via merimer.</u>
<u>28/01/19</u>	<u>@ 12:45 p.m. mandate requested authorize repair to Tong Shing via merimer.</u>
	MV: _____
	PV: _____
	Nett: _____
<u>25/01/19</u>	<u>@ 16:42 p.m. mandate approved by victor Koh via merimer</u>
<u>28/01/19</u>	<u>@ 17:03 p.m. revert authorize repair to Tong (repairer?) via email.</u>
<u>28/03/19</u>	<u>And. ind P/P # 29,255-84 @ 21 days with Adrian.</u>

RECEIVED 17 APR 2019

Date/Time, File Pgs to?	Date/Time, File Return to?	Part Prices Check:	Survey Fee:	Date:
1) <u>17/04/19</u> <u>Typist</u>	2) _____	IN _____ OUT _____	Basic & Add _____ S + RS, SI _____	<u>200</u>
3) _____	4) _____		Photos _____	<u>10</u>
5) _____	6) _____		Others _____	<u>210</u>
Prefl. Report: _____			TOTAL _____	
Final Report: <u>\$29,255-84 P/P</u>				

(\$ 16,170.16 Rec - 36%)

Reserve No. of Trip - 2

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Thursday, 28 March 2019 10:42 AM
To: 'Boo seng yak'
Cc: Adrian Ling (LKKAuto); SUR; 'Carrine Leong'; jiyee.yap@premiumauto.com.sg; 'Chang Chee Sing'
Subject: RE: FINAL REVISION - EY 1313 A - OD AIG - SURVEYED 25 JAN 19

Dear Mr Boo,

Confirmed final fig \$29,255.84 @ 21 days of repairs before excess \$800/- & GST.

Kindly expedite the discharge voucher and tax invoice to us for close case.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak [mailto:boojohnny@gmail.com]

Sent: Monday, 11 March 2019 4:35 PM

To: Adrian Ling <adrianling@lkkauto.com>; shirleyHiew@lkkauto.com; sur@lkkauto.com; Carrine Leong <carrine.leong@premiumauto.com.sg>; jiyee.yap@premiumauto.com.sg; Chang Chee Sing <claims@premiumauto.com.sg>

Subject: FINAL REVISION - EY 1313 A - OD AIG - SURVEYED 25 JAN 19

Hi Adrian and all,

Revised estimate, owner's supply quote and photographs of checked items attached.

Please confirm repair cost of \$29,255.84 @ 21 days of repairs exclude 4 Sundays and 1 Public Holiday.

Your early closure is well appreciated.

Best regards - jb

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Monday, 28 January 2019 5:03 PM
To: 'Claims'
Cc: 'SUR'
Subject: RE: EY 1313 A - OD CLAIM

Dear Tony,

As instructed by our client, please proceed to repair the insured vehicle **EY 1313A (Excess \$ 800/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims [mailto:claims@premiumauto.com.sg]
Sent: Monday, 28 January 2019 4:13 PM
To: 'SUR' <sur@lkkauto.com>
Cc: claims@premiumauto.com.sg
Subject: RE: EY 1313 A - OD CLAIM

record

Thank you.

Best Regards,

Tony Foong
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

View Received Message

This mail is associated with :

***EY1313A (9746614895SG)**

OO
Jan 21 2019 6:30PM
[TEO TOH SENG]
Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 28/01/2019 16:42 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$30600.00) - EY1313A - Claim Handler: Loo, Tong Shing

Approved:30600.00:Kindly breakdown why 8 days of labour needed. Re-inspection to be done for damage check and supplementary items / labour.

DOCUMENTS SUMMARY

There are no documents.

External Body work : 5 days .
Sectioned Part Pillar A/B : 3 Days .
)

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 25 Jan 2019

Preliminary Advice

Vehicle No	: EY1313A	Accident Date	: 21/01/2019
Make	: AUDI A5 SPORTBACK	Policy No.	: 800013026
Assignment Date	: 25/01/2019	Excess	: S\$0.00
Date of Inspection	: 25/01/2019	Est. Duration of Repair	: 18 days
Inspection At	: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	44,176.00
Revised Amount	:S\$	30,600.00
Check Items (Estimated)	:S\$	1,931.00
Total	:S\$	32,531.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	152,000.00
COE / PARF Rebate	:S\$	73,777.00
Salvage Value	:S\$	
Margin for Repair	:S\$	78,223.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/01/2019 17:50
Date Of Accident	21/01/2019 18:30
Exact Location Of Accident	JUNCTION OF STILL RD AND EAST COAST RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	EY1313A
Insured/Policyholder	
Name Of Registered Owner	TEO TOH SENG
NRIC No	S0099547I
Email Address	STEVEN_TEO@WESLEYNET.COM
Mobile Phone No	(LOCAL) +65-96234773
Alternative Phone No	OTHERS-96234773

Vehicle Particulars

Manufacturer	AUDI
Model	A5 SPORTBACK 2.0 TFSI S TRONIC
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	800013026
Cover Note Number	-

Driver

Name of Driver	TEO TOH SENG
NRIC No	S0099547I
Date Of Birth	21/09/1953
Occupation	INDOOR
Date Of Driving Pass	30/06/1976
Driving Experience	42 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96234773
Fax Number	
Contact Number	OTHERS-96234773
EEmail Address	STEVEN_TEO@WESLEYNET.COM

Address	7 AMBER GARDENS #07-18
Postcode	439974
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	MARINE PARADE N.P.C
Police Station Address	ROAD: 300 MARINE PARADE ROAD , POSTCODE: 449296 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO THE ATTACHED POLICE REPORT: T/20190122/2000

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	FBJ5824E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

Approximate Age

Injuries Sustain

Injured person in which vehicle?

FBJ5824E

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

YES

Address

Postcode

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This form must be **completed by the Policyholder and/or the Authorized Driver**.
3. Information provided must be **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8 Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time: 22/1/19

Driver's Signature
(If driver is not the policyholder)
Date & Time



Reporting Centre Personnel's Signature
Name: Gary Fong
NIC/PIN No: 6200014716

Sketch Plan #2

SKETCH PLAN

Please Refer to Sketch Plan

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please Refer Attached Police Report

T / 2019 0122 / 2000

DECLARATION

I/We declare the foregoing particulars are true in every respect

[Signature]

Policyholder's Signature

Date & Time: 27/1/19

Driver's Signature

(If driver is not the policyholder)

Date & Time




Reporting Officer's Signature

Name: Tony Fong

NRIC/PIN No: 65040127X

Sketch Plan #3



SKETCH OF ACCIDENT

BETWEEN EYIISA and FRTS824E

DATE 21 JAN 2019

Henry Lee

Police Report



SINGAPORE
POLICE FORCE



T/20190122/000

Police Station Of Origin
Marine Parade N.P.C.
300 Marine Parade Road SINGAPORE
449298
Tel No: 1800-4428999

2 of 3

Report No: T/20190122/000

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
EY1313A	AIG ASIA PACIFIC INSURANCE PTE LTD.	1800013026	08/02/2018	07/02/2019

Brief Details.

See G/20190121/0151

I am the above mentioned person residing at the above mentioned address. I am the registered vehicle owner of a white Audi A5 (VRN: EY1313A). I wish to state that this traffic accident report is written to the best of my recollection and without prejudice.

At about 6.28pm on Monday 21 January 2018, I drove along Still Road heading towards East Coast Road with the intention to turn right to East Coast Road and I did so slowly after seeing the cars in the opposite direction have already stopped at the junction. The path was clear of oncoming traffic coming from Still Road South heading towards the direction of Changi Road but unfortunately as I was turning, a motorcycle speed towards my car and smashed onto the left door on the side of the front passenger and damaging it. Upon impact, the motorcyclist fell off her motorcycle and was injured according to my observation but I was unable to ascertain the seriousness of her injury as I am not medically trained. Thereafter, she was attended to by paramedics and taken away by ambulance.

Traffic Police was at the accident location and have taken the SD card for my in-car camera.

Police Report



SINGAPORE
POLICE FORCE



T201901220000

Police Station Of Origin
Marine Parade N.P.C
300 Marine Parade Road SINGAPORE
449296
Tel No: 1800-4428599

3 of 3

Report No: T201901220000

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: G / Sgt 3 MUHAMMAD YOUSUF AKMAL BIN MAHMOOD SHAH	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 22/01/2019 00:05
Officer In Charge Of Case: TP / GIT / Sr Staff Sgt RAZIZ BIN TAHAR Contact No : 65476200	Classification Of Case:
Authentication Stamp MP168 	

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: **S00995471**

Name: **TEO TOH SENG**

Birth Date: **21 Sep 1953**

Issue Date: **18 Mar 2004**

0011645520




REPUBLIC OF SINGAPORE

IDENTITY CARD NO. **S00995471**



Name: **TEO TOH SENG**

Race: **CHINESE**

Date of birth: **21-09-1953**

Country/Place of birth: **SINGAPORE**

Sex: **M**

S00995471




YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

PASS DATE: **30 Jun 1976**

Licence No: **S00995471**

NP 428A



5779043

S00995471



S00995471



Date of issue: **03-08-2017**

Address: **7 AMBER GARDENS
#07-18
SINGAPORE 439974**

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : TEO TOH SENG
Period of Insurance : 08 Feb 2018 To 07 Feb 2019
Engine No. : CVK051690
Chassis No. : WAUZZZF55JA054228

Vehicle No. : EY1313A
Policy No. : 1800013026
Endorsement No. : 000000000251216
Issued Date : 14 Jan 2019

ABOUT THE COVER

Make/Model : AUDI A5 Sportback 2.0TFSI S Tronic (Design)
Engine Capacity/Tonnage : 1,984.00 CC **Sum Insured** : Market Value **First Year of Registration** : 2018
Driver Restriction : NA **Off Peak Car** : No **Insuring with COE/PARF** : Yes
Person or Classes of Persons Entitled to Drive* :

a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition
Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
 This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 185) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
 Fire - \$0 Own Damage - \$1600 Theft - \$0 Flood Cover - \$0

Section 2
 Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

TEO TOH SENG - \$1600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1 Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63862323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: MayBank

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125217

PREMIUM LEASING - EF
 281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
 SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

88CFU

IMPORTANT: KEEP THIS DOCUMENT IN YOUR CAR AT ALL TIMES.

What can the 24-hour AIG Auto Emergency Hotline provide for you?

- Immediate assistance after an accident
- Emergency breakdown service
- Towing service (accident or non-accident related)
- Advice on Motor Claims procedures
- Medical Referral Assistance

If no one is injured in the accident:

- You are not required to make any police report.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s).
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

If the accident involves injuries or damage to government property & vehicles, foreign registered vehicles or non-injury hit & run case:

- Report the accident to the police, providing full details of the circumstances of the accident.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s), if applicable.
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

What should I do in the event of an accident?

- Keep calm and move your car to a safe place
- Do not admit or discuss fault or blame with the other party(ies).
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.
- Submit Writ/Summons/Correspondences from third party(ies) to AIG immediately.

LOSS OF USE CAR REPLACEMENT BENEFIT

Applicable only if this benefit is included in your motor insurance. Please refer to your Policy Schedule for details. Policy terms and conditions apply. Please call our customer service hotline number (65) 6419-3000 for assistance.

The Certificate of Insurance (CI) should be produced without demand when collecting the Rental Car and the Rental Car Company reserves the right to verify the identity of the holder. The CI is the property of AIG and its use is subject to the terms and conditions contained in the Loss of Use Endorsement under the policy issued to the policyholder.

Steps to activate Loss of Use Car Replacement Benefit and Important Information

1. To activate your loss of use car replacement, please contact the Rental Car Company (listed below) after filing/reporting your accident claim.
2. Your rental car will be made available within **5** working hours of activation with the Rental Car Company.
3. At the time of collection of the Rental Car, the **original** insurance policy and schedule issued by AIG, a copy of the Accident Report from **Audi Customer Service Centre** must be produced.
4. The number of days is based on the period your vehicle is in the repair workshop unless the number of days of loss of use entitlement is stated in the Policy.
5. Rental cars are strictly for use in Singapore only.
6. Extension of rental beyond repair period approved by AIG surveyor will be chargeable by the Rental Car Company on per day basis.
7. Upgrade of Rental Car is available upon request subject to additional charges by the Rental Car Company.

Rental Car Company: Popular Rent A Car Pte. Ltd.

Activation Hotline: 67428888

501 Guillemard Road Singapore 399840

Operation Hours: Monday to Friday: 9am to 6pm Saturday (Half Day): 9am to 4pm

*The Rental Car Company's Terms & Conditions apply (i.e., refundable security deposit, excess liability for the Rental Car, Collision Damage Waiver, etc)

IMPORTANT NOTICE

If you sell your motor vehicle, this Notice is IMPORTANT and MUST be complied with. Policyholders are hereby warned that under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.99), it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.

The Policyholder is further warned that on the sale of a motor vehicle, they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.88).

This Policy will cease to be valid once the motor vehicle has been sold to another person unless the transfer of interest has been duly notified to and agreed to by the insurance company concerned. If the insurance company agrees to cover the new owner, they will issue a new Certificate of Insurance in the new owner's name. The premium chargeable may vary according to the new owner's profile.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khal@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/01117/2019/GW
Date : 24-Jan-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Teo Toh Seng
Address : 7 Amber Gardens
#07-18, One Amber
Singapore 439974
Telephone : HP +65 96234773
Type of Claim : Own Damage Claims
Policy No. : 800013026
Vehicle No : **EY 1313 A**
Model Code : Audi A5 SB 2.0 TFSI S - Tronic
Model / Year : Feb-18
Engine No : CVK 051690
Chassis No : WAUZZZF55JA054228
Mileage : 11378
Date In : 22-Jan-19
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 21-Jan-19
Place of Accident : Junction of Still Rd and East Coast Rd

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle EY 1313 A

S/n	Nature of Jobs	Estimated Charges
1	To tow and recover vehicle from scene of accident.	S/N \$ 280.00 ✕
2	To remove and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 ✓
3	To dislodge and reinstall lhs A- pillar, lhs front and rear doors harness , multi-lock system and power window devices. Inspect for damages.	S/N \$ 1,400.00 ✓
4	To remove and reinstall front seat assy, back rest , ABCD pilar trims, sill trims, carpets , electronic components and fuse trays.	S/N \$ 1,800.00 ✓
5	To remove center console and dashboard assy for A - pillar and door hinges renewal. Inspect for damages.	S/N \$ 3,200.00 ✓
6	To dismantle front bumper, lhs front fender, lhs front and rear doors and lhs sill panel trim. Cut out and reweld lhs lower A-pillar and lhs sill panel. Renew lhs front fender, lhs front and rear doors, lhs wing mirror assy and lhs wing lhs sill panel trim. Re-organise crash management components, reinstall all parts removed.	\$ 8,400.00 ✓ 4000.
SUB-TOTAL LABOUR CHARGES		: \$ 15,560.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle EY 1313 A

S/n	Nature of Jobs	Estimated Charges
7	To respray lhs front fender, lhs front and rear door, lhs wing mirror cover, door handle, lhs sill panel trim, lhs upper A-pillar, lhs lower A-pillar, lhs sill panel and door entrances. To carry out joint sealant works and stone chip treatment.	2 Door 1 Sill 1 Window Pillar 6 main pieces = 3300 1 A Pillar 1 Fender 1 wing Mirror = 150 \$ 6,700.00 3450.
8	To renew lhs front rim. To carry our wheel alignment.	S/N \$ 280.00 ✓
9	To carry out diagnostic check.	S/N \$ 384.00 ✓
TOTAL LABOUR CHARGES		: \$ 22,924.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. EY 1313 A

S/N	Parts Description		Damaged Parts & Prices S/Nett
1	FRONT FENDER-LH <i>Distorted</i>	S	968.00 ✓ 774.40
2	FRONT FENDER ATTACHMENT PARTS-LH <i>na</i>	S	48.00 ✓ 38
3	FRONT FENDER CLOSING ELEMENT-LH	S	68.00 +
4	FRONT FENDER TOP BRACKET-LH	S	32.00 +
5	FRONT FENDER BRACKET-LH <i>na</i>	S	53.00 +
6	FRONT FENDER BRACKET CENTER-LH	S	32.00 +
7	FRONT FENDER BRACE-LH <i>na</i>	S	107.00 ? X
8	FRONT FENDER BRACKET DEFORMATION ELEMENT-LH <i>na</i>	S	45.00 ? X
9	FRONT FENDER COVER-LH <i>na</i>	S	16.00 ✓ X
10	FRONT FENDER CLOSING ELEMENT-LH <i>na</i>	S	30.00 ✓ 3.76
11	FRONT WHEEL HOUSING LINER-LH <i>na</i>	S	256.00 ✓ 204.20
12	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS-LH <i>na</i>	S	82.00 ? X
13	FRONT WHEEL SPOILER-LH <i>na</i>	S	66.00 +
14	FRONT WHEEL SPOILER TRIM-LH <i>na</i>	S	32.00 +
15	FRONT STONE CHIP GUARD-LH <i>na</i>	S	46.00 ✓ 36.64
16	FRONT FENDER LEDGE COVER -LH <i>na</i>	S	32.00 ✓ 25.44
17	FRONT FENDER LEDGE TOP COVER-LH <i>na</i>	S	14.00 ✓ 11.04
18	FRONT FENDER TRIM-LH <i>na</i>	S	145.00 ✓ 115.60
19	FRONT DOOR TRIM-LH <i>na</i>	S	145.00 ✓ 115.60
20	FRONT DOOR -LH <i>Distorted</i>	S	2,829.00 ✓ 2263.20
SUB-TOTAL SPARE PARTS CHARGES		:	\$ 5,046.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. EY 1313 A

S/N	Parts Description		Damaged Parts & Prices S/Nett
21	FRONT OUTER DOOR SEAL-LH <i>an</i>	S	201.00 ✓ 160.20
22	BONDING AGENT <i>Not nec</i>	S	45.00 ? X
23	CLEANING SOLUTION <i>Not nec</i>	S	65.00 ? X
24	APPLICATOR <i>Not nec</i>	S	7.00 ? X
25	FRONT DOOR CATCH-LH <i>Not nec</i>	S	109.00 ? X
26	FRONT DOOR CATCH COVER-LH <i>Not nec</i>	S	13.00 ? X
27	FORNT DOOR SEAL, INNER-LH <i>an</i>	S	537.00 +
28	FRONT DOOR HANDLE TRIM PLATE-LH	S	80.00 +
29	FRONT DOOR HANDLE TRIM CHROME-LH	S	124.00 +
30	FORNT DOOR HANLDE HOUSING-LH	S	7.00 +
31	FRONT DOOR HANDLE SENSOR-LH	S	208.00 +
32	FRONT DOOR HADLE EXTERIOR-LH	S	35.00 +
33	FRONT DOOR MOUNTING BAR-LH	S	149.00 +
34	FRONT WINDOW REGULATOR WITHOUT MOTOR-LH <i>Damaged</i>	S	320.00 + ✓ 256.00
35	FRONT WINDOW REGULATOR MOTOR-LH <i>an</i>	S	278.00 +
36	FRONT DOOR CONTROL UNIT <i>an</i>	S	685.00 +
37	FRONT EXTERIOR MIRROR MOUNTING-LH <i>Dischd</i>	S	999.00 ✓ 799.20
38	FRONT MIRROR CAP-LH <i>Dischd</i>	S	220.00 ✓ 175.60
39	FRONT MIRROR GLASS-LH <i>Dischd</i>	S	1,132.00 ✓ 905.60
40	EDGE PROTECTION-LH <i>not nec</i>	S	141.00 X
SUB-TOTAL SPARE PARTS CHARGES		:	\$ 5,355.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. EY 1313 A**

S/N	Parts Description	Damaged Parts & Prices	
		S/	Nett
40	FRONT MOLDING ROOF-LH <i>cut</i>	\$	574.00 ✓ 459.20
41	FRONT WATER DEFLECTOR STRIP-LH <i>cut</i>	\$	61.00 ✓ 48.72
42	FRONT WINDOW SLOT SEAL WITH-LH <i>cut + 1/2 in cut</i>	\$	364.00 ✓ 291.20
43	FRONT TRIM FOR PILLAR B-LH <i>cut</i>	\$	247.00 ✓ 197.20
44	FRONT TRIM FOR PILLAR B COVER-LH <i>new</i>	\$	16.00 +
45	CORNER TRIM-LH <i>new</i>	\$	41.00 +
46	FRONT WINDOW APERTURE SEAL-LH <i>new</i>	\$	372.00 +
47	REAR DOOR <i>Dented</i>	\$	2,829.00 ✓ 2263.20
48	REAR OUTER DOOR SEAL-LH <i>new</i>	\$	201.00 ✓ 160.80
49	BONDING AGENT <i>Not new</i>	\$	45.00 ? X
50	CLEANING SOLUTION <i>Not new</i>	\$	65.00 ? X
51	APPLICATOR <i>Not new</i>	\$	7.00 ? X
52	REAR DOOR CATCH-LH <i>Not new Damaged</i>	\$	109.00 ✓ 87.20
53	REAR DOOR CATCH COVER-LH <i>new</i>	\$	12.00 +
54	REAR WINDOW SLOT SEAL WITH TRIM STIP-LH <i>new</i>	\$	335.00 +
55	FRONT DOOR WINDOW-LH <i>cut</i>	\$	265.00 ✓ 211.60
56	REAR DOOR WINDOW-LH <i>cut</i>	\$	265.00 ✓ 211.60
57	SILL TRIM STRIP-LH <i>new</i>	\$	109.00 ✓ 87.20
58	SIDE MEMBER TRIM-LH <i>Dented</i>	\$	736.00 ✓ 602.80
59	SIDE MEMBER TRIM ATTACHMENT PARTS-LH <i>new</i>	\$	118.00 ✓ 94
60	1 SET OF ADHESIVE TAPE <i>new</i>	\$	192.00 ✓ 153.20
SUB-TOTAL SPARE PARTS CHARGES		\$	6,963.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. EY 1313 A

S/N	Parts Description	Damaged Parts & Prices S/Nett
61	SECTIONAL PART-PILLAR A /B <i>Dented</i>	\$ 1,989.00 ✓ 1597.20
62	<i>Front</i> REAR DOOR UPPER HINGE HALF-LH UPPER <i>} Bent</i>	\$ 41.00 ✓ 32.88
63	<i>Front</i> REAR DOOR LOWER HINGE HALF-LH LOWER <i>} Bent</i>	\$ 41.00 ✓ 32.80
64	REAR DOOR UPPER HINGE HALF-LH LOWER <i>} Bent</i>	\$ 39.00 +
65	REAR DOOR HINGE HALVES-LH LOWER <i>} Bent</i>	\$ 42.00 +
66	RUBBER VALVE <i>nee</i>	4 \$ 13.00 - 9.92
67	STICKER WITH PICTOGRAM FOR AIR BAG <i>nee</i>	\$ 23.00 - 17.76
68	FRONT LHS RIM <i>wt</i>	TBC - 1250
69	ACRYLIC SEALNT <i>} Bent</i>	S/N \$180.00 -
70	CAVITY WAX <i>} Bent</i>	S/N \$ 140.00 -
71	STONE CHIP <i>} Bent</i>	S/N \$ 180.00 -
72	SUNDRIES <i>Rec.</i>	\$ 1,200.00 54.48
TOTAL SPARE PARTS CHARGES		\$ 21,252.00
TOTAL LABOUR CHARGES		\$ 22,924.00
GRAND TOTAL		\$ 44,176.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

45426

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lj
Surveyed Date : 25/01/19.
Authorised Date :
Excess Cost :
Liability :
Remarks : not authorized, 18 Pags.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant



東南膠輪公司
South East Tyre Co.

Sales Quotation

Date: 08 March 2019

Messrs: Steven Teo - EY1313 A

Quotation No: 1007

<u>Brand/Model</u>	<u>Quantity</u>	<u>Price</u>
BBS CHR102 9x20 et25 (Inclusive of Freight) Satin Black	1	\$1,250
	Total (Including GST)	\$1,250

Prepared by:

Zack Tan
South East Tyre Co

No 10 Kaki Bukit Road 1
KB Industrial Building
#01-20
Singapore 416175

Tel: 58442288

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0167/2019/GW
Date : 24-Jan-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Hi Adrian

*You recommended 18 days
We took 21 days exclude
4 Sundays and 1 Public Holiday
in 11 Mar 19*

Owner's Name : Mr. Teo Toh Seng
Address : 7 Amber Gardens
#07-18, One Amber
Singapore 439974
Telephone : HP +65 96234773
Type of Claim : Own Damage Claims
Policy No. : 800013026
Vehicle No : **EY 1313 A**
Model Code : Audi A5 SB 2.0 TFSI S - Tronic
Model / Year : Feb-18
Engine No : CVK 051690
Chassis No : WAUZZZF55JA054228
Mileage : 11378
Date In : 22-Jan-19
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 21-Jan-19
Place of Accident : Junction of Still Rd and East Coast Rd

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle EY 1313 A

S/n	Nature of Jobs	Estimated Charges	
1	To tow and recover vehicle from scene of accident.	S/N \$ 280.00	
2	To remove and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00	\$ 480.00
3	To dislodge and reinstall lhs A- pillar, lhs front and rear doors harness , multi-lock system and power window devices. Inpect for damages.	S/N \$ 1,400.00	\$ 1,400.00
4	To remove and reinstall front seat assy, back rest , ABCD pillar trims, sill trims, carpets , electronic components and fuse trays.	S/N \$ 1,800.00	\$ 1,800.00
5	To remove center console and dashboard assy for A - pillar and door hinges renewal. Inspect for damages.	S/N \$ 3,200.00	\$ 3,200.00
6	To dismantle front bumper, lhs front fender, lhs front and rear doors and lhs sill panel trim. Cut out and reweld lhs lower A-pillar and lhs sill panel. Renew lhs front fender, lhs front and rear doors, lhs wing mirror assy and lhs wing lhs sill panel trim. Re-organise crash management components, reinstall all parts removed.	\$ 8,400.00	\$ 4,000.00
SUB-TOTAL LABOUR CHARGES		\$ 15,560.00	\$ 10,880.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle EY 1313 A

S/n	Nature of Jobs		Estimated Charges		
		<i>c/f</i>		\$	10,880.00
7	To respray lhs front fender, lhs front nad rear door, lhs wing mirror cover, door handle , lhs sill panel trim, lhs upper A- pillar, lhs lower A-pillar, lhs sill panel and door entrances. To carry out joint sealant works and stone chip treatment.		\$ 6,700.00	\$	3,450.00
8	To renew lhs front rim. To carry our wheel alignment.	S/N	\$ 280.00	\$	280.00
9	To carry out diagnostic check.	S/N	\$ 384.00	\$	384.00
TOTAL LABOUR CHARGES			\$ 22,924.00	\$	14,994.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. EY 1313 A**

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	
1	FRONT FENDER-LH	\$ 968.00	\$ 774.40
2	FRONT FENDER ATTACHNEBT PARTS-LH	\$ 48.00	\$ 38.00
3	FRONT FENDER CLOSING ELEMENT-LH	\$ 68.00	
4	FRONT FENDER TOP BRACKET-LH	\$ 32.00	
5	FRONT FENDER BRACKET-LH	\$ 53.00	
6	FRONT FENDER BRACKET CENTER-LH	\$ 32.00	
7	FRONT FENDER BRACE-LH	\$ 107.00	
8	FRONT FENDER BRACKET DEFORMATION ELEMENT-LH	\$ 45.00	
9	FRONT FENDER COVER-LH	\$ 16.00	
10	FRONT FENDER CLOSING ELEMENT-LH	\$ 30.00	\$ 23.76
11	FORNT WHEEL HOUSING LINER-LH	\$ 256.00	\$ 204.80
12	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS-LH	\$ 82.00	
13	FORNT WHEEL SPOILER-LH	\$ 66.00	
14	FRONT WHEEL SPOILER TRIM-LH	\$ 32.00	
15	FRONT STONE CHIP GUARD-LH	\$ 46.00	\$ 36.64
16	FRONT FENDER LEDGE COVER -LH	\$ 32.00	\$ 25.44
17	FRONT FENDER LEDGE TOP COVER-LH	\$ 14.00	\$ 11.04
18	FRONT FENDER TRIM-LH	\$ 145.00	\$ 115.60
19	FRONT DOOR TRIM-LH	\$ 145.00	\$ 115.60
20	FRONT DOOR -LH	\$ 2,829.00	\$ 2,263.20
SUB-TOTAL SPARE PARTS CHARGES		\$ 5,046.00	\$ 3,608.48

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. EY 1313 A**

S/N	Parts Description	Damaged Parts & Prices		
			S/Nett	
		<i>c/f</i>	\$	3,608.48
21	FRONT OUTER DOOR SEAL-LH	\$	201.00	\$ 160.80
22	BONDING AGENT	\$	45.00	
23	CLEANING SOLUTION	\$	65.00	
24	APPLICATOR	\$	7.00	
25	FRONT DOOR CATCH-LH	\$	109.00	
26	FRONT DOOR CATCH COVER-LH	\$	13.00	
27	FORNT DOOR SEAL, INNER-LH	\$	537.00	
28	FRONT DOOR HANDLE TRIM PLATE-LH	\$	80.00	
29	FRONT DOOR HANDLE TRIM CHROME-LH	\$	124.00	
30	FORNT DOOR HANLDE HOUSING-LH	\$	7.00	
31	FRONT DOOR HANDLE SENSOR-LH	\$	208.00	
32	FRONT DOOR HADLE EXTERIOR-LH	\$	35.00	
33	FRONT DOOR MOUNTING BAR-LH	\$	149.00	
34	FRONT WINDOW REGULATOR WITHOUT MOTOR-LH	\$	320.00	\$ 256.00
35	FRONT WINDOW REGULATOR MOTOR-LH	\$	278.00	
36	FRONT DOOR CONTROL UNIT	\$	685.00	
37	FRONT EXTERIOR MIRROR MOUNTING-LH	\$	999.00	\$ 799.20
38	FRONT MIRROR CAP-LH	\$	220.00	\$ 175.60
39	FRONT MIRROR GLASS-LH	\$	1,132.00	\$ 905.60
40	EDGE PROTECTION-LH	\$	141.00	
SUB-TOTAL SPARE PARTS CHARGES		\$	5,355.00	\$ 5,905.68

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. EY 1313 A

S/N	Parts Description	Damaged Parts & Prices		
		c/f	S/Nett	
			\$	5,905.68
40	FRONT MOLDING ROOF-LH	\$	574.00	\$ 459.20
41	FRONT WATER DEFLECTOR STRIP-LH	\$	61.00	\$ 48.72
42	FRONT WINDOW SLOT SEAL WITH-LH	\$	364.00	\$ 291.20
43	FRONT TRIM FOR PILLAR B-LH	\$	247.00	\$ 197.20
44	FRONT TRIM FOR PILLAR B COVER-LH	\$	16.00	
45	CORNER TRIM-LH	\$	41.00	
46	FRONT WINDOW APERTURE SEAL-LH	\$	372.00	
47	REAR DOOR	\$	2,829.00	\$ 2,263.20
48	REAR OUTER DOOR SEAL-LH	\$	201.00	\$ 160.80
49	BONDING AGENT	\$	45.00	
50	CLEANING SOLUTION	\$	65.00	
51	APPLICATOR	\$	7.00	
52	REAR DOOR CATCH-LH	\$	109.00	\$ 87.20
53	REAR DOOR CATCH COVER-LH	\$	12.00	
54	REAR WINDOW SLOT SEAL WITH TRIM STIP-LH	\$	335.00	
55	FRONT DOOR WINDOW-LH	\$	265.00	\$ 211.60
56	REAR DOOR WINDOW-LH	\$	265.00	\$ 211.60
57	SILL TRIM STRIP-LH	\$	109.00	\$ 87.20
58	SIDE MEMBER TRIM-LH	\$	736.00	\$ 602.80
59	SIDE MEMBER TRIM ATTACHMENT PARTS-LH	\$	118.00	\$ 94.00
60	1 SET OF ADHESIVE TAPE	\$	192.00	\$ 153.20
SUB-TOTAL SPARE PARTS CHARGES		:	\$ 6,963.00	\$ 10,773.60

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. EY 1313 A**

S/N	Parts Description	<u>Damaged Parts & Prices</u>		
			S/Nett	
		<i>c/f</i>	\$	10,773.60
61	SECTIONAL PART-PILLAR A /B	\$	1,989.00	\$ 1,591.20
62	REAR DOOR UPPER HINGE HALF-LH UPPER	\$	41.00	\$ 32.08
63	REAR DOOR LOWER HINGE HALF-LH LOWER	\$	41.00	\$ 32.80
64	REAR DOOR UPPER HINGE HALF-LH LOWER	\$	39.00	
65	REAR DOOR HINGE HALVES-LH LOWER	\$	42.00	
66	RUBBER VALVE	4 \$	13.00	\$ 9.92
67	STICKER WITH PICTOGRAM FOR AIR BAG	\$	23.00	\$ 17.76
68	FRONT LHS RIM (By owner)	S/N \$	1,250.00	\$ 1,250.00
69	ACRYLIC SEALNT	S/N	\$180.00	\$ 180.00
70	CAVITY WAX	S/N \$	140.00	\$ 140.00
71	STONE CHIP	S/N \$	180.00	\$ 180.00
72	SUNDRIES	\$	1,200.00	\$ 54.48
	TOTAL SPARE PARTS CHARGES	:	\$ 22,502.00	\$ 14,261.84
	TOTAL LABOUR CHARGES		\$ 22,924.00	\$ 14,994.00
	GRAND TOTAL		\$ 45,426.00	\$ 29,255.84

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: EY 1313 A

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0117/2019/MAS

16 April 2019

Dear Sir,

RE: INSURANCE CLAIM FOR EY 1313 A, Audi A5 SB 2.0 TFSI S-Tro

With reference to the above-mentioned vehicle, no. **EY 1313 A**, claimant, **Mr. Teo Toh Seng**, please find the related document per attached.

1. A copy of the Original invoice no. 85013681 – S\$30,447.75
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – EY 1313 A

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 119938
Main Telephone: 6836 2222
Main Telefax: 6471 3783

Alexandra Service Centre
281 Alexandra Road
Singapore 119938
Telephone: 6386 2222
Telefax: 6475 1922

Ubi Service Centre
55 Ubi Road 1
Singapore 408692
Telephone: 6386 2222

Customer Service
Service Appointment: 6346 2113
24-hour Breakdown Service: 9838 1219
customer.care@premiumauto.com.sg

INS TAX INVOICE

Company Reg. No: Y99902271W
GST Reg. No. 199902271W

Page 1 14:24

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013681 Date : 09/04/2019 Order : EY1313A Term : 30	Accounts: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	---

Regn No.: EY1313A (V 36203)	Regn Date: 08/02/2018	Mileage: 11381	WIP No.: 40513
Model: AS SPORTBACK 2.0 TFSI S tronic	Chassis: WAUZZZF55JA054228	Engine: CVK 051690	Dept: U
VSB No.:			
You have been assisted by :- UB-Jiayee (33)			

	Details	Qty	Unit Price	Amount
Q	EXC M: 8888 Insurance Excess/Liability	-800.00	1.00	-800.00
S	BODYWORK M: TO REMOVE AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHT, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	480.00	1.00	480.00
S	BODYWORK M: TO DISLodge AND REINSTALL LHS A PILLAR, LHS FRONT AND REAR DOORS HARNESS, MULTI LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	1400.00	1.00	1,400.00
S	BODYWORK M: TO REMOVE AND REINSTALL FRONT SEAT ASSY, BACK REST, ABCD PILLAR TRIMS, SILL TRIMS, CARPETS, ELECTRONIC COMPONENTS AND FUSE TRAYS	1800.00	1.00	1,800.00
S	BODYWORK M: TO REMOVE CENTRE CONSOLE AND DASHBOARD ASSY	3200.00	1.00	3,200.00

Sub-Total

7% GST

Grand Total



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 119938
Main Telephone: 6346 2223
Main Telefax: 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 119938
Telephone: 6388 2221
Telefax: 6475 1021

Ubi Service Centre
55 Ubi Road 1
Singapore 408722
Telephone: 6388 2222

Customer Service
Service Appointment
6388 2223
6388 1239
Customer Breakdown Service
customer.care@premiumauto.com.sg

INSURANCE TAX INVOICE

Company Reg. No: 199902271M

GST Reg. No. 199902271M

Page 2 14:24

ATG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT ATG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013681 Date : 09/04/2019 Order : EY1313A Term : 30	Account: A0006 (T 0) ATG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT ATG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	--

Regn No.: EY1313A (V 36203)	Regn Date: 08/02/2018	Mileage: 11381	WIP No.: 40513
Model: A5 SPORTBACK 2.0 TFSI S tronic	Chassis: WAUZZZF55JA054228	Engine: CVK 051690	Dept: U
VSB No.:			
You have been assisted by :- UB-Jiayee (33)			

		Details	Qty	Unit Price	Amount
S	BODYWORK	FOR A PILLAR AND DOOR HINGES RENEWAL. INSPECT FOR DAMAGES M:	4000.00	1.00	4,000.00
S	BODYWORK	TO DISMANTLE FRONT BUMPER, LHS FRONT FENDER, LHS FRO AND REAR DOOR AND LHS SILL PANEL TRIM. CUT OUT AND REMELD LHS LOWER A PILLAR AND LHS SILL PANEL. RENEW LHS FRONT FENDER, LHS FRONT AND REAR DOORS, LHS WING MIRROR ASSY AND LHS SILL PANEL TRIM. REORGANISE CRA MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED M:	3450.00	1.00	3,450.00
S	BODYWORK	TO RESPRAY LHS FRONT FENDER, LHS FRONT AND REAR DOOR, LHS WING MIRROR COVER, LHS SILL PANEL TRIM, LHS UPPER A PILLAR AND LHS LOWER A PILLAR. TO CARRY OUT JOINT SEALANT WORKS AND STONE CHIP TREATMENT M:	280.00	1.00	280.00

Sub-Total

7% GST

Grand Total



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 119908
Main Telephone: 6386 2223
Main Telefax: 6471 3333

Alexandra Service Centre
281 Alexandra Road
Singapore 119908
Telephone: 6386 2223
Telefax: 6471 1022

Ubi Service Centre
55 Ubi Road 1
Singapore 408722
Telephone: 6386 2223

Customer Service
Service Appointment
Breakdown Service
customer.care@premiumaudis.com.sg

6386 2223
9628 1233

INSURANCE TAX INVOICE

Company Reg. No: 199902271W
GST Reg. No. 199902271W

Page 3 14:24

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoices: 85013681 Date : 09/04/2019 Order : EY1313A Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: EY1313A (V 36203)	Regn Date: 08/02/2018	Mileage: 11381	WIP No.: 40513
Model: A5 SPORTBACK 2.0 TFSI S tronic	Chassis: WAUZZZF55JA054228	Engine: CVK 051690	Dept: U
VSB No.:			
You have been assisted by :- UB-Jiayee (33)			

		Details	Qty	Unit Price	Amount
S	BODYWORK	N: TO CARRY OUT DIAGNOSTIC CHECK	384.00	1.00	384.00
S	BODYWORK	N: TO SUPPLY ACRYLIC SEALANT,CAVITY WAX AND STONE CHIP	500.00	1.00	500.00
Q	OTHERS	N: TO SUPPLY LHS FRONT RIM (BY OWNER)	1250.00	1.00	1,250.00
X	ABW88574090 989	(A) (SK)MOUNTING 31/0 Less 020%	1.00	999.00	799.20
X	ABW8853703 222	(A) (SK)MOLDING 31/01 Less 020%	1.00	574.00	459.20
X	ABW8853283 222	(A) (SK)WINDOW SLD 31 Less 020%	1.00	364.00	291.20
X	ABW8853289 T94	(A) (SK)TRIM 31/01/19 Less 020%	1.00	246.50	197.20
X	ABW8845201	(A) (SK)WINDOW 31/01/ Less 020%	1.00	264.50	211.60
X	ABW8845205	(A) (SK)WINDOW 31/01/ Less 020%	1.00	264.50	211.60
X	ABW8853373F 989	(A) (SK)SCUFF PLAT 31 Less 020%	1.00	109.00	87.20
X	ABW8809839	(V) (B)SECTION 31/01/ Less 020%	1.00	1989.00	1,591.20
X	ABX4833407A	(A) (SK)HINGE 31/01/1 Less 020%	1.00	40.10	32.08
X	AB0A831403A	(V) (B)HINGE 01/02/19 Less 020%	1.00	41.00	32.08
X	ABW8837461	(A) (SK)REGULATOR 19/ Less 020%	1.00	320.00	256.00
Sub-Total					
7% GST					
Grand Total					



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 119938
Main Telephone: 6826 2222
Main Telefax: 6471 3253

Alexandra Service Centre
281 Alexandra Road
Singapore 119938
Telephone: 6388 2233
Telefax: 6475 1021

Ubi Service Centre
55 Ubi Road 1
Singapore 408722
Telephone: 6388 2233

Customer Service
Service Appointment: 6388 2233
24 Hour Breakdown Service: 9828 1233
customer.care@premiumauto.com.sg

INSURANCE TAX INVOICE
Company Reg. No: 099902271W
GST Reg. No. 199902271W

Page 4 14:24

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013681 Date : 09/04/2019 Order : EY1313A Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	--

Regn No.: EY1313A (V 36203) Regn Date: 08/02/2018 Mileage: 11381 WIP No.: 40513
Model: A5 SPORTBACK 2.0 TFSI S tronic Chassis: WAUZZZF55JA054228 Engine: CVK 051690 Dept: U
VSB No.:
You have been assisted by :- UB-Jiayee (33)

		Details		Qty	Unit Price	Amount
X	ABW6853921A	(V) (G) HOLDER 20/02/1	Less 020%	1.00	21.20	16.96
X	AN 90780402	(SK) BOLT	Less 020%	2.00	1.20	1.92
X	ABW6821111	PLATE	Less 020%	1.00	29.70	23.76
X	ABW6821105B	(V) (G) FENDER 31/01/1	Less 020%	1.00	968.00	774.40
X	ABW6821171C	WHEEL HOUS	Less 020%	1.00	256.00	204.80
X	ABW8831051F	(V) (G) DOOR 31/01/19	Less 020%	1.00	2629.00	2,263.20
X	ABW8853855 GRU	(V) (G) TRIM 31/01/19	Less 020%	1.00	753.50	602.80
X	ABW8833051J	(A) (SK) DOOR 31/01/19	Less 020%	1.00	2629.00	2,263.20
X	ABW6090625	MOUNT KIT	Less 020%	1.00	47.50	38.00
X	ABW6853603A PUZ	TRIM	Less 020%	1.00	144.50	115.60
X	ABW6820501E	(V) (G) COVER 01/02/19	Less 020%	1.00	31.00	25.44
X	ABW6823745	(A) (SK) COVER 31/01/1	Less 020%	1.00	13.00	11.04
X	ABW6853823B 909	STONEGUARD	Less 020%	1.00	45.00	36.64
X	ABW6853601A PUZ	(A) (SK) TRIM 31/01/19	Less 020%	1.00	144.50	115.60
X	ABW8837911	SEAL	Less 020%	1.00	201.00	160.80
X	ABT0877449	NUT	Less 020%	3.00	6.10	14.64
X	ABW8839911	(V) (G) SEAL 01/02/19	Less 020%	1.00	201.00	160.80
X	ABW8839249	CHECK ROD	Less 020%	1.00	109.00	87.20

Sub-Total

7% GST

Grand Total



Premium Automobiles Pte Ltd

Acad Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone: 6386 2223
Fax: 6475 1924

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone: 6386 2223
Telefax: 6475 1924

Ubi Service Centre
55 Ubi Avenue 1
Singapore 408722
Company Reg. No. 199902271M
GST Reg. No. 199902271M

Customer Service
1500 Appointment
24 Hour Breakdown Service
Email: customer.care@premiumauto.com.sg
6386 2223
6328 1238

Page 5 of 14

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013681 Date: 09/04/2019 Order: EY1313A Term: 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: EY1313A (V 36203) Regn Date: 08/02/2018 Mileage: 11381 WIP No.: 40513

Model: A5 SPORTBACK 2.0 TFSI S tronic Chassis: WAUZZZF55JA054228 Engine: CVK 051690 Dept: U

VSB No.:

You have been assisted by :- UB-Jiayee (33)

		Details	Qty	Unit Price	Amount
X	ABW0057527 BRU	(V) (B) CAP 31/01/19	1.00	219.50	175.60
X	ABW6898909A	(V) (B) ADHES. TAPE 01/	1.00	191.50	153.20
X	ABW6898909	SECUR. SET	1.00	117.50	94.00
X	ABW0057535G	(A) (SK) MIRROR 31/01/	1.00	1132.00	905.60
X	A311601351	RUBBER VAL	4.00	3.10	9.92
X	AS60010029J	STICKER	1.00	22.20	17.76
X	AHHT003497	BOLT	1.00	2.10	1.68
X	AHHT003237	BOLT	2.00	1.00	1.60
X	AHHT004750	RIVET	4.00	2.50	8.00
X	ABW6854327B 989	Strip	1.00	60.90	48.72
X	AN 10528301	SUNDIR	1.00	12.10	9.68

Parts 12,511.84
Labour 1,250.00
Sublet 15,494.00
Menus 0.00
Lubricant 0.00

Sub-Total 28,455.84
7% GST 1,991.91
Grand Total 30,447.75



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Customer

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: EY1313A

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0117/2019/TF
25 February 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1

total pages


RE: CLAIM – OWNER’S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A5 SPORTBACK 2.0 TFSI S tronic
Vehicle Chassis No. : WAUZZZF55JA054228
Vehicle Regn No. : **EY1313A**
Vehicle Mileage : 11381 KM
Vehicle Owner : Mr Teo Toh Seng
Certificate No : 1800013026
Own Damage Excess : \$856.00 (Inclusive 7%GST)
Accident Date : 21/1/2019
Place : Junction of Still Road and East Coast Road
Repair Cost : \$ 30,447.75
WIP No. : 40513
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : 
Time : _____
Date : 26/2/19

REPUBLIC OF SINGAPORE DRIVING LICENCE

License Number **S00995471**

Name
TEO TOH SENG

Birth Date: **21 Sep 1953**

Issue Date: **18 Mar 2004**

001164552D




REPUBLIC OF SINGAPORE
IDENTITY CARD NO. **S00995471**



Name
TEO TOH SENG

Race:
CHINESE

Date of birth:
21-09-1953

Country/Place of birth:
SINGAPORE

Sex
M

S00995471




YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

Class	Description	PASS DATE
Class 3	Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	30 Jun 1976

NP 428A

Licence No: S00995471



3779043



NRIC No. **S00995471**



Date of issue:
03-08-2017

Address
**7 AMBER GARDENS
#07-18
SINGAPORE 439974**

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : TEO TOH SENG
 Period of Insurance : 08 Feb 2018 To 07 Feb 2019
 Engine No. : CVK051690
 Chassis No. : WAUZZZF55JA054228

Vehicle No. : EY1313A
 Policy No. : 1800013026
 Endorsement No. : 000000000251216
 Issued Date : 14 Jan 2019

ABOUT THE COVER

Make/Model : AUDI A5 Sportback 2.0TFSI S Tronic (Design)
 Engine Capacity/Tonnage : 1,984.00 CC Sum Insured : Market Value First Year of Registration : 2018
 Driver Restriction : NA Off Peak Car : No Insuring with COE/PARF : Yes
 Person or Classes of Persons Entitled to Drive* :

a) The Policyholder

b) Any other person who is driving on the Policyholder's order or with his/her permission.

This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$1600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

TEO TOH SENG - \$1600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download 'AIG SG' from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: MayBank

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125217

PREMIUM LEASING - EF

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

M. J. J. J.

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	27 Jan 2019		25 Jan 2019 14:51 Edit Adj Rpt	S\$29,255.84 Edit Estimates	S\$29,255.84 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	TEO TOH SENG , ID: S00995471, Tel: +6596234773, Email: steven_teo@wesleynet.com								
Vehicle Reg. No.:	EY1313A	Date of Loss:	21/01/2019 00:00 - :59 [11 Months and 13 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 9746614895SG	Policy/Cover Note No.:	1800013026 (Comprehensive)						
		Excess:	S\$800.00						
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Loo, Tong Shing] TongShing.Loo@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 07/02/2019]								
Driver/Custodian:	TEO TOH SENG (65 / Male), NRIC: S00995471, Tel: +6596234773 Email: steven_teo@wesleynet.com								
ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail						
<ul style="list-style-type: none"> AIG_SG (28/01/2019): Alert - Adj Mandate Approved (S\$30600.00) - EY1313A - Claim Handler: Loo, Tong S... AIG_SG (28/01/2019): EY1313A / OD / 21/01/2019 / Coverage & Excess update 									
ALL ASSOCIATED TASKS		View All	Search Tasks	Create New Task	Complete				
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*EY1313A (9746614895SG)
 OD
 Jan 21 2019 12:00AM
 [TEO TOH SENG]
 Premium Automobiles Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View	View in Browser
Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	22/01/19 17:57	Video - Accident <small>[Linked Accident Report Documents]</small>	Load MP4	<input type="checkbox"/>
2	22/01/19 17:57	Video - Accident <small>[Linked Accident Report Documents]</small>	Load MP4	<input type="checkbox"/>
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/01/19 12:45	Adjuster Immediate Advice	Load HTM	<input type="checkbox"/>
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/01/19 17:21	General View	Load JPG	<input checked="" type="checkbox"/>
2	25/01/19 17:21	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
3	25/01/19 17:21	General View	Load JPG	<input checked="" type="checkbox"/>
4	25/01/19 17:21	General View	Load JPG	<input checked="" type="checkbox"/>
5	25/01/19 17:21	General View	Load JPG	<input checked="" type="checkbox"/>
6	25/01/19 17:21	General View	Load JPG	<input checked="" type="checkbox"/>
7	25/01/19 17:21	General View	Load JPG	<input checked="" type="checkbox"/>
8	25/01/19 17:21	General View	Load JPG	<input checked="" type="checkbox"/>
9	25/01/19 17:21	General View	Load JPG	<input checked="" type="checkbox"/>
10	25/01/19 17:21	General View	Load JPG	<input checked="" type="checkbox"/>
11	25/01/19 17:21	General View	Load JPG	<input checked="" type="checkbox"/>
12	25/01/19 17:21	General View	Load JPG	<input checked="" type="checkbox"/>
13	25/01/19 17:21	General View	Load JPG	<input checked="" type="checkbox"/>
14	25/01/19 17:21	General View	Load JPG	<input checked="" type="checkbox"/>
15	25/01/19 17:21	General View	Load JPG	<input checked="" type="checkbox"/>
16	25/01/19 17:21	General View	Load JPG	<input checked="" type="checkbox"/>
17	25/01/19 17:21	General View	Load JPG	<input checked="" type="checkbox"/>
18	25/01/19 17:21	General View	Load JPG	<input checked="" type="checkbox"/>
19	25/01/19 17:21	General View	Load JPG	<input checked="" type="checkbox"/>
20	25/01/19 17:21	General View	Load JPG	<input checked="" type="checkbox"/>
21	25/01/19 17:21	General View	Load JPG	<input checked="" type="checkbox"/>
22	25/01/19 17:21	General View	Load JPG	<input checked="" type="checkbox"/>
23	25/01/19 17:21	General View	Load JPG	<input checked="" type="checkbox"/>
24	25/01/19 17:21	General View	Load JPG	<input checked="" type="checkbox"/>
25	25/01/19 17:21	General View	Load JPG	<input checked="" type="checkbox"/>
26	25/01/19 17:21	General View	Load JPG	<input checked="" type="checkbox"/>
27	25/01/19 17:21	General View	Load JPG	<input checked="" type="checkbox"/>
28	25/01/19 17:21	General View	Load JPG	<input checked="" type="checkbox"/>
29	25/01/19 17:21	General View	Load JPG	<input checked="" type="checkbox"/>
30	25/01/19 17:21	General View	Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
31	25/01/19 17:21	General View	Load JPG	<input checked="" type="checkbox"/>
32	25/01/19 17:21	General View	Load JPG	<input checked="" type="checkbox"/>
33	25/01/19 17:21	General View	Load JPG	<input checked="" type="checkbox"/>
34	25/01/19 17:21	General View	Load JPG	<input checked="" type="checkbox"/>
35	25/01/19 17:21	General View	Load JPG	<input checked="" type="checkbox"/>
36	25/01/19 17:21	General View	Load JPG	<input checked="" type="checkbox"/>
37	25/01/19 17:21	General View	Load JPG	<input checked="" type="checkbox"/>
38	21/03/19 09:17	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
39	21/03/19 09:17	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
40	21/03/19 09:17	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
41	21/03/19 09:17	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
42	21/03/19 09:18	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
43	21/03/19 09:18	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
44	21/03/19 09:18	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
45	21/03/19 09:18	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/01/19 17:20	DRIVING & INS. CERT.pdf	Load PDF	
2	25/01/19 17:20	ESTIMATE.pdf	Load PDF	
3	28/03/19 10:30	ESTIMATE MARKED.pdf	Load PDF	
4	30/04/19 17:50	Workshop Invoice	Load PDF	
5	30/04/19 17:50	Discharge Voucher	Load PDF	

Linked Accident Report Documents

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	22/01/19 17:57	Video - Accident	Load MP4	
2	22/01/19 17:57	Video - Accident	Load MP4	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	22/01/19 18:11	Accident Statement	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	22/01/19 17:59	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	22/01/19 17:59	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	22/01/19 17:59	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	22/01/19 17:59	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	22/01/19 17:59	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	22/01/19 17:59	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	22/01/19 17:59	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
8	22/01/19 17:59	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
9	22/01/19 17:59	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
10	22/01/19 17:59	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
11	22/01/19 17:59	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
12	22/01/19 17:59	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
13	22/01/19 17:59	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
14	22/01/19 17:59	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
15	22/01/19 17:59	Accident Photo	Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
16	22/01/19 17:59	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
17	22/01/19 18:02	Police Report	 Load JPG	<input checked="" type="checkbox"/>
18	22/01/19 18:02	Police Report	 Load JPG	<input checked="" type="checkbox"/>
19	22/01/19 18:02	Police Report	 Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	22/01/19 18:01	Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	22/01/19 18:01	Sketch Plan #2	 Load JPG	<input checked="" type="checkbox"/>
3	22/01/19 18:02	Sketch Plan #3	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG19001688/ASD3E2

Date: 02/05/2019

REFERENCE

Insured/Claimant:	TEO TOH SENG	Policy No:	1800013026	
Date of Loss:	21/01/2019	Nature of Claim:	OD	Claim No: 9746614895SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	EY1313A	Engine No:	CVK051690
Make & Model:	AUDI A5 SPORTBACK, 2.0 TFSI QUATTRO (A)	Chassis No:	WAUZZZF55JA054228
Reg. Date:	08/02/2018 (Man. Year: 2017)	Odometer:	11378 km
Colour:	White		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$152,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	265/30 R20	Rear Tyre Size:	265/30 R20
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,502.00	14,261.84	8,240.16	36.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	22,924.00	14,994.00	7,930.00	34.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	45,426.00	29,255.84	16,170.16	35.60
- Excess (S\$)	800.00	800.00	0.00	0.00
	(S\$)	44,626.00	28,455.84	16,170.16
+ GST 7.00/7.00% (S\$)	3,123.82	1,991.91	1,131.91	36.23
Nett Amount (S\$)	47,749.82	30,447.75	17,302.07	36.23

INSPECTION

Date of Assignment:	25/01/2019		
Date Inspected:	25/01/2019	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	21.0 days		

Adjuster: ADRIAN LING

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER - LH	Distorted	968.00 FS	*774.40 FS
2	1		*FRONT FENDER ATTACHMENT PARTS - LH	Necessary	48.00 FS	*38.00 FS
3	1		*FRONT FENDER CLOSING ELEMENT - LH	Not Necessary	68.00 FS	*- FS
4	1		*FRONT FENDER TOP BRACKET - LH	Not Necessary	32.00 FS	*- FS
5	1		*FRONT FENDER BRACKET - LH	Not Necessary	53.00 FS	*- FS
6	1		*FRONT FENDER BRACKET CENTER - LH	Not Necessary	32.00 FS	*- FS
7	1		*FRONT FENDER BRACE - LH	Not Necessary	107.00 FS	*- FS
8	1		*FRONT FENDER BRACKET DEFORMATION ELEMENT - LH	Not Necessary	45.00 FS	*- FS
9	1		*FRONT FENDER COVER - LH	Not Necessary	16.00 FS	*- FS
10	1		*FRONT FENDER CLOSING ELEMENT - LH	Damaged	30.00 FS	*23.76 FS
11	1		*FRONT WHEEL HOUSING LINER - LH	Deformed	256.00 FS	*204.80 FS
12	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS - LH	Not Necessary	82.00 FS	*- FS
13	1		*FRONT WHEEL SPOILER - LH	Not Necessary	66.00 FS	*- FS
14	1		*FRONT WHEEL SPOILER TRIM - LH	Not Necessary	32.00 FS	*- FS
15	1		*FRONT STONE CHIP GUARD - LH	Necessary	46.00 FS	*36.64 FS
16	1		*FRONT FENDER LEDGE COVER - LH	Necessary	32.00 FS	*25.44 FS
17	1		*FRONT FENDER LEDGE TOP COVER - LH	Necessary	14.00 FS	*11.04 FS
18	1		*FRONT FENDER TRIM - LH	Necessary	145.00 FS	*115.60 FS
19	1		*FRONT DOOR TRIM - LH	Necessary	145.00 FS	*115.60 FS
20	1		*FRONT DOOR - LH	Distorted	2,829.00 FS	*2,263.20 FS
21	1		*FRONT OUTER DOOR SEAL - LH	Necessary	201.00 FS	*160.80 FS
22	1		*BONDING AGENT	Not Necessary	45.00 FS	*- FS
23	1		*CLEANING SOLUTION	Not Necessary	65.00 FS	*- FS
24	1		*APPLICATOR	Not Necessary	7.00 FS	*- FS
25	1		*FRONT DOOR CATCH - LH	Not Necessary	109.00 FS	*- FS
26	1		*FRONT DOOR CATCH COVER - LH	Not Necessary	13.00 FS	*- FS
27	1		*FRONT DOOR SEAL, INNER - LH	Not Necessary	537.00 FS	*- FS
28	1		*FRONT DOOR HANDLE TRIM PLATE - LH	Not Necessary	80.00 FS	*- FS
29	1		*FRONT DOOR HANDLE TRIM CHROME - LH	Not Necessary	124.00 FS	*- FS
30	1		*FRONT DOOR HANDLE HOUSING - LH	Not Necessary	7.00 FS	*- FS
31	1		*FRONT DOOR HANDLE SENSOR - LH	Not Necessary	208.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
32	1		*FRONT DOOR HANDLE EXTERIOR - LH	Not Necessary	35.00 FS	*- FS
33	1		*FRONT DOOR MOUNTING BAR - LH	Not Necessary	149.00 FS	*- FS
34	1		*FRONT WINDOW REGULATOR WITHOUT MOTOR - LH	Damaged	320.00 FS	*256.00 FS
35	1		*FRONT WINDOW REGULATOR MOTOR - LH	Not Necessary	278.00 FS	*- FS
36	1		*FRONT DOOR CONTROL UNIT	Not Necessary	685.00 FS	*- FS
37	1		*FRONT EXTERIOR MIRROR MOUNTING - LH	Distorted	999.00 FS	*799.20 FS
38	1		*FRONT MIRROR CAP - LH	Distorted	220.00 FS	*175.60 FS
39	1		*FRONT MIRROR GLASS - LH	Distorted	1,132.00 FS	*905.60 FS
40	1		*EDGE PROTECTION - LH	Not Necessary	141.00 FS	*- FS
41	1		*FRONT MOLDING ROOF - LH	Cut	574.00 FS	*459.20 FS
42	1		*FRONT WATER DEFLECTOR STRIP - LH	Cut	61.00 FS	*48.72 FS
43	1		*FRONT WINDOW SLOT SEAL WITH - LH	Cut	364.00 FS	*291.20 FS
44	1		*FRONT TRIM FOR PILLAR B - LH	Cut	247.00 FS	*197.20 FS
45	1		*FRONT TRIM FOR PILLAR B COVER - LH	Not Necessary	16.00 FS	*- FS
46	1		*CORNER TRIM - LH	Not Necessary	41.00 FS	*- FS
47	1		*FRONT WINDOW APERTURE SEAL - LH	Not Necessary	372.00 FS	*- FS
48	1		*REAR DOOR	Dented	2,829.00 FS	*2,263.20 FS
49	1		*REAR OUTER DOOR SEAL - LH	Necessary	201.00 FS	*160.80 FS
50	1		*BONDING AGENT	Not Necessary	45.00 FS	*- FS
51	1		*CLEANING SOLUTION	Not Necessary	65.00 FS	*- FS
52	1		*APPLICATOR	Not Necessary	7.00 FS	*- FS
53	1		*REAR DOOR CATCH - LH	Damaged	109.00 FS	*87.20 FS
54	1		*REAR DOOR CATCH COVER - LH	Not Necessary	12.00 FS	*- FS
55	1		*REAR WINDOW SLOT SEAL WITH TRIM STIP - LH	Not Necessary	335.00 FS	*- FS
56	1		*FRONT DOOR WINDOW - LH	Cut	265.00 FS	*211.60 FS
57	1		*REAR DOOR WINDOW - LH	Cut	265.00 FS	*211.60 FS
58	1		*SILL TRIM STRIP - LH	Necessary	109.00 FS	*87.20 FS
59	1		*SIDE MEMBER TRIM - LH	Deformed	736.00 FS	*602.80 FS
60	1		*SIDE MEMBER TRIM ATTACHMENT PARTS - LH	Necessary	118.00 FS	*94.00 FS
61	1		*SET OF ADHESIVE TAPE	Necessary	192.00 FS	*153.20 FS
62	1		*SECTIONAL PART - PILLAR A/B	Dented	1,989.00 FS	*1,591.20 FS
63	1		*FRONT DOOR UPPER HINGE HALF - LH UPPER	Bent	41.00 FS	*32.08 FS
64	1		*FRONT DOOR LOWER HINGE HALF - LH LOWER	Bent	41.00 FS	*32.80 FS
65	1		*REAR DOOR UPPER HINGE HALF - LH LOWER	Not Necessary	39.00 FS	*- FS
66	1		*REAR DOOR HINGE HALVES - LH LOWER	Not Necessary	42.00 FS	*- FS
67	4		*RUBBER VALVE	Necessary	13.00 FS	*9.92 FS
68	1		*STICKER WITH PICTOGRAM FOR AIR BAG	Necessary	23.00 FS	*17.76 FS
69	1		*FRONT LHS RIM	Cut	1,250.00 FS	*1,250.00 FS
70	1		*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
71	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
72	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
73	1		*SUNDRIES	Necessary	1,200.00 FS	*54.48 FS
Total Parts (\$\$)					22,502.00	14,261.84

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TOW AND RECOVER VEHICLE FROM SCENE OF ACCIDENT	New	280.00	0.00
2	TO REMOVE AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
3	TO DISLODGE AND REINSTALL LHS A-PILLAR, LHS FRONT AND REAR DOORS HARNESS, MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	1,400.00	1,400.00
4	TO REMOVE AND REINSTALL FRONT SEAT ASSY, BACK REST, ABCD PILLAR TRIMS, SILL TRIMS, CARPETS, ELECTRONIC COMPONENTS AND FUSE TRAYS	New	1,800.00	1,800.00
5	TO REMOVE CENTER CONSOLE AND DASHBOARD ASSY FOR A-PILLAR AND DOOR HINGES RENEWAL. INSPECT FOR DAMAGES	New	3,200.00	3,200.00
6	TO DISMANTLE FRONT BUMPER, LHS FRONT FENDER, LHS FRONT AND REAR DOORS AND LHS SILL PANEL TRIM. CUT OUT AND REWELD LHS LOWER A-PILLAR AND LHS SILL PANEL. RENEW LHS FRONT FENDER, LHS FRONT AND REAR DOORS, LHS WING MIRROR ASSY AND LHS WING LHS SILL PANEL TRIM. RE-ORGANISE CRASH MANAGEMENT COMPONENTS, REINSTALL ALL PARTS REMOVED	New	8,400.00	4,000.00
7	TO RESPRAY LHS FRONT FENDER, LHS FRONT AND REAR DOOR, LHS WING MIRROR COVER, DOOR HANDLE, LHS SILL PANEL TRIM, LHS UPPER A-PILLAR, LHS LOWER A-PILLAR, LHS SILL PANEL AND DOOR ENTRANCES. TO CARRY OUT JOINT SEALANT WORKS AND STONE CHIP TREATMENT	New	6,700.00	3,450.00
8	TO RENEW LHS FRONT RIM. TO CARRY OUR WHEEL ALIGNMENT	New	280.00	280.00
9	TO CARRY OUT DIAGNOSTIC CHECK	New	384.00	384.00
Gross Labour Cost (S\$)			22,924.00	14,994.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >