

BMW Dealer

Performance Motors LimitedA member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

24 JAN 2019

E S T I M A T E

Estimate No. : b1 49886		Page No. : 1 of 5	
Date Estimated : 24/01/2019			
Prepared By : Inthiran A/L Thurasamy			

- ESTIMATE REPAIR FOR - Hong Meng Loong (Fang Minglong) 1 Berwick Drive Singapore 559891	- ACCOUNT - 238 AXA Insurance Pte Ltd 8 Shenton Way #24-01 AXA Tower Singapore 068811
---	--

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKN9119D	WE60509	30/11/2018	520i	0

DESCRIPTION	VALUE
To replace front bumper, bonnet, fender right, inner supports, attachments and repair front right fender.	3400 w/handlay support 5100 5,950.00
Painting front bumper, fender right, bonnet and front right door.	3695. 4,106.00
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	150 177.00
To replace right headlight.	408. 481.00
To carry out body cavity preservation. (Per panel).	200. 236.00
To check steering geometry and conduct wheel alignment according to BMW specification (1x)	451 ? 531.00
Sundries.	? 150.00
Total Labour 1: 11,631.00	

DESCRIPTION	QTY	PRIC	VALUE
FRT RH SIDE PANEL BRACKET 1	1	57.05	? 57.05
FRT RH SIDE PANEL ALUMINIUM	1	929.15	61 829.15
COVER GRILLE RH	1	78.10	? 78.10
GRILLE AIR INLET OPEN RH (LINES)	1	87.35	ut 87.35
RH PROTECTIVE STRIP LINES (SPORT)	1	51.95	ut 51.95
IMPACT ABSORBER TOP	1	62.05	? 62.05
FRT BUMPER CARRIER	1	723.05	? 723.05
RH FOG LAMP SUPPORT	1	64.70	? 64.70
RH GUIDE TOP	1	34.55	? 34.55
RH BUMPER GUIDE	1	16.15	rec 16.15
FRT BUMPER PANEL PRIMED (PMA/PDC)	1	1,348.75	de 1,348.75
SET MOUNTING PDC/PMA SENSOR FRT	1	77.60	rec 77.60
PLAQUE 74MM	1	71.25	rec 71.25

Car In

Performance Motors LimitedA member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No.	: b1 49886	Page No. : 2 of 5
Date Estimated	: 24/01/2019	
Prepared By	: Inthiran A/L Thurasamy	

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKN9119D	WE60509	30/11/2018	520i	0

DESCRIPTION	QTY	PRIC	VALUE
RH HEADLIGHT MOUNTING	1	140.20	re 140.20
FRT RH WHEEL ARCH FRT SECTION COVER	1	132.05	de 132.05
RH COVER BOTTOM	1	66.25	? 66.25
FRT ENGINE BONNET SEAL	1	33.70	? 33.70
UPPER RH ENGINE COMPARTMENT COVER	1	35.80	? 35.80
RH SEALING SIDE PANEL	1	51.50	de 51.50
RH LED MODULE DAYTIME DRIVING LIGHT	1	229.10	? 229.10
RH LED MODULE DIRECTION INDICATOR	1	786.65	? 786.65
RH HEADLIGHT LED AHL HIGH (ICON LIG	1	4,855.25	cr 4,855.25
CONTROL UNIT FRT LIGHT ELECTRONICS	1	893.90	? 893.90
Total Parts :			10,826.10

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement	
Regn No.	Claim No.
Date&Time 24/1/19 @ 1620	Excess S\$
Surveyor's Name Tanjir	Sign
Surveyor's Tel 97495749	Authorised Yes / No
Authorised Date WP	Time
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No	
Surveyor's E-mail tanjir@lkkauto.com	
No. of Working Days Recommend 7-9 days	

Labour 1	:	11,631.00
Parts	:	10,826.10
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,572.00
Grand Total	:	24,029.10

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **