

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0107/2019/KN
Date : 23-Jan-19

Vehicle not IN workshop. Kindly arrange for survey.

Your insured vehicle number : SMC 5899 X

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms. Adeline Goh I'Ling
Address : Blk 673 Hougang Ave 8
#09-651
Singapore 530673
Telephone : HP +65 96863160
Type of Claim : Own Damage Claim
Policy No. : 180081532
Vehicle No : **SMC 5899 X**
Model Code : Audi A3 Sedan 1.0 TFSI 8v
Model / Year : Jul-18
Engine No : CHZ 953027
Chassis No : WAUZZZ8V7JA118914
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 18-Jan-19
Place of Accident : Carpark of Goodwood Grand

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMC 5899 X

S/n	Nature of Jobs	Estimated Charges
1	To remove and reinstall rear parking aid. Check function.	S/N \$ 280.00 ✓
2	To dismantle and renew rear bumper. To inspect rhs rear fender for further damages. Re-organise crash management components. Reinstall all parts removed.	\$ 900.00 500
3	To respray rear bumper.	\$ 800.00 550
4	To carry out diagnostic check	S/N \$ 192.00 ✓
TOTAL LABOUR CHARGES - FRONT		: \$ <u>2,172.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMC 5899 X

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER COVER <i>Rehond</i>	\$ 1,708.00	✓
2	REAR BUMPER STICKY PAD <i>new</i>	\$ 11.00	+
3	REAR BUMPER FIXING PARTS <i>set new</i>	\$ 175.00	+
4	REAR BUMPER LOCKING MECHNISM - LH <i>2</i>	\$ 12.00	+
5	REAR BUMPER LOCKING MECHNISM - RH <i>2</i>	\$ 12.00	+
6	REAR ADAPTER WHEEL HOUSING LINER - LH <i>2</i>	\$ 34.00	+
7	REAR ADAPTER WHEEL HOUSING LINER - RH <i>2</i>	\$ 34.00	+
8	REAR BUMPER SPOILER <i>Rehond</i>	\$ 216.00	✓
9	REAR SIDE LIGHT REFLECTOR - RH <i>new</i>	\$ 27.00	+
10	REAR BUMPER SIDE REINFORCEMENTS <i>new</i>	\$ 522.00	+
11	REAR BUMPER BRACKET - RH <i>new</i>	\$ 26.00	+
12	REAR BUMPER GUIDE SECTION - RH <i>new</i>	\$ 60.00	+
13	REAR BUMPER SENSOR <i>the new</i>	2 \$ 462.00	+
14	REAR BUMPER SENSOR SEAL RING <i>new</i>	4 \$ 12.00	+
15	REAR LED TAIL LIGHT - RH <i>Cracked</i>	\$ 800.00	✓
16	SUNDRIES <i>?</i>	\$ 300.00	?
TOTAL SPARE PARTS CHARGES		\$ 4,411.00	
TOTAL LABOUR CHARGES		\$ 2,172.00	
GRAND TOTAL		\$ 6,583.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

: Adnan (L)
: 25/01/19.

: Authorised Repairs, 03 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant