

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0116/2019/KN
Date : 24-Jan-19

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle no : SKQ 7394 Y

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms. Tan Lay Hoon
Address : 352 Laurel Wood Avenue
Singapore 275959
Telephone : HP +65 97862823
Type of Claim : Own Damage Claims
Policy No. : 2100395403-04
Vehicle No : **SKQ 7394 Y**
Model Code : A4 1.8 TFSI MU
Model / Year : Dec-14
Engine No : CJE 090117
Chassis No : WAUZZZ8K5FA045622
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 24-Jan-19
Place of Accident : TRAFFIC LIGHT OF NORTH BUONA VISTA ROAD

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SKQ 7394 Y

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To tow and recover vehicle from scene of accident	S/N	\$280.00	X
2	To remove and transfer rear parking aid. Check function.	S/N \$	280.00	✓
3	To remove and transfer rear lid's convenience lock system and wire harness for tail light	S/N \$	280.00	✓
4	To dislodge and reinstall rear wire harness for tail lights, battery manager, fuse, relay trays, electrical and audio components.	S/N \$	480.00	✓ ?
SUB - TOTAL LABOUR CHARGES		:	<u><u>\$1,320.00</u></u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
 Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SKQ 7394 Y

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
5	To dismantle and reinstall centre console. Renew airbag control unit and both front seatbelt.	S/N \$ 1,800.00	✓
6	To dismantle and renew rear bumper and rear lid. Cut out and reweld end panelling. To repair spare wheel housing. To inspect for further damages. Reorganise rear crash management components. Reinstall all parts removed.	\$ 4,800.00	1500,
7	To respray rear bumper, rear lid, both rear fender, hinges, spare wheel housing and end panelling. To carry out joint sealer works and stone chip treatment.	\$ 4,400.00	3 x 550 = 1650 2 Hinge = 300 1950.
8	To carry out diagnostic check	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: <u><u>\$12,512.00</u></u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKQ 7394 Y

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER <i>Distorted</i>	\$ 2,100.00	✓
2	REAR BUMPER STICKY PAD <i>3</i>	4 \$ 21.00	+
3	REAR BUMPER FIXING PARTS <i>3</i>	\$ 206.00	+
4	REAR BUMPER SPOILER - LH <i>6t</i>	\$ 243.00	✓
5	REAR BUMPER CARRIER <i>?</i>	\$ 587.00	?
6	HOLDER FOR BUMPER BRACKET - LH <i>?</i>	\$ 203.00	?
7	HOLDER FOR BUMPER BRACKET - RH <i>?</i>	\$ 203.00	?
8	REAR BUMPER GUIDE SECTION - LH <i>2</i>	\$ 40.00	+
9	REAR BUMPER GUIDE SECTION - RH <i>2</i>	\$ 41.00	+
10	REAR BUMPER GUIDE SECTION - UPPER LH <i>2</i>	\$ 21.00	+
11	REAR BUMPER GUIDE SECTION - UPPER RH <i>2</i>	\$ 20.00	+
13	REAR LID SECURING STRIP <i>2</i>	\$ 12.00	✓
14	REAR PARKING SENSOR <i>2</i>	4 \$ 838.00	✓
15	REAR PARKING SENSOR SEAL RING <i>2</i>	4 \$ 5.00	✓
16	REAR BUMPER WIRING SET <i>2</i>	\$ 472.00	+
17	REAR LID <i>Distorted</i>	\$ 2,554.00	✓
18	REAR LID ATTACHMENT PARTS <i>?</i>	\$ 67.00	?
19	REAR LID HINGE - LH <i>2</i>	\$ 233.00	✓
20	REAR LID HINGE - RH <i>2</i>	\$ 233.00	✓
SUB TOTAL SPARE PARTS CHARGES		\$ 8,099.00	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKQ 7394 Y

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	REAR LID GASKET FOR FLAP ?	\$ 185.00 ?	
22	REAR LID STOP BUFFER - LH/RH ?	2 \$ 50.00 ?	
23	REAR LID COVER ?	2 \$ 66.00 ?	
24	REAR LID CLOSING ELEMENT - LH ?	\$ 29.00 ?	
25	REAR LID CLOSING ELEMENT - RH ?	\$ 29.00 ?	
26	REAR LID STOP CAP - LH/ RH ?	2 \$ 6.00 ?	
27	REAR STOP BUFFER ?	2 \$ 51.00 ?	
28	REAR STOPPER ?	2 \$ 14.00 ?	
29	REAR LID LOCK <i>Ignored</i>	\$ 199.00 ✓	
30	REAR LID LOCK COVER <i>Ignored</i>	\$ 18.00 ✓	
31	PROTECTIVE CAP ?	\$ 18.00 ?	
32	REAR LID LOCK STRIKER ?	\$ 45.00 ?	
33	PUSH BUTTON FOR ELECTRIC LOCK LID ACTUATOR ?	\$ 167.00 ?	
34	GUARD PLATE ?	\$ 56.00 ?	
35	SEAL FOR PUSH BUTTON <i>new</i>	\$ 14.00 ✕	
36	BOOT DAMPER <i>new</i>	\$ 109.00 ✕	
37	BALL STUD <i>new</i>	\$ 19.00 ✕	
38	PACKING ADHESIVE <i>new</i>	\$ 18.00 ✓	
39	AUDI EMBLEM <i>new</i>	\$ 113.00 ✓	
40	CHROME INSCRIPTION - A4 <i>new</i>	\$ 87.00 ✓	
SUB TOTAL SPARE PARTS CHARGES		\$ 1,293.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKQ 7394 Y

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
41	CHROME INSCRIPTION - TFSI <i>all</i>	\$ 87.00	✓
42	REAR CROSS PANEL - OUTER ?	\$ 286.00	?
43	REAR REINFORCEMENT BEAN - INNER ?	\$ 484.00	?
44	REAR CROSS PANEL - LOWER ?	\$ 794.00	?
45	REAR LID TRIM PANEL ?	\$ 240.00	?
46	TRIM FOR REAR CROSS PANEL ?	\$ 168.00	?
47	LUGGAGE COMP. FLOOR COVERING ?	\$ 646.00	?
48	LED TAIL LIGHT - LEFT <i>cut</i>	\$ 824.00	✓
49	LED TAIL LIGHT - RIGHT ?	\$ 824.00	?
50	LICENSE PLATE LIGHT <i>RH cancelled</i>	2 \$ 105.00 52.50	
51	EXHAUST TAIL PIPE <i>new</i>	2 \$ 557.00	+
52	SEAT BELT WITH TENSIONER - LH } <i>Activated</i>	\$ 1,005.00	✓
53	SEAT BELT WITH TENSIONER - RH } <i>Activated</i>	\$ 1,005.00	✓
54	TAIL PIPE ADJUSTMENT FITTING <i>new</i>	2 \$ 357.00	+
55	AIRBAG CONTROL UNIT } <i>Activated</i>	\$ 1,927.00	✓
56	CENTRAL PROTECTION } <i>Activated</i>	\$ 543.00	✓
57	STONE CHIP ?	S/N \$ 180.00	?
58	REAR NO.PLATE <i>Bent</i>	S/N \$ 25.00	✓
59	ACRYLIC SEALANT ?	S/N \$ 180.00	?
60	CAVITY WAX ?	S/N \$ 140.00	?
SUB TOTAL SPARE PARTS CHARGES		: \$ 10,377.00	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKQ 7394 Y

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
61	SUNDRIES ?	\$ 1,000.00	?
	TOTAL SPARE PARTS CHARGES	\$ 20,769.00	
	TOTAL LABOUR CHARGES	\$ 12,512.00	
	GRAND TOTAL	\$ 33,281.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *Adrian Gij*
Surveyed Date : *25/01/19*
Authorised Date :
Excess Cost :
Liability :
Remarks : *Not Authorised, 05 Rps.*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant