

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19001694/ABA3Q2
Date: 18/08/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100236321
Claimant
Vehicle No : SFR7242G **Insured Vehicle No :** SJZ3234S
 Date of Loss: 11/12/2018 Nature of Claim: TP Claim No: 2817214800SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SFR7242G**
 Make & Model: LAND ROVER DISCOVERY SPORT, 2.0 HSE (A) Engine No: 015074153002204PT
 Reg. Date: 02/03/2017 (Man. Year: 2017) Chassis No: SALCA2AG5HH676483
 Colour: Black Odometer: 39193 km
 Engine Capacity: 1999 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 235/55 R19 Rear Tyre Size: 235/55 R19
 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
 Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,183.48	3,675.51	8,507.97	69.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,960.00	1,010.00	950.00	48.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	14,143.48	4,685.51	9,457.97	66.87
+ Car Rental (4.0 x S\$170.00/day) (S\$)		680.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,372.96		
Global Sum Settlement (S\$)		5,350.00		

INSPECTION

Date of Assignment: 24/01/2019
 Date Inspected: 24/01/2019 Inspected At: Chin Meng Motors (HQ)
 1 Kaki Bukit Ave 6 #01-40/63, Autobay
 @ Kaki Bukit
 Singapore 417883
 Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Repair	4,528.50 FL	*- FL
2	1		*TAILGATE EMBLEM -SPORT	Necessary	45.80 FL	*45.80 FL
3	1		*TAILGATE EMBLEM -LAND ROVER	Necessary	85.60 FL	*85.60 FL
4	1		*TAILGATE EMBLEM -HSE SI4	Necessary	55.60 FL	*55.60 FL
5	1		*TAILGATE EMBLEM -DISCOVERY	Necessary	62.50 FL	*62.50 FL
6	1		*TAILGATE WEATHERSTRIP	Not Necessary	385.50 FL	*- FL
7	1		*REAR BUMPER	Deformed	2,242.70 FL	*2,242.70 FL
8	1		*REAR BUMPER REFLECTORS	N/S Cracked	267.00 FL	*133.00 FL
9	1		*REAR BUMPER INNER GARNISH	Not Necessary	355.60 FL	*- FL
10	1		*REAR BUMPER BEAM	Not Necessary	855.60 FL	*- FL
11	2		*REAR BUMPER SIDE BRACKETS	Not Necessary	331.60 FL	*- FL
12	2		*REAR BUMPER SIDE RETAINERS	Necessary	197.00 FL	*197.00 FL
13	4		*REAR BUMPER REVERSE SENSOR	Damaged (2 PCS ONLY)	1,009.20 FL	*504.60 FL
14	4		*REAR BUMPER REVERSE SENSOR HOLDERS	Necessary (2 PCS ONLY)	140.80 FL	*70.40 FL
15	1		*REAR BUMPER TOW COVER	Not Necessary	58.50 FL	*- FL
16	1		*REAR BUMPER CENTRE PAD (SILVER)	Deformed	686.70 FL	*686.70 FL
17	1		*REAR END PANEL	Repair	1,685.50 FL	*- FL
18	1		*REAR END PANEL GARNISH	Not Necessary	543.50 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	13,537.20	4,083.90
- List Item Discount on L Items 10.00/10.00% (\$)	1,353.72	408.39
Total Parts (\$)	12,183.48	3,675.51

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEATING ,WELDING ,REMOVING DAMAGED PARTS AND REPLACEMENT OF THE NEW PARTS AS MENTIONED ABOVE ETC	New	850.00	400.00
2	TO RESPRAY AFFECTED PART	New	900.00	500.00
3	TO APPLY UNDERSEAL	New	100.00	0.00
4	TO RESET FAULT CODE AFTER REPAIR	New	80.00	80.00
5	TO CHECK WIRINGS	New	30.00	30.00
			Gross Labour Cost (\$\$)	1,960.00
				1,010.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >