

# 振明摩托

## CHIN MENG MOTORS

1 Kaki Bukit Ave 6, #01-40 Autobay@Kaki Bukit, Singapore 417883  
 Tel: 6747-4810 Fax: 6745-5018  
 cmmotors@singnet.com.sg  
 Our Ref: EST027/18/TP  
 Your Ref: TP claim against SJZ3234S

### ESTIMATE

24-Jan-19

**AIG Asia Pacific Insurance Pte Ltd**  
 78 Shenton Way  
 #08-16  
 Singapore 409179

cc6/AUG19001674/Alva3

Vic

**Attn: Motor Claims Department**

Dear Sir/Ms,

**Re: Estimated cost of repair to Land Rover Discovery no: SFR7242G**

Date of accident: 11-12-2018

Parts supply:

1 pc Tailgate <i>Ryri</i>		SS\$ 4,528.50 +
1 pc Tailgate emblem - SPORT		45.80 ✓
1 pc Tailgate emblem - LAND ROVER		85.60 ✓
1 pc Tailgate emblem - HSE Si4		55.60 ✓
1 pc Tailgate emblem - DISCOVERY		62.50 ✓
1 pc Tailgate weatherstrip <i>new</i>		385.50 +
1 pc Rear bumper <i>del</i>		2,242.70 ✓
2 pcs Rear bumper reflectors @\$133.50 <i>lit cancelled</i>		<del>267.00</del> 133.50
1 pc Rear bumper inner garnish <i>new</i>		355.60 +
1 pc Rear bumper beam <i>new</i>		855.60 +
2 pcs Rear bumper side brackets @\$165.80 <i>new</i>		331.60 +
2 pcs Rear bumper side retainers @\$98.50 <i>new</i>		197.00 ✓
4 pcs Rear bumper reverse sensor @\$252.30 <i>2 pieces damaged</i>		1,009.20 <del>504.60</del>
4 pcs Rear bumper reverse sensor holders @\$35.20 <i>2 pieces new</i>		140.80 <i>pieces</i>
1 pc Rear bumper tow cover <i>new</i>		58.50 +
1 pc Rear bumper centre pad (silver) <i>del</i>		686.70 ✓
1 pc Rear end panel <i>Ryri</i>		1,685.50 +
1 pc Rear end panel garnish <i>new</i>		543.50 +
		<u>13,537.20</u>
		Less 10%: (1,353.72)

4083.90  
3675.51

Labour charges:

To panel beating, welding, removing damaged parts and replacement of the new parts as mentioned above etc.

To respray affected part.

To supply underseal

To reset fault code after repair

To check wirings.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

	850.00 <i>car</i>
	<del>900.00</del> <i>500</i>
	100.00 +
	80.00 ✓
	30.00 ✓
SS\$	<u>14,143.48</u>

1010  
 total: 4685.51  
 (P/P)  
 P/P 24/01/19  
 03 Rps.