

振明摩哆 CHIN MENG MOTORS

1 Kaki Bukit Ave 6, #01-40 Autobay@Kaki Bukit, Singapore 417883
Tel: 6747-4810 Fax: 6745-5018
cmmotors@singnet.com.sg

Our Ref: CMM062/20/TP

31-Mar-20

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16
Singapore 079120

Attn: Motor Claims Department

Dear Sir/Ms,

Re: Final cost of repair to Land Rover Discovery no: SFR7242G

Date of accident: 11-12-2018

Parts supply:

1 pc Tailgate emblem - SPORT	S\$	45.80
1 pc Tailgate emblem - LANDROVER		85.60
1 pc Tailgate emblem - HSE Si4		55.60
1 pc Tailgate emblem - DISCOVERY		62.50
1 pc Rear bumper		2,242.70
1 pc Rear bumper reflector L/h		133.00
1 pc Rear bumper inner garnish		197.00
1 pc Rear bumper beam		504.60
2 pcs Rear bumper reverse sensor holder @\$35.20		70.40
1 pc Rear bumper centre pad (silver)		686.70
		<hr/>
		4,083.90
		(408.39)

Labour charges:

To panel beating, welding, removing damaged parts and replacement of the new parts as mentioned above etc.		400.00
To respray affected part.		500.00
To reset fault code after repair.		80.00
To check wirings.		30.00
	S\$	<hr/> <hr/>
		4,685.51

Dollars: Four thousand six hundred eighty five and cents fifty one only.

振明摩哆
CHIN MENG MOTORS

